

List of Subjects in 14 CFR Part 33

Air Transportation, Aircraft, Aviation, Aviation safety, Safety.

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

The Proposed Special Conditions

Accordingly, the Federal Aviation Administration (FAA) proposes the following special conditions as part of the type certification basis for Pratt and Whitney Canada PW210A engine model.

Flat 30-Second and 2-Minute OEI*1. Part 1.1 Definitions*

“Rated Flat 30-second and 2-minute One Engine Inoperative (OEI) Power,” with respect to rotorcraft turbine engines, means (1) a single rating for which the shaft horsepower and associated operating limitations of the 30-second OEI and 2-minute OEI ratings are equal, and (2) the shaft horsepower is that developed under static conditions at the altitude and temperature for the hot day, and within the operating limitations established under Part 33. The rating is for continuation of flight operation after the failure or shutdown of one engine in multiengine rotorcraft, for up to three periods of use no longer than 2.5 minutes each in any one flight, and followed by mandatory inspection and prescribed maintenance action.

2. Part 33 Requirements

(a) The airworthiness standards in Part 33 Amendment 30 for the 30-second OEI and 2-minute OEI ratings are applicable to the Flat 30-second and 2-minute OEI Power rating. In addition the following special conditions apply;

(b) Section 33.7 Engine ratings and operating limitations. Flat 30-second and 2-minute OEI Power rating and operating limitations are established for power, torque, rotational speed, gas temperature, and time duration.

(c) Section 33.27 Turbine, compressor, fan, and turbosupercharger rotor overspeed. The requirements of § 33.27, except that following the test, the rotor may not exhibit conditions such as cracking or distortion which preclude continued safe operation.

(d) Section 33.28 Engine controls systems. Must incorporate a means, or a provision for a means, for automatic availability and automatic control of the Flat 30-second and 2-minute OEI Power within the declared operating limitations.

(e) Section 33.29 Instrument Connection. In lieu of the requirements

of 33.29(c) the PW210A must incorporate a means or a provision for a means to:

(1) Alert the pilot when the engine is at the Flat 30-second and 2-minute OEI Power level, when the event begins, and when the time interval expires;

(2) Automatically record each usage and duration of power at the Flat 30-second and 2-minute OEI Power rating;

(3) Following each flight when the Flat 30-second and 2-minute OEI Power rating is used, alert maintenance personnel in a positive manner that the engine has been operated at the Flat 30-second and 2-minute OEI Power level, and permit retrieval of the recorded data; and

(4) Enable routine verification of the proper operation of the above means.

(f) Section 33.87 Endurance test. The requirements applicable to 30-second and 2-minute OEI ratings, except for:

(1) The test of § 33.87(a)(7) for the purposes of temperature stabilization, must be run with a test period time of 2.5 minutes.

(2) The tests in § 33.87(f)(2) and (3) must be run continuously for the duration of 2.5 minutes, and

(3) The tests in § 33.87(f)(6) and (7) must be run continuously for the duration of 2.5 minutes.

(g) Section 33.88 Engine overtemperature test. The requirements of § 33.88(b) except that the test time is 5 minutes instead of 4 minutes.

Issued in Burlington, Massachusetts, on May 18, 2015.

Carlos Pestana,

Acting Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2015-12986 Filed 5-27-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2015-1425; Directorate Identifier 2014-NM-185-AD]

RIN 2120-AA64

Airworthiness Directives; Lockheed Martin Corporation/Lockheed Martin Aeronautics Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Lockheed Martin Corporation/Lockheed Martin Aeronautics Company Model

188 series airplanes. This proposed AD was prompted by an evaluation by the design approval holder (DAH) indicating that a certain circumferential fuselage splice is subject to widespread fatigue damage (WFD). This proposed AD would require an inspection for corrosion and previous repairs, severed stringers, cracking, and loose or distressed fasteners of the forward and aft ends of the stringer splices of certain stringers, inspection for cracking and modification of certain fastener holes common to the stringer and splice member at the forward and aft ends of the splice, and related investigative and corrective actions if necessary. We are proposing this AD to prevent loss of residual strength of a certain circumferential fuselage splice, which could lead to rapid decompression of the cabin and potential loss of the airplane.

DATES: We must receive comments on this proposed AD by July 13, 2015.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Lockheed Martin Corporation/Lockheed Martin Aeronautics Company, Airworthiness Office, Dept. 6A0M, Zone 0252, Column P-58, 86 S. Cobb Drive, Marietta, GA 30063; phone: 770-494-5444; fax: 770-494-5445; email: ams.portal@lmco.com; Internet <http://www.lockheedmartin.com/ams/tools/TechPubs.html>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-1425; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday,

except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Carl Gray, Aerospace Engineer, Airframe Branch, ACE-117A, FAA, Atlanta Aircraft Certification Office (ACO), 1701 Columbia Avenue, College Park, GA 30337; phone: 404-474-5554; fax: 404-474-5605; email: carl.w.gray@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2015-1425; Directorate Identifier 2014-NM-185-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

Structural fatigue damage is progressive. It begins as minute cracks, and those cracks grow under the action of repeated stresses. This can happen because of normal operational conditions and design attributes, or because of isolated situations or incidents such as material defects, poor fabrication quality, or corrosion pits, dings, or scratches. Fatigue damage can occur locally, in small areas or structural design details, or globally. Global fatigue damage is general degradation of large areas of structure with similar structural details and stress levels. Multiple-site damage is global damage that occurs in a large structural element such as a single rivet line of a lap splice joining two large skin panels. Global damage can also occur in multiple elements such as adjacent frames or stringers. Multiple-site-damage and multiple-element-damage cracks are typically too small initially to be reliably detected with normal

inspection methods. Without intervention, these cracks will grow, and eventually compromise the structural integrity of the airplane, in a condition known as WFD. As an airplane ages, WFD will likely occur, and will certainly occur if the airplane is operated long enough without any intervention.

The FAA's WFD final rule (75 FR 69746, November 15, 2010) became effective on January 14, 2011. The WFD rule requires certain actions to prevent structural failure due to WFD throughout the operational life of certain existing transport category airplanes and all of these airplanes that will be certificated in the future. For existing and future airplanes subject to the WFD rule, the rule requires that DAHs establish a limit of validity (LOV) of the engineering data that support the structural maintenance program. Operators affected by the WFD rule may not fly an airplane beyond its LOV, unless an extended LOV is approved.

The WFD rule (75 FR 69746, November 15, 2010) does not require identifying and developing maintenance actions if the DAHs can show that such actions are not necessary to prevent WFD before the airplane reaches the LOV. Many LOVs, however, do depend on accomplishment of future maintenance actions. As stated in the WFD rule, any maintenance actions necessary to reach the LOV will be mandated by airworthiness directives through separate rulemaking actions.

In the context of WFD, this action is necessary to enable DAHs to propose LOVs that allow operators the longest operational lives for their airplanes, and still ensure that WFD will not occur. This approach allows for an implementation strategy that provides flexibility to DAHs in determining the timing of service information development (with FAA approval), while providing operators with certainty regarding the LOV applicable to their airplanes.

This proposed AD was prompted by an evaluation by the DAH indicating that the circumferential fuselage splice at fuselage-station (FS) 695 is subject to WFD. The root cause of this WFD is fatigue cracks manifesting and growing simultaneously at similar structural details and stress levels at the circumferential fuselage splice. Fatigue cracking is increasingly likely as the airplane is operated and aged, and without intervention, fatigue cracking could lead to loss of residual strength of the circumferential fuselage splice at FS 695, which could lead to rapid decompression of the cabin area and potential loss of the airplane.

Related Service Information Under 1 CFR Part 51

We reviewed Lockheed Martin Electra Service Bulletin 88/SB-722, dated April 30, 2014. This service bulletin describes procedures for doing the following actions:

- A general visual inspection (GVI) for corrosion and previous repairs, severed stringers, cracking, and loose or distressed fasteners of the forward and aft ends of the stringer splices of stringers 1-7 and 66-72, and corrective actions if necessary.

- At stringers 1-7 and 66-72, removing the four rivets common to the stringer and splice member at the forward and aft ends of the splice and doing a bolt hole eddy current (BHEC) inspection or an equivalent inspection procedure for cracking in each of the fastener holes, and corrective actions if necessary.

- Corrective actions for cracked holes include reaming to the maximum permissible hole diameter of the next larger size rivet. If a crack indication remains after reaming, this service information specifies repairing the cracked stringer.

- If a severed stringer is found during the GVI, doing related investigative actions of an eddy current surface scan inspection for cracking of the fuselage skin at the skin-to-stringer attachments immediately forward and aft of the stringer break and confirming skin cracks with a dye penetrant inspection. Corrective actions include repairing the severed stringer or skin cracks.

- For holes without crack indications, other specified actions include modifying the fastener holes by reaming to a certain maximum permissible hole diameter of the same size rivet and installing replacement fasteners; or if original hole is larger than the maximum permissible diameter, installing the next rivet size and type.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this NPRM.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described

previously, except as discussed under “Differences Between this Proposed AD and the Service Information.”

Differences Between This Proposed AD and the Service Information

Although Lockheed Martin Electra Service Bulletin 88/SB-722, dated April 30, 2014, specifies that crack indications should be confirmed by an alternate inspection method, this proposed AD would not require that action.

Operators should note that, although the Accomplishment Instructions of Lockheed Martin Electra Service Bulletin 88/SB-722, dated April 30, 2014, describe procedures for

submitting a report of damage, this proposed AD would not require that action.

Lockheed Martin Electra Service Bulletin 88/SB-722, dated April 30, 2014, does not describe corrective actions if any corrosion or previous repair is found, and if any loose or distressed fastener is found. This proposed AD would require repair.

Explanation of Proposed Compliance Time

The compliance time for the modification specified in this proposed AD for addressing WFD was established to ensure that discrepant structure is

replaced before WFD develops in airplanes. Standard inspection techniques cannot be relied on to detect WFD before it becomes a hazard to flight. We will not grant any extensions of the compliance time to complete any AD-mandated service bulletin related to WFD without extensive new data that would substantiate and clearly warrant such an extension.

Costs of Compliance

We estimate that this proposed AD affects 4 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspections and Modification	18 work-hours × \$85 per hour = \$1,530	\$5,000	\$6,530	\$26,120

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Lockheed Martin Corporation/Lockheed Martin Aeronautics Company: Docket No. FAA-2015-1425; Directorate Identifier 2014-NM-185-AD.

(a) Comments Due Date

We must receive comments by July 13, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Lockheed Martin Corporation/Lockheed Martin Aeronautics Company Model 188A and 188C airplanes, certificated in any category, serial numbers 1001 and subsequent.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder (DAH) indicating that the circumferential fuselage splice at fuselage-station (FS) 695 is subject to widespread fatigue damage (WFD). We are issuing this AD to prevent loss of residual strength of the circumferential fuselage splice at FS 695, which could lead to rapid decompression of the cabin and potential loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspections, Modification, Related Investigative Actions, and Corrective Actions

Before the accumulation of 38,200 total flight hours or within 30 days after the effective date of this AD, whichever occurs later: Do a general visual inspection for corrosion and previous repairs, severed stringers, cracking, and loose or distressed fasteners of the forward and aft ends of the stringer splices of stringers 1-7 and 66-72; remove the four rivets common to the stringer and splice member at the forward and aft ends of the splice and do a bolt hole eddy current inspection or an equivalent inspection procedure for cracking in each of the fastener holes; modify the fastener holes;

and do all applicable related investigative and corrective actions and other specified actions; in accordance with the Accomplishment Instructions of Lockheed Martin Electra Service Bulletin 88/SB-722, dated April 30, 2014, except as specified in paragraph (h) of this AD. Do all applicable related investigative and corrective actions and other specified actions before further flight. If any repairs exceed the repair limits specified in Lockheed Martin Electra Service Bulletin 88/SB-722, dated April 30, 2014, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(h) Corrective Action

(1) If, during any inspection required by paragraph (g) of this AD, any corrosion or previous repair is found, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(2) If, during any inspection required by paragraph (g) of this AD, any loose or distressed fastener is found, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(i) Exception

Although Lockheed Martin Electra Service Bulletin 88/SB-722, dated April 30, 2014, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

(1) For more information about this AD, Carl Gray, Aerospace Engineer, Airframe Branch, ACE-117A, FAA, Atlanta ACO, 1701 Columbia Avenue, College Park, GA 30337; phone: 404-474-5554; fax: 404-474-5605; email: carl.w.gray@faa.gov.

(2) For service information identified in this AD, contact Lockheed Martin Corporation/Lockheed Martin Aeronautics Company, Airworthiness Office, Dept. 6A0M, Zone 0252, Column P-58, 86 S. Cobb Drive, Marietta, GA 30063; phone: 770-494-5444; fax: 770-494-5445; email: ams.portal@lmco.com; Internet <http://www.lockheedmartin.com/ams/tools/TechPubs.html>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on May 19, 2015.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-12859 Filed 5-27-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 91

[Docket No.: FAA-2015-1746; Notice No. 15-05]

RIN 2120-AK54

Changes to the Application Requirements for Authorization to Operate in Reduced Vertical Separation Minimum Airspace

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action would revise the FAA's requirements for an application to operate in Reduced Vertical Separation Minimum (RVSM) airspace. This proposal would eliminate the burden and expense of developing, processing, and approving RVSM maintenance programs. As a result of this proposed revision, an applicant to operate in RVSM airspace would no longer be required to develop and submit an RVSM maintenance program solely for the purpose of an RVSM authorization. Because of other, independent FAA airworthiness regulations, all aircraft operators would nevertheless continue to be required to maintain RVSM equipment in an airworthy condition.

DATES: Send comments on or before July 27, 2015.

ADDRESSES: Send comments identified by docket number FAA-2015-1746 using any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov> and follow the online instructions for sending your comments electronically.
- *Mail:* Send comments to Docket Operations, M-30; U.S. Department of Transportation (DOT), 1200 New Jersey Avenue SE., Room W12-140, West Building Ground Floor, Washington, DC 20590-0001.

- *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Fax:* Fax comments to Docket Operations at 202-493-2251.

Privacy: In accordance with 5 U.S.C. 553(c), DOT solicits comments from the public to better inform its rulemaking process. DOT posts these comments, without edit, including any personal information the commenter provides, to www.regulations.gov, as described in the system of records notice (DOT/ALL-14 FDMS), which can be reviewed at www.dot.gov/privacy.

Docket: Background documents or comments received may be read at <http://www.regulations.gov> at any time. Follow the online instructions for accessing the docket or go to Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: For technical questions concerning this action, contact Charles Fellows, Aviation Safety Inspector, Avionics Branch, Aircraft Maintenance Division, Flight Standards Services, AFS-360, Federal Aviation Administration, 950 L'Enfant Plaza North SW., Washington, DC 20024; telephone (202) 267-1706; email Charles.Fellows@faa.gov.

For legal questions concerning this action, contact Benjamin Jacobs, Attorney-Advisor, Office of Chief Counsel, AGC-200, Federal Aviation Administration, 800 Independence Ave. SW., Washington, DC 20591; telephone (202) 267-7240; email Benjamin.Jacobs@faa.gov.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Sections 106(f), 40113, and 44701 authorize the FAA Administrator to prescribe regulations necessary for aviation safety. Section 40103 authorizes the Administrator to prescribe regulations to enhance the efficiency of the national airspace. This rulemaking is within the scope of these authorities because it would remove existing safety and airspace-related regulations that the FAA no longer finds necessary to protect aviation safety.

I. Executive Summary

A. Summary of Proposed Rule

This Notice of Proposed Rulemaking (NPRM) proposes to remove the requirement in Appendix G of part 91 of Title 14 of the Code of Federal Regulations (14 CFR) that any operator seeking Reduced Vertical Separation Minimum (RVSM) authorization must