

Proposed Rules

Federal Register

Vol. 80, No. 153

Monday, August 10, 2015

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF AGRICULTURE

Grain Inspection, Packers and Stockyards Administration

9 CFR Part 201

Market Agencies Selling on Commission; Purchases From Consignment

AGENCY: Grain Inspection, Packers and Stockyards Administration, USDA.

ACTION: Request for information; Extension of comment period.

SUMMARY: We published a Request for Information in the **Federal Register** on June 15, 2015 (80 FR 34097), asking for comments regarding a regulation issued under the Packers and Stockyards Act, 1921, as amended and supplemented (P&S Act). GIPSA regulations address circumstances under which a market agency selling livestock on a commission basis may permit its owners, officers, and employees to purchase livestock from consignments to the market. The Request for Information provided an opportunity for interested parties to submit written comments to the Grain Inspection, Packers and Stockyards Administration (GIPSA) until August 14, 2015. In response to requests from the livestock industry, we are extending the comment period to provide interested parties with additional time in which to comment.

DATES: The comment period for the Request for Information published at 80 FR 34097, June 15, 2015, which originally was to close August 14, 2015, is extended through October 13, 2015.

ADDRESSES: We invite you to submit comments on this Request for Information. You may submit comments by any of the following methods:

- *E-Mail:* Send comments via electronic mail to comments.gipsa@usda.gov.

- *Mail:* Send hardcopy written comments to M. Irene Omade, GIPSA, USDA, 1400 Independence Avenue SW., Room 2530-S, Washington, DC 20250-3613.

- *Fax:* Send comments by facsimile transmission to: (202) 690-2173.

- *Hand Delivery or Courier:* Deliver comments to: M. Irene Omade, GIPSA, USDA, 1400 Independence Avenue SW., Room 2530-S, Washington, DC 20250-3613.

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the on-line instructions for submitting comments.

Instructions: All comments should make reference to the date and page number of the June 15, 2015, issue of the **Federal Register** [80 FR 34097].

Read Comments: Regulatory analyses and other documents relating to this action will be available for public inspection in Room 2530-S, 1400 Independence Avenue SW., Washington, DC 20250-3613 during regular business hours. All comments will be available for public review in the above office during regular business hours (7 CFR 1.27(b)). Please call the Management and Budget Services staff of GIPSA at (202) 720-8479 to arrange a viewing of comments.

FOR FURTHER INFORMATION CONTACT: S. Brett Offutt, Director, Litigation and Economic Analysis Division, P&SP, GIPSA, 1400 Independence Ave. SW., Washington, DC 20250-3601, (202) 690-4355, s.brett.offutt@usda.gov.

SUPPLEMENTARY INFORMATION: GIPSA published a Request for Information in the **Federal Register** on June 15, 2015 (80 FR 34097), seeking public comment regarding Section 201.56 of the regulations issued under the P&S Act. The comment period of 60 days from the date of publication closes on August 14, 2015. GIPSA has received requests from the livestock industry to provide interested parties additional time to comment. In response, the comment period is extended for additional 60-day period. All comments submitted between June 15, 2015 and October 13, 2015 will be considered.

Larry Mitchell,

Administrator, Grain Inspection, Packers and Stockyards Administration.

[FR Doc. 2015-19528 Filed 8-7-15; 8:45 am]

BILLING CODE 3410-KD-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-3300; Directorate Identifier 2015-CE-024-AD]

RIN 2120-AA64

Airworthiness Directives; Fiberglas-Technik Rudolf Lindner GmbH & Co. KG Gliders

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for Fiberglas-Technik Rudolf Lindner GmbH & Co. KG Model G103 TWIN ASTIR, G103 TWIN II, and G103A TWIN II ACRO gliders. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as a broken bell-crank installed in the air brake control system. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by September 24, 2015.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Fiberglas-Technik Rudolf Lindner GmbH & Co. KG, Steige 3, D-88487 Walpertshofen, Germany; phone: ++49

(0) 7353/22 43; fax: ++49 (0) 7353/30 96; email: info@LTB-Lindner.com; internet: <http://www.ltb-lindner.com/>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3300; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Jim Rutherford, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2015-3300; Directorate Identifier 2015-CE-024-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No.: 2015-0116, dated June 24, 2015 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

A report was received concerning a broken bell-crank, installed in the air brake control circuit approximately 1.4 m outside the wing root rib of a GROB G 103 Twin II sailplane. Preliminary investigation results revealed additional cases of cracks on the same part, installed in the air brake control systems of the early Twin II type design.

The same bell-cranks are also installed at the same location in the control systems of other models belonging to the same type design (see list of affected models under Applicability).

This condition, if not detected and corrected, could lead to failure of the air brake system, possibly resulting in reduced control of the sailplane.

To address this potential unsafe condition, Fiberglas-Technik issued Technische Mitteilung (TM)/Service Bulletin (SB) TM-G08/SB-G08 (one document) and Anweisung (A)/Instructions (I) A/I-G08 (one document) to provide instructions for a check of the air brake locking forces, the inspection of the bell-crank and, if cracks are found, replacement of the bell-crank.

Additionally, TM-G07/SB-G07 (one document) and A/I-G07 (one document) provide instructions for the installation of inspection openings in the wing of GROB G 103 TWIN II and G 103 A TWIN II ACRO sailplanes to facilitate the inspection of the bell-crank. (For the TWIN ASTIR and TWIN ASTIR TRAINER sailplanes, such an opening is required by LBA AD 92-190/2 (GROB SB 315-45/2.) This installation is optional for sailplanes not exceeding the original intended life limit.

For the reason described above, this AD requires a check of the air brake locking forces, an inspection for cracks in the air brake control unit and, if cracks are found, replacement of the affected flight control system parts. This AD is a temporary measure and further AD action may follow.

You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3300.

Related Service Information Under 1 CFR Part 51

Fiberglas-Technik Rudolf Lindner GmbH & Co. KG has issued Fiberglas-Technik Rudolf Lindner Technische Mitteilung (English translation: Service Bulletin), (TM-G08)/(SB-G08), Ausgabe (English translation: Edition) April 24, 2015; and Fiberglas-Technik Rudolf Lindner Anweisung (English translation: Instructions), (A/I-G08), Ausgabe (English translation: Edition) April 24, 2015. The service information describes procedures for inspecting the air brake locking forces; inspecting the bell-crank; and, if cracks are found during the inspections, replacing the bell-crank. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this NPRM.

Interim Action

We consider this AD interim action. The design approval holder is working toward a terminating action for the inspections. We may take further AD action in the future.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 106 products of U.S. registry. We also estimate that it would take about 2 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$18,020, or \$170 per product.

In addition, we estimate that any necessary follow-on actions would be as follows:

- Replacement of bell-crank would take about 5 work-hours per product. Required parts would cost about \$566 for a total of \$991 per product.
- Installation of optional inspection openings would take about 15 work-hours per product. Required parts would cost about \$1,004 for a total of \$2,279 per product.

We have no way of determining the number of products that may need these actions.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this AD is 2120-0056. The paperwork cost associated with this AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and

reviewing the collection of information. Therefore, all reporting associated with this AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW., Washington, DC 20591. ATTN: Information Collection Clearance Officer, AES-200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

Fiberglas-Technik Rudolf Lindner GmbH & Co. KG: Docket No. FAA-2015-3300; Directorate Identifier 2015-CE-024-AD.

(a) Comments Due Date

We must receive comments by September 24, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Fiberglas-Technik Rudolf Lindner GmbH & Co. KG Model G103 TWIN ASTIR, G103 TWIN II, and G103A TWIN II ACRO gliders, all manufacturer serial numbers, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 27: Flight Controls.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as a broken bell-crank installed in the air brake control system. We are issuing this AD to detect and correct a broken bell-crank which could lead to failure of the air brake system, possibly resulting in reduced control.

(f) Actions and Compliance

Unless already done, do the following actions:

(1) Within 30 days after the effective date of this AD and repetitively thereafter at intervals not to exceed 12 months, inspect the locking forces of the air brake control unit, and, if any discrepancy is found, before further flight, correct the locking forces. Do the inspection and correction of any discrepancy following the instructions of Fiberglas-Technik Rudolf Lindner Technische Mitteilung (English translation: Service Bulletin), (TM-G08)/(SB-G08), Ausgabe (English translation: Edition) April 24, 2015; and Fiberglas-Technik Rudolf Lindner Anweisung (English translation: Instructions), (A/I-G08), Ausgabe (English translation: Edition) April 24, 2015.

Note 1 to paragraph (f)(1) of this AD: This service information contains German to English translation. The European Aviation Safety Agency (EASA) used the English translation in referencing the document. For

enforceability purposes, we will refer to the Fiberglas-Technik Rudolf Lindner service information as it appears on the document.

(2) Within 60 days after the effective date of this AD, inspect the bell-crank installed in the air brake control system, and, if any cracks are found, before further flight, replace the bell-crank with a serviceable part. Do the inspection and replacement following the instructions of Fiberglas-Technik Rudolf Lindner Technische Mitteilung (English translation: Service Bulletin), (TM-G08)/(SB-G08), Ausgabe (English translation: Edition) April 24, 2015; and Fiberglas-Technik Rudolf Lindner Anweisung (English translation: Instructions), (A/I-G08), Ausgabe (English translation: Edition) April 24, 2015.

Note 2 to paragraph (f)(1) of this AD: In the lower wing surface inspection, openings near the bell-crank may be installed to simplify the inspection and make a possible replacement of the bell-crank possible. This optional installation is described in GROB Luft Und Raumfahrt Service Bulletin 315-45/2, dated December 21, 1995; and Fiberglas-Technik Rudolf Lindner Technische Mitteilung (English translation: Service Bulletin), (TM-G07)/(SB-G07), Ausgabe (English translation: Edition) April 24, 2015.

(3) Within 30 days after replacing a bell-crank as required by paragraph (f)(2) of this AD, report the inspection results of the removed bell-crank to Fiberglas-Technik Rudolf Lindner GmbH & Co. KG. You may find contact information for Fiberglas-Technik Rudolf Lindner GmbH & Co. KG in paragraph (h) of this AD.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Jim Rutherford, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information

collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(h) Related Information

Refer to MCAI EASA AD No.: 2015-0116, dated June 24, 2015; GROB Luft Und Raumfahrt Service Bulletin 315-45/2, dated December 21, 1995; and Fiberglas-Technik Rudolf Lindner Technische Mitteilung (English translation: Service Bulletin), (TM-G07)/(SB-G07), Ausgabe (English translation: Edition) April 24, 2015, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3300. For service information related to this AD, contact Fiberglas-Technik Rudolf Lindner GmbH & Co. KG, Steige 3, D-88487 Walpertshofen, Germany; phone: ++49 (0) 7353/22 43; fax: ++49 (0) 7353/30 96; email: info@LTB-Lindner.com; internet: <http://www.ltb-lindner.com/>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on July 31, 2015.

Earl Lawrence,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-19323 Filed 8-7-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOUSING AND URBAN DEVELOPMENT

24 CFR Part 200

[Docket No. FR-5850-P-01]

RIN 2502-AJ28

Retrospective Review—Improving the Previous Participation Reviews of Prospective Multifamily Housing and Healthcare Programs Participants

AGENCY: Office of the Assistant Secretary for Housing—Federal Housing Commissioner, HUD.

ACTION: Proposed rule.

SUMMARY: This proposed rule would revise HUD's regulations for reviewing the previous participation in federal programs of certain participants seeking to take part in multifamily housing and healthcare programs administered by HUD's Office of Housing. Specifically, the proposed rule would clarify and

simplify the process by which HUD reviews the previous participation of participants that have decision-making authority over their projects as one component of HUD's responsibility to assess financial and operational risk to the projects in these programs. The proposed rule would clarify which individuals and entities will be reviewed, HUD's purpose in conducting such review, and describe the review to be undertaken. By targeting more closely the individuals and actions that would be subject to prior participation review, HUD not only brings greater certainty and clarity to the process but provides HUD with flexibility as to the necessary previous participation review for entities and individuals that is not possible in a one-size fits all approach. Through this rule, HUD proposes to replace the current previous participation regulations in their entirety.

DATES: *Comment Due Date:* October 9, 2015.

ADDRESSES: Interested persons are invited to submit comments regarding this proposed rule to the Regulations Division, Office of General Counsel, Department of Housing and Urban Development, 451 7th Street SW., Room 10276, Washington, DC 20410-0500. Communications must refer to the above docket number and title. There are two methods for submitting public comments. All submissions must refer to the above docket number and title.

1. Submission of Comments by Mail. Comments may be submitted by mail to the Regulations Division, Office of General Counsel, Department of Housing and Urban Development, 451 7th Street SW., Room 10276, Washington, DC 20410-0500.

2. Electronic Submission of Comments. Interested persons may submit comments electronically through the Federal eRulemaking Portal at www.regulations.gov. HUD strongly encourages commenters to submit comments electronically. Electronic submission of comments allows the commenter maximum time to prepare and submit a comment, ensures timely receipt by HUD, and enables HUD to make them immediately available to the public. Comments submitted electronically through the www.regulations.gov Web site can be viewed by other commenters and interested members of the public. Commenters should follow the instructions provided on that site to submit comments electronically.

Note: To receive consideration as public comments, comments must be submitted through one of the two methods specified

above. Again, all submissions must refer to the docket number and title of the rule.

No Facsimile Comments. Facsimile (fax) comments are not acceptable.

Public Inspection of Public Comments. All properly submitted comments and communications submitted to HUD will be available for public inspection and copying between 8 a.m. and 5 p.m., weekdays, at the above address. Due to security measures at the HUD Headquarters building, an appointment to review the public comments must be scheduled in advance by calling the Regulations Division at 202-708-3055 (this is not a toll-free number). Individuals with speech or hearing impairments may access this number via TTY by calling the Federal Relay Service at 800-877-8339. Copies of all comments submitted are available for inspection and downloading at www.regulations.gov.

FOR FURTHER INFORMATION CONTACT:

Aaron Hutchinson, Office of Housing, Department of Housing and Urban Development, 451 7th Street SW., Room 6178, Washington, DC 20410; telephone number 202-708-3994 (this is not a toll-free number). Individuals with speech or hearing impairments may access this number through TTY by calling the toll-free Federal Relay Service at 800-877-8339 (this is not a toll-free number).

SUPPLEMENTARY INFORMATION:

I. Background

Currently, applicants seeking to participate in HUD's multifamily housing and healthcare programs must certify that all principals involved in a proposed project have acted responsibly and have honored their legal, financial, and contractual obligations in their previous participation in HUD programs, in certain programs administered by the U.S. Department of Agriculture, and in projects assisted or insured by state and local government housing finance agencies. HUD's regulations governing the assessment of previous participation are codified in 24 CFR part 200, subpart H (Subpart H), and require applicants to complete a very detailed and lengthy certification form (HUD Form 2530).¹

The 2530 form currently requires disclosure of all principals to be involved in the proposed project, a list of projects in which those principals have previously participated or currently participate in, a detailed account of the principals' involvement in the listed project(s), and assurances that the principals have upheld their

¹ See <http://portal.hud.gov/hudportal/documents/huddoc?id=2530.pdf>.