

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2015–17–17 Pratt & Whitney: Amendment 39–18250 ; Docket No. FAA–2014–1130; Directorate Identifier 2015–NE–04–AD.

(a) Effective Date

This AD is effective October 2, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Pratt & Whitney (PW) PW4164–1D, PW4168–1D, PW4168A–1D and PW4170 engines; and all PW4164, PW4168, and PW4168A turbofan engines that have incorporated either PW Service Bulletin (SB) No. PW4G–100–72–214, dated December 15, 2011 or PW SB No. PW4G–100–72–219, Revision 1, dated October 5, 2011.

(d) Unsafe Condition

This AD was prompted by fuel nozzle-to-fuel supply manifold interface fuel leaks. We are issuing this AD to prevent fuel leaks which could result in engine fire and damage to the airplane.

(e) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Within 800 flight hours after the effective date of this AD, and within every 800 flight hours since last inspection thereafter, inspect all fuel nozzle-to-fuel supply manifold interfaces for evidence of fuel leaks, soot, and coke formation. Use the Accomplishment Instructions, Part A, of PW Alert Service Bulletin (ASB) No. PW4G–100–A73–44, Revision 1, dated February 12, 2015 to do the inspections.

(2) Replace hardware that fails an inspection. Use the Accomplishment Instructions, Part A, of PW ASB No. PW4G–100–A73–44, Revision 1, dated February 12, 2015 to do the replacement.

(f) Mandatory Terminating Action

As terminating action to the repetitive inspection requirements in paragraph (e)(1) of this AD do the following:

(1) Inspect all fuel nozzle-to-fuel supply manifold interfaces for fuel leaks, soot, and coke formation, replace hardware that fails inspection, and re-torque all fuel nozzle-to-fuel supply manifold B-nuts as follows:

(i) For engines with fewer than 1,500 cycles on the effective date of this AD, before accumulating another 650 cycles, not to exceed 1,900 cycles.

(ii) For engines with 1,500 cycles or more, but less than 2,500 cycles on the effective date of this AD, before accumulating another 400 cycles, not to exceed 2,700 cycles.

(iii) For engines with 2,500 cycles or more on the effective date of this AD, before accumulating another 200 cycles.

(2) Use the Accomplishment Instructions, Parts B through E, of PW ASB No. PW4G–100–A73–44, Revision 1, dated February 12, 2015 to do the inspection, replacement, and retorquing.

(g) Credit for Previous Action

This paragraph provides credit for the actions required by paragraphs (e) and (f) of this AD, if the actions were performed before the effective date of this AD, using the procedures specified in PW ASB No. PW4G–100–A73–44, dated October 10, 2014 or Special Instruction 129F–14.

(h) Definition

For the purpose of this AD “cycles” is defined as cycles since new or cycles since last torque application to the B-nuts on the fuel nozzle installation.

(i) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(j) Related Information

For more information about this AD, contact Katheryn Malatek, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781–238–7747; fax: 781–238–7199; email: katheryn.malatek@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Pratt & Whitney (PW) ASB No. PW4G–100–A73–44, Revision 1, dated February 12, 2015.

(ii) Reserved.

(3) For PW service information identified in this AD, contact Pratt & Whitney, 400 Main St., East Hartford, CT 06108; phone: 860–565–8770; fax: 860–565–4503.

(4) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781–238–7125.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on August 18, 2015.

Diane S. Romanosky,

Acting Directorate Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2015–21204 Filed 8–27–15; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2015–0823; Directorate Identifier 2014–NM–211–AD; Amendment 39–18249; AD 2015–17–16]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL–600–2B19 (Regional Jet Series 100 & 440) airplanes. This AD was prompted by results of a design review indicating that the burst pressure of the flexible hose, used to vent oxygen from the high-pressure relief valve of the oxygen cylinder overboard, was lower than the opening pressure of the high-pressure relief valve, which could cause the flexible hose to burst before it can vent the excess oxygen overboard. This AD requires replacing the oxygen hose assembly with a new, improved assembly. We are issuing this AD to prevent the accumulation of oxygen in an enclosed space, which could result in an uncontrolled oxygen-fed fire if an ignition source is nearby.

DATES: This AD becomes effective October 2, 2015.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 2, 2015.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov/#/docketDetail;D=FAA-2015-0823> or in person at the Docket Management Facility, U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0823.

FOR FURTHER INFORMATION CONTACT:

Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (516) 228-7318; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. The NPRM published in the **Federal Register** on April 13, 2015 (80 FR 19570).

Transport Canada Civil Aviation (TCCA), which is the airworthiness authority for Canada, has issued Canadian Airworthiness Directive CF-2014-36, dated October 17, 2014 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. The MCAI states:

Design review found that the burst pressure of the flexible hose, used to vent oxygen from the high-pressure relief valve of the oxygen cylinder overboard, is lower than the opening pressure of the high-pressure relief valve. This could cause the flexible hose to burst before it is able to vent the excess oxygen overboard. If an ignition source is present, the accumulation of oxygen in an enclosed space may result in an uncontrolled oxygen-fed fire.

This [Canadian] AD mandates the replacement of the oxygen hose assembly with a new design oxygen hose assembly.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/>

#!documentDetail;D=FAA-2015-0823-0002.

Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM (80 FR 19570, April 13, 2015) and the FAA’s response to each comment.

Request To Extend the Compliance Time

Mesa Airlines asked that the compliance time specified in paragraph (g) of the NPRM (80 FR 19570, April 13, 2015) be changed. Mesa Airlines stated that the current compliance time would immediately ground airplanes on the effective date of the AD. Mesa Airlines asked that we change the compliance time to “Within 6,000 flight hours, or within 44 months after the effective date of this AD, whichever occurs first.” Mesa Airlines added that this would allow for scheduling with heavy maintenance inspection and parts procurement.

We partially agree with the request. We have changed the compliance time in paragraph (g) of this AD to “Within 5,800 flight hours or 44 months after the effective date of this AD, whichever occurs first.” This change matches the compliance time in the MCAI, and will allow operators to remain in compliance.

We do not agree that the compliance time should be extended to “Within 6,000 flight hours, or within 44 months after the effective date of this AD, whichever occurs first”. After considering all the available information, we have determined that the compliance time represents an appropriate interval of time in which the required actions can be performed in a timely manner within the affected fleet, while still maintaining an adequate level of safety. In developing an appropriate compliance time, we considered the safety implications, parts availability, and normal maintenance schedules for timely accomplishment of the replacement. However, if additional data are presented that would justify a longer compliance time, we may consider further rulemaking on this issue. We have not changed the AD in this regard.

Request To Refer To Revised Service Information

Richard Rupslauskas asked that we include Bombardier Service Bulletin 601R-35-018, Revision A, in the NPRM (80 FR 19570, April 13, 2015), and give credit for Bombardier Service Bulletin 601R-35-018, dated May 21, 2013. The

commenter stated that Revision A should be distributed very soon, and added that no additional work will be required on aircraft that have had the modification incorporated using the original issue of the service information. The commenter added that the NPRM should recognize that either the original or Revision A of the service information is acceptable as a method of compliance.

We do not agree to reference Bombardier Service Bulletin 601R-35-018, Revision A, because that revision has not yet been issued. However, after Revision A is issued, affected operators may request approval to use that revision of the referenced service bulletin as an alternative method of compliance, under the provisions of paragraph (i)(1) of this AD.

Request To Include Parts Cost

Richard Rupslauskas stated that the parts cost is \$835 per airplane, and added that since 575 airplanes are affected, the total cost for parts is \$480,125.

We infer that the commenter wants the parts cost included in the “Costs of Compliance” section of this AD. We agree to include the parts cost of \$835 in that section. We have changed this AD accordingly.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this AD with the changes described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (80 FR 19570, April 13, 2015) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (80 FR 19570, April 13, 2015).

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

Related Service Information Under 1 CFR Part 51

Bombardier has issued Service Bulletin 601R-35-018, dated May 21, 2013. The service information describes procedures for replacing the oxygen hose assembly with a new, improved assembly. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI. This service information is reasonably available because the interested parties have access to it

through their normal course of business or by the means identified in the ADDRESSES section of this AD.

Costs of Compliance

We estimate that this AD affects 575 airplanes of U.S. registry.

We also estimate that it takes about 2 work-hours per product to comply with the basic requirements of this AD. Required parts will cost about \$835 per product. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$577,875, or \$1,005 per airplane.

According to the manufacturer, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and

4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2015-0823>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the ADDRESSES section.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2015-17-16 Bombardier, Inc.: Amendment 39-18249. Docket No. FAA-2015-0823; Directorate Identifier 2014-NM-211-AD.

(a) Effective Date

This AD becomes effective October 2, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes, certificated in any category, serial numbers 7003 and subsequent.

(d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

(e) Reason

This AD was prompted by results of a design review indicating that the burst pressure of the flexible hose, used to vent oxygen from the high-pressure relief valve of the oxygen cylinder overboard, was lower than the opening pressure of the high-pressure relief valve, which could cause the

flexible hose to burst before it can vent the excess oxygen overboard. We are issuing this AD to prevent the accumulation of oxygen in an enclosed space, which could result in an uncontrolled oxygen-fed fire if an ignition source is nearby.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

Within 5,800 flight hours or 44 months after the effective date of this AD, whichever occurs first: Replace all oxygen hose assemblies having part number (P/N) 38026-4-0280-000 with new, improved assemblies having P/N 601R44045-1, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 601R-35-018, dated May 21, 2013.

(h) Parts Installation Prohibition

As of the effective date of this AD, no person may install an oxygen hose assembly, P/N 38026-4-0280-000, on any airplane.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2014-36, dated October 17, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2015-0823-0002>.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 601R-35-018, dated May 21, 2013.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crij@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 17, 2015.

Kevin Hull,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-20959 Filed 8-27-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-0455; Directorate Identifier 2014-NM-006-AD; Amendment 39-18247; AD 2015-17-14]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Airbus Model A319, A320, and A321 series airplanes. This AD was prompted by reports that during a full scale fatigue test, several broken frames in certain areas of the cargo compartment have been found, especially on the cargo floor support fittings and open tack holes on the left-hand side. This AD requires a rototest inspection of the open tack holes and rivet holes at the cargo floor support fittings of the fuselage, including doing all applicable related investigative actions, and repair if necessary. We are issuing this AD to detect and correct cracking in the open tack holes and rivet holes at the cargo floor support fittings of the fuselage, which could affect the structural integrity of the airplane.

DATES: This AD becomes effective October 2, 2015.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of October 2, 2015.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2014-0455>; or in person at the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Airbus, Airworthiness Office—ELAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0455.

FOR FURTHER INFORMATION CONTACT:

Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Model A319, A320, and A321 series airplanes. The NPRM published in the **Federal Register** on July 23, 2014 (79 FR 42716).

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2013-0310, dated December 20, 2013 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A319, A320, and A321 series airplanes. The MCAI states:

During a full scale fatigue test, several broken frames in the cargo compartment area between Frame (FR) 50 and FR 63, have been found, especially on the cargo floor support fittings and open tack holes on [the] left hand side.

This condition, if not detected and corrected, could affect the structural integrity of the aeroplane.

For the reason described above, this [EASA] AD requires repetitive inspections of the frames in the cargo compartment area and of the cargo floor support fittings and open tack holes on the left hand (LH) side, and depending on findings, the accomplishment of applicable corrective action(s). This [EASA] AD also requires a modification, which constitutes terminating action for the repetitive inspections required by this [EASA] AD.

The actions in this AD include a rototest inspection for cracking of the open tack holes and rivet holes at the cargo floor support fittings of the fuselage; modification of the fuselage, including doing all applicable related investigative actions; and repair if necessary. Related investigative actions include rotating probe inspections for cracking of the holes. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-0455-0002>.

Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM (79 FR 42716, July 23, 2014) and the FAA’s response to each comment.

Requests To Remove Service Information Not Applicable to the U.S. Fleet

Delta Air Lines (DAL), United Airlines (UAL), and US Airways requested that certain service information be removed from the NPRM (79 FR 42716, July 23, 2014) as it is not applicable to the U.S. fleet.

DAL stated that Airbus Service Bulletin A320-53-1261, dated December 21, 2012, which provides a terminating modification for the repetitive inspections specified in the NPRM (79 FR 42716, July 23, 2014), is one of eight structural modification service bulletins required to operate Model A320 airplanes beyond 48,000 flight cycles/96,000 flight hours (referred to as extended service goal (ESG)). DAL stated that Airbus Service Bulletin A320-53-1261, dated December 21, 2012, does not affect DAL or any other U.S. operator, since Airbus only recognizes airplane effectivity for those operators that have accomplished this service bulletin (which can only be purchased from Airbus) through ESG embodiment.

UAL and US Airways stated that, in paragraph (h) of the proposed AD (79 FR 42716, July 23, 2014), modification of the fuselage in accordance with Airbus