

Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on October 5, 2015.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-26217 Filed 10-16-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-4213; Directorate Identifier 2015-CE-022-AD]

RIN 2120-AA64

Airworthiness Directives; Piper Aircraft, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Piper Aircraft, Inc. Model PA-46-500TP airplanes. This proposed AD was prompted by a report of the wing upper skin joints being manufactured without sealant, which allows water to enter and stay in sealed, bonded stringers. This proposed AD would require inspecting the upper wing surface for sealant; inspecting the wing stringers for water intrusion; inspecting for deformation and corrosion if evidence of water intrusion exists; and taking corrective actions as necessary. We are proposing this AD to correct the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by December 3, 2015.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5

p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Piper Aircraft, Inc., Customer Service, 2926 Piper Drive, Vero Beach, Florida 32960; telephone: (877) 879-0275; fax: none; email: customer.service@piper.com; Internet: www.piper.com. You may review the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-4213; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Gregory "Keith" Noles, Aerospace Engineer, FAA, Atlanta Aircraft Certification Office, 1701 Columbia Avenue, College Park, Georgia 30337; phone: (404) 474-5551; fax: (404) 474-5606; email: gregory.noles@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2015-4213; Directorate Identifier 2015-CE-022-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each

substantive verbal contact we receive about this proposed AD.

Discussion

We received a report of wing upper skin joints on Piper Aircraft, Inc. Model PA-46-500TP airplanes being manufactured without sealant, which allows water to enter and stay in sealed, bonded stringers. This condition, if not corrected, could result in water entering the stringers common to the upper wing skin. Left uncorrected, corrosion could develop, and freeze/thaw cycles of water at this location could cause deformation of the skin with follow-on disbonding between the stringer flanges and the inner surface of the wing skin. Consequently, the corrosion or disbonding could reduce the structural integrity of the wing.

Related Service Information Under 14 CFR Part 51

We reviewed Piper Aircraft, Inc. Service Bulletin No. 1262B, dated April 23, 2015. The service bulletin provides instructions for inspecting the upper wing surface for sealant and sealing or resealing (if necessary). This service bulletin also provides instructions for inspecting the wing stringers for water intrusion, and, if water intrusion was found as a result of the inspection, inspecting for corrosion or deformation. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this NPRM.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

We estimate that this proposed AD affects 440 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection for sealant	2 work-hours × \$85 per hour = \$170	Not Applicable	\$170	\$74,800

We estimate the following costs to do any additional necessary inspections, rework of the stringers, and installation

of sealant that would be required based on the results of the proposed initial inspection. We have no way of

determining the number of airplanes that might need this rework of the stringers and installation of sealant:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Rework stringers and seal skin joints	12 work-hours × \$85 per hour = \$1,020	\$200	\$1,220

According to the manufacturer, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Piper Aircraft, Inc.: Docket No. FAA–2015–4213; Directorate Identifier 2015–CE–022–AD.

(a) Comments Due Date

We must receive comments by December 3, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Piper Aircraft, Inc. Model PA–46–500TP airplanes, serial numbers 4697001 through 4697528, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 5700, Wings.

(e) Unsafe Condition

This AD was prompted by a report of wing upper skin joints being manufactured without sealant, which allows water to enter and stay in sealed, bonded stringers. We are issuing this AD to prevent water from entering the stringers common to the upper wing skin. Left uncorrected, corrosion could develop, and freeze/thaw cycles of water at this location could cause deformation of the skin with follow-on disbonding between the stringer flanges and the inner surface of the wing skin. Consequently, the corrosion or disbonding could reduce the structural integrity of the wing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspect the Upper Skin Joints for Adequate Sealant

Within the next 100 hours time-in-service (TIS) after the effective date of this AD or 12 months after the effective date of this AD, whichever occurs first, inspect the upper skin joints for adequate sealant following Part I of Piper Aircraft, Inc. Service Bulletin No. 1262B, dated April 23, 2015. No further action per this AD is required if adequate sealant is already applied.

(h) Inspect for Evidence of Water Intrusion/Moisture

If you find missing or inadequate sealant during the inspection required by paragraph (g) of this AD, before further flight, inspect for evidence of water intrusion/moisture following Part II of Piper Aircraft, Inc. Service Bulletin No. 1262B, dated April 23, 2015.

(1) If no evidence of water intrusion/moisture is found during the inspection required in paragraph (h) of this AD, before further flight, rework the stringers and apply sealant as required in paragraph (k) of this AD.

(2) If evidence of water intrusion/moisture is found during the inspection required in

paragraph (h) of this AD, before further flight, do the actions required in paragraphs (i) and (j) of this AD.

(i) Inspect for Corrosion

If you find, as a result of the inspection required by paragraph (h) of this AD, evidence of water intrusion/moisture, before further flight, inspect for corrosion following Part II of Piper Aircraft, Inc. Service Bulletin No. 1262B, dated April 23, 2015.

(1) If no evidence of corrosion is found during the inspection required in paragraph (i) of this AD, before further flight, rework the stringers and apply sealant as required in paragraph (k) of this AD.

(2) If evidence of corrosion is found during the inspection required in paragraph (i) of this AD, before further flight, obtain and implement an FAA-approved corrective action, approved specifically for this AD. At the operator's discretion, assistance may be provided by contacting Piper Aircraft, Inc. at the address identified in paragraph (o)(2) of this AD. After obtaining and implementing an FAA-approved corrective action, approved specifically for this AD, before further flight, rework the stringers and apply sealant as required in paragraph (k) of this AD.

(j) Inspect for Deformation

If you find, as a result of the inspection required by paragraph (h) of this AD, evidence of water intrusion/moisture, before further flight, do a visual inspection for skin or stringer deformation.

(1) If no evidence of deformation is found during the inspection required in paragraph (j) of this AD, before further flight, rework the stringers and apply sealant as required in paragraph (k) of this AD.

(2) If any visible deformation is found during the inspection required in paragraph (j) of this AD, before further flight, obtain and implement an FAA-approved corrective action, approved specifically for this AD. At the operator's discretion, assistance may be provided by contacting Piper Aircraft, Inc. at the address identified in paragraph (o)(2) of this AD. After obtaining and implementing an FAA-approved corrective action, approved specifically for this AD, before further flight, rework the stringers and apply sealant as required in paragraph (k) of this AD.

(k) Rework Stringers and Seal Skin Joints

If any inspection required by paragraphs (g) through (j) of this AD reveals discrepancies (no sealant/inadequate sealant, evidence of water intrusion/moisture, corrosion, or deformation), before further flight, after completing any necessary corrective actions, rework wing stringers and seal skin joints following Part II of Piper Aircraft, Inc. Service Bulletin No. 1262B, dated April 23, 2015.

(l) Credit for Actions Done in Accordance With Previous Service Information

Actions done before the effective date of this AD following Part I and Part II of Piper Aircraft, Inc. Service Bulletin No. 1262, dated October 16, 2013; or Part I and Part II of Piper Aircraft, Inc. Service Bulletin No. 1262A, dated November 14, 2013, as applicable, are

considered acceptable for compliance with the corresponding actions specified in paragraphs (g), (h), (i), and (k) (including subparagraphs) of this AD. Additional inspections beyond Service Bulletin No. 1262 are required to fully comply with paragraph (j) of this AD.

(m) Special Flight Permit

(1) In accordance with 14 CFR 39.23, a single flight is allowed to a location to do the actions in paragraph (g) of this AD.

(2) In accordance with 14 CFR 39.23, a single flight is allowed to a location to do the inspections, rework and installation of sealant required in paragraphs (h) through (k) of this AD. Prior to the flight to perform the inspections, rework, and installation of sealant, the following inspection must be performed: If the inspection required by paragraph (g) of this AD reveals no sealant, inspect for evidence of wing damage (skin or stringer deformation, e.g. buckling). Any wing damage that is found must be repaired before further flight and before any special flight permit is authorized.

(n) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(o) Related Information

(1) For more information about this AD, contact Gregory "Keith" Noles, Aerospace Engineer, FAA, Atlanta ACO, 1701 Columbia Avenue, College Park, Georgia 30337; phone: (404) 474-5551; fax: (404) 474-5606; email: gregory.noles@faa.gov.

(2) For service information identified in this AD, contact Piper Aircraft, Inc., Customer Service, 2926 Piper Drive, Vero Beach, Florida 32960; telephone: (877) 879-0275; fax: none; email: customer.service@piper.com; Internet: www.piper.com. You may view this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on October 7, 2015.

Pat Mullen,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-26230 Filed 10-16-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 73

[Docket No. FAA-2015-3680; Airspace Docket No. 13-ASW-15]

RIN 2120-AA66

Proposed Establishment of and Modification to Restricted Areas; Fort Sill, OK

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to establish 2 new restricted areas (R-5601G and R-5601H) to expand the special use airspace (SUA) complex located at Fort Sill, OK, to provide additional maneuvering airspace for current and planned training activities determined to be hazardous to non-participating aircraft. Specifically, the proposed restricted areas would provide participating fighter or bomber aircraft with laser-firing and maneuvering airspace when training at the Falcon Bombing Range contained in R-5601C, at the West Range Target Area contained in R-5601B, or at the East Range Target Area contained in R-5601A. In addition, the using agency for all Fort Sill restricted areas would be updated to reflect the current organization tasked with that responsibility. The U.S. Army requested that the FAA take this action to allow realistic training on current tactics developed and refined during recent combat operations for employing hazardous targeting laser systems and weapons capabilities at longer ranges from the target area.

DATES: Comments must be received on or before December 3, 2015.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, M-30, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001; telephone: (202) 366-9826. You must identify FAA Docket No. FAA-2015-3680 and Airspace Docket No. 13-ASW-15, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>. Comments on environmental and land use aspects to should be directed to: Mr. Glen Wheat, U.S. Army Garrison, Directorate of Public Works, IMWE-SIL-PWE, 5503 NW. Currie Road, Fort Sill, OK 73503-9051; email: glen.wheat@us.army.mil and telephone: (580) 442-2715.