

By order of the Board of Governors of the Federal Reserve System, acting through the Director of the Division of Monetary Affairs under delegated authority, November 12, 2015.

**Robert deV. Frierson,**  
Secretary of the Board.

[FR Doc. 2015-29336 Filed 11-16-15; 8:45 am]

BILLING CODE 6210-01-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2015-0929; Directorate Identifier 2014-NM-218-AD; Amendment 39-18323; AD 2015-23-07]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier, Inc. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Bombardier, Inc. Model BD-100-1A10 (Challenger 300) airplanes. This AD was prompted by multiple reports of chafing found on an electrical wiring harness in the aft equipment bay, caused by contact between the wiring harness and a neighboring hydraulic line. This AD requires an inspection, repair if necessary, and modification of the wiring harness installation to ensure that the wiring harness routing is correct and a minimum clearance between the wire and the hydraulic line is maintained. We are issuing this AD to detect and correct chafing on an electrical wiring harness, which could cause an electrical short circuit or lead to a malfunction of the flight control system, the engine indication system, or the hydraulic power control system; and adversely affect the continued safe operation and landing of the airplane.

**DATES:** This AD becomes effective December 22, 2015.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 22, 2015.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2015-0929> or in person at the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone: 514-855-5000; fax: 514-855-7401; email: [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0929.

#### FOR FURTHER INFORMATION CONTACT:

Assata Dessaline, Aerospace Engineer, Avionics and Service Branch, ANE-172, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7301; fax: 516-794-5531.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bombardier, Inc. Model BD-100-1A10 (Challenger 300) airplanes. The NPRM published in the **Federal Register** on May 8, 2015 (80 FR 26490).

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2014-32, dated September 8, 2014 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Bombardier, Inc. Model BD-100-1A10 (Challenger 300) airplanes. The MCAI states:

There have been multiple in-service reports of chafing found on an electrical wiring harness in the aft equipment bay. An investigation determined that the chafing was attributed to contact between the wiring harness and a neighboring hydraulic line. This chafing could cause an electrical short circuit or lead to a malfunction of the flight control system, the engine indication system, or the hydraulic power control system; which could adversely affect the continued safe operation and landing of the aeroplane.

This [Canadian] AD mandates the inspection [general visual inspection], rectification as required [repair of damage (including wear and chafing)], and modification of the wiring harness installation to ensure the correct wiring routing and a minimum clearance between the wire and the hydraulic line is maintained.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2015-0929-0002>.

[www.regulations.gov/#!documentDetail;D=FAA-2015-0929-0002](http://www.regulations.gov/#!documentDetail;D=FAA-2015-0929-0002).

#### Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (80 FR 26490, May 8, 2015) or on the determination of the cost to the public.

#### Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (80 FR 26490, May 8, 2015) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (80 FR 26490, May 8, 2015).

#### Related Service Information Under 14 CFR Part 51

Bombardier, Inc. has issued Service Bulletin 100-24-24, dated June 6, 2014. The service information describes procedures for an inspection, repair if necessary, and modification of the wiring harness installation to prevent contact with the hydraulic line. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this AD.

#### Costs of Compliance

We estimate that this AD affects 107 airplanes of U.S. registry.

We also estimate that it will take about 4 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts will cost about \$64 per product. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$43,228, or \$404 per product.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this AD. We have no way of determining the number of aircraft that might need these actions.

According to the manufacturer, all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2015-0929>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone: 800-647-5527) is in the **ADDRESSES** section.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2015-23-07 Bombardier, Inc.:** Amendment 39-18323. Docket No. FAA-2015-0929; Directorate Identifier 2014-NM-218-AD.

#### (a) Effective Date

This AD becomes effective December 22, 2015.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Bombardier, Inc. Model BD-100-1A10 (Challenger 300) airplanes, certificated in any category, having serial numbers 20003 through 20382 inclusive, 20384, and 20386.

#### (d) Subject

Air Transport Association (ATA) of America Code 24, Electrical Power.

#### (e) Reason

This AD was prompted by multiple reports of chafing found on an electrical wiring harness in the aft equipment bay, caused by contact between the wiring harness and a neighboring hydraulic line. We are issuing this AD to detect and correct chafing on an electrical wiring harness, which could cause an electrical short circuit or lead to a malfunction of the flight control system, the engine indication system, or the hydraulic power control system; which could adversely affect the continued safe operation and landing of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Inspection, Repair, and Preventive Modification

Within 36 months after the effective date of this AD, do the actions required by paragraphs (g)(1) and (g)(2) of this AD.

- (1) Do a one-time general visual inspection to detect damage (including wear and chafing) of the wiring harness, in accordance with the Accomplishment Instructions of Bombardier, Inc. Service Bulletin 100-24-24,

dated June 6, 2014. Repair any damage before further flight, in accordance with the Accomplishment Instructions of Bombardier, Inc. Service Bulletin 100-24-24, dated June 6, 2014; except, where Bombardier, Inc. Service Bulletin 100-24-24, dated June 6, 2014, specifies to contact Bombardier for repair instructions, repair using a method approved by the Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO).

(2) Modify the wiring harness routing, in accordance with the Accomplishment Instructions of Bombardier, Inc. Service Bulletin 100-24-24, dated June 6, 2014.

#### (h) Definition of General Visual Inspection

For the purposes of this AD, a general visual inspection is a visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked.

#### (i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO, ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7300; fax: 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or TCCA; or Bombardier, Inc.'s TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature.

#### (j) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2014-32, dated September 8, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2015-0929-0002>.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier, Inc. Service Bulletin 100–24–24, dated June 6, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone: 514–855–5000; fax: 514–855–7401; email: [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 30, 2015.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2015–28822 Filed 11–16–15; 8:45 am]

**BILLING CODE 4910–13–P**

---

**FEDERAL TRADE COMMISSION**
**16 CFR Parts 500 and 502**
**RIN 3084–AB33**
**Rules, Regulations, Statements of General Policy or Interpretation and Exemptions Under the Fair Packaging and Labeling Act**

**AGENCY:** Federal Trade Commission (“FTC” or “Commission”).

**ACTION:** Final rule.

**SUMMARY:** The Commission amends the rules and regulations promulgated under the Fair Packaging and Labeling Act (“Rules”) to: Modernize the place-of-business listing requirement; incorporate a more comprehensive metric chart; address the use of exponents with customary inch/pound measurements; delete outdated prohibitions on retail price sales representations; and acknowledge the role of the weights-and-measures laws of individual states.

**DATES:** This rule is effective on December 17, 2015. The incorporation by reference of certain publications

listed in the regulations is approved by the Director of the Federal Register as of December 17, 2015.

**ADDRESSES:** Relevant portions of the proceeding, including this document, are available at the Commission’s Web site, [www.ftc.gov](http://www.ftc.gov).

**FOR FURTHER INFORMATION CONTACT:** Megan E. Gray, Attorney, (202) 326–3408, Division of Enforcement, Bureau of Consumer Protection, Federal Trade Commission, 600 Pennsylvania Avenue NW., Washington, DC 20580.

**SUPPLEMENTARY INFORMATION:**
**I. Introduction**

Congress enacted the Fair Packaging and Labeling Act, 15 U.S.C. 1451 *et seq.*, (“FPLA” or “Act”) in 1966 to enable consumers to obtain accurate package quantity information to facilitate value comparisons and prevent unfair or deceptive packaging and labeling of “consumer commodities.”<sup>1</sup> Pursuant to the FPLA, the Commission promulgated the Rules, which generally concern products consumed during household use. However, several categories of these products are exempt from FTC regulations under the FPLA.<sup>2</sup> Moreover, the FTC has excluded certain others from the Rules.<sup>3</sup>

Section 1453 of the Act directs the Commission to issue regulations requiring that all “consumer commodities” be labeled to disclose: (a) The identity of the commodity (*e.g.*, detergent, sponges), which must appear on the principal display panel of the commodity in conspicuous type and position so that identity is easy to read and understand;<sup>4</sup> (b) the name and place of business of the product’s manufacturer, packer, or distributor;<sup>5</sup>

<sup>1</sup> Consumer commodities are any food, device, or cosmetic, and any other article, product, or commodity that is customarily produced or distributed for sale through retail sales agencies or instrumentalities for consumption or use by individuals for purposes of personal care or in the performance of services ordinarily rendered within the household, and which usually is consumed or expended in the course of such consumption or use. 15 U.S.C. 1459(a). The Food and Drug Administration (“FDA”) administers the FPLA with respect to food, drugs, cosmetics, and medical devices. 15 U.S.C. 1454(a); 15 U.S.C. 1456(a).

<sup>2</sup> 15 U.S.C. 1459(a)(1–5) (excluding, among other products, specified categories of meat, poultry, tobacco, insecticide, fungicide, drug, alcohol, and seed products).

<sup>3</sup> 16 CFR 503.2, 503.5. Many products outside the scope of the FPLA and the Rules nevertheless fall within the purview of individual state laws. 15 U.S.C. 1461. *See also* National Institute of Standards and Technology Handbook 130, Uniform Laws and Regulations in the areas of legal metrology and engine fuel quality (2015 ed.) (compilation of state and federal laws and regulations pertaining to product labeling and packaging).

<sup>4</sup> 16 CFR 500.4.

<sup>5</sup> 16 CFR 500.5.

and (c) the net quantity of contents in terms of weight, measure, or numerical count, with such disclosure’s placement and content in accordance with the Rules.<sup>6</sup> The Rules detail how units of weight or mass and measure must be stated, and require use of both U.S. (*e.g.*, pounds, feet, and gallons) and metric measures.<sup>7</sup> The Rules also require net quantity disclosures for packages containing more than one product or unit, including: (a) “multi-unit packages”;<sup>8</sup> (b) “variety packages”;<sup>9</sup> and (c) “combination packages.”<sup>10</sup>

In addition, the Act grants the FTC authority to issue rules to prevent consumer deception and facilitate value comparisons.<sup>11</sup> The FTC has used this authority to address three types of representations: “cents-off,”<sup>12</sup> “introductory offer,”<sup>13</sup> and “economy size.”<sup>14</sup>

As part of its ongoing regulatory review program, the Commission published an Advance Notice of Proposed Rulemaking (“ANPR”) in March 2014 seeking comment on the economic impact of, and the continuing need for, the Rules; the benefits of the

<sup>6</sup> 16 CFR 500.6(b). The Office of Weights and Measures of the National Institute of Standards and Technology, U.S. Department of Commerce, is authorized to promote, to the greatest practical extent, uniformity in state and federal regulation of the labeling of consumer commodities. 15 U.S.C. 1458(a)(2).

<sup>7</sup> Congress amended the FPLA in 1992 to require use of metric measurements, in addition to customary inch/pound measures. Pub. L. 102–245 (February 14, 1992); Pub. L. 102–329 (August 3, 1992). In 1994, the FTC modified its regulations accordingly. 59 FR 1872 (Jan. 12, 1994).

<sup>8</sup> 16 CFR 500.27.

<sup>9</sup> 16 CFR 500.28.

<sup>10</sup> 16 CFR 500.29.

<sup>11</sup> 15 U.S.C. 1454(c). This discretionary authority enables the FTC to address four situations: (1) Setting standards for characterizing package sizes to supplement the net quantity statement (*e.g.*, establishing a uniform size for a single sheet of toilet paper); (2) regulating packaging that claims a product price is lower than its customary retail price; (3) requiring labels to use common names or listing ingredients in order of decreasing prominence; and (4) preventing nonfunctional slack-fill. 15 U.S.C. 1454(c).

<sup>12</sup> A cents-off representation is one in which “cents-off” or a similar term is used to indicate that the consumer commodity is being offered for sale at a price lower than the ordinary and customary retail price. 16 CFR 502.100.

<sup>13</sup> An introductory offer is one in which “introductory offer” or a similar phrase is used to indicate that the consumer commodity is being offered for sale at a price lower than the ordinary and customary retail price. 16 CFR 502.101. The Rules prohibit introductory offers in a trade area for a duration in excess of six months. 16 CFR 502.101(b)(3).

<sup>14</sup> An economy size representation is one in which “economy size” or similar phrase is used to indicate that the consumer commodity has a retail sale price advantage due to the size of that package or the quantity of its contents. 16 CFR 502.102.