current circular. Additionally, this section discusses a new MOU between EEOC and FTA which allows FTA to obtain the agency's EEO-4 utilization numbers. As a result, the transit agency or grantee will be able to access their current utilization numbers and complete the required utilization in FTA's electronic database under the proposed language. For agencies under 100 employees that do not submit reports to EEOC, this proposed section also includes links to a Microsoft Excel spreadsheet template (with instructions) for use in completing the utilization and availability analysis. The proposed language adds requirements for Availability Analysis, including explanation of and requirements for explaining why agencies selected particular areas for the analysis and quantifying plans when underutilization is identified.

Proposed subsection 2.2.5, "Goals and Timetables," proposes to require agencies to set long term and short term numerical goals and timetables for each individual minority group, broken down by specific racial/ethnic subcategories for men and women. This section includes changes to the guidelines for goal setting, including a guideline to set goals that are realistic and measurable. The proposed requirements reduce the long term goal period from 4–5 years to 2 or more years. FTA also proposes to add a requirement that agencies collect reports from unit managers on a scheduled basis to determine what goals are being met and to review these reports with all levels of management.

Proposed subsection 2.2.6, "Assessment of Employment Practices," removes reference to "Affirmative Action" in the heading. It also proposes to move discussion of self-analysis from the Goals and Timetables section of the current circular to proposed subsection 2.2.6. We propose to add a requirement that statistical data show any potential impact of an agency's employment practices on persons with disabilities and veterans. This includes the number of applicants for employment, the number hired, and the number promoted, cross-references by sex and race. Having this data will assist in measuring the effectiveness of outreach and recruitment efforts for persons with disabilities and veterans. The proposed section also adds requirements for a description of the agency's training programs, review of wage and salary structure, establishment of privacy protocols, and collection of reports from unit managers on a scheduled basis in a manner similar to Goals and Timetables requirements.

Proposed subsection 2.2.7, "Monitoring and Reporting," updates the description of the purposes of the monitoring and reporting system. The proposed section adds a requirement for agencies to describe the complaint process and maintain a log of complains. The proposed section also requires agencies to maintain records on applicants, hires, transfers, promotions, training and termination. Finally, the proposed section adds a list of Required EEOP Attachments.

FTA seeks comment on the content of Chapter 2. With regards to the EEOP process, FTA seeks comment on the paperwork burdens for carrying out the requirements set forth in the proposed circular. Specifically FTA seeks comment on how long it will take to develop an EEO Program with the requirements set out in Chapter 2 of the proposed Circular. FTA also seeks suggestions from grantees regarding how to use information technology to decrease the amount of time it takes to develop an EEO Program.

C. Chapter 3—EEO Compliance Oversight, Complaints, and Enforcement

Chapter 3 of the proposed circular combines topics covered in chapters IV, V, and VI of the existing circular. It explains how FTA carries out its EEO oversight and enforcement responsibilities. This includes a discussion of factors that lead to FTA conducting a compliance review such as lawsuits, complaints, or investigations conducted by organizations other than FTA, insufficient EEO program submissions, EEO findings, or recommendations from prior triennial, state management reviews that are deficient. The chapter explains the EEO compliance review process and the required steps for implementing corrective actions for any deficiencies found during the review. The chapter also covers the complaint process and how grantees can file a complaint.

Proposed section 3.1, "Compliance Oversight," updates the description of types of oversight reviews and authorities for such reviews. FTA proposes to change the description of compliance reviews to encompass all reviews and remove the distinction between "Application Reviews" and "Post-Approval Reviews" in the existing circular. Further, FTA proposes to change the frequency requirement for compliance reviews outside of the Triennial Review or State Management Review cycle. The current circular requires these reviews "at least once every 3 years." FTA proposes to change the frequency to allow FTA to

determine the frequency and scope of the reviews at its discretion and on a case-by-case basis.

Proposed section 3.1.3 removes the explanation of Remedial Action Plans.

Proposed section 3.2, "Complaints," is reorganized and proposes to add significantly more detail to the complaint process. In proposed subsection 3.2.6, FTA proposes to add an Administrative Closure option.

FTA seeks comment on the content of Chapter 3.

D. Appendix A—References

Proposed Appendix A adds a list of references to the proposed circular. A similar list is contained on the cover page of the existing circular. The proposed list of references in Appendix A updates and adds references based on the current state of the law and guidance.

FTA seeks comment on the content of Appendix A.

Issued in Washington, DC.

Therese W. McMillan,

Acting Administrator.

[FR Doc. 2016-04648 Filed 3-2-16; 8:45 am]

BILLING CODE 4910-57-P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

Denial of Motor Vehicle Defect Petition

AGENCY: National Highway Traffic Safety Administration, (NHTSA), Department of Transportation. **ACTION:** Denial of a petition for a defect

investigation.

SUMMARY: This notice sets forth the reasons for denying a petition (DP15–007) submitted to NHTSA under 49 U.S.C. 30162 and 49 CFR part 552, requesting that the agency "have Toyota correct software defects in their electronic throttle control software" and then "issue a national recall of all effected [sic] vehicles and have Toyota replace the old faulty code with the new safer code."

FOR FURTHER INFORMATION CONTACT: Mr. Stephen McHenry, Vehicle Control Division, Office of Defects Investigation, NHTSA, 1200 New Jersey Avenue SE., Washington, DC 20590. Telephone 202–366–4883. Email stephen.mchenry@dot.gov.

SUPPLEMENTARY INFORMATION:

1.0 Introduction

Interested persons may petition NHTSA requesting that the agency initiate an investigation to determine whether a motor vehicle or item of replacement equipment does not comply with an applicable motor vehicle safety standard or contains a defect that relates to motor vehicle safety. 49 U.S.C. 30162(a)(2); 49 CFR 552.1. Upon receipt of a properly filed petition, the agency conducts a technical review of the petition, material submitted with the petition, and any additional information. 49 U.S.C. 30162(c); 49 CFR 552.6. The technical review may consist solely of a review of information already in the possession of the agency, or it may include the collection of information from the motor vehicle manufacturer and/or other sources. After considering the technical review and taking into account appropriate factors, which may include, among others,, agency priorities, the likelihood of uncovering sufficient evidence to establish the existence of a defect, and the likelihood of success in any necessary enforcement litigation, the agency will grant or deny the petition. See 49 U.S.C. 30162(d); 49 CFR 552.8.

2.0 Petition Background Information

In a letter dated September 15, 2015, Dr. James Stobie (the petitioner) requested that NHTSA "have Toyota correct software defects in their electronic throttle control software" and then "issue a national recall of all effected [sic] vehicles and have Toyota replace the old faulty code with the safer code." Dr. Stobie references two previous defect petitions related to unintended acceleration in Toyota vehicles that NHTSA recently evaluated and denied. The petitioner stated that his petition contains new information affecting NHTSA's conclusions in the previous petition evaluations. This includes: (1) Information related to a crash that occurred as his wife was attempting to park their model year 2010 Lexus HS250H; (2) the source of EDR data in Toyota vehicles; (3) alleged defects in the Toyota Electronic Throttle Control (ETC) software; and (4) a recall conducted by Honda in Japan. NHTSA has reviewed the material cited by the petitioner. The results of this review and our evaluation of the petition are set forth in the DP15-007 Petition Analysis Report, published in its entirety as an appendix to this notice.

After a thorough assessment of the material submitted by the petitioner, the information already in NHTSA's possession, and the potential risks to safety implicated by the petitioner's allegations, it is unlikely that an order concerning the notification and remedy of a safety-related defect would result from any proceeding initiated by

granting Dr. Stobie's petition. After full consideration of the potential for finding a safety related defect in the vehicle, and in view of NHTSA's enforcement priorities and its previous investigations into this issue, the petition is denied.

Appendix—Petition Analysis—DP15-007

1.0 Introduction

On September 23, 2015, the National Highway Traffic Safety Administration (NHTSA) received a September 15, 2015 letter from Dr. James Stobie, Ph.D. (the petitioner), petitioning the agency to "have Toyota correct software defects in their electronic throttle control software" and then "issue a national recall of all effected [sic] vehicles and have Toyota replace the old faulty code with the safer code." The petition cites a crash that occurred as his wife was attempting to park their model year 2010 Lexus HS250H in an angled parking space facing a brick building and references two previous Toyota unintended acceleration defect petitions that NHTSA evaluated and denied. Dr. Stobie's petition also alleges that new information not considered by the Agency in those prior petitions should be evaluated by NHTSA. This new information includes: (1) The facts and circumstances of a crash that occurred as his wife was attempting to park their model year 2010 Lexus HS250H; (2) the source of EDR data in Toyota vehicles; (3) alleged defects in the Toyota Electronic Throttle Control (ETC) software; and (4) a recall conducted by Honda in Japan.

2.0 Petition Analysis

2.1 Background

2.1.1 EDR Data Limitations

The Toyota EDR collects pre-trigger data (vehicle speed, engine speed, brake switch status, and accelerator pedal position sensor #1 voltage) from the vehicle's High Speed Controller Area Network (HS–CAN), which is refreshed either periodically or immediately by the respective control modules.

TABLE 1—EDR PRE-CRASH PARAMETERS, BY REFRESH RATE

| Parameter | Refresh rate | Resolution | | |
|---|--------------------------------|--|--|--|
| Brake Switch Engine RPM Vehicle Speed. | Immediately 24 ms 500 ms | On/Off. 400 RPM. ¹ 2 km/h. ² | | |
| Accelerator Rate. | 512 ms | 0.039 volts. | | |

The EDR continuously performs 1 Hz sampling of HS—CAN pre-trigger data and stores the data in a temporary buffer. The EDR only saves this data, along with the trigger data, when it detects a triggering event such as a crash.² Table 1 shows the refresh

rates and resolutions for the pre-crash data signals. Any analysis of EDR data for Toyota vehicles should apply these data time tolerances and resolutions at each of the precrash data points.

In 2010, NHTSA's Vehicle Research and Test Center (VRTC) conducted testing to validate the EDR pre-crash data used in NHTSA field investigations.³ The testing found that the pre-crash data recorded by the Toyota EDR were accurate within the known limitations resulting from the data resolution and sampling rates. The testing also demonstrated that the EDR does not necessarily capture all accelerator pedal applications during an event and the accelerator pedal voltage recorded at each EDR time interval may not be the actual accelerator pedal voltage at that interval. Subsequent studies have confirmed the limitations of stored EDR pre-crash data in capturing the entire crash event due to the data refresh rates, data resolutions and EDR sampling rates.456

The EDR download report clearly notes these issues in the first two items of Data Limitations section on page one of the report:

- Due to limitations of the data recorded by the airbag ECU, such as the resolution, data range, sampling interval, time period of the recording, and the items recorded, the information provided by this data may not be sufficient to capture the entire crash.
- Pre-Crash data is recorded in discrete intervals. Due to different refresh rates within the vehicle's electronics, the data recorded may not be synchronous to each other.

2.1.2 National Research Council Report

In 2012, the National Research Council released a report that included a review of NHTSA's processes for investigating allegations of sudden unintended acceleration in Toyota and other vehicles.⁷ As noted in the agency's denial of DP14–003, the report concluded that NHTSA's decision to close its investigations of Toyota's ETC were justified based on the initial investigations, complaint analyses, field investigations using EDR data and NASA's examination of the Toyota ETC. With regard to allegations of low-speed surging with ineffective brakes, the report stated:

Reports of braking ineffectiveness in controlling a vehicle experiencing the onset of unintended acceleration from a stopped position or when moving slowly requires an explanation for the ineffectiveness, such as

¹ EDR recorded data are rounded down in the indicated resolution increments.

² An event is triggered by detection of a deceleration of approximately 2 g's.

³ "Event Data Recorder—Pre Crash Data Validation of Toyota Products," NHTSA–NVS– 2011–ETC–SR07, February 2011.

⁴ Brown, R., White, S., "Evaluation of Camry HS–CAN Pre-Crash Data," SAE Technical Paper 2012–01–0996, 2012, doi: 10.4271/2012–01–0996.

⁵ Brown, R., Lewis, L., Hare, B., Jakstis, M. et al., "Confirmation of Toyota EDR Pre-crash Data," SAE Technical Paper 2012–01–0998, 2012, doi: 10.4271/2012–01–0998.

⁶Ruth, R., Bartlett, W., Daily, J., "Accuracy of Event Data in the 2010 and 2011 Toyota Camry During Steady State and Braking Conditions," SAE Technical Paper 2012–01–0999, 2012, doi: 10.4271/ 2012–01–0999.

⁷ NRC. 2011. TRB Special Report 308: The Safety Challenge and Promise of Automotive Electronics: Insights from Unintended Acceleration. Washington, DC: National Academies Press, (164).

physical evidence of damage to the brake system. Under these circumstances, investigating for phenomena other than pedal misapplication absent an explanation for the ineffectiveness of the brakes, which are independent of the throttle control system and are designed to dominate engine torque, is not likely to be useful.

2.2 Crash Incident

The crash identified by the petitioner involved a sudden acceleration incident experienced by his wife as she attempted to park the family's 2010 Lexus HS250H on June 20, 2015, while on the grounds of the United States Naval Academy.

2.2.1 Driver's Statement

Mrs. Stobie described the sudden unintended acceleration incident in several complaints submitted to ODI from June 21, 2015 to August 17, 2015 (VOQ's 10726415, 10726781, and 10749195). She provided the following statement in the most recent complaint (VOQ 10749195):

My accident was caused by unintended acceleration. As I was slowly turning right into a parking place, the car suddenly accelerated and crashed into a brick building. The force of the crash caused the air bags to deploy. There was so much damage to the car that it was a total loss. After the crash I obtained the event data

recorder (EDR) reading from a contractor hired by Toyota. It showed that for the last 5 seconds before the crash, I was applying very light pressure to the gas pedal up until the last .8 seconds. For the last .8 second the EDR shows that my foot was on the brake and the throttle was at nearly maximum value. During the last .8 seconds the car went from 5 mph to 9.9 mph and the engine rpm went from 1200 to 2800. I did not apply pressure to the gas pedal at this time. I was applying pressure to the brake pedal . . .

2.2.2 Event Data Recorder Data

The petitioner provided a copy of the EDR download data (Table 2).

Table 2—Pre-Crash Data for VOQ 10749195

| Time (sec) | -4.8 | -3.8 | -2.8 | -1.8 | -0.8 | 0 (TRG) |
|----------------------------|-----------------|-----------------|------------------|------|------------------|--------------------|
| Vehicle Speed (MPH [km/h]) | OFF 0.78 [0] | OFF 0.98 [8] | OFF 1.45 [27] | OFF | OFF 1.33 [22] | ON. 3.32 [106]. |

The EDR data shows that at the most recent EDR sample prior to impact (t = -0.8 s), the vehicle is nominally within 10 ft. of the building, travelling approximately 7 ft./s, the accelerator is at approximately 22 percent of full apply and the brake is not applied. The recorded data at the airbag trigger point (t = 0 s), shows that the accelerator pedal was fully applied 8 at sometime within 0.512 seconds prior to the trigger point (see Section 2.1.1 EDR Data Limitations for the source and refresh rate of Accelerator Rate) and the brake switch is "On."

In support of his allegation that data provided to the EDR was corrupted by an undefined software error, the petitioner notes that the EDR erroneously states that the brake pedal and accelerator were both being pressed at the same time. Other vehicle data shows that they were not: This information does not validate the conclusion adopted in the petition. Separate data downloaded from the Hybrid Control Unit (HCU) for the petitioner's vehicle indicates that the brake pedal and the accelerator pedal were not applied simultaneously at any time during the key cycle in which the petitioner's accident occurred.9 As noted above, the EDR reads the position of the brake light switch instantaneously while there can be a time lag as long as 0.512 seconds in writing accelerator position to the EDR. Since the brake light switch was in the ON state at the air bag trigger point, this indicates that the brake was not applied until after the

accelerator pedal was released, which must have occurred in the final half second of travel.

In addition, as noted by the petitioner, brake testing conducted by Toyota field inspectors after the incident found that the system performed normally and was capable of stopping a vehicle at full throttle:

During the test drive they floored the accelerator and then quickly slammed on the brakes. The car behaved as expected. Nowhere did they find a safety defect.

Based on the recorded vehicle speeds, the vehicle was inside the parking space when the most significant acceleration occurred. At this time and distance from impact, a driver would normally be applying the brake or coasting and not applying the accelerator to full throttle. Although the driver alleged that the brakes were not effective during the incident, the brakes had no prior history of malfunction and the post-incident inspection did not identify any issues with the brake system. Review of the EDR and HCU data indicate very late activation of the Brake Stop Lamp Switch after full application of the accelerator pedal. These data do not support the driver's statement that the brake was applied when the acceleration occurred. Based on the foregoing information, this incident appears to be a case of pedal misapplication.

$2.3\quad Source\ of\ EDR\ Data$

The petitioner correctly notes that the EDR receives the Accelerator Rate voltage from the engine computer and not directly from the pedal and asserts that this is "new critical information about EDR data." In the petitioner's view, the analog to digital conversion of the accelerator pedal signal and subsequent processing by the engine computer creates a potential pathway for an unknown software error to create erroneous accelerator position data. However, this is not "new" information about the source of the accelerator pedal position data sampled and recorded by the EDR. All prior work by

the agency related to Toyota EDR data dating back to the joint NHTSA/NASA study, including the two previous petitions and other studies referenced in that work, recognized and reported that the EDR samples Accelerator Rate voltage data from the HS–CAN bus. Further, as discussed below, the engine computer software has been exhaustively examined, including analysis in the NHTSA/NASA study, and no one, even consultants who have offered testimony asserting the software is defective, has identified a specific and reproducible mechanism or set of conditions that produces unintended acceleration or the "false" data phenomenon put forward in the petition. As noted in the prior work and in Section 2.1.1 of this report, the HS-CAN bus receives the Accelerator Rate data from the engine control module, which refreshes the data every 512 ms (see Table 1).

The EDR continuously samples the HS-CAN data once per second and stores the data in a temporary buffer. The EDR only saves this data, along with the trigger data, when it detects a triggering event such as a crash. Because of the manner in which the ECM updates/refreshes the data to the HS-CAN, the "recorded" Accelerator Rate data saved by the EDR is not necessarily the "actual" data at the precise time intervals captured by the EDR. For example, the Accelerator Rate recorded by the EDR for the petitioner's crash at the trigger point (t = 0s) is not necessarily the actual data at the trigger point, but the most recent value refreshed to the HS–CAN over the prior 512 ms. This explains why it is possible for the EDR data to show that the accelerator appeared to be applied fully at the same time the brake switch was in the ON position when the HCU data shows that the brake and the accelerator were not applied simultaneously.

2.4 Alleged Software Defects

The petitioner states that software defect theories posited by plaintiff experts in

⁸ According to Toyota, an Accelerator Rate of 3.188 volts corresponds with a 100% accelerator pedal application resulting in wide-open throttle. Any further application of the pedal may produce higher voltage, but will not result in any additional throttle opening.

⁹ The HCU receives data directly from the Accelerator Pedal Position Sensor and Brake Stop Lamp Switch and records any instance in which the pedals are applied at the same time in a particular drive cycle. Hybrid motor protection logic will override accelerator pedal signals that occur when the brake is applied.

unintended acceleration litigation against Toyota is new evidence since the joint NHTSA/NASA study. However, ODI has previously reviewed this information during its evaluation of DP14–003. The petitioner does not provide any new information about the theories or his allegations of defects in the Toyota ETC software. As noted in ODI's denial report for DP14-003, the software defect theories failed to identify a precise cause for sudden acceleration, the software experts did not reproduce the alleged software defects in testing, and the theorized conditions did not result in sudden acceleration when artificially simulated. We find no basis for concluding that the software defect theories constitute scientifically valid evidence or could explain the incident alleged by the petitioner.

ODI's assessment of the software defect theories is not substantially different from that of one of the plaintiff attorneys who hired the software experts. These plaintiff attorneys provided the following characterization of the software experts' work and findings in a document related to the Toyota SUA property loss settlement in 2013:

While Plaintiffs' software experts raised certain software design and architecture issues, they have not been able to identify a defect that is responsible for the vast array of SUAs reported to Toyota and NHTSA by vehicle owners. More specifically, Plaintiffs have been unable to reproduce a UA in a Subject vehicle under $\bar{d}riving\ conditions.^{10}$

In addition, an October 2013 order from the presiding judge in the Toyota ETC multidistrict litigation provided the following characterization of the software defect theories cited by the petitioner when issuing a ruling in a sudden acceleration case:

Toyota's Motion for Summary Judgment is premised on the uncontroverted fact that Plaintiff has been unable to identify a precise software design or manufacturing defect and point to physical or otherwise traceable evidence that the defect actually caused the Camry throttle to open from an idle position to a much wider angle without analog input from the driver via the accelerator pedal. To a lesser extent, it is also premised upon the fact that Plaintiff cannot prove the actual failure of Toyota's fail-safe mechanisms in the Camry on the day of the collision.

2.5 The Honda Example

The petitioner references a 2014 recall of 175,000 Honda Fit vehicles in Japan as an example of a software defect causing unintended acceleration accidents (Honda Foreign Campaign Number 14F-057). The Honda recall addressed programming flaws that may result in unintended acceleration during specific operating conditions. Honda's Foreign Recall Report to NHTSA described

the programming flaws and operating conditions:

The vehicle may lurch forward due to excessive driving force generated by the motor if the accelerator pedal is pressed strongly when the vehicle is in Engine mode and shifted into Drive or Reverse, or the vehicle is in EV mode and being operated on a slope. The vehicle may also lurch forward momentarily due to excessive driving force generated by the motor when switching from EV mode to Engine mode after being in stop and go traffic.

Honda was able to reproduce the conditions described in the recall and develop a software update to address the "lurching" concerns. The conditions addressed by the Honda recall are associated with brief surges that occur when the accelerator pedal is being applied under specific operating conditions and, thus, are not related to the petitioner's incident or allegations (which claim sustained acceleration during brake application), nor have they been observed in the general population of Toyota ETC vehicles. Finally, ODI is not aware of any vehicle defect theories, from the software experts cited by the petitioner or anyone else, that have similarly documented and reproduced a sudden unintended acceleration condition in the Toyota vehicles that would be attributable to the electronic throttle control software in those vehicles.

3.0 Conclusion

The petitioner does not provide any new evidence in support of his petition. In our view, a defects investigation is unlikely to result in a finding that a defect related to motor vehicle safety exists, or a NHTSA order for the notification and remedy of a safety related defect as alleged by the petitioner, at the conclusion of the requested investigation. Therefore, given a thorough analysis of the potential for finding a safety related defect in the vehicle, and in view of NHTSA's enforcement priorities and its previous investigations into this issue, the petition is denied. This action does not constitute a finding by NHTSA that a safety related defect does not exist. The agency will take further action if warranted by future

Authority: 49 U.S.C. 30162(d); delegations of authority at 49 CFR 1.50 and 501.8.

Frank S. Borris II,

Acting Associate Administrator for Enforcement.

[FR Doc. 2016-04605 Filed 3-2-16; 8:45 am] BILLING CODE 4910-59-P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-2013-0109, Notice 2]

Decision That Certain Nonconforming Model Year 2006-2007 European Market Ferrari 599 GTB Passenger **Cars Manufactured Prior to September** 2007 Are Eligible for Importation

AGENCY: National Highway Traffic Safety Administration (NHTSA), Department of Transportation (DOT).

ACTION: Grant of petition.

SUMMARY: This document announces a decision by the National Highway Traffic Safety Administration (NHTSA) that certain model year (MY) 2006-2007 European market Ferrari 599 GTB passenger cars (PCs) manufactured prior to September 2007 that were not originally manufactured to comply with all applicable Federal motor vehicle safety standards (FMVSS), are eligible for importation into the United States because they are substantially similar to vehicles originally manufactured for importation into and sale in the United States that were certified by their manufacturer as complying with the safety standards (the U.S. certified version of the MY 2007 Ferrari 599 GTB PC), and they are capable of being readily altered to conform to the standards.

DATES: This decision became effective on February 26, 2016.

ADDRESSES: For further information contact George Stevens, Office of Vehicle Safety Compliance, NHTSA (202-366-5308).

SUPPLEMENTARY INFORMATION:

Background

Under 49 U.S.C. 30141(a)(1)(A), a motor vehicle that was not originally manufactured to conform to all applicable FMVSS shall be refused admission into the United States unless NHTSA has decided that the motor vehicle is substantially similar to a motor vehicle originally manufactured for importation into and sale in the United States, certified as required under 49 U.S.C. 30115, and of the same model year as the model of the motor vehicle to be compared, and is capable of being readily altered to conform to all applicable FMVSS.

Petitions for eligibility decisions may be submitted by either manufacturers or importers who have registered with NHTSA pursuant to 49 CFR part 592. As specified in 49 CFR 593.7, NHTSA publishes notice in the Federal Register

¹⁰ Berman, S., Seltzer, M., and Pitre,. F. (2013, April 23). Plaintiff's Memorandum in Support of Plaintiffs' Motion for an Award of Attorneys' Fees, Reimbursement of Expenses, and Compensation to Named Plaintiffs, page 12. In Re: Toyota Motor Corp. Unintended Acceleration Marketing, Sales Practices, and Products Liability Litigation. United States District Court, Central District of California. Case No. 8:10ML2151. Retrieved from https:// www.toyotaelsettlement.com/Home/CaseDocs.