

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2016-5578; Directorate Identifier 2016-CE-005-AD]

RIN 2120-AA64

Airworthiness Directives; Pacific Aerospace Limited Airplanes**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).**ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Pacific Aerospace Limited Model 750XL (type certificate previously held by Pacific Aerospace Corporation Ltd.) airplanes that would supersede AD 2006-13-05. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as some critical rivets on the wing not being fully age-hardened and being installed in specific locations where reduction in rivet strength reduces wing strength. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by May 27, 2016.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Pacific Aerospace Limited, Airport Road, Hamilton, Private Bag 3027, Hamilton 3240, New Zealand; telephone: +64 7 843 6144; facsimile: +64 7 843 6134; email: pacific@aerospace.co.nz; Internet: www.aerospace.co.nz. You may review copies of the referenced

service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5578; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4123; fax: (816) 329-4090; email: karl.schletzbaum@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2016-5578; Directorate Identifier 2016-CE-005-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On June 12, 2006, we issued AD 2006-13-05, Amendment 39-14658 (71 FR 35509, June 21, 2006) ("AD 2006-13-05"). That AD required actions intended to address an unsafe condition on certain Pacific Aerospace Corporation Ltd. Model 750XL airplanes and was based on mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country.

Since we issued AD 2006-13-05, additional airplanes have been identified that need to be added to the applicability of the AD.

The Civil Aviation Authority (CAA), which is the aviation authority for New Zealand, has issued AD No. DCA/750XL/7B, dated February 25, 2016 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

DCA/750XL/7B revised to introduce PACSB/XL/018 issue 4, dated 20 January 2016, which reduces the applicability to S/N 101 through to 131 with no change to the requirements. Aircraft with S/N 132 onwards have been modified in accordance with PACSB/XL/018 at manufacture, which is a terminating action for the requirements of this AD.

This proposed AD would require you to remove rivets that have not been fully age hardened and replace them with bolts, washers, and nuts in specific locations where reduction in rivet strength affects overall structural capability. The proposed AD would retain the airplane weight AFM limitations until the rivets are replaced with the bolts, washers, and nuts. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5578.

Related Service Information Under 14 CFR Part 51

Pacific Aerospace Limited has issued Service Bulletin PACSB/XL/018, Issue 4, dated January 20, 2016. The service bulletin describes procedures for removing rivets (part number (P/N) MS20470 DD6) and installing bolts (P/N NAS 6203-7X or NAS 6203-6X), washers (P/N AN960-10), and nuts (P/N MS21044N3) in place of the rivets to restore airplane to full take-off weight of 7,500 pounds. The service bulletin is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this NPRM.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or

develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 9 products of U.S. registry. We also estimate that it would take about 32 work-hours per product to comply with the replacement requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$519 per product.

Based on these figures, we estimate the cost of this proposed AD on U.S. operators to be \$29,151, or \$3,239 per product.

AD 2006–13–05 affected 8 of the 9 U.S. registered airplanes reflected in the above cost information. This proposed AD would only increase the cost already required by AD 2006–13–05 by one additional airplane. The FAA has a report that the additional airplane is already in compliance, thus the proposed AD would impose no additional cost impact on U.S. operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Amendment 39–14658 (71 FR 35509, June 21, 2006), and adding the following new AD:

Pacific Aerospace Limited: Docket No. FAA–2016–5578; Directorate Identifier 2016–CE–005–AD.

(a) Comments Due Date

We must receive comments by May 27, 2016.

(b) Affected ADs

This AD replaces AD 2006–13–05, Amendment 39–14658 (71 FR 35509, June 21, 2006) ("AD 2006–13–05").

(c) Applicability

This AD applies to the following Pacific Aerospace Limited Model 750XL airplanes (type certificate previously held by Pacific Aerospace Corporation Ltd.), that are certificated in any category.

(1) *Airplanes previously affected by AD 2006–13–05:* Serial numbers 101, 102, 104 through 120, and 125.

(2) *Airplanes new to this AD:* Serial numbers 103, 121, 122, 123, 124, and 126 to 131.

(d) Subject

Air Transport Association of America (ATA) Code 57: Wings.

(e) Reason

This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as some critical rivets on the wing not being fully age-

hardened and being installed in specific locations where reduction in rivet strength reduces wing strength. We are issuing this AD to add airplanes to the Applicability section, paragraph (c) of this AD, and to ensure wing ultimate load requirements are met. If wing ultimate load requirements are not met, wing failure could result with consequent loss of control.

(f) Actions and Compliance

Unless already done, do the following actions:

(1) Insert the following information into the Limitations section of the airplane flight manual (AFM) at the compliance time specified in paragraphs (f)(1)(i) and (f)(1)(ii) of this AD. You may do this by inserting a copy of this AD into the Limitations section of the AFM: "The maximum takeoff weight is reduced from 7,500 pounds to 7,125 pounds." The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may do the flight manual changes requirement of this AD. Make an entry in the aircraft records showing compliance with this portion of the AD following section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

(i) *For airplanes previously affected by AD 2006–13–05:* Before further flight after January 16, 2006 (the effective date retained from AD 2005–26–53, Amendment 39–14451 (71 FR 2453, January 17, 2006), which was replaced by AD 2006–13–05).

(ii) *For airplanes new to this AD:* Before further flight after the effective date of this AD.

(2) Remove rivets, part number (P/N) MS20470 DD6, on the main spar web and replace with bolts, P/N NAS 6203–6X or –7X, as indicated for the position, assembled with washers, P/N AN960–10, and nut, P/N MS21044N3, at the compliance time specified in paragraphs (f)(2)(i) and (f)(2)(ii) of this AD.

(i) *For airplanes previously affected by AD 2006–13–05:* Within the next 100 hours time-in-service (TIS) after July 31, 2006 (the effective date retained from AD 2006–13–05). Do the removal and replacement actions following Pacific Aerospace Corporation Ltd. Service Bulletin PACSB/XL/018, Issue 3, dated December 23, 2005, and amended January 16, 2006.

(ii) *For airplanes new to this AD:* Within the next 100 hours TIS after the effective date of this AD or within the next 12 months after the effective date of this AD, whichever occurs first. Do the removal and replacement actions following Pacific Aerospace Limited Service Bulletin PACSB/XL/018, Issue 4, dated January 20, 2016.

(3) *For all affected airplanes:* Before further flight after doing the action required in paragraph (f)(2) of this AD, remove the restrictive information from the Limitations section of the AFM that you were required to insert in paragraph (f)(1) of this AD. The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may do the flight manual changes requirement of this AD.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4123; fax: (816) 329-4090; email: karl.schletzbaum@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

Refer to MCAI Civil Aviation Authority (CAA) AD No. DCA/750XL/7B, dated February 25, 2016, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5578. For service information related to this AD, contact Pacific Aerospace Limited, Airport Road, Hamilton, Private Bag 3027, Hamilton 3240, New Zealand; telephone: +64 7 843 6144; facsimile: +64 7 843 6134; email: pacific@aerospace.co.nz; Internet: www.aerospace.co.nz. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on April 4, 2016.

Pat Mullen,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-08261 Filed 4-11-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2016-5459; Directorate Identifier 2015-NM-148-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model BD-700-1A10 and BD-700-1A11 airplanes. This proposed AD was prompted by a design review, which found that the burst pressure of the flexible hose used to vent oxygen from the high-pressure relief valve of the oxygen cylinder overboard is lower than the opening pressure of the high-pressure relief valve. This pressure difference could cause the flexible hose to burst before it is able to vent excess oxygen overboard. This proposed AD would require replacement of flexible relief hoses for the crew oxygen bottles with new metal design relief hoses. We are proposing this AD to prevent the accumulation of excess oxygen in an enclosed space, which could, if near a source of ignition, cause an uncontrolled oxygen-fed fire.

DATES: We must receive comments on this proposed AD by May 27, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal*: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax*: 202-493-2251.
- *Mail*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5459; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the

regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Fabio Buttitta, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7303; fax 516-794-5531.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2016-5459; Directorate Identifier 2015-NM-148-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2015-25, dated September 10, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Bombardier, Inc. Model BD-700-1A10 and BD-700-1A11 airplanes. The MCAI states:

A design review found that the burst pressure of the flexible hose used to vent oxygen from the high-pressure relief valve of the oxygen cylinder overboard is lower than the opening pressure of the high-pressure relief valve. This could cause the flexible hose to burst before it is able to vent the excess oxygen overboard. If an ignition source is present, the accumulation of oxygen in an enclosed space may result in an uncontrolled oxygen-fed fire.

This [Canadian] AD mandates the replacement of the oxygen [flexible] hose assembly with a new design oxygen [metal] hose assembly.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov>