

or harvested outside of this time period, they must be treated for *C. capitata* in accordance with part 305 of this chapter and the operational workplan.

(8) *Safeguarding*. Lots of lemons destined for export to the continental United States must be safeguarded during movement from registered places of production to registered packinghouses as specified by the operational workplan.

(9) *Phytosanitary certificate*. Each consignment of lemons imported from Argentina into the continental United States must be accompanied by a phytosanitary certificate issued by the NPPO of Argentina with an additional declaration stating that the requirements of this section have been met and that the consignments have been inspected and found free of *Brevipalpus* spp. mites, *B. chilensis*, *C. capitata*, *C. gnidiella*, and *G. aurantianum*.

(b) *Place of production requirements*.

(1) Prior to each harvest season, registered places of production of lemons destined for export to the continental United States must be determined by APHIS and the NPPO of Argentina to be free from *B. chilensis* based on biometric sampling conducted in accordance with the operational workplan. If a single live *B. chilensis* mite is discovered as a result of such sampling, the place of production will not be considered free from *B. chilensis*. Each place of production will have only one opportunity per harvest season to be considered free of *B. chilensis*, and certification of *B. chilensis* freedom will only last one harvest season.

(2) Places of production must remove plant litter and fallen debris from groves in accordance with the operational workplan. Fallen fruit may not be included in field containers of fruit brought to the packinghouse to be packed for export.

(3) Places of production must trap for *C. capitata* in accordance with the operational workplan. The NPPO must keep records regarding the placement and monitoring of all traps, as well as records of all pest detections in these traps, and provide the records to APHIS, as requested.

(4) Places of production must carry out any additional grove sanitation and phytosanitary measures specified for the place of production by the operational workplan.

(5) The NPPO of Argentina must visit and inspect registered places of production regularly throughout the exporting season for signs of infestations. These inspections must start no more than 30 days before harvest and continuing until the end of the export season. The NPPO of

Argentina must allow APHIS to monitor these inspections. The NPPO of Argentina must also provide records of pest detections and pest detection practices to APHIS. Before any place of production may export lemons to the continental United States pursuant to this section, APHIS must review and approve of these practices.

(6) If APHIS or the NPPO of Argentina determines that a registered place of production has failed to follow the requirements in this paragraph (b), the place of production will be excluded from the export program until APHIS and the NPPO of Argentina jointly agree that the place of production has taken appropriate remedial measures to address the plant pest risk.

(c) *Packinghouse requirements*. (1) During the time registered packinghouses are in use for packing lemons for export to the continental United States, the packinghouses may only accept lemons that are from registered places of production and that have been produced in accordance with the requirements of this section.

(2) Lemons destined for export to the continental United States must be packed within 24 hours of harvest in a registered pest-exclusionary packinghouse or stored in a degreening chamber in the registered pest-exclusionary packinghouse. Lemons must be packed for shipment to the continental United States in insect-proof cartons or containers, or covered with insect-proof mesh or plastic tarpaulin. These safeguards must remain intact until the lemons arrive in the United States, or the consignment will not be allowed to enter the United States.

(3) Prior to packing, the lemons must be washed, brushed, and surface disinfected for *E. australis* and *X. citri* and in accordance with the operational workplan, treated with an APHIS-approved fungicide, and waxed.

(4) After treatment, the NPPO of Argentina or officials authorized by the NPPO of Argentina must visually inspect a biometric sample of each consignment for quarantine pests, wash the lemons in this sample, and inspect the filtrate for *B. chilensis* in accordance with the operational workplan. A portion of the lemons must then be cut open and inspected for evidence of quarantine pests.

(i) If a single *C. gnidiella* or *G. aurantianum* in any stage of development is found on the lemons, the entire consignment is prohibited from export to the United States, and the registered place of production that produced the lemons is suspended from the export program until APHIS and the NPPO of Argentina jointly agree that the

place of production has taken appropriate remedial measures to address plant pest risk.

(ii) If a single *B. chilensis* or *Brevipalpus* spp. mite in any stage of development is found on the lemons, the entire consignment is prohibited from export, and the registered place of production that produced the lemons may be suspended from the export program, pending an investigation.

(iii) If a single immature Medfly is found in or with the lemons, the lemons must be treated in accordance with part 305 of this chapter and the operational workplan. Additionally, the registered place of production that produced the lemons in the consignment may be suspended from the export program, pending an investigation.

(5) If APHIS or the NPPO of Argentina determines that a registered packinghouse has failed to follow the requirements in this paragraph (c), the packinghouse will be excluded from the export program until APHIS and the NPPO of Argentina jointly agree that the packinghouse has taken appropriate remedial measures to address the plant pest risk.

(d) *Port of entry requirements*. Consignments of lemons from Argentina will be inspected at the port of entry into the United States. If any quarantine pests are discovered on the lemons during inspection, the entire lot in which the quarantine pest was discovered will be subject to appropriate remedial measures to address this risk.

Done in Washington, DC, this 4th day of May 2016.

**Michael L. Gregoire,**

*Acting Administrator, Animal and Plant Health Inspection Service.*

[FR Doc. 2016-10957 Filed 5-9-16; 8:45 am]

**BILLING CODE 3410-34-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2016-6414; Directorate Identifier 2015-NM-175-AD]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier, Inc. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. This proposed AD was prompted by two in-service incidents of a loss of all air data information in the flight deck. This proposed AD would require a revision of the airplane flight manual (AFM) emergency procedures section to provide procedures to guide the crew on how to stabilize the airplane airspeed and attitude for continued safe flight when a loss of all air data information has occurred in the flight deck. We are proposing this AD to prevent loss of control when a loss of all air data information has occurred in the flight deck.

**DATES:** We must receive comments on this proposed AD by June 24, 2016.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

#### *Examining the AD Docket*

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6414; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Assata Dessaline, Aerospace Engineer, Avionics and Services Branch, ANE-172, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7301; fax 516-794-5531.

#### **SUPPLEMENTARY INFORMATION:**

##### **Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2016-6414; Directorate Identifier 2015-NM-175-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

##### **Discussion**

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2015-12, dated June 23, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. The MCAI states:

Two in-service incidents have been reported on CL-600-2C10 aeroplanes regarding a loss of all air data information in the cockpit. The air data information was recovered as the aeroplane descended to lower altitudes. An investigation determined that the root cause in both events was high altitude icing (ice crystal contamination). If not addressed, this condition may affect continued safe flight.

Due to similarities in the air data systems, such events could happen on all Bombardier CRJ models, CL-600-2B19, CL-600-2C10, CL-600-2D15, CL-600-2D24 and CL-600-2E25. Therefore, the corrective actions for these models will be mandated once their respective Airplane Flight Manual (AFM) revisions become available.

This [Canadian] AD mandates the incorporation of AFM procedures to guide the crew to stabilize the aeroplane’s airspeed and attitude for continued safe flight.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for

and locating Docket No. FAA-2016-6414.

#### **Related Service Information Under 1 CFR Part 51**

We reviewed Section 03-19, Unreliable Airspeed, Revision 63, dated February 13, 2015, of Chapter 3, Emergency Procedures, in the Bombardier CRJ Series Regional Jet Model CL-600-2B19 Airplane Flight Manual CSP A-012, Revision 64B, dated December 8, 2015. The service information describes procedures to guide the crew to stabilize the airplane’s airspeed and attitude for continued safe flight when a loss of all air data information has occurred in the flight deck. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

#### **FAA’s Determination and Requirements of This Proposed AD**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type designs.

#### **Costs of Compliance**

We estimate that this proposed AD affects 500 airplanes of U.S. registry.

We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of this proposed AD on U.S. operators to be \$42,500, or \$85 per product.

#### **Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in

air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Bombardier, Inc.:** Docket No. FAA-2016-6414; Directorate Identifier 2015-NM-175-AD.

#### (a) Comments Due Date

We must receive comments by June 24, 2016.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes, certificated in any category, serial numbers 7003 and subsequent.

#### (d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

#### (e) Reason

This AD was prompted by two in-service incidents of a loss of all air data information in the flight deck. We are issuing this AD to prevent loss of control when a loss of all air data information has occurred in the flight deck.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Airplane Flight Manual Revision

Within 30 days after the effective date of this AD, revise the emergency procedures section of the airplane flight manual (AFM) by incorporating Section 03-19, Unreliable Airspeed, Revision 63, dated February 13, 2015, of Chapter 3, Emergency Procedures, in the Bombardier CRJ Series Regional Jet Model CL-600-2B19 Airplane Flight Manual CSP A-012, Revision 64B, dated December 8, 2015.

#### (h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

#### (i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2015-12, dated June 23, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov>

searching for and locating Docket No. FAA-2016-6414.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on April 28, 2016.

#### Dionne Palermo,

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2016-10732 Filed 5-9-16; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2016-6551; Directorate Identifier 2013-SW-070-AD]

RIN 2120-AA64

#### Airworthiness Directives; Bell Helicopter Textron Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Bell Helicopter Textron (Bell) Model 430 helicopters. This proposed AD would require establishing a life limit for a certain main rotor hub attachment bolt (bolt) and removing from service each bolt that has met or exceeded its life limit. This proposed AD is prompted by a documentation error that omitted the life limit of a certain part-numbered bolt from the Airworthiness Limitations section of the maintenance manual. The proposed actions are intended to establish a life limit for a certain part-numbered bolt to prevent failure of a bolt, failure of a main rotor hub, and subsequent loss of control of a helicopter.

**DATES:** We must receive comments on this proposed AD by July 11, 2016.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.
- *Fax:* 202-493-2251.
- *Mail:* Send comments to the U.S. Department of Transportation, Docket