

Rules and Regulations

Federal Register

Vol. 81, No. 102

Thursday, May 26, 2016

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF AGRICULTURE

Agricultural Marketing Service

7 CFR Part 948

Irish Potatoes Grown in Colorado

CFR Correction

In Title 7 of the Code of Federal Regulations, Parts 900 to 999, revised as of January 1, 2016, on page 338, § 948.215 is reinstated to read as follows:

§ 948.215 Assessment rate.

On or after July 1, 2005, an assessment rate of \$0.02 per hundredweight is established for Colorado Area No. 3 potatoes.

[70 FR 36816, June 27, 2005]

[FR Doc. 2016-12582 Filed 5-25-16; 8:45 am]

BILLING CODE 1505-01-D

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-7528; Directorate Identifier 2015-NM-004-AD; Amendment 39-18524; AD 2016-10-13]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Airbus Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Model

A310 series airplanes. This AD was prompted by reports of premature aging of certain passenger chemical oxygen generators that resulted in the generators failing to activate. This AD requires an inspection to determine if certain passenger chemical oxygen generators are installed and replacement of affected passenger chemical oxygen generators. We are issuing this AD to prevent failure of the passenger chemical oxygen generator to activate and consequently not deliver oxygen during an emergency, possibly resulting in injury to airplane occupants.

DATES: This AD is effective June 30, 2016.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of June 30, 2016.

ADDRESSES: For Airbus service information identified in this final rule, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. For B/E Aerospace service information identified in this final rule, contact B/E Aerospace Inc., 10800 Pflumm Road, Lenexa, KS 66215; telephone: 913-338-9800; fax: 913-469-8419; Internet <http://beaerospace.com/home/globalsupport>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-7528.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-7528; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation,

Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116 Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-2125; fax: 425-227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Model A310 series airplanes. The NPRM published in the **Federal Register** on December 23, 2015 (80 FR 79745) (“the NPRM”). The NPRM was prompted by reports of premature aging of certain passenger chemical oxygen generators that resulted in the generators failing to activate. The NPRM proposed to require an inspection to determine if certain passenger chemical oxygen generators are installed and replacement of affected passenger chemical oxygen generators. We are issuing this AD to prevent failure of the passenger chemical oxygen generator to activate and consequently not deliver oxygen during an emergency, possibly resulting in injury to airplane occupants.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2015-0118, dated June 24, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Model A310 series airplanes. The MCAI states:

Reports have been received indicating premature ageing of certain chemical oxygen generators, Part Number (P/N) 117042-XX (XX representing any numerical value), manufactured by B/E Aerospace. Some operators reported that when they tried to activate generators, some older units failed to activate. Given the number of failed units reported, all generators manufactured in

1999, 2000, and 2001 were considered unreliable.

This condition, if not corrected, could lead to failure of the generator to activate and consequently not deliver oxygen during an emergency, possibly resulting in injury to aeroplane occupants.

To address this potential unsafe condition, Airbus issued Alert Operators Transmission (AOT) A35W008–14, making reference to B/E Aerospace Service Information Letter (SIL) D1019–01 (currently at Revision 1) and B/E Aerospace Service Bulletin (SB) 117042–35–001. Consequently, EASA issued AD 2014–0280 [<http://ad.easa.europa.eu/ad/2014-0280>] to require identification and replacement of the affected oxygen generators.

Since EASA AD 2014–0280 was issued, and following new investigation results, EASA [has] decided to introduce a life limitation concerning all P/N 117042–XX chemical oxygen generators, manufactured by B/E Aerospace.

For the reason described above, this [EASA] AD retains the requirements of EASA AD 2014–0280, which is superseded, expands the scope of the [EASA] AD to include chemical oxygen generators manufactured after 2001, and requires their removal from service before exceeding 10 years since date of manufacture.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–7528.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Additional Change Made to This AD

In paragraph (i) of the proposed AD, we inadvertently referred to Airbus Alert Operators Transmission (AOT) A35N006–14, including Appendix 01, dated December 10, 2014, as the appropriate source of service information for replacing 22 minute passenger chemical oxygen generators. We have corrected that error in paragraph (i) of this AD, which refers to Airbus AOT A35W008–14, dated December 18, 2014, including Appendix A, undated, as the appropriate source of service information for replacing 22 minute passenger chemical oxygen generators.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this AD with the change described previously, and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

Related Service Information Under 1 CFR Part 51

We reviewed the following service information.

- Airbus AOT A35W008–14, dated December 18, 2014, including Appendix A, undated.
- B/E Aerospace Service Bulletin 117042–35–001, dated December 10, 2014.

This service information describes procedures to replace certain passenger chemical oxygen generators. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 166 airplanes of U.S. registry.

We also estimate that it will take about 2 work-hours per product to comply with the basic requirements of this AD, and 1 work-hour per product for reporting. The average labor rate is \$85 per work-hour. Required parts will cost about \$390 per product. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$107,070, or \$645 per product.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this AD is 2120–0056. The paperwork cost associated with this AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW., Washington,

DC 20591, ATTN: Information Collection Clearance Officer, AES–200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2016-10-13 Airbus: Amendment 39-18524. Docket No. FAA-2015-7528; Directorate Identifier 2015-NM-004-AD.

(a) Effective Date

This AD is effective June 30, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplanes identified in paragraphs (c)(1), (c)(2), (c)(3), (c)(4), and (c)(5) of this AD, certificated in any category, all manufacturer serial numbers.

(1) Airbus Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes.

(2) Airbus Model A300 B4-605R and B4-622R airplanes.

(3) Airbus Model A300 F4-605R and F4-622R airplanes.

(4) Airbus Model A300 C4-605R Variant F airplanes.

(5) Airbus Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

(e) Reason

This AD was prompted by reports of premature aging of certain passenger chemical oxygen generators that resulted in the generators failing to activate. We are issuing this AD to prevent failure of the passenger chemical oxygen generator to activate and consequently not deliver oxygen during an emergency, possibly resulting in injury to airplane occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Part Number Inspection

Within 30 days after the effective date of this AD, do a one-time inspection of passenger chemical oxygen generators, part numbers (P/N) 117042-02 (15 minutes (min)—2 masks), 117042-03 (15 min—3 masks), 117042-04 (15 min—4 masks), 117042-22 (22 min—2 masks), 117042-23 (22 min—3 masks), or 117042-24 (22 min—4 masks), to determine the date of manufacture, as specified in Airbus Alert Operators Transmission (AOT) A35W008-14, dated December 18, 2014, including Appendix A, undated. Refer to Figure 1 to paragraph (g) of this AD and Figure 2 to paragraph (g) of this AD for the location of the date. A review of airplane maintenance records is acceptable for the inspection required by this paragraph, provided the date of manufacture can be conclusively determined by that review.

Figure 1 to paragraph (g) of this AD - Location of date (MM-YY)





Figure 2 to paragraph (g) of this AD – Manufacturing Date (06-02 = June 2002)
example



BILLING CODE 4910-13-C

(h) Replacement of Passenger Chemical Oxygen Generators Manufactured in 1999, 2000, and 2001

If, during any inspection required by paragraph (g) of this AD, any passenger chemical oxygen generator having a date of manufacture in 1999, 2000, or 2001 is found: At the applicable time specified in paragraph (h)(1), (h)(2), or (h)(3) of this AD, remove and replace the affected passenger chemical oxygen generator with a serviceable unit, in accordance with the Accomplishment Instructions of B/E Aerospace Service Bulletin 117042-35-001, dated December 10, 2014 (for 15 minute passenger chemical oxygen generators); or Airbus AOT A35W008-14, dated December 18, 2014, including Appendix A, undated (for 22

minute passenger chemical oxygen generators); as applicable.

(1) For passenger chemical oxygen generators that have a date of manufacture in 1999: Remove and replace within 30 days after the effective date of this AD.

(2) For passenger chemical oxygen generators that have a date of manufacture in 2000: Remove and replace within 6 months after the effective date of this AD.

(3) For passenger chemical oxygen generators that have a date of manufacture in 2001: Remove and replace within 12 months after the effective date of this AD.

(i) Replacement of Passenger Chemical Oxygen Generators Manufactured in 2002 and Later

If, during any inspection required by paragraph (g) of this AD, any passenger

chemical oxygen generator having a date specified in Table 1 to paragraph (i) of this AD is found: At the applicable time specified in Table 1 to paragraph (i) of this AD, remove and replace the affected passenger chemical oxygen generator with a serviceable unit, in accordance with the Accomplishment Instructions of B/E Aerospace Service Bulletin 117042-35-001, dated December 10, 2014 (for 15 minute passenger chemical oxygen generators); or Airbus AOT A35W008-14, dated December 18, 2014, including Appendix A, undated (for 22 minute passenger chemical oxygen generators); as applicable.

TABLE 1 TO PARAGRAPH (i) OF THIS AD—REPLACEMENT COMPLIANCE TIMES

Year of manufacture	Compliance time
2002	Within 12 months after the effective date of this AD.
2003	Within 16 months after the effective date of this AD.
2004	Within 20 months after the effective date of this AD.
2005	Within 24 months after the effective date of this AD.
2006	Within 28 months after the effective date of this AD.
2007	Within 32 months after the effective date of this AD.
2008	Within 36 months after the effective date of this AD.
2009	Before exceeding 10 years since date of manufacture of the passenger chemical oxygen generator.

(j) Definition of Serviceable

For the purpose of this AD, a serviceable unit is a passenger chemical oxygen generator having P/N 117042-XX (XX represents any numerical value) with a manufacturing date not older than 10 years, or any other approved part number, provided that the generator has not exceeded the life limit established for that generator by the manufacturer.

(k) Reporting

At the applicable time specified in paragraph (k)(1) or (k)(2) of this AD, submit a report of the findings (both positive and negative) of the inspection required by paragraph (g) of this AD, in accordance with paragraph 7., "Reporting," of Airbus AOT A35W008-14, dated December 18, 2014, including Appendix A, undated. The report must include the information specified in Appendix A, undated, of Airbus AOT A35W008-14, dated December 18, 2014.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(l) Parts Installation Limitation

As of the effective date of this AD, no person may install a passenger chemical oxygen generator, unless it is determined, prior to installation, that the oxygen generator is a serviceable unit (as defined in paragraph (j) of this AD).

(m) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116 Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227- 2125; fax: 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify

your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(n) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2015-0118, dated June 24, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-7528.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Alert Operators Transmission (AOT) A35W008-14, dated December 18, 2014, including Appendix A, undated.

(ii) B/E Aerospace Service Bulletin 117042-35-001, dated December 10, 2014.

(3) For Airbus service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) For B/E Aerospace service information identified in this AD, contact B/E Aerospace Inc., 10800 Pflumm Road, Lenexa, KS 66215; telephone: 913-338-9800; fax: 913-469-8419; Internet <http://beaerospace.com/home/globalsupport>.

(5) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 12, 2016.

Suzanne Masterson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-12156 Filed 5-25-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-2457; Directorate Identifier 2014-NM-209-AD; Amendment 39-18525; AD 2016-10-14]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain