

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Airplane Logbook Check

(1) Check the airplane logbook to determine if all four of the original engine mounting brackets have been replaced. Do the logbook check at the following compliance time, as applicable. The owner/operator holding at least a private pilot certificate as authorized by section 43.7 may do this action.

(i) *For airplanes previously affected by AD 2008-15-06:* Within the next 30 days after September 2, 2008 (the effective date retained from AD 2008-15-06).

(ii) *For the new airplane affected by this AD:* Within the next 30 days after August 11, 2016 (the effective date of this AD).

(2) If you can positively determine that all four of the original engine mounting brackets have been replaced, no further action is required. Make an entry into the airplane logbook showing compliance with this portion of the AD in accordance with 14 CFR 43.9. The owner/operator holding at least a private pilot certificate as authorized by section 43.7 may do this action.

(3) If you cannot positively determine that all four of the original engine mounting brackets have been replaced, inspect each of the upper and lower engine mounting brackets on both the left and right sides for cracks following Cessna Single Engine Service Bulletin SEB07-2, Revision 2, dated June 18, 2007. Do the inspections at the following compliance times, as applicable.

(i) *For airplanes previous affected by AD 2008-15-06:* Initially inspect within the next 12 months after September 2, 2008 (the effective date retained from AD 2008-15-06). If no cracks are found, repetitively inspect thereafter at intervals not to exceed 500 hours time-in-service (TIS) until all four of the original engine mounting brackets are replaced.

(ii) *For the new airplane affected by this AD:* Initially inspect within the next 12 months after August 11, 2016 (the effective date of this AD). If no cracks are found, repetitively inspect thereafter at intervals not to exceed 500 hours TIS until all four of the original engine mounting brackets are replaced.

(h) Engine Mounting Bracket Replacement

If cracks are found in any of the engine mounting brackets during any inspection required in paragraph (g)(3) of this AD, including all subparagraphs, before further flight after the inspection in which cracks are found, replace the cracked engine mounting bracket(s) following Cessna Single Engine Service Bulletin SEB07-2, Revision 2, dated June 18, 2007. Replacing the cracked engine mounting bracket terminates the repetitive inspections required in paragraphs (g)(3)(i) and (ii) of this AD only for the replaced engine mounting bracket.

(i) Terminating Action

To terminate the repetitive inspections required in paragraphs (g)(3)(i) and (ii) of this AD, you may replace all four original engine

mounting brackets following Cessna Single Engine Service Bulletin SEB07-2, Revision 2, dated June 18, 2007.

(j) Engine Mounting Bracket Disposal

For all airplanes affected by this AD: Before further flight after the engine mounting bracket is removed for replacement, dispose of every replaced bracket following 14 CFR 43.10, paragraph (c)(6), which states the following: "Mutilation. The part may be mutilated to deter its installation in a type certificated product. The mutilation must render the part beyond repair and incapable of being reworked to appear to be airworthy."

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) AMOCs approved for AD 2008-15-06 are approved as AMOCs for the corresponding provisions of this AD.

(l) Related Information

For more information about this AD, contact Gary Park, Aerospace Engineer, Wichita ACO, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4123; fax: (316) 946-4107, email: gary.park@faa.gov

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on September 2, 2008 (73 FR 43845, July 29, 2008).

(i) Cessna Single Engine Service Bulletin SEB07-2, Revision 2, dated June 18, 2007.

(ii) Reserved.

(4) For Cessna Aircraft Company service information identified in this AD, contact Cessna Aircraft Company, Product Support, P.O. Box 7706, Wichita, Kansas 67277; telephone: (316) 517-5800; fax: (316) 942-9006; Internet: www.cessna.txtav.com.

(5) You may view this service information at FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. In addition, you can access this service information on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5579.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on June 28, 2016.

Pat Mullen,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-15866 Filed 7-6-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY
Coast Guard**33 CFR Part 165**

[Docket No. USCG-2016-0493]

Safety Zone; Southern California Annual Fireworks for the San Diego Captain of the Port Zone

AGENCY: Coast Guard, DHS.

ACTION: Notice of enforcement of regulation.

SUMMARY: The Coast Guard will enforce a safety zone for the San Diego, CA POPS Fireworks Display on the waters of San Diego Bay, CA on specific evenings from July 1, 2016 to September 4, 2016. This safety zone is necessary to provide for the safety of the participants, spectators, official vessels of the events, and general users of the waterway. Our regulation for the southern California annual fireworks for the San Diego Captain of the Port Zone identifies the regulated area for the events. During the enforcement period, no spectators shall anchor, block, loiter in, or impede the transit of official patrol vessels in the regulated area without the approval of the Captain of the Port, or designated representative.

DATES: The regulations in 33 CFR 165.1123 will be enforced from 9:00 p.m. through 10:00 p.m. on July 1 through July 3, July 8 and July 9, July 15 and July 16, July 29 and July 30, August 5 and August 6, August 12 and August 13, August 20, August 26 and August 27 and September 1 through September 4, 2016 for Item 1 in Table 1 of 33 CFR 165.1123.

FOR FURTHER INFORMATION CONTACT: If you have questions on this publication, call or email Petty Officer Randolph Pahilanga, Waterways Management, U.S. Coast Guard Sector San Diego, CA; telephone 619-278-7656, email D11MarineEventsSD@uscg.mil.

SUPPLEMENTARY INFORMATION: The Coast Guard will enforce the regulations in 33 CFR 165.1123 for a safety zone on the waters of San Diego Bay, CA for the San Diego, CA POPS Fireworks Display in 33 CFR 165.1123, Table 1, Item 1 of that section, from 9:00 p.m. through 10:00 p.m. on specific evenings from July 1, 2016 to September 4, 2016. This enforcement action is being taken to provide for the safety of life on navigable waterways during the fireworks events. Our regulation for southern California annual fireworks events for the San Diego Captain of the Port Zone identifies the regulated entities for the events. Under the provisions of 33 CFR 165.1123, a vessel may not enter the regulated area, unless it receives permission from the Captain of the Port, or his designated representative. Spectator vessels may safely transit outside the regulated area but may not anchor, block, loiter, or impede the transit of participants or official patrol vessels. The Coast Guard may be assisted by other Federal, state, or local law enforcement agencies in enforcing this regulation.

This document is issued under authority of 33 CFR 165.1123 and 5 U.S.C. 552(a). In addition to this document in the **Federal Register**, the Coast Guard will provide the maritime community with advance notification of this enforcement period via the Local Notice to Mariners and local advertising by the event sponsor.

If the Captain of the Port or his designated representative determines that the regulated area need not be enforced for the full duration stated on this document, he or she may use a Broadcast Notice to Mariners or other communications coordinated with the event sponsor to grant general permission to enter the regulated area.

Dated: June 22, 2016.

E.M. Cooper,

Commander, U.S. Coast Guard, Acting Captain of the Port San Diego.

[FR Doc. 2016-16014 Filed 7-6-16; 8:45 am]

BILLING CODE 9110-04-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Parts 52 and 81

[EPA-R04-OAR-2012-0323; FRL-9948-68-Region 4]

Air Plan Approval and Air Quality Designation; TN; Redesignation of the Sullivan County Lead Nonattainment Area to Attainment

AGENCY: Environmental Protection Agency.

ACTION: Final rule.

SUMMARY: On July 15, 2015, the State of Tennessee, through the Tennessee Department of Environment and Conservation (TDEC), submitted a request for the Environmental Protection Agency (EPA) to redesignate the Bristol, Tennessee 2008 lead nonattainment area (hereafter referred to as the "Bristol Area" or the "Area") to attainment for the 2008 lead National Ambient Air Quality Standards (NAAQS) and an associated State Implementation Plan (SIP) revision containing a maintenance plan and a reasonably available control measures (RACM) determination for the Area. EPA is taking the following separate final actions related to the July 15, 2015, redesignation request and SIP revision: Determining that the Bristol Area is continuing to attain the 2008 lead NAAQS; approving and incorporating into the SIP the State's plan for maintaining attainment of the 2008 lead standard; approving and incorporating into the SIP the State's RACM determination; and redesignating the Bristol Area to attainment for the 2008 lead NAAQS.

DATES: This rule will be effective August 8, 2016.

ADDRESSES: EPA has established a docket for this action under Docket Identification No. EPA-R04-OAR-2012-0323. All documents in the docket are listed on the www.regulations.gov Web site. Although listed in the index, some information is not publicly available, *i.e.*, Confidential Business Information or other information whose disclosure is restricted by statute. Certain other material, such as copyrighted material, is not placed on the Internet and will be publicly available only in hard copy form. Publicly available docket materials are available either electronically through www.regulations.gov or in hard copy at the Air Regulatory Management Section, Air Planning and Implementation Branch, Air, Pesticides and Toxics Management Division, U.S. Environmental Protection Agency,

Region 4, 61 Forsyth Street SW., Atlanta, Georgia 30303-8960. EPA requests that if at all possible, you contact the person listed in the **FOR FURTHER INFORMATION CONTACT** section to schedule your inspection. The Regional Office's official hours of business are Monday through Friday 8:30 a.m. to 4:30 p.m., excluding federal holidays. **FOR FURTHER INFORMATION CONTACT:** Sean Lakeman of the Air Regulatory Management Section, Air Planning and Implementation Branch, Air, Pesticides and Toxics Management Division, U.S. Environmental Protection Agency, Region 4, 61 Forsyth Street SW., Atlanta, Georgia 30303-8960. Mr. Lakeman may be reached by phone at (404) 562-9043 or via electronic mail at lakeman.sean@epa.gov.

SUPPLEMENTARY INFORMATION:

I. Background

On November 12, 2008, EPA promulgated a revised primary and secondary lead NAAQS of 0.15 micrograms per cubic meter ($\mu\text{g}/\text{m}^3$). See 73 FR 66964. Under EPA's regulations at 40 CFR part 50, the 2008 lead NAAQS are met when the maximum arithmetic 3-month mean concentration for a 3-year period, as determined in accordance with appendix R of 40 CFR part 50, is less than or equal to 0.15 $\mu\text{g}/\text{m}^3$. See 40 CFR 50.16. Ambient air quality monitoring data for the 3-year period must meet a data completeness requirement.

EPA designated the Bristol Area as a nonattainment area for the 2008 lead NAAQS on November 22, 2010 (effective December 31, 2010), using 2007-2009 ambient air quality data. See 75 FR 71033. This established an attainment date five years after the December 31, 2010, effective date for the 2008 lead nonattainment designations pursuant to CAA section 172(a)(2)(A). Therefore, the Bristol Area's attainment date is December 31, 2015. EPA determined that Tennessee had attained the 2008 lead NAAQS prior to the attainment date and issued a Clean Data Determination on August 29, 2012 (77 FR 52232).

In a notice of proposed rulemaking (NPRM) published on April 26, 2016 (81 FR 24536), EPA proposed to approve four separate but related actions: (1) To approve Tennessee's RACM determination for the Bristol Area pursuant to Clean Air Act (CAA or Act) section 172(c)(1) into the SIP; (2) to determine that the Area is continuing to attain the 2008 lead NAAQS; (3) to approve Tennessee's maintenance plan for maintaining the 2008 lead NAAQS in the Area into the SIP; and (4) to