

device, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-71-1028, dated March 23, 2001.

(2) For Configuration 02 airplanes identified in Airbus Service Bulletin A320-71-1028, dated March 23, 2001: Install a new hold-open device, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-71-1028, dated March 23, 2001.

(h) New Modifications

Within 36 months after the effective date of this AD, do the actions required by paragraphs (h)(1), (h)(2), and (h)(3) of this AD, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-71-1069, dated December 18, 2015.

(1) Modify the left-hand and right-hand FCDs on engines 1 and 2.

(2) Install a placard on the box located at the bottom of the 120 VU panel or at the bottom of the coat stowage, as applicable.

(3) Re-identify both engine FCDs with the new part numbers (P/Ns), as specified in table 1 to paragraph (h) of this AD and table 2 to paragraph (h) of this AD, as applicable.

TABLE 1 TO PARAGRAPH (h) OF THIS AD—LEFT-SIDE DOOR

Old part No.	New part No.
740-4000-501	740-4000-9501
740-4000-503	740-4000-9503
745-4000-501	745-4000-513
745-4000-503	745-4000-515
745-4000-505	745-4000-517

TABLE 2 TO PARAGRAPH (h) OF THIS AD—RIGHT-SIDE DOOR

Old part No.	New part No.
740-4000-502	740-4000-9502
740-4000-504	740-4000-9504
740-4000-506	740-4000-9506
740-4000-508	740-4000-9508
745-4000-502	745-4000-512
745-4000-504	745-4000-514
745-4000-506	745-4000-516
745-4000-508	745-4000-518
745-4000-510	745-4000-520
745-4000-512	745-4000-522

(i) New Alternative Compliance

(1) Replacing an engine FCD having a part number listed as “Old Part Number” in table 1 to paragraph (h) of this AD or table 2 to paragraph (h) of this AD, as applicable, with a FCD having the corresponding part number listed as “New Part Number” in table 1 to paragraph (h) of this AD or table 2 to paragraph (h) of this AD, as applicable, is an acceptable method of compliance with the requirements of paragraphs (h)(1) and (h)(3) of this AD for that engine FCD only.

(2) An airplane on which Airbus Modification 157516 has been embodied in production is compliant with the requirements of paragraph (h)(1) and (h)(3) of this AD, provided no engine FCD, having a part number identified as “Old Part Number”

in table 1 to paragraph (h) of this AD or table 2 to paragraph (h) of this AD, as applicable, is installed on that airplane.

(3) An airplane on which Airbus Modification 157718 has been embodied in production is compliant with the requirements of paragraph (h)(2) of this AD.

(j) New Parts Installation Limitations

(1) For an airplane with an engine FCD installed having a part number identified as “Old Part Number” in table 1 to paragraph (h) of this AD or table 2 to paragraph (h) of this AD, as applicable: After modification of that airplane as required by paragraph (h) of this AD, do not install an engine FCD, having a part number identified as “Old Part Number” in table 1 to paragraph (h) of this AD or table 2 to paragraph (h) of this AD, as applicable.

(2) For an airplane that does not have an engine FCD installed having a part number identified as “Old Part Number” in table 1 to paragraph (h) of this AD or table 2 to paragraph (h) of this AD, as applicable: On or after the effective date of this AD, do not install an engine FCD, having a part number identified as “Old Part Number” in table 1 to paragraph (h) of this AD or table 2 to paragraph (h) of this AD, as applicable.

(k) New Method of Compliance

Installation on an engine of a right-hand and left-hand engine FCD having a part number approved after the effective date of this AD is a method of compliance with the requirements of paragraphs (g), (h)(1), and (h)(3) of this AD for that engine only, provided the part number is approved, and the installation is accomplished, in accordance with a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus’s EASA Design Organization Approval (DOA).

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-1405; fax: 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from

a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Airbus’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (k) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016-0053, dated March 14, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-8185.

(2) For service information identified in this AD, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on July 26, 2016.

Victor Wicklund,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-18492 Filed 8-4-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-3143; Directorate Identifier 2015-NM-047-AD]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (Embraer) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: We are revising an earlier proposed airworthiness directive (AD) for certain Empresa Brasileira de Aeronautica S.A. (Embraer) Model EMB-135 airplanes and Model EMB-145, -145ER, -145MR, -145LR, -145MP, and -145EP airplanes. The NPRM proposed to require a detailed inspection for chafing on the electrical harness of each electrical fuel pump in the fuel tanks, replacement of the affected electrical fuel pump with a new or serviceable pump if necessary, and installation of clamps on the fuel pump electrical harnesses. The NPRM was prompted by a report of chafing found between the fuel pump electrical harness and the fuel pump tubing during scheduled maintenance. This action revises the NPRM by expanding the proposed applicability and revising the compliance time for the detailed inspection. We are proposing this supplemental NPRM (SNPRM) to detect and correct chafing of the fuel pump harnesses with other parts inside the fuel tank, which could present a potential ignition source that could result in a fire or fuel tank explosion. Since certain actions impose an additional burden over those proposed in the NPRM, we are reopening the comment period to allow the public the chance to comment on these proposed changes.

DATES: We must receive comments on this SNPRM by September 19, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this SNPRM, contact Empresa Brasileira de Aeronautica S.A. (Embraer), Technical Publications Section (PC 060), Av. Brigadeiro Faria Lima, 2170—Putim—12227-901 São Jose dos Campos—SP—Brasil; telephone +55 12 3927-5852 or +55 12 3309-0732; fax +55 12 3927-7546; email distrib@embraer.com.br; Internet <http://www.flyembraer.com>. You may view

this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3143; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1175; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2015-3143; Directorate Identifier 2015-NM-047-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Empresa Brasileira de Aeronautica S.A. (Embraer) Model EMB-135 airplanes and Model EMB-145, -145ER, -145MR, -145LR, -145MP, and -145EP airplanes. The NPRM published in the **Federal Register** on August 21, 2015 (80 FR 50812) (“the NPRM”).

Actions Since Previous NPRM was Issued

Since we issued the NPRM, we have determined that certain airplanes were inadvertently omitted from the applicability, and the compliance time for the detailed inspection required by paragraph (h)(1) of this AD must be revised to “within 5,000 flight hours or 24 months after the effective date of this AD, whichever occurs first.”

The Agência Nacional de Aviação Civil (ANAC), which is the aviation authority for Brazil, has issued Brazilian Airworthiness Directive 2015-03-01, effective March 23, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition on certain Empresa Brasileira de Aeronautica S.A. (Embraer) Model EMB-135 airplanes and Model EMB-145, -145ER, -145MR, -145LR, -145MP, and -145EP airplanes. The MCAI states:

Chafing between the fuel pump electrical harness and fuel pump tubing was detected during scheduled maintenance. We are issuing this [Brazilian] AD to protect the fuel pump harnesses against chafing with other parts inside the fuel tank, which could present a potential ignition source that could result in a fire or fuel tank explosion.

The required actions include a detailed inspection for chafing on the electrical harness of each electrical fuel pump in the fuel tanks, replacement of the affected electrical fuel pump with a new or serviceable pump if necessary, and installation of clamps on the fuel pump electrical harnesses. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3143.

Related Service Information Under 1 CFR Part 51

Embraer has issued Service Bulletin 145-28-0030, Revision 01, dated October 22, 2010; and Service Bulletin 145LEG-28-0032, Revision 01, dated November 20, 2012. The service information describes procedures for a detailed inspection for chafing on the electrical harness of each electrical fuel pump in the fuel tanks, replacement of the affected electrical fuel pump with a new or serviceable pump if necessary, and installation of clamps on the fuel pump electrical harnesses. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Comments

We gave the public the opportunity to participate in developing this proposed AD. We considered the comments received.

Request To Clarify Airplane Applicability

ExpressJet Airlines stated that the airplane effectivity in Embraer Service Bulletin 145–28–0030, Revision 01, dated October 22, 2010, included Model EMB–145XR airplanes. ExpressJet Airlines stated that Model EMB–145XR airplanes are not included in paragraph (c), “Applicability,” of the proposed AD (in the NPRM) and asked if this is the intent of the NPRM or if the Model EMB–145XR airplanes should be included.

We agree with the commenter to clarify the applicability of this SNPRM. Although ANAC unintentionally omitted Model EMB–145XR airplanes from the applicability of its AD, the serial numbers corresponding to Model EMB–145XR airplanes are identified in the Embraer Service Bulletin 145–28–0030, Revision 01, dated October 22, 2010. We have added Model EMB–145XR airplanes to the applicability of this SNPRM. We have coordinated this issue with ANAC.

Request To Extend the Compliance Time

ExpressJet requested that we revise the compliance time for the detailed inspection in the proposed AD (in the NPRM) to “within 5,000 flight hours or 24 months after the effective date of this AD, whichever occurs first,” instead of “within 2,500 flight hours or 24 months after the effective date of this AD, whichever occurs first.” ExpressJet stated that this would allow the majority of the airplanes to be inspected during a C-check interval, which would be the most effective time to accomplish the task as the fuel tanks have to be drained and vented for the inspection to be performed. ExpressJet commented that these limits also line up with the current recommendations in the service information.

We agree with the commenter for the reasons stated previously. Data from Embraer confirms that increasing the flight hours another 2,500 flight hours is acceptable. We have changed this SNPRM accordingly.

FAA’s Determination and Requirements of This SNPRM

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of

Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of these same type designs.

Certain changes described above expand the scope of the NPRM. As a result, we have determined that it is necessary to reopen the comment period to provide additional opportunity for the public to comment on this SNPRM.

Costs of Compliance

We estimate that this SNPRM affects 731 airplanes of U.S. registry.

We estimate that it would take about 11 work-hours per product to comply with the new basic requirements of this SNPRM. The average labor rate is \$85 per work-hour. Required parts would cost about \$0 per product. Based on these figures, we estimate the cost of this SNPRM on U.S. operators to be \$683,485, or \$935 per product.

In addition, we estimate that any necessary follow-on actions would take about 6 work-hours and would require parts costing \$11,242, for a cost of \$11,752 per product. We have no way of determining the number of aircraft that might need this action.

According to the manufacturer, some of the costs of this SNPRM may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Empresa Brasileira de Aeronautica S.A.

(Embraer): Docket No. FAA–2015–3143; Directorate Identifier 2015–NM–047–AD.

(a) Comments Due Date

We must receive comments by September 19, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplanes specified in paragraphs (c)(1) and (c)(2) of this AD.

(1) Empresa Brasileira de Aeronautica S.A. (Embraer) Model EMB–135ER, –135KE, –135KL, and –135LR airplanes; and Model EMB–145, –145ER, –145MR, –145LR, –145MP, –145EP, and –145XR airplanes, certificated in any category, as identified in Embraer Service Bulletin 145–28–0030, Revision 01, dated October 22, 2010.

(2) Empresa Brasileira de Aeronautica S.A. (Embraer) Model EMB–135BJ airplanes,

certificated in any category, as identified in Embraer Service Bulletin 145LEG–28–0032, Revision 01, dated November 20, 2012.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

(e) Reason

This AD was prompted by a report of chafing found between the fuel pump electrical harness and the fuel pump tubing during scheduled maintenance. We are issuing this AD to detect and correct chafing of the fuel pump harnesses with other parts inside the fuel tank, which could present a potential ignition source that could result in a fire or fuel tank explosion.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Detailed Inspection and Corrective Action

Do the actions specified in paragraphs (g)(1) and (g)(2) of this AD at the applicable times specified in paragraph (h)(1) or (h)(2) of this AD.

(1) Do a detailed inspection for chafing on the electrical harness of each electrical fuel pump in the fuel tanks, in accordance with the Accomplishment Instructions of Embraer Service Bulletin 145–28–0030, Revision 01, dated October 22, 2010 (for Model EMB–135ER, –135KE, –135KL, and –135LR airplanes; and Model EMB–145, –145ER, –145MR, –145LR, –145MP, –145EP, and –145XR airplanes); or Embraer Service Bulletin 145LEG–28–0032, Revision 01, dated November 20, 2012 (for Model EMB–135BJ airplanes). If any chafing is found, before further flight, replace the affected electrical fuel pump with a new or serviceable pump having the same part number, in accordance with the Accomplishment Instructions of Embraer Service Bulletin 145–28–0030, Revision 01, dated October 22, 2010; or Embraer Service Bulletin 145LEG–28–0032, Revision 01, dated November 20, 2012; as applicable.

(2) Install clamps on the fuel pump electrical harnesses, in accordance with the Accomplishment Instructions of Embraer Service Bulletin 145–28–0030, Revision 01, dated October 22, 2010 (for Model EMB–135ER, –135KE, –135KL, and –135LR airplanes; and Model EMB–145, –145ER, –145MR, –145LR, –145MP, –145EP, and –145XR airplanes); or Embraer Service Bulletin 145LEG–28–0032, Revision 01, dated November 20, 2012 (for Model EMB–135BJ airplanes).

(h) Compliance Times

(1) For Model EMB–135ER, –135KE, –135KL, and –135LR airplanes; and Model EMB–145, –145ER, –145MR, –145LR, –145MP, –145EP, and –145XR airplanes: Do the actions specified in paragraph (g) of this AD within 5,000 flight hours or 24 months after the effective date of this AD, whichever occurs first.

(2) For Model EMB–135BJ airplanes: Do the actions specified in paragraph (g) of this AD within 4,800 flight hours or 48 months

after the effective date of this AD, whichever occurs first.

(i) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Embraer Service Bulletin 145–28–0030, dated September 1, 2010 (for Model EMB–135ER, –135KE, –135KL, and –135LR airplanes; and Model EMB–145, –145ER, –145MR, –145LR, –145MP, –145EP, and –145XR airplanes); or Embraer Service Bulletin 145LEG–28–0032, dated September 15, 2011 (for Model EMB–135BJ airplanes), as applicable. This service information is not incorporated by reference in this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1175; fax 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the Agência Nacional de Aviação Civil (ANAC); or ANAC's authorized Designee. If approved by the ANAC Designee, the approval must include the Designee's authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Brazilian Airworthiness Directive 2015–03–01, effective March 23, 2015, for related information. This MCAI may be found in the AD docket on the Internet by searching for and locating Docket No. FAA–2015–3143.

(2) For service information identified in this AD, contact Empresa Brasileira de Aeronautica S.A. (Embraer), Technical Publications Section (PC 060), Av. Brigadeiro Faria Lima, 2170—Putim—12227–901 São Jose dos Campos—SP—Brasil; telephone +55 12 3927–5852 or +55 12 3309–0732; fax +55 12 3927–7546; email distrib@embraer.com.br; Internet <http://www.flyembraer.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601

Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on July 25, 2016.

Victor Wicklund,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–18500 Filed 8–4–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2016–8184; Directorate Identifier 2016–NM–036–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Airbus Model A300 series airplanes; and Airbus Model A300 B4–600, B4–600R, and F4–600R series airplanes, and Model A300 C4–605R Variant F airplanes (collectively called Model A300–600 series airplanes). This proposed AD was prompted by reports of cracks in certain pins in the main landing gear (MLG). This proposed AD would require repetitive detailed visual inspections of the pins for cracks, and replacing the MLG leg if necessary. We are proposing this AD to detect and correct cracking of certain pins in the MLG, which could result in a MLG collapse, and consequent damage to the airplane and injury to the airplane occupants.

DATES: We must receive comments on this proposed AD by September 19, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5