

Web site will waive any CBI claims for the information submitted. For information on submitting CBI, see the Confidential Business Information section below.

DOE processes submissions made through www.regulations.gov before posting them. Normally, comments will be posted within a few days of being submitted. However, if large volumes of comments are being processed simultaneously, your comment may not be viewable for up to several weeks. Please keep the comment tracking number that www.regulations.gov provides after you have successfully uploaded your comment.

2. *Submitting comments via email, mail or hand delivery/courier.* Comments and documents submitted via email, mail, or hand delivery/courier, also will be posted to www.regulations.gov. If you do not want your personal contact information to be publicly viewable, do not include it in your comment or any accompanying documents. Instead, provide your contact information in a cover letter. Include your first and last names, email address, telephone number, and optional mailing address. The cover letter will not be publicly viewable as long as it does not include any comments.

Include contact information each time you submit comments, data, documents, and other information to DOE. If you submit via mail or hand delivery/courier, please provide all items on a CD or USB flash drive, if feasible. It is not necessary to submit printed copies. No facsimiles (faxes) will be accepted.

Comments, data, and other information submitted to DOE electronically should be provided in PDF (preferred), Microsoft Word or Excel, WordPerfect, or text (ASCII) file format. Provide documents that are not secured, that are written in English, and that are free of any defects or viruses. Documents should not contain special characters or any form of encryption and, if possible, they should carry the electronic signature of the author.

3. *Confidential Business Information.* Pursuant to the provisions of 10 CFR 1004.11, anyone submitting information or data he or she believes to be confidential and exempt by law from public disclosure should submit via email, or postal mail two well-marked copies: One copy of the document marked "CONFIDENTIAL BUSINESS INFORMATION" including all the information believed to be confidential, and one copy of the document marked "NO CONFIDENTIAL BUSINESS INFORMATION" with the information believed to be confidential deleted.

Submit these documents via email or CD, if feasible. DOE will make its own determination as to the confidentiality of the information and treat it accordingly. Factors of interest to DOE when evaluating requests to treat submitted information as confidential include: (1) A description of the items; (2) whether and why such items are customarily treated as confidential within the industry; (3) whether the information is generally known by or available from other sources; (4) whether the information has previously been made available to others without obligation concerning its confidentiality; (5) an explanation of the competitive injury to the submitting person which would result from public disclosure; (6) when such information might lose its confidential character due to the passage of time; and (7) why disclosure of the information would be contrary to the public interest.

It is DOE's policy that all comments may be included in the public docket, without change and as received, including any personal information provided in the comments (except information deemed to be exempt from public disclosure).

4. *Campaign form letters.* Please submit campaign form letters by the originating organization in batches of between 50 to 500 form letters per PDF or as one form letter with a list of supporters' names compiled into one or more PDFs. This reduces comment processing and posting time.

Appendix A—References

1. International Commission on Radiological Protection (ICRP), 1994. *Dose Coefficients for Intakes of Radionuclides by Workers*. ICRP Publication 68. Ann. ICRP 24 (4).
2. ICRP, 2012. Corrigenda to ICRP Publication 119: Compendium of Dose Coefficients based on ICRP Publication 60. Ann. ICRP 41 (suppl.).

V. Approval of the Office of the Secretary

The Secretary of Energy has approved publication of this proposed rule.

List of Subjects in 10 CFR Part 835

Federal buildings and facilities, Nuclear energy, Nuclear materials, Nuclear power plants and reactors, Nuclear safety, Occupational safety and health, Radiation protection, and Reporting and recordkeeping requirements.

Issued in Washington, DC, on October 31, 2016.

Matthew B. Moury,

Associate Under Secretary for Environment, Health, Safety and Security.

For the reasons set forth in the preamble, the Department of Energy proposes to amend part 835 of chapter III of title 10 of the Code of Federal Regulations as set forth below:

PART 835—OCCUPATIONAL RADIATION PROTECTION

- 1. The authority citation for part 835 continues to read as follows:

Authority: 42 U.S.C. 2201, 7191, 50 U.S.C. 2410.

Appendix C to Part 835—[Amended]

- 2. At the end of the table, in appendix C, the last sentence is amended by removing "6 E-06 $\mu\text{Ci}/\text{mL}$ (2 E+04 Bq/m³)" and adding in its place "1 E-06 $\mu\text{Ci}/\text{mL}$ (7 E+04 Bq/m³)".

Appendix E to Part 835—[Amended]

- 3. Appendix E is amended by removing the activity value in the second column for:
 - a. Rh-102, value of "3.0E+05" and adding in its place "6.4E+05"; and
 - b. Rh-102m, value of "6.4E+05" and adding in its place "3.0E+05".

[FR Doc. 2016-27510 Filed 11-17-16; 8:45 am]

BILLING CODE 6450-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-9388; Directorate Identifier 2016-NM-145-AD]

RIN 2120-AA64

Airworthiness Directives; Learjet Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Learjet Inc. Model 36A airplanes. This proposed AD was prompted by a report indicating that an aileron cable failed on an airplane during a tension check and a determination that Model 36A airplanes were not included in AD 2005-13-36, which addresses this issue for other Learjet Inc. airplanes. This proposed AD would require a one-time inspection of the center ball of the aileron control cables for a defective

swage, and corrective actions if necessary. We are proposing this AD to prevent the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by January 3, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Learjet, Inc., One Learjet Way, Wichita, KS 67209-2942; telephone 316-946-2000; fax 316-946-2220; email ac.ict@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9388; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Donald Ristow, Aerospace Engineer, Systems and Propulsion Branch, ACE-116W, FAA, Wichita Aircraft Certification Office (ACO), 1801 Airport Road, Room 100, Dwight D. Eisenhower National Airport, Wichita, Kansas 67209; phone: 316-946-4120; fax: 316-

946-4107; email: donald.ristow@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2016-9388; Directorate Identifier 2016-NM-145-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We received a report indicating that an aileron cable failed on a Learjet Inc. Model 35A (C-21A) airplane when the cable underwent a tension check while being installed. Further investigation showed that an over-sized ball was swaged onto the cable during manufacture. Swaging an over-sized ball onto a cable allows excess material into the swaging die, which causes the ball to over-swage and then sever the cable strands. This condition, if not corrected, could result in severe weakening of the aileron cable, and consequent reduced controllability of the airplane.

The subject area on Learjet Inc. Model 36A airplanes is identical to that on the affected Model 35A (C-21A) airplane. Therefore, Model 36A airplanes may be subject to the same unsafe condition.

We previously issued AD 2005-13-36, Amendment 39-14173 (70 FR 38578, July 5, 2005) (“AD 2005-13-36”), for Learjet Inc. Model 23, 24, 24A, 24B, 24B-A, 24C, 24D, 24D-A, 24E, 24F, 24F-A, 25, 25A, 25B, 25C, 25D, 25F, 28, 29, 31, 31A, 35, 35A (C-21A), and 36 airplanes. Model 36A airplanes were inadvertently omitted from the applicability of that AD. The applicability of AD 2005-13-36 referred to Bombardier Alert Service Bulletin A35/36-27-42, dated December 23, 2002, for Model 35, 35A (C-21A), and 36 airplanes. However, Model 36A

airplanes are also identified in that service information.

Related Service Information Under 1 CFR Part 51

We reviewed Bombardier Alert Service Bulletin A35/36-27-42, dated December 23, 2002. The service information describes procedures for a one-time inspection of the center ball of the aileron control cables for a defective swage, and replacement of defective cables. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously, except as described in “Differences between this Proposed AD and the Service Information.”

Differences Between This Proposed AD and the Service Information

Bombardier Alert Service Bulletin A35/36-27-42, dated December 23, 2002, recommends that operators accomplish the actions within 10 flight hours after receipt. This proposed AD would require that operators accomplish the actions within 100 flight hours, or 90 days after the effective date of the AD, whichever occurs first. We find that the proposed compliance time addresses the unsafe condition soon enough to maintain an adequate level of safety for the affected fleet. In developing an appropriate compliance time for this proposed AD we considered the degree of urgency associated with addressing the unsafe condition, and the maximum interval of time allowable for all affected airplanes to continue to operate without compromising safety.

Costs of Compliance

We estimate that this proposed AD affects 21 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$1,785

We estimate the following costs to do any necessary replacement that would be required based on the results of the proposed inspection. We have no way of determining the number of aircraft that might need this replacement:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Cable Replacement	¹ Up to 48 work-hours × \$85 per hour = up to \$4,080	¹ Up to \$2,020 ..	¹ Up to \$6,100.

¹ These costs assume replacement of all 5 cables.

According to the manufacturer, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Learjet Inc.: Docket No. FAA–2016–9388; Directorate Identifier 2016–NM–145–AD.

(a) Comments Due Date

We must receive comments by January 3, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Learjet Inc. Model 36A airplanes, certificated in any category, as identified in Bombardier Alert Service Bulletin A35/36–27–42, dated December 23, 2002.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Unsafe Condition

This AD was prompted by a report indicating that an aileron cable failed on an airplane during a tension check. We are issuing this AD to prevent severe weakening of the aileron cable, and consequent reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

Within 100 flight hours or 90 days after the effective date of this AD, whichever occurs first, do a detailed inspection of the center ball of the aileron control cables for a defective swage, and before further flight, replace any damaged or defective cable with a new cable, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A35/36–27–42, dated December 23, 2002. For the purposes of this AD, a detailed inspection is: An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirrors, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required.

(h) Parts Installation Limitation

As of the effective date of this AD, no person may install on any airplane an aileron control cable unless it has been inspected in accordance with paragraph (g) of this AD.

(i) No Reporting or Parts Return Requirement

Although Bombardier Alert Service Bulletin A35/36–27–42, dated December 23, 2002, has procedures for submitting a report showing compliance and for returning any discrepant parts to the manufacturer, this AD does not include those requirements.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

(1) For more information about this AD, contact Donald Ristow, Aerospace Engineer, Systems and Propulsion Branch, ACE-116W, FAA, Wichita ACO, 1801 Airport Road, Room 100, Dwight D. Eisenhower National Airport, Wichita, Kansas 67209; phone: 316-946-4120; fax: 316-946-4107; email: donald.ristow@faa.gov.

(2) For service information identified in this AD, contact Learjet, Inc., One Learjet Way, Wichita, KS 67209-2942; telephone 316-946-2000; fax 316-946-2220; email ac.ict@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on November 7, 2016.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-27532 Filed 11-17-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2016-9391; Directorate Identifier 2016-NM-129-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all The Boeing Company Model 737-300, -400, and -500 series airplanes. This proposed AD was prompted by a report of a crack in a certain body station (BS) frame inboard chord during

supplemental structural inspection document (SSID) inspections. This proposed AD would require repetitive detailed and high frequency eddy current (HFEC) inspections for any crack at the frame inboard chords, and repair if necessary. We are proposing this AD to prevent the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by January 3, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740; telephone: 562-797-1717; Internet: <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9391.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9391; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Galib Abumeri, Aerospace Engineer, Airframe Branch, ANM 120L, FAA, Los Angeles Aircraft Certification Office

(ACO), 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5324; fax: 562-627-5210; email: galib.abumeri@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2016-9391; Directorate Identifier 2016-NM-129-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received a report indicating a crack of approximately 1.00 inch was found in the BS 616 frame inboard chord during SSID inspections. The crack was located at the lowest fastener hole of the inboard chord inboard strap below stringer S-11R. The airplane had accumulated 75,584 total flight hours and 63,570 total flight cycles. Cracking in the inboard chord is the result of fatigue caused by cyclic pressurization of the fuselage. This condition, if not corrected, could result in structural failure of the frame and possible rapid decompression.

Related Service Information Under 14 CFR Part 51

We reviewed Boeing Alert Service Bulletin 737-53A1366, dated May 17, 2016. The service information describes procedures for repetitive detailed and HFEC inspections for cracking at the frame inboard chords, and repair. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.