

Airworthiness Limitations, of Chapter 5–40, Airworthiness Limitations, of the Dassault Falcon 50/50EX Maintenance Manual, Revision 21, dated June 2011. The initial compliance times for the tasks are at the applicable times specified in Section 05–40/00, Airworthiness Limitations, of Chapter 5–40, Airworthiness Limitations, of the Dassault Falcon 50/50EX Maintenance Manual, Revision 21, dated June 2011, or within 30 days after March 19, 2013, whichever occurs later.

**(h) Retained Provision Regarding Alternative Actions, Intervals, and Critical Design Configuration Control Limitations (CDCCLs), With New Exception**

This paragraph restates the requirements of paragraph (h) of AD 2013–03–12, with a new exception. Except as required by paragraph (i) of this AD: After accomplishing the revisions required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, and/or CDCCLs may be used other than those specified in Section 05–40/00, Airworthiness Limitations, of Chapter 5–40, Airworthiness Limitations, of the Dassault Falcon 50/50EX Maintenance Manual, Revision 21, dated June 2011, unless the actions, intervals, and/or CDCCLs are approved as an alternative methods of compliance (AMOC) in accordance with the procedures specified in paragraph (l)(1) of this AD.

**(i) New Maintenance or Inspection Program Revision**

Within 30 days after the effective date of this AD: Revise the maintenance or inspection program, as applicable, to incorporate airworthiness limitations, maintenance tasks, and associated thresholds and intervals specified in Section 05–40/00, Airworthiness Limitations, of Chapter 5–40, Airworthiness Limitations, of the Erratum to Dassault Falcon 50/50EX Maintenance Manual, Revision 23, dated July 2015. The initial compliance times for the tasks are at the applicable times specified in Section 05–40/00, Airworthiness Limitations, of Chapter 5–40, Airworthiness Limitations, of the Erratum to Dassault Falcon 50/50EX Maintenance Manual, Revision 23, dated July 2015, or within 30 days after the effective date of this AD, whichever occurs later. Accomplishing the revision of the maintenance or inspection program required by this paragraph terminates the requirements of paragraph (g) of this AD.

**(j) New Provision Regarding Alternative Actions and Intervals**

After the maintenance or inspection program has been revised as required by paragraph (i) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions and intervals are approved as an AMOC in accordance with the procedures specified in paragraph (l)(1) of this AD.

**(k) Terminating Action for Certain ADs**

Accomplishing the actions required by paragraph (g) or (i) of this AD terminates all requirements of AD 2010–26–05 and AD 2012–02–18 for the Dassault Aviation Model

MYSTERE–FALCON 50 airplanes specified in those ADs.

**(l) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1137; fax 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

**(m) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016–0067, dated April 7, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9569.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1137; fax 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(5) and (n)(6) of this AD.

**(n) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR as of June 13, 2017.

(i) Chapter 5–40, Airworthiness Limitations, of the Erratum to Dassault

Falcon 50/50EX Maintenance Manual, Revision 23, dated July 2015.

(ii) Reserved.

(4) The following service information was approved for IBR on March 19, 2013 (78 FR 9798, February 12, 2013).

(i) Section 05–40/00, Airworthiness Limitations, of Chapter 5–40, Airworthiness Limitations, of the Dassault Falcon 50/50EX Maintenance Manual, Revision 21, dated June 2011.

(ii) Reserved.

(5) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201–440–6700; Internet <http://www.dassaultfalcon.com>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 24, 2017.

**Paul Bernado,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2017–08829 Filed 5–8–17; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA–2016–9303; Directorate Identifier 2016–NM–093–AD; Amendment 39–18875; AD 2017–10–01]**

**RIN 2120–AA64**

**Airworthiness Directives; Dassault Aviation Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for all Dassault Aviation Model FAN JET FALCON airplanes; all Model FAN JET FALCON SERIES C, D, E, F, and G airplanes; and all Model MYSTERE–FALCON 20–C5, 20–D5, 20–E5, and 20–F5 airplanes. This AD was prompted by a determination that inspections for discrepancies of the fuselage bulkhead are necessary. This AD requires repetitive inspections for discrepancies of the fuselage bulkhead, and repair if

necessary. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective June 13, 2017.

**ADDRESSES:**

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9303; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-1137; fax: 425-227-1149.

**SUPPLEMENTARY INFORMATION:**

**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Dassault Aviation Model FAN JET FALCON airplanes; all Model FAN JET FALCON SERIES C, D, E, F, and G airplanes; and all Model MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes. The NPRM published in the **Federal Register** on November 1, 2016 (81 FR 75757) (“the NPRM”).

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2016-0096, dated May 19, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Dassault Aviation Model FAN JET FALCON airplanes; all Model FAN JET FALCON SERIES C, D, E, F, and G airplanes; and all Model MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes. The MCAI states:

A detailed inspection (DET) of the fuselage bulkhead at frame (FR) 33 is established through a subset of inspection/check maintenance procedure referenced in the applicable aircraft maintenance manual

(AMM), task 53-10-0-6 “MAIN FRAME—INSPECTION/CHECK”, with periodicity established in Chapter 5-10, at every C-Check. Failure to accomplish this DET could lead to deterioration of the affected structure.

This condition, if not detected and corrected, could lead to bulkhead failure, possibly resulting in a rapid depressurization of the aeroplane and consequent injury to occupants.

For the reasons described above, this [EASA] AD requires repetitive DET of the bulkhead at FR33 [for discrepancies, such as buckling, deformations, cracks, loose countersinks, scratches, dents, and corrosion], and depending on findings, repair of the affected structure.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9303.

**Comments**

We gave the public the opportunity to participate in developing this AD. The following presents the comment received on the NPRM and the FAA’s response to the single commenter.

**Request To Reduce Compliance Time**

The commenter, Mark Reiner, asked that the compliance time for the repetitive inspections required by paragraph (g) of the proposed AD be reduced from 5,000 to 2,500 flight cycles. The commenter reasoned that since so many airplanes are flying around the world and accumulating numerous flight cycles, the chances of problems occurring on an airplane are greatly increased.

We do not agree with the commenter’s request. In developing an appropriate compliance time for this action, we considered not only the degree of urgency associated with addressing the subject unsafe condition, but the manufacturer’s recommendation for an appropriate compliance time, and the practical aspect of accomplishing the inspections within an interval of time that corresponds to the typical scheduled maintenance for the majority of affected operators. Further, we determined that the compliance time recommended by the manufacturer and EASA, and the time required for the rulemaking process provide an acceptable level of safety. Therefore, we have not changed this AD in this regard.

**Conclusion**

We reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this AD as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

**Costs of Compliance**

We estimate that this AD affects 133 airplanes of U.S. registry.

We also estimate that it takes about 8 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$90,440, or \$680 per product.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

#### 2017-10-01 Dassault Aviation:

Amendment 39-18875; Docket No. FAA-2016-9303; Directorate Identifier 2016-NM-093-AD.

#### (a) Effective Date

This AD is effective June 13, 2017.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to the Dassault Aviation airplanes specified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category, all manufacturer serial numbers.

(1) Model FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G airplanes.

(2) Model MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes.

#### (d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

#### (e) Reason

This AD was prompted by a determination that inspections for discrepancies of the fuselage bulkhead at frame (FR) 33 are necessary. We are issuing this AD to detect and correct discrepancies of the fuselage bulkhead; such discrepancies could result in the deterioration and subsequent failure of the bulkhead, which could result in rapid decompression of the airplane and consequent injury to occupants.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Repetitive Inspections

Before exceeding 5,000 total flight cycles since first flight of the airplane, or within 500 flight cycles after the effective date of this AD, whichever occurs later: Do a detailed inspection for discrepancies of the fuselage bulkhead at FR 33 using a method approved

by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature. Repeat the inspection thereafter at intervals not to exceed 5,000 flight cycles.

#### (h) Repair

If any discrepancy is found during any inspection required by paragraph (g) of this AD: Before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Dassault Aviation's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature. Repair of an airplane as required by this paragraph does not constitute terminating action for the repetitive actions required by paragraph (g) of this AD, unless specified otherwise in the repair instructions.

#### (i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-1137; fax: 425-227-1149. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Dassault Aviation's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

#### (j) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016-0096, dated May 19, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9303.

#### (k) Material Incorporated by Reference

None.

Issued in Renton, Washington, on May 1, 2017.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2017-09323 Filed 5-8-17; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 91

[Docket No. FAA-2006-24981; Amdt. Nos. 61-138A, 91-344A, and 135-134A]

**RIN 2120-AK63**

#### MU-2B Series Airplane Training Requirements Update; Correction

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; correcting amendment.

**SUMMARY:** The FAA is correcting a final rule published on September 7, 2016. In that rule, the FAA amended its regulations to relocate and update the content of SFAR No. 108 to the newly created subpart N of part 91 in order to improve the safety of operating the Mitsubishi Heavy Industries (MHI) MU-2B series airplane. This document corrects two errors in the codified text of the final rule.

**DATES:** Effective May 9, 2017.

**FOR FURTHER INFORMATION CONTACT:** For technical questions concerning this action, contact Joseph Hemler, Commercial Operations Branch, Flight Standards Service, AFS-820, Federal Aviation Administration, 55 M Street SE., 8th floor, Washington, DC 20003-3522; telephone (202) 267-1100; email [joseph.k.hemler-jr@faa.gov](mailto:joseph.k.hemler-jr@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Background

On September 7, 2016, the FAA published a final rule entitled, "MU-2B Series Airplane Training Requirements Update" (81 FR 61583). In that final rule, the FAA amended its regulations to relocate and update the content of SFAR No. 108 to the newly created subpart N of part 91 in order to improve the safety of operating the MHI MU-2B series airplane. The FAA relocated the training program from the SFAR No. 108 appendices to advisory material in order to allow the FAA to update policy while ensuring significant training adjustments still go through notice-and-comment rulemaking. The FAA also corrected and updated several inaccurate maneuver profiles to reflect