

Accomplishment Instructions of Boeing Alert Service Bulletin 737–53A1353, dated July 21, 2016.

(1) If no crack is found: Repeat the inspections thereafter at the applicable times specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737–53A1353, dated July 21, 2016.

(2) If any crack is found: Do the actions specified in paragraphs (g)(2)(i) and (g)(2)(ii) of this AD.

(i) Repair the crack before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD. Although Boeing Alert Service Bulletin 737–53A1353, dated July 21, 2016, specifies to contact Boeing for repair instructions, and specifies that action as “RC” (Required for Compliance), this AD requires repair as specified in this paragraph.

(ii) On areas that are not repaired, repeat the inspections thereafter at the applicable times specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737–53A1353, dated July 21, 2016.

(h) Service Information Exception

Where paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737–53A1353, dated July 21, 2016, specifies a compliance time “after the Original Issue date of this Service Bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (g)(2)(i) of this AD: For service information that contains steps that are labeled as RC, the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is

labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Alan Pohl, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: 425–917–6450; fax: 425–917–6590; email: alan.pohl@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737–53A1353, dated July 21, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740; telephone: 562–797–1717; Internet: <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 10, 2017.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017–10263 Filed 5–22–17; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2016–9394; Directorate Identifier 2016–NM–162–AD; Amendment 39–18872; AD 2017–09–10]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all The Boeing Company Model 747–400, 747–400D, and 747–400F airplanes. This AD was prompted by a report of a crack in the left wing front spar web, found following a fuel leak. This AD requires repetitive inspections for cracking of the front spar web, and repairs if necessary. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective June 27, 2017.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 27, 2017.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9394.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9394; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800–647–5527) is Docket Management Facility, U.S. Department of Transportation, Docket

Operations, M-30, West Building
Ground Floor, Room W12-140, 1200
New Jersey Avenue SE., Washington,
DC 20590.

FOR FURTHER INFORMATION CONTACT: Bill
Ashforth, Aerospace Engineer, Airframe
Branch, ANM-120S, FAA, Seattle
Aircraft Certification Office (ACO), 1601
Lind Avenue SW., Renton, WA 98057-
3356; phone: 425-917-6432; fax: 425-
917-6590; email: bill.ashforth@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed
rulemaking (NPRM) to amend 14 CFR
part 39 by adding an AD that would
apply to all The Boeing Company Model
747-400, 747-400D, and 747-400F
airplanes. The NPRM published in the
Federal Register on December 2, 2016
(81 FR 86977) (“the NPRM”). The
NPRM was prompted by a report
indicating that a fuel leak in one
airplane led to the discovery of a 13.4-
inch crack in the left wing front spar
web inboard of pylon number 2 between
front spar station inboard (FSSI) 655.75
and FSSI 660. The NPRM proposed to
require repetitive detailed, ultrasonic,
and high frequency eddy current
inspections for cracking of the front spar
web between FSSI 628 and FSSI 713,
and repairs if necessary. We are issuing
this AD to detect and correct cracking in
the front spar web, which could lead to
fuel leaks and a consequent fire.

Comments

We gave the public the opportunity to
participate in developing this AD. The
following presents the comments
received on the NPRM and the FAA’s
response to each comment.

Support for the NPRM

Boeing and commenter Melanie Smith
stated that they support the NPRM.

Request To Update the Labor Costs

British Airways (BA), Cargolux
Airlines (CLX), and KLM Royal Dutch
Airlines (KLM) all stated that the actual
work-hours required to do the mandated

inspections are higher than the estimate
listed in the NPRM. They estimated the
inspections actually take between 137
and 159 work-hours, not the 55 work-
hours stated in the NPRM.

We agree that the estimated work-
hours should be increased. When
issuing a service bulletin, Boeing
estimates work-hours under expected
conditions. As operators implement the
service bulletin, they may find the
actual work-hours are higher or lower
than estimated. We have updated the
Costs of Compliance section of this AD
to reflect a conservative estimate of 159
work-hours per inspection cycle.

**Request To Change the Initial and
Repetitive Compliance Times**

BA, CLX, and KLM all requested that
we change the initial and/or repetitive
compliance times to align with
scheduled maintenance checks. BA
proposed to do time-limited alternative
inspections in the most critical web
locations and to defer the majority of the
web inspections to coincide with longer
planned maintenance checks. CLX
requested that we change the initial
compliance time from 6 months to 24
months, and that we change the
repetitive inspection interval from 1,200
flight cycles to 2,000 flight cycles. KLM
requested that we extend the repetitive
inspection intervals for Model 747
freighters from 1,200 flight cycles to
1,800 flight cycles. Each of the
commenters noted that the actual work-
hours are higher than estimated in the
NPRM, and the inspections would
require additional downtime and costs
if not done at the same time as regularly
scheduled maintenance. None of the
commenters provided engineering
analyses to support their proposed
extended compliance times.

We disagree with the requests. In
developing an appropriate compliance
time for this action, we considered the
urgency associated with the subject
unsafe condition and the practical
aspect of accomplishing the required
modification within a period of time
that corresponds to the normal

scheduled maintenance for most
affected operators. Boeing is aware of
the discrepancy in work-hours and is
developing a request for a global
alternative method of compliance
(AMOC) to provide operators an
alternative for both the areas of
inspection and the compliance times. In
addition, operators have the option of
proposing an adjustment to the
compliance times, supported by
appropriate engineering analyses, in
accordance with the provisions of
paragraph (j) of this AD. We have not
changed this final rule regarding this
issue.

Conclusion

We reviewed the relevant data,
considered the comments received, and
determined that air safety and the
public interest require adopting this AD
as proposed, except for minor editorial
changes. We have determined that these
minor changes:

- Are consistent with the intent that
was proposed in the NPRM for
correcting the unsafe condition; and
- Do not add any additional burden
upon the public than was already
proposed in the NPRM.

**Related Service Information Under 1
CFR Part 51**

We reviewed Boeing Alert Service
Bulletin 747-57A2357, dated September
12, 2016. The service information
describes procedures for repetitive
detailed, ultrasonic, and high frequency
eddy current inspections, and repairs of
cracking of the front spar web between
FSSI 628 and FSSI 713. This service
information is reasonably available
because the interested parties have
access to it through their normal course
of business or by the means identified
in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 137
airplanes of U.S. registry. We estimate
the following costs to comply with this
AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspections	159 work-hours × \$85 per hour = \$13,515 per inspection cycle.	\$0	\$13,515 per inspection cycle	\$1,851,555 per inspection cycle.

We have received no definitive data
that would enable us to provide cost
estimates for the on-condition actions
specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code
specifies the FAA’s authority to issue
rules on aviation safety. Subtitle I,

section 106, describes the authority of
the FAA Administrator. Subtitle VII:
Aviation Programs, describes in more
detail the scope of the Agency’s
authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2017-09-10 The Boeing Company:
Amendment 39-18872; Docket No. FAA-2016-9394; Directorate Identifier 2016-NM-162-AD.

(a) Effective Date

This AD is effective June 27, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 747-400, 747-400D, and 747-400F airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a report of a 13.4-inch crack in the left wing front spar web inboard of pylon number 2 between front spar station inboard (FSSI) 655.75 and FSSI 660, found following a fuel leak. We are issuing this AD to detect and correct cracking in the front spar web, which could lead to fuel leaks and a consequent fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Detailed, Ultrasonic, and High Frequency Eddy Current Inspections

At the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-57A2357, dated September 12, 2016, except as provided by paragraph (i) of this AD, do detailed, ultrasonic, and high frequency eddy current inspections for any cracking in the front spar web, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2357, dated September 12, 2016. Repeat the inspections thereafter at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-57A2357, dated September 12, 2016.

(h) Repair of Any Cracking

If any crack is found during any inspection required by paragraph (g) of this AD, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD. Thereafter, repeat the inspections specified in paragraph (g) of this AD at all unrepaired areas.

(i) Service Information Exceptions

Where paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-57A2357, dated September 12, 2016, specifies a compliance time "after the original date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in

paragraph (k) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (i) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

For more information about this AD, contact Bill Ashforth, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6432; fax: 425-917-6590; email: bill.ashforth@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 747-57A2357, dated September 12, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 27, 2017.

Paul Bernado,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-10257 Filed 5-22-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-9439; Directorate Identifier 2016-NM-170-AD; Amendment 39-18870; AD 2017-09-08]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 787-8 airplanes. This AD was prompted by a report indicating that during an airplane inspection in production, the variable frequency starter generator (VFSG) power feeder cables were found to contain terminal lugs incorrectly installed common to terminal blocks located in the wing front spar. This AD requires a general visual inspection of the wings, section 16, terminal lugs at the terminal power block of the VFSG power feeder cable for correct installation and applicable corrective actions. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective June 27, 2017.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 27, 2017.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone: 562-797-1717; Internet: <https://www.myboeingfleet.com>. You may view this referenced service

information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9439.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9439; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Brendan Shanley, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6492; fax: 425-917-6590; email: brendan.shanley@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 787-8 airplanes. The NPRM published in the **Federal Register** on December 16, 2016 (81 FR 91066) ("the NPRM"). The NPRM was prompted by a report indicating that during an airplane inspection in production, the VFSG power feeder cables were found to contain terminal lugs incorrectly installed common to terminal blocks located in the wing front spar. The NPRM proposed to require a general visual inspection of the wings, section 16, terminal lugs at the terminal power block of the VFSG power feeder cable for correct installation and applicable corrective actions. We are issuing this AD to detect and correct incorrectly installed terminal lugs which may contact adjacent structure and be damaged. Damaged terminal lugs could cause the potential loss of several functions essential for safe flight or electrical arcing in a flammable leakage zone, which could result in an electrical

short and the possible introduction of energy into the main fuel tanks.

Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM and the FAA's response to each comment.

Support for the NPRM

The Air Line Pilots Association, International, expressed support for the NPRM.

Request To Revise Compliance Time

Boeing and All Nippon Airways (ANA) requested that we revise the compliance time specified in paragraph (g) of the proposed AD. Boeing stated that paragraph (g) of the proposed AD refers to paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin B787-81205-SB240027-00, Issue 002, dated September 6, 2016 ("ASB B787-81205-SB240027-00, Issue 002") and requested that we instead refer to paragraph 5., "Compliance," of ASB B787-81205-SB240027-00, Issue 002," because that is the correct location for the applicable times. ANA stated that paragraph 1.E., "Compliance," doesn't exist in ASB B787-81205-SB240027-00, Issue 002, and recommended a compliance time of "within 12 months after the effective date of this AD." Boeing also recommended that the compliance time be tied to the effective date of the AD to allow operators a valid and acceptable time frame to perform the actions specified in ASB B787-81205-SB240027-00, Issue 002. Additionally, the commenters stated that the compliance time "within 12 months after the original issue date of this service bulletin," as specified in ASB B787-81205-SB240027-00, Issue 002, would put operators out of compliance upon AD issuance.

We agree with the commenters. We have revised paragraph (g) of this AD to specify "Within 12 months after the effective date of this AD" and have removed reference to paragraph 1.E., "Compliance," of ASB B787-81205-SB240027-00, Issue 002. We have determined that extending the compliance time from what was proposed will provide an acceptable level of safety.

Request To Clarify the Unsafe Condition Statement

Boeing requested that we revise the "Discussion" section of the NPRM and paragraph (e) of the proposed AD to remove information about the potential to introduce energy into the main fuel tanks and include information about