

(c) Applicability

This AD applies to Airbus Model A320–211, –212, –214, and –231 airplanes, certificated in any category, manufacturer serial numbers up through 0104 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Reason

This proposed AD is intended to complete certain mandated programs intended to support the airplane reaching its limit of validity (LOV) of the engineering data that support the established structural maintenance program. We are proposing this AD to prevent fatigue cracking in the pressurized floor fittings at frame 36, which could result in the reduced structural integrity of the floor fittings and subsequent depressurization of the fuselage.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

(1) At the latest of the times specified in paragraphs (g)(1)(i), (g)(1)(ii), and (g)(1)(iii) of this AD: Do a detailed inspection of the pressurized floor fittings at FR 36, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320–57–1028, Revision 02, dated June 3, 2013. Repeat the inspection thereafter at intervals not to exceed 9,300 flight cycles or 18,600 flight hours, whichever occurs first.

(i) Before exceeding 20,900 flight cycles or 41,800 flight hours, whichever occurs first since first flight of the airplane.

(ii) Within 9,300 flight cycles or 18,600 flight cycles since the most recent inspection accomplished in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320–57–1028, Revision 02, dated June 3, 2013.

(iii) Within 1,250 flight cycles or 2,500 flight hours after March 3, 2016 (the effective date of AD 2016–02–01), without exceeding 12,000 flight cycles since the most recent inspection accomplished in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320–57–1028, Revision 02, dated June 3, 2013.

(2) If any crack is found during any inspection required by paragraph (g)(1) of this AD: Before further flight, repair using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

(h) Modification

Before exceeding 48,000 total flight cycles or 96,000 total flight hours, whichever occurs first since first flight of the airplane: Modify (replace aluminum fittings with titanium fittings) the pressurized floor fittings at FR 36, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320–57–1029, Revision 02, dated June 16, 1999. Accomplishment of this modification is terminating action for the repetitive

inspections required by paragraph (g) of this AD for the modified airplane only.

(i) Credit for Previous Actions

(1) This paragraph provides credit for the inspection required by paragraph (g) of this AD, if that inspection was performed before the effective date of this AD using Airbus Service Bulletin A320–57–1028, dated August 12, 1991; or Revision 01, dated June 3, 2013.

(2) This paragraph provides credit for the modification required by paragraph (h) of this AD, if that modification was performed before the effective date of this AD using Airbus Service Bulletin A320–57–1029, dated August 12, 1991; or Revision 01, dated November 10, 1992.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Staff, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the EASA; or Airbus's DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2016–0181, dated September 13, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–0716.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1405; fax 425–227–1149.

(3) For service information identified in this AD, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA.

For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on July 28, 2017.

John P. Piccola, Jr.,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2017–16569 Filed 8–14–17; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2017–0777; Product Identifier 2017–NM–050–AD]

RIN 2120–AA64

Airworthiness Directives; Saab AB, Saab Aeronautics (Formerly Known as Saab AB, Saab Aerosystems) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Saab AB, Saab Aeronautics Model SAAB 340B airplanes. This proposed AD was prompted by reports of natural stall events in icing conditions, without prior stall warnings. This proposed AD would require modifying the stall warning system, installing new stall warning computers, and activating the stall warning system. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by September 29, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Saab AB, Saab Aeronautics, SE–581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email

saab340techsupport@saabgroup.com; Internet <http://www.saabgroup.com>. You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0777; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-1112; fax: 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2017-0777; Product Identifier 2017-NM-050-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2017-0067, dated April 24, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Saab AB, Saab Aeronautics Model SAAB 340B airplanes. The MCAI states:

Discussion

A few natural stall events, specifically when operating in icing conditions, have been experienced on SAAB 340 series aeroplanes, without receiving a prior stall warning.

This condition, if not corrected, could result in loss of control of the aeroplane.

To address this potential unsafe condition, SAAB developed a modified stall warning system, incorporating improved stall warning logic, and issued various Service Bulletins (SB) providing instructions to replace the Stall Warning Computer (SWC) with a new SWC, and instructions to activate the new SWC. The new system includes stall warning curves optimized for operation in icing conditions, which are activated by selection of Engine Anti-Ice.

Consequently, EASA issued AD 2014-0218 [which corresponds to FAA AD 2016-22-15, Amendment 39-18704 (81 FR 76843, November 4, 2016)] to require installation and activation of the improved SWC. That [EASA] AD excluded certain SAAB 340B aeroplanes by s/n.

Since EASA AD 2014-0218 was issued, SAAB developed a technical solution applicable for some of those previously excluded aeroplanes, and issued SB 340-27-117 and SB 340-27-118, providing instructions to modify and activate the new SWC.

For the reasons described above, this [EASA] AD requires installation and activation of the improved SWC.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0777.

Related Service Information Under 1 CFR Part 51

Saab AB, Saab Aeronautics has issued Service Bulletin 340-27-117, dated January 23, 2017. The service information describes procedures for modifying the stall warning system.

Saab AB, Saab Aeronautics has also issued Service Bulletin 340-27-118, dated January 23, 2017. The service information describes procedures for installing new stall warning computers and activating the modified stall warning system.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD affects 4 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Modification, installation, and activation	78 work-hours × \$85 per hour = \$6,630	\$33,000	\$39,630	\$158,520

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for

safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft

Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Saab AB, Saab Aeronautics (Formerly Known as Saab AB, Saab Aerosystems): Docket No. FAA-2017-0777; Product Identifier 2017-NM-050-AD.

(a) Comments Due Date

We must receive comments by September 29, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Saab AB, Saab Aeronautics (formerly known as Saab AB, Saab Aerosystems) Model SAAB 340B airplanes, certificated in any category, serial numbers 362, 363, 385, and 405.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Reason

This AD was prompted by reports of natural stall events in icing conditions, without prior stall warnings. We are issuing this AD to prevent a natural stall event in icing conditions without any stall warning, which could result in loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification

Within 12 months after the effective date of this AD, do the actions specified in paragraphs (g)(1) and (g)(2) of this AD.

(1) Install a provision for a modified stall warning system, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340-27-117, dated January 23, 2017.

(2) Install new stall warning computers and activate the modified stall warning system, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340-27-118, dated January 23, 2017.

(h) Parts Installation Prohibition

After modification of an airplane as required by paragraph (g) of this AD, no person may install a stall warning computer having part number (P/N) 20AK5 or P/N 0020AK5 on that airplane.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Saab AB, Saab Aeronautics’s EASA Design Organization Approval (DOA). If approved by

the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2017-0067, dated April 24, 2017, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0777.

(2) For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-1112; fax: 425-227-1149.

(3) For service information identified in this AD, contact Saab AB, Saab Aeronautics, SE-581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email saab340.techsupport@saabgroup.com; Internet <http://www.saabgroup.com>. You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on August 3, 2017.

Jeffrey E. Duven,

Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2017-17095 Filed 8-14-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0776; Product Identifier 2017-NM-062-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737-200, -300, -400, and -500 series airplanes. This proposed AD was prompted by reports of cracks in the frame web adjacent to the air-conditioning support brackets. This proposed AD would require an inspection for any air conditioning bracket assembly or intercostal, and depending on the results, repetitive inspections for cracking of certain locations and applicable on-condition actions. We are proposing this AD to address the unsafe condition on these products.