

2017-07-02, Amendment 39-18840 (82 FR 15120, March 27, 2017), and adding the following new AD:

Sikorsky Aircraft Corporation (Sikorsky):
Docket No. FAA-2017-0896; Product Identifier 2017-SW-034-AD.

(a) Applicability

This AD applies to Sikorsky Model 269D and Model 269D Configuration A helicopters with a KAflex engine side drive shaft part number (P/N) SKCP2738-7 and KAflex pulley side drive shaft P/N SKCP2738-5 installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as failure of a drive shaft. This condition could result in loss of rotor drive and subsequent loss of control of the helicopter.

(c) Affected ADs

This AD supersedes AD 2017-07-02, Amendment 39-18840 (82 FR 15120, March 27, 2017).

(d) Comments Due Date

We must receive comments by November 21, 2017.

(e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(f) Required Actions

(1) Before further flight:

(i) For Model 269D helicopters, remove from service any KAflex engine side drive shaft P/N SKCP2738-7 and any KAflex pulley side drive shaft P/N SKCP2738-5 that has 6,000 or more hours time-in-service (TIS). Thereafter, remove from service any KAflex engine side drive shaft P/N SKCP2738-7 and any KAflex pulley side drive shaft P/N SKCP2738-5 before accumulating 6,000 hours TIS.

(ii) For Model 269D Configuration A helicopters, remove from service any KAflex engine side drive shaft P/N SKCP2738-7 and any KAflex pulley side drive shaft P/N SKCP2738-5 that has 1,200 or more hours TIS. Thereafter, remove from service any KAflex engine side drive shaft P/N SKCP2738-7 and any KAflex pulley side drive shaft P/N SKCP2738-5 before accumulating 1,200 hours TIS.

(iii) If interchanged between Model 269D and Model 269D Configuration A helicopters, remove from service any KAflex engine side drive shaft P/N SKCP2738-7 and any KAflex pulley side drive shaft P/N SKCP2738-5 that has 1,200 or more hours TIS. Thereafter, if interchanged between Model 269D and Model 269D Configuration A helicopters, remove from service any KAflex engine side drive shaft P/N SKCP2738-7 and any KAflex pulley side drive shaft P/N SKCP2738-5 before accumulating 1,200 hours TIS.

(2) Within 25 hours TIS, and thereafter at intervals not to exceed 25 hours TIS, using a belt drive alignment tool 269T3303-003, inspect the lower pulley to engine alignment by engaging the tool on the drive shaft and inserting in the lower pulley bore. Rotate the

tool 360° around the drive shaft and inspect for interference. If there is any interference with the rotation of the tool, before further flight, adjust the engine elevation alignment to eliminate the interference.

(3) Within 25 hours TIS, and thereafter at intervals not to exceed 100 hours TIS:

(i) Remove the drive shaft to adapter bolt and inspect the drive shaft alignment. Engage and disengage the splines a minimum of 3 times by sliding the engine power output shaft in and out of the engine. Inspect the alignment at each 90° interval by rotating the lower pulley with the power shaft disengaged. Determine whether the adapter slides on and off the drive shaft splines without spline engagement interference or resistance along the entire length of movement. If there is any spline engagement interference or resistance, before further flight, replace both the engine side and pulley side drive shafts.

(ii) Inspect each drive shaft for a crack, any corrosion or pitting, a nick, a dent, and a scratch. If there is a crack, any corrosion or pitting, a nick, a dent, or a scratch that exceeds allowable limits, before further flight, replace both the engine side and pulley side drive shafts.

(4) Within 25 hours TIS, and thereafter at intervals not to exceed 400 hours TIS, remove the engine side drive shaft and pulley side drive shaft and perform the following:

(i) Inspect each flex frame (frame) bolted joint (joint) for movement by hand. If there is any movement, before further flight, replace both the engine side and pulley side drive shafts.

(ii) Visually inspect each joint for fretting corrosion (which might be indicated by metallic particles) and each frame and mount bolt torque stripe for movement. If there is any fretting corrosion or torque stripe movement, before further flight, replace both the engine side and pulley side drive shafts.

(iii) Using a 10x or higher power magnifying glass, visually inspect each joint for fretting and for a crack around the bolt head and washer side, and around the nut and washer side. Also inspect both sides of each frame for a crack on the inside and outside corner radii and radii edge (four). If there is any fretting, a crack at any point over the full circumference (360°) of the bolt head and washer side or the nut and washer side, or a crack in any of the corner radii edges, before further flight, replace both the engine side and pulley side drive shafts.

(5) As an optional terminating action to the repetitive inspections in this AD, you may install KAflex engine side drive shaft P/N SKCP2738-9 and KAflex pulley side drive shaft P/N SKCP2738-101.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Boston ACO Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Michael Schwetz, Aviation Safety Engineer, Boston ACO Branch, Compliance and Airworthiness Division, FAA, 1200 District Avenue, Burlington, Massachusetts 01803; telephone (781) 238-7761; email michael.schwetz@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under

14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

Appendix B of Sikorsky S-330 Model 269D Helicopter Basic Handbook of Maintenance Instructions, No. CSP-D-2, dated February 1, 1993, and revised October 15, 2014; Appendix B of Sikorsky S-330 Model 269D Config. "A" Helicopter Basic Handbook of Maintenance Instructions, No. CSP-D-9, dated July 20, 2001, and revised October 15, 2014; and Sikorsky 269D Helicopter Alert Service Bulletin DB-052, Basic Issue, dated January 16, 2014, which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact Sikorsky Aircraft Corporation, Customer Service Engineering, 124 Quarry Road, Trumbull, CT 06611; telephone 1-800-Winged-S or 203-416-4299; email wcs_cust_service_eng_gr-sik@lmco.com. You may review the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(i) Subject

Joint Aircraft Service Component (JASC) Code: 6310, Engine/Transmission Coupling.

Issued in Fort Worth, Texas, on September 11, 2017.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2017-19945 Filed 9-21-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0658; Product Identifier 2017-NE-20-AD]

RIN 2120-AA64

Airworthiness Directives; GE Aviation Czech s.r.o. Turboprop Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain GE Aviation Czech s.r.o. M601D-11, M601E-11, M601E-11A, M601E-11AS, M601E-11S, and M601F turboprop engines. This proposed AD was prompted by a review that determined that certain power turbine (PT) rotors have less overspeed margin than originally declared during product

certification. This proposed AD would require removal of the affected PT disks. We are proposing this AD to correct the unsafe condition on these products.

DATES: We must receive comments on this NPRM by November 6, 2017.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Fax:* 202-493-2251.

For service information identified in this proposed AD, contact GE Aviation Czech s.r.o., Beranových 65, 199 02 Praha 9—Letňany, Czech Republic; phone: +420 222 538 111; fax: +420 222 538 222. You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0658; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the mandatory continuing airworthiness information (MCAI), the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is

in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Robert Green, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7754; fax: 781-238-7199; email: robert.green@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this NPRM. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2017-0658; Directorate Identifier 2017-NE-20-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this NPRM.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2017-0100, dated June 8, 2017 (referred to hereinafter as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

It was identified during a recent design review that power turbine (PT) rotors with certain disks, part number (P/N) M601-3220.6 and P/N M601-3220.7, have a reduction in the declared theoretical PT rotor overspeed limit.

This condition, if not corrected, may lead to high energy debris release in case of PT rotor overspeed occurrence, possibly resulting in damage to, and/or reduced control of, the aeroplane.

You may obtain further information by examining the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0658.

Related Service Information

GE Aviation Czech s.r.o. has issued Alert Service Bulletin (ASB) No. ASB-M601E-72-50-00-0069, ASB-M601D-72-50-00-0052, ASB-M601F-72-50-00-0035, ASB-M601T-72-50-00-0028, and ASB-M601Z-72-50-00-0038, (single document), dated February 21, 2017. The ASB describe procedures for replacing the PT disk.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of Czech Republic, and is approved for operation in the United States. Pursuant to our bilateral agreement with the European Community, EASA has notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design. This proposed AD would require removal of the affected PT disks.

Costs of Compliance

We estimate that this proposed AD affects 50 engines installed on airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Disk removal and replacement	56 work-hours × \$85 per hour = \$4,760	\$6,989	\$14,749	\$587,450

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII,

Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on

products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has

delegated the authority to issue ADs applicable to engines, propellers, and appliances to the Manager, Engine and Propeller Standards Branch, Policy and Innovation Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

GE Aviation Czech s.r.o. (Type Certificate previously held by WALTER Engines a.s., Walter a.s., and MOTORLET a.s.):
Docket No. FAA-2017-0658; Product Identifier 2017-NE-20-AD.

(a) Comments Due Date

We must receive comments by November 6, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to certain GE Aviation Czech s.r.o. M601D-11, M601E-11, M601E-11A, M601E-11AS, M601E-11S, and M601F turboprop engines, with power turbine (PT) rotor disks, part number (P/N) M601-3220.6 or P/N M601-3220.7, installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

(e) Reason

This AD was prompted by a review that determined that PT rotors with certain disks, P/N M601-3220.6 or P/N M601-3220.7, have less overspeed margin than originally declared during product certification. We are issuing this AD to prevent failure of the PT rotor, uncontained release of the PT rotor disk, damage to the engine, and damage to the airplane.

(f) Compliance

(1) Comply with this AD within the compliance times specified, unless already done.

(2) After the effective date of this AD, remove the affected PT disk from service during the next engine shop visit, or within 5 years, whichever occurs first.

(g) Installation Prohibition

After the effective date of this AD, do not install an affected PT disk on any engine.

(h) Definition

For the purpose of this AD, an engine shop visit is when an engine is overhauled or rebuilt.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Robert Green, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7754; fax: 781-238-7199; email: robert.green@faa.gov.

(2) Refer to MCAI European Aviation Safety Agency AD 2017-0100, dated June 8, 2017, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2017-0658.

(3) GE Aviation Czech s.r.o. Alert Service Bulletin No. ASB-M601E-72-50-00-0069,

ASB-M601D-72-50-00-0052, ASB-M601F-72-50-00-0035, ASB-M601T-72-50-00-0028, and ASB-M601Z-72-50-00-0038, (single document), dated February 21, 2017, can be obtained from GE Aviation Czech s.r.o, using the contact information in paragraph (j)(4) of this proposed AD.

(4) For service information identified in this proposed AD, contact GE Aviation Czech s.r.o., Beranových 65, 199 02 Praha 9—Letňany, Czech Republic; phone: +420-222-538-111; fax: +420-222-538-222.

(5) You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Issued in Burlington, Massachusetts, on September 13, 2017.

Robert J. Ganley,

Manager, Engine and Propeller Standards Branch, Aircraft Certification Service.

[FR Doc. 2017-19969 Filed 9-21-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0750; Product Identifier 2017-NE-24-AD]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce Corporation Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Rolls-Royce Corporation (RRC) AE 3007A and AE 3007C model turbofan engines. This proposed AD was prompted by an updated analysis that lowered the life limit of fan wheels installed on the affected engines. This proposed AD would require removal of the affected fan wheel at new, lower life limits. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by November 6, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room