

# Proposed Rules

Federal Register

Vol. 82, No. 212

Friday, November 3, 2017

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## OFFICE OF PERSONNEL MANAGEMENT

### 5 CFR 890

RIN: 3206-AN33

#### Federal Employees Health Benefits (FEHB) Program: FEHB Employee Premium Contributions for Employees in Leave Without Pay or Other Nonpay Status

**AGENCY:** U.S. Office of Personnel Management.

**ACTION:** Proposed rule; withdrawal.

**SUMMARY:** The United States Office of Personnel Management (OPM) is withdrawing a previously published Notice of Proposed Rulemaking (NPRM) that would have amended the Federal Employees Health Benefits (FEHB) regulations at 5 CFR part 890 to provide flexibility to agencies regarding payment for FEHB coverage for employees entering leave without pay (LWOP) or any other type of nonpay status, except when nonpay is as a result of a lapse of appropriations. The regulation also would have affected employees who have insufficient pay to cover their premium contribution, and certain categories of employees were exempt.

**DATES:** OPM is withdrawing the proposed rule published August 30, 2016 (81 FR 59518) as of November 3, 2017.

**FOR FURTHER INFORMATION CONTACT:** Julia Elam, Program Analyst at (202) 606-0004.

**SUPPLEMENTARY INFORMATION:** On August 30, 2016, OPM published an NPRM (81 FR 59518) that would complement the FEHB Modification of Eligibility final regulation (79 FR 62325, published on October 17, 2014) which allows generally for certain temporary, intermittent and seasonal employees to enroll in the FEHB Program if they are expected to work at least 130 hours per month for at least 90 days. In the NPRM, OPM recognized that the expansion of eligibility for FEHB coverage may

impact an agency's budget due to the required FEHB Government health benefit contributions for newly eligible employees who elect to participate in FEHB coverage and go into LWOP or other nonpay status based on the intermittent nature of the work performed. The NPRM would have provided flexibility to agencies regarding payment for FEHB coverage for employees entering leave without pay (LWOP) or any other type of nonpay status, except when nonpay is as a result of a lapse of appropriations.

OPM received comments from Federal employees, Federal agencies, a Federal shared service provider, and unions representing Federal employees. The majority of commenters objected to the regulation based on concerns that the rule would place an undue financial burden on Federal employees on LWOP or other nonpay status and would make it difficult for these employees to maintain health insurance. OPM also received comments about the impact of the rule on Permanent Seasonal Employees (PSEs). The commenters stated that PSEs are placed in nonpay status annually and there is a reasonable expectation that these employees will return to employment and repay the unpaid premiums that have been incurred as a debt.

In reviewing these objections, OPM attempted to determine whether the potential cost savings from this proposed rulemaking outweighs the negative impact asserted by commenters. To estimate cost savings, OPM requested the current amount of unrecoverable premium debt from employees on LWOP and nonpay status from several agencies with large numbers of temporary, seasonal and intermittent employees. However, these agencies were generally unable to provide this data. Agencies do not have reliable data on unrecoverable FEHB debt because, due to constantly changing circumstances, these amounts are difficult to track. OPM did obtain one estimate of unpaid FEHB debt or FEHB debt in default for all employees on seasonal and intermittent Schedules in LWOP or insufficient pay for one agency for FY2016. The agency reported that total FEHB debt incurred by the agency for these employees was \$1,068,065, but that only \$48,797 of this total debt remained unpaid by employees once they returned to pay (or

sufficient pay) status. Further, there are debt collection mechanisms in place to recover the remaining \$48,797.

Agencies must already comply with the Debt Collection Improvement Act (DCIA) of 1996 (DCIA) to collect delinquent debt, including FEHB debt. Therefore, appropriate actions are being taken for the collection of FEHB debt for employees entering leave without pay (LWOP) or any other type of nonpay status. OPM determined that the potential cost savings from this proposed rulemaking does not outweigh the potential negative impact of the undue financial burden or risk of losing health insurance on certain Federal employees.

Withdrawal of this NPRM (81 FR 59518, August 30, 2016) does not preclude the agency from issuing future rulemakings on this issue, nor does it commit the agency to any course of action in the future.

U.S. Office of Personnel Management.

**Kathleen McGettigan,**  
*Acting Director.*

[FR Doc. 2017-23956 Filed 11-2-17; 8:45 am]

**BILLING CODE 6325-63-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2017-0838; Product Identifier 2017-NE-33-AD]

RIN 2120-AA64

#### Airworthiness Directives; Safran Helicopter Engines, S.A., Turboshift Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all Safran Helicopter Engines, S.A., Arriel 2E turboshift engines. This proposed AD was prompted by reports of ruptured front support pins on the accessory gearbox front support. This proposed AD would require replacement of the accessory gearbox front support. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this NPRM by December 18, 2017.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Mail:* Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- *Fax:* 202-493-2251.

For service information identified in this proposed AD, contact Safran Helicopter Engines, S.A., 40220 Tarnos, France; phone: (33) 05 59 74 40 00; fax: (33) 05 59 74 45 15. You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0838; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the mandatory continuing airworthiness information (MCAI), the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Robert Green, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7754; fax: 781-238-7199; email: [robert.green@faa.gov](mailto:robert.green@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2017-0838; Product Identifier 2017-NE-33-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this NPRM.

**Discussion**

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No. 2016-0235, dated November 24, 2016 (referred to hereinafter as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

Some cases were reported of ruptured front support pins on ARRIEL 1E2 engines. That condition, if not detected and corrected, could lead to the loss of the load path integrity of the engine front support. Consequently, Turboméca issued Mandatory Service Bulletin (MSB) 292 72 0842 to provide instructions for the inspection of the pins and front support replacement, and EASA issued AD 2015-0064 (later revised) to require those actions. Since EASA AD 2015-0064R1 was issued, SAFRAN Helicopter Engines developed a new pin design, in order to increase the mechanical strength of the pin, through modification TU380, for ARRIEL 1E2 engines. Although no cases of front support pin rupture have been reported on ARRIEL 2E engines, since the ARRIEL 1E2 and 2E type designs have the same front support, SAFRAN Helicopter Engines decided to also apply this new pin design on ARRIEL 2E engines through modification TU197. To address this potential unsafe

condition, SAFRAN Helicopter Engines decided, as precautionary measure, to replace the front support on ARRIEL 2E engines, and published MSB 292 72 2197 to provide instructions for in-service front support replacement. For the reasons described above, this AD requires modification of the affected engines by replacement of each pre-mod TU197 front support.

You may obtain further information by examining the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0838.

**Related Service Information**

We reviewed Safran Helicopter Engines, S.A., Mandatory Service Bulletin (MSB) No. 292 72 2197, Version A, dated September 15, 2016. The MSB describes procedures for replacement of the accessory gearbox front support. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**FAA’s Determination and Requirements of This Proposed AD**

This product has been approved by the aviation authority of France, and is approved for operation in the United States. Pursuant to our bilateral agreement with the European Community, EASA has notified us of the unsafe condition described in the MCAI. We are proposing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design. This proposed AD would require for replacement of the accessory gearbox front support.

**Costs of Compliance**

We estimate that this proposed AD affects 28 engines installed on aircraft of U.S. registry.

We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Front support replacement .....	2 work-hours × \$85 per hour = \$170 .....	\$19,731	\$19,901	\$557,228

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII:

Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701:

General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for

safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to engines, propellers, and associated appliances to the Manager, Engine and Propeller Standards Branch, Policy and Innovation Division.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Safran Helicopter Engines, S.A. (Type Certificate previously held by Turbomeca, S.A.):** Docket No. FAA–2017–0838; Product Identifier 2017–NE–33–AD.

### (a) Comments Due Date

We must receive comments by December 18, 2017.

### (b) Affected ADs

None.

### (c) Applicability

This AD applies to all Safran Helicopter Engines S.A. Arriel 2E turboshaft engines with front support, part number 0 292 11 715 0, installed (pre-mod TU 197 configuration).

### (d) Subject

Joint Aircraft System Component (JASC) Code 8300, Accessory Gearboxes.

### (e) Reason

This AD was prompted by reports of ruptured front support pins on the accessory gearbox front support. We are issuing this AD to prevent failure of a front support, loss of engine thrust control and reduced control of the helicopter.

### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

### (g) Required Actions

Before the accessory gearbox and transmission shaft module (Module 01) accumulates 1,600 engine operating hours since new, or within 80 engine operating hours after the effective date of this AD, whichever occurs later, replace the front support with a part eligible for installation.

### (h) Definition

For the purpose of this AD, a part eligible for installation is a Module 01 with a pre-mod TU 197 front support, that has not accumulated more than 1,680 engine operating hours since new; or a Module 01 with a post-mod TU 197 front support.

### (i) Installation Prohibition

As of the effective date of this AD, you may not install a pre-mod TU 197 front support on any engine with a post-mod TU 197 front support installed.

### (j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, FAA, ECO Branch, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ECO Branch, send it to the attention of the person identified in paragraph (k)(1) of this AD. You may email your request to: [ANE-AD-AMOC@faa.gov](mailto:ANE-AD-AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

### (k) Related Information

(1) For more information about this AD, contact Robert Green, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781–238–7754; fax: 781–238–7199; email: [robert.green@faa.gov](mailto:robert.green@faa.gov).

(2) Refer to MCAI EASA AD 2016–0235, dated November 24, 2016, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA–2017–0838.

Issued in Burlington, Massachusetts, on October 24, 2017.

**Robert J. Ganley,**

*Manager, Engine and Propeller Standards Branch, Aircraft Certification Service.*

[FR Doc. 2017–23606 Filed 11–2–17; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2017–0906; Product Identifier 2017–NM–039–AD]

RIN 2120–AA64

### Airworthiness Directives; Fokker Services B.V. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to supersede Airworthiness Directive (AD) 2005–12–16, for all Fokker Services B.V. Model F28 Mark 0100 airplanes. AD 2005–12–16 requires an inspection to determine the part number of the passenger service unit (PSU) panels for the PSU modification status, and corrective actions if applicable. Since we issued AD 2005–12–16, we have determined that the required modification actions might not have been implemented correctly. This proposed AD would require an inspection of the PSU panels and the PSU panel/airplane interface connectors for discrepancies, and corrective actions if necessary. This proposed AD would also remove airplanes from the applicability. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by December 18, 2017.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods: