

Instructions of Airbus Service Bulletin A350-27-P021, dated February 13, 2018. If any fault message appears after accomplishment of the SPPU calibration test, before further flight, apply the corresponding airplane fault isolation and continue with the SPPU calibration test. Repeat the SPPU calibration test thereafter at intervals not to exceed 200 flight cycles.

#### (h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (i)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2018-0058, dated March 14, 2018, for related information. You may examine the MCAI on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0269.

(2) For more information about this AD, contact Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218.

#### (j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A350-27-P021, dated February 13, 2018.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email

*continued-airworthiness.a350@airbus.com*; internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on March 27, 2018.

**Chris Spangenberg,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018-06946 Filed 4-6-18; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2016-9559; Airspace Docket No. 16-ACE-11]

RIN 2120-AA66

#### Amendment of Class D and E Airspace for the Following Missouri Towns; Cape Girardeau, MO; St. Louis, MO; and Macon, MO

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule, correction.

**SUMMARY:** This action corrects the final rule published in the **Federal Register** on February 9, 2018, modifying Class D airspace at Spirit of St. Louis Airport, St. Louis, MO; Class E airspace designated as a surface area at Cape Girardeau Regional Airport, Cape Girardeau, MO, and Spirit of St. Louis Airport; Class E airspace designated as an extension at Cape Girardeau Regional Airport; and Class E airspace extending upward from 700 feet above the surface at Cape Girardeau Regional Airport, Spirit of St. Louis Airport, and Macon-Fower Memorial Airport, Macon, MO. A typographical error was made in the geographic coordinates for the St. Louis Lambert International Runway 30L Localizer listed in the legal description of the Class E airspace extending upward from 700 feet above the surface for St. Louis, MO.

**DATES:** Effective date 0901 UTC, May 24, 2018.

**FOR FURTHER INFORMATION CONTACT:** Jeffrey Claypool, Federal Aviation Administration, Operations Support

Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5711.

#### SUPPLEMENTARY INFORMATION:

##### History

The FAA published a final rule in the **Federal Register** (83 FR 5707; February 9, 2018) for Docket No. FAA-2016-9559 modifying Class D airspace at Spirit of St. Louis Airport, St. Louis, MO; Class E airspace designated as a surface area at Cape Girardeau Regional Airport, Cape Girardeau, MO, and Spirit of St. Louis Airport; Class E airspace designated as an extension at Cape Girardeau Regional Airport; and Class E airspace extending upward from 700 feet above the surface at Cape Girardeau Regional Airport, Spirit of St. Louis Airport, and Macon-Fower Memorial Airport, Macon, MO. A typographical error was made in the geographic coordinates for the St. Louis Lambert International Runway 30L Localizer listed in the legal description of Class E airspace extending upward from 700 feet above the surface for St. Louis, MO. This action corrects this error.

##### Correction to Final Rule

Accordingly, pursuant to the authority delegated to me, in the **Federal Register** of February 9, 2018 (83 FR 5707) FR Doc. 2018-02139, Amendment of Class D and E Airspace for the Following Missouri Towns; Cape Girardeau, MO; St. Louis, MO; and Macon, MO, is corrected as follows:

##### § 71.1 [Amended]

##### ACE MO E5 St. Louis, MO [Corrected]

On page 5710, column 2, line 38, remove (lat. 38°45'44" N, long. 90°22'56" W) and add in its place (lat. 38°45'19" N, long. 90°22'56" W).

Issued in Fort Worth, Texas, on April 2, 2018.

**Christopher L. Southerland,**

*Acting Manager, Operations Support Group, ATO Central Service Center.*

[FR Doc. 2018-07100 Filed 4-6-18; 8:45 am]

**BILLING CODE 4910-13-P**