

# Rules and Regulations

Federal Register

Vol. 83, No. 94

Tuesday, May 15, 2018

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2018-0372; Product Identifier 2018-CE-011-AD; Amendment 39-19279; AD 2018-10-04]

RIN 2120-AA64

#### Airworthiness Directives; Pacific Aerospace Limited Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule; request for comments

**SUMMARY:** We are superseding Airworthiness Directive (AD) 2018-03-15 for Pacific Aerospace Limited Model 750XL airplanes. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as reports of finding abrasion damage behind the instrument panel caused by ventilation hose chafing. We are issuing this AD to require actions to address the unsafe condition on these products.

**DATES:** This AD is effective June 4, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of June 4, 2018.

We must receive comments on this AD by June 29, 2018.

**ADDRESSES:** You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0372; or in person at Docket Operations, U.S. Department of Transportation, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

For service information identified in this AD, contact Pacific Aerospace Limited, Airport Road, Hamilton,

Private Bag 3027, Hamilton 3240, New Zealand; phone: +64 7843 6144; fax: +64 843 6134; email: [pacific@aerospace.co.nz](mailto:pacific@aerospace.co.nz); internet: [www.aerospace.co.nz](http://www.aerospace.co.nz). You may view this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0372.

**FOR FURTHER INFORMATION CONTACT:** Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Standards Branch, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: [mike.kiesov@faa.gov](mailto:mike.kiesov@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Discussion

We issued AD 2018-03-15, Amendment 39-19188 (83 FR 6110; February 13, 2018) (“AD 2018-03-15”). That AD required actions intended to address an unsafe condition on Pacific Aerospace Limited Model 750XL airplanes and was based on mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country.

Since we issued AD 2018-03-15, it has been found that an optional SCAT hose configuration may be found fitted to certain airplanes, and instructions have been clarified on the installation of the self-adhesive mounts and the tape used on the SCAT hose.

The Civil Aviation Authority (CAA), which is the aviation authority for New Zealand, has issued CAA AD DCA/750XL/22A, dated February 28, 2018 (referred to after this as “the MCAI”), to correct an unsafe condition for Pacific Aerospace Limited Model 750XL airplanes. The MCAI states:

This AD is prompted by two reports of finding abrasion damage behind the instrument panel caused by ventilation hose chafing. This [CAA] AD supersedes DCA/750XL/22 to introduce Pacific Aerospace Limited Mandatory Service Bulletin (MSB) PACSB/XL/083 issue 2, dated 16 January 2018. There are no changes to the AD applicability. The PAL MSB revised to include an optional scat hose configuration which may be found fitted to certain aircraft, to clarify that the self-adhesive mounts should be attached directly to the metallic

surface, and recommend that 25mm wide 3M Scotch 27 glass cloth tape is used to wrap the scat hose.

You may examine the MCAI on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0372.

#### Related Service Information Under 1 CFR Part 51

Pacific Aerospace Limited has issued Pacific Aerospace Mandatory Service Bulletin PACSB/XL/083, Issue 2, dated January 16, 2018. The service information describes procedures for inspecting the ventilation SCAT hose behind the instrument panel, wrapping the ventilation hose with anti-abrasion tape, and rerouting the hose. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section of the AD.

#### FAA's Determination and Requirements of the AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all information provided by the State of Design Authority and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because chafing of the ventilation hose on instrument components and wiring could cause abrasion damage and lead to a short circuit, smoke, and/or inflight fire. Therefore, we determined that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in fewer than 30 days.

## Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2018–0372; Directorate Identifier 2018–CE–011–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

## Costs of Compliance

We estimate that this AD will affect 22 products of U.S. registry. We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour.

Based on these figures, we estimate the cost of the AD on U.S. operators to be \$1,870, or \$85 per product.

In addition, we estimate that any necessary follow-on actions would take about 2 work-hours with parts costing \$90, for a cost of \$260 per product. The extent of abrasion damage could vary from airplane to airplane. We have no way of knowing how many airplanes may have abrasion damage or the extent of that damage to determine the cost of any necessary repair/replacement.

## Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority

because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to small airplanes, gliders, balloons, airships, domestic business jet transport airplanes, and associated appliances to the Director of the Policy and Innovation Division.

## Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2018–03–15, Amendment 39–19188 (83 FR 6110; February 13, 2018) and adding the following new AD:

**2018–10–04 Pacific Aerospace Limited:**  
Amendment 39–19279; Docket No. FAA–2018–0372; Product Identifier 2018–CE–011–AD.

### (a) Effective Date

This AD becomes effective June 4, 2018.

### (b) Affected ADs

This AD replaces AD 2018–03–15, Amendment 39–19188 (83 FR 6110; February 13, 2018) (“AD 2018–03–15”).

### (c) Applicability

This AD applies to Pacific Aerospace Limited Model 750XL airplanes, all serial numbers up to and including serial number 220, certificated in any category.

### (d) Subject

Air Transport Association of America (ATA) Code 31: Instruments.

### (e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as reports of finding abrasion damage behind the instrument panel caused by ventilation hose chafing. We are issuing this AD to prevent such abrasion damage, which could cause short circuit of electrical equipment, smoke and/or inflight fire.

### (f) Actions and Compliance

Unless already done, do the actions in paragraphs (f)(1) through (3) of this AD.

(1) Within 15 days after June 4, 2018 (the effective date of this AD), inspect behind the left, center, and right instrument panels for chafing or damage following Part A of the Accomplishment Instructions in Pacific Aerospace Mandatory Service Bulletin PACSB/XL/083, Issue 2, dated January 16, 2018.

(2) If any chafing or damage is found during the inspection required in paragraph (f)(1) of this AD, before further flight, contact Pacific Aerospace Limited for FAA-approved repair instructions and incorporate those instructions. Use the contact information found in paragraph (i)(3) of this AD to contact the manufacturer.

(3) If no damage is found during the inspection required in paragraph (f)(1) of this AD, within 45 days after June 4, 2018 (the effective date of this AD), do the actions in Part B of the Accomplishment Instructions in Pacific Aerospace Mandatory Service Bulletin PACSB/XL/083, Issue 2, dated January 16, 2018.

### (g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Small Airplane Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Standards Branch, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone:

(816) 329-4144; fax: (816) 329-4090; email: [mike.kiesov@faa.gov](mailto:mike.kiesov@faa.gov). Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, Standards Office, FAA; or the Civil Aviation Authority of New Zealand (CAA).

#### (h) Related Information

Refer to the MCAI by the CAA, AD DCA/750XL/22A, dated February 28, 2018; and for related information. You may examine the MCAI on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0372.

#### (i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Pacific Aerospace Mandatory Service Bulletin PACSB/XL/083, Issue 2, dated January 16, 2018.

(ii) Reserved.

(3) For service information identified in this AD, contact Pacific Aerospace Limited, Airport Road, Hamilton, Private Bag 3027, Hamilton 3240, New Zealand; phone: +64 7843 6144; fax: +64 843 6134; email: [pacific@aerospace.co.nz](mailto:pacific@aerospace.co.nz); internet: [www.aerospace.co.nz](http://www.aerospace.co.nz).

(4) You may view this service information at the FAA, Policy and Innovation Division, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the internet at <http://www.regulations.gov> by searching for locating Docket No. FAA-2018-0372.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on May 4, 2018.

**Melvin J. Johnson,**

*Deputy Director, Policy & Innovation Division, Aircraft Certification Service.*

[FR Doc. 2018-10025 Filed 5-14-18; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2016-9523; Product Identifier 2016-NM-134-AD; Amendment 39-19270; AD 2018-09-13]

RIN 2120-AA64

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for all The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. This AD was prompted by reports indicating additional cracking in the inspar upper skin at wing buttock line (WBL) 157 and in the skin at two holes common to the rear spar in the same area, and rear spar web cracks were also noted on both wings. Subsequent inspections revealed that the right rear spar upper chord was almost completely severed and the left rear spar upper chord was completely severed. Additional reports identified cracking in the main landing gear (MLG) beam forward support fitting. This AD requires the installation of standard-size fasteners for a certain configuration and inspections for any crack in certain locations of the rear spar. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective June 19, 2018.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of June 19, 2018.

**ADDRESSES:** For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9523.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov>

by searching for and locating Docket No. FAA-2016-9523; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is Docket Operations, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### FOR FURTHER INFORMATION CONTACT:

Payman Soltani, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5313; fax: 562-627-5210; email: [payman.soltani@faa.gov](mailto:payman.soltani@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. The NPRM published in the **Federal Register** on January 5, 2017 (82 FR 1254). The NPRM was prompted by reports of cracking in locations outside the inspection area identified in AD 2014-12-13, Amendment 39-17874 (79 FR 39300, July 10, 2014) (“AD 2014-12-13”), in the inspar upper skin at WBL 157 and in the skin at two holes common to the rear spar in the same area, and in the rear spar web on both wings. Subsequent inspections revealed that the right rear spar upper chord was almost completely severed and the left rear spar upper chord was completely severed. Operators also reported cracking in the MLG beam forward support fitting.

We subsequently issued a supplemental notice of proposed rulemaking (SNPRM) which was published in the **Federal Register** on August 11, 2017 (83 FR 37549) (“the first SNPRM”). The first SNPRM proposed to require expanding the inspection area, add applicable related investigative and corrective actions, and to terminate (rather than supersede) the requirements of AD 2014-12-13 after accomplishment of the initial inspections.

We issued a second SNPRM which was published in the **Federal Register** on January 17, 2018 (83 FR 2378) (“the 2018 SNPRM”). The 2018 SNPRM proposed to require the installation of standard-size fasteners for a certain