

parent-only *pro forma* balance sheet as of the most recent quarter; or

(B) If the bank holding company has consolidated assets of less than \$3 billion, a *pro forma* parent-only balance sheet as of the most recent quarter, and, if the redemption is to be debt funded, one-year income statement and cash flow projections.

* * * * *

■ 6. In § 225.14, revise paragraph (a)(1)(v) to read as follows:

§ 225.14 Expedited action for certain bank acquisitions by well-run bank holding companies.

(a) * * *

(1) * * *

(v)(A) If the bank holding company has consolidated assets of \$3 billion or more, an abbreviated consolidated *pro forma* balance sheet as of the most recent quarter showing credit and debit adjustments that reflect the proposed transaction, consolidated *pro forma* risk-based capital ratios for the acquiring bank holding company as of the most recent quarter, and a description of the purchase price and the terms and sources of funding for the transaction; or

(B) If the bank holding company has consolidated assets of less than \$3 billion, a *pro forma* parent-only balance sheet as of the most recent quarter showing credit and debit adjustments that reflect the proposed transaction, and a description of the purchase price, the terms and sources of funding for the transaction, and the sources and schedule for retiring any debt incurred in the transaction;

* * * * *

■ 7. In § 225.17(a)(6), revise footnote 6 to read as follows:

§ 225.17 Notice procedure for one-bank holding company formations.

(a) * * *

(6) * * *

⁶ For a banking organization with consolidated assets, on a *pro forma* basis, of less than \$3 billion (other than a banking organization that will control a *de novo* bank), this requirement is satisfied if the proposal complies with the Board’s Small Bank Holding Company and Savings and Loan Holding Company Policy Statement (appendix C of this part).

* * * * *

■ 8. In § 225.23, revise paragraph (a)(1)(iii) to read as follows:

§ 225.23 Expedited action for certain nonbanking proposals by well-run bank holding companies.

(a) * * *

(1) * * *

(iii) If the proposal involves an acquisition of a going concern:

(A) If the bank holding company has consolidated assets of \$3 billion or more, an abbreviated consolidated *pro forma* balance sheet for the acquiring bank holding company as of the most recent quarter showing credit and debit adjustments that reflect the proposed transaction, consolidated *pro forma* risk-based capital ratios for the acquiring bank holding company as of the most recent quarter, a description of the purchase price and the terms and sources of funding for the transaction, and the total revenue and net income of the company to be acquired;

(B) If the bank holding company has consolidated assets of less than \$3 billion, a *pro forma* parent-only balance sheet as of the most recent quarter showing credit and debit adjustments that reflect the proposed transaction, a description of the purchase price and the terms and sources of funding for the transaction and the sources and schedule for retiring any debt incurred in the transaction, and the total assets, off-balance sheet items, revenue and net income of the company to be acquired; or

(C) For each insured depository institution whose Tier 1 capital, total capital, total assets or risk-weighted assets change as a result of the transaction, the total risk-weighted assets, total assets, Tier 1 capital and total capital of the institution on a *pro forma* basis;

* * * * *

■ 9. In appendix C, under the header “1. *Applicability of Policy Statement*,” revise the first undesignated paragraph to read as follows:

Appendix C to Part 225—Small Bank Holding Company and Savings and Loan Holding Company Policy Statement

* * * * *

1. Applicability of Policy Statement

This policy statement applies only to bank holding companies with *pro forma* consolidated assets of less than \$3 billion that (i) are not engaged in significant nonbanking activities either directly or through a nonbank subsidiary; (ii) do not conduct significant off-balance sheet activities (including securitization and asset management or administration) either directly or through a nonbank subsidiary; and (iii) do not have a material amount of debt or equity securities outstanding (other than trust preferred securities) that are registered with the Securities and Exchange Commission. The Board may in its discretion exclude any bank holding company, regardless of asset size, from the policy statement if such action is warranted for

supervisory purposes.¹ With the exception of section 4 (Additional Application Requirements for Expedited/Waived Processing), the policy statement applies to savings and loan holding companies as if they were bank holding companies.

* * * * *

By order of the Board of Governors of the Federal Reserve System, April 24, 2018.

Ann Misback,
Secretary of the Board.

Editorial note: This document was received for publication by the Office of the Federal Register on August 24, 2018. [FR Doc. 2018–18756 Filed 8–29–18; 8:45 am]

BILLING CODE 6210–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2018–0272; Product Identifier 2018–NM–005–AD; Amendment 39–19377; AD 2018–17–23]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all The Boeing Company Model 737–100, –200, –200C, –300, –400, and –500 series airplanes. This AD was prompted by a report indicating that during a fleet survey on a retired Model 737 airplane, cracking was found common to the number 3 windshield assembly, aft sill web. This AD requires, at certain locations, repetitive high frequency eddy current (HFEC) inspections of the number 3 windshield assembly, aft sill web; and applicable on-condition actions. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective October 4, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 4, 2018.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>. You

¹ [RESERVED].

may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0272.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0272; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is Docket Operations, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

David Truong, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5224; fax: 562-627-5210; email: david.truong@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. The NPRM published in the **Federal Register** on April 16, 2018 (83 FR 16243). The NPRM was prompted by a report indicating that during a fleet survey on a retired Model 737 airplane, cracking was found common to the number 3 windshield assembly, aft sill web. The NPRM proposed to require, at certain locations, repetitive HFEC inspections of the number 3 windshield assembly, aft sill web; and applicable on-condition actions.

We are issuing this AD to address such cracking common to the number 3 windshield assembly, aft sill web, which could adversely affect the structural integrity of the windshield assembly.

Comments

We gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA's response to each comment.

Effect of Winglets on Accomplishment of the Proposed Actions

Aviation Partners Boeing stated that accomplishing the Supplemental Type Certificate (STC) ST01219SE does not affect the actions specified in the NPRM.

We agree with the commenter. We have redesignated paragraph (c) of the proposed AD as paragraph (c)(1) of this AD and added paragraph (c)(2) to this AD to state that installation of STC ST01219SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

Request To Clarify Inspection Location

Boeing requested that the language in the "Related Service Information under 1 CFR part 51" paragraph be clarified in the proposed AD. Boeing requested that we replace "repetitive HFEC inspections of the number 3 windshield and of the aft sill web" with "repetitive HFEC inspections of the number 3 windshield aft sill web." Boeing stated that there is no requirement in Boeing Alert Requirements Bulletin 737-53A1377 RB, dated December 11, 2017, to inspect the windshield with an HFEC inspection. Boeing commented that the only HFEC requirement in Boeing Alert Requirements Bulletin 737-53A1377 RB, dated December 11, 2017, is to accomplish the HFEC inspections of the number 3 windshield aft sill web.

We agree with the request to clarify the inspection location, for the reasons provided. We have revised the "Summary and Related Service Information under 1 CFR part 51" section, as well as the **SUMMARY**, of this final rule accordingly. For consistency within this AD and in response to the following Boeing comment, this AD specifies the "number 3 windshield assembly, aft sill web."

Request To Clarify Location of Cracking

Boeing requested that we clarify the unsafe condition in paragraph (e) of the NPRM. Boeing requested that we replace the language "common to the windshield and aft sill web" with "common to the number 3 windshield assembly, aft sill web." Boeing stated that the cracking in the aft sill web is at the fastener common to the aft sill web and the outer chord of the number 3 windshield assembly and is not actually common to the windshield.

We agree with the request, for the reasons provided. We have revised

paragraph (e) of this AD, as well as the **SUMMARY** and the Discussion section of this final rule, accordingly.

Request To Clarify Certain Language in the "Exceptions to Service Information Specifications" Paragraph

Boeing requested that we revise paragraph (i)(2) of the "Exceptions to Service Information Specifications" paragraph in the proposed AD. Boeing requested that we replace the language "specifies contacting Boeing" with "specifies contacting Boeing for repair instructions." Boeing commented that this addition adds clarity.

We agree with the request and have revised this AD to clarify the requirements accordingly.

Explanation of Change to Applicability Description

The applicability of the proposed AD referred to affected airplanes identified in Boeing Alert Requirements Bulletin 737-53A1377 RB, dated December 11, 2017. The effectivity in the service information is identified in terms of line numbers. Since those line numbers include all airplanes of the affected models, we have revised the applicability in this AD as all Model 737-100, -200, -200C, -300, -400, and -500 series airplanes.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule with the changes described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

Related Service Information Under 1 CFR Part 51

We reviewed Boeing Alert Requirements Bulletin 737-53A1377 RB, dated December 11, 2017. The service information describes procedures for repetitive HFEC inspections of the number 3 windshield assembly, aft sill web at station 254.6, between stringers S-9 and S-11 on the left- and right-hand sides; and applicable on-condition actions. This service information is reasonably available because the interested parties

have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 63 airplanes of U.S. registry. We estimate

the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
HFEC inspection	4 work-hours × \$85 per hour = \$340 per inspection cycle.	\$0	\$340 per inspection cycle	\$21,420 per inspection cycle.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2018-17-23 The Boeing Company:

Amendment 39-19377; Docket No. FAA-2018-0272; Product Identifier 2018-NM-005-AD.

(a) Effective Date

This AD is effective October 4, 2018.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to all The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by a report indicating that during a fleet survey on a retired Model 737 airplane, cracking was found common to the number 3 windshield assembly, aft sill web. We are issuing this AD to address such cracking at this location, which could adversely affect the structural integrity of the windshield assembly.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions for Group 1 Airplanes

For airplanes identified as Group 1 in Boeing Alert Requirements Bulletin 737-53A1377 RB, dated December 11, 2017: Within 120 days after the effective date of this AD, do an inspection to correct the unsafe condition, using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(h) Required Actions for Group 2 Airplanes

For airplanes identified as Group 2 in Boeing Alert Requirements Bulletin 737-53A1377 RB, dated December 11, 2017: Except as required by paragraph (i) of this AD, at the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 737-53A1377 RB, dated December 11, 2017, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737-53A1377 RB, dated December 11, 2017.

Note 1 to paragraph (h) of this AD:

Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737-53A1377, dated December 11, 2017, which is referred to in Boeing Alert Requirements Bulletin 737-53A1377 RB, dated December 11, 2017.

(i) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Requirements Bulletin 737-53A1377 RB, dated December 11, 2017, uses the phrase "the original issue date of Requirements Bulletin 737-53A1377 RB," this AD requires using "the effective date of this AD."

(2) Where Boeing Alert Requirements Bulletin 737-53A1377 RB, dated December 11, 2017, specifies contacting Boeing for

repair instructions, this AD requires repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

For more information about this AD, contact David Truong, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5224; fax: 562-627-5210; email: david.truong@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 737-53A1377 RB, dated December 11, 2017.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued in Des Moines, Washington, on August 17, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-18658 Filed 8-29-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0411; Product Identifier 2017-NM-157-AD; Amendment 39-19376; AD 2018-17-22]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Airbus SAS Model A319-115 and -132 airplanes, and Model A320-214, -216, -232, and -233 airplanes. This AD was prompted by a report indicating that certain modified airplanes do not have electrical ground wires on the fuel level sensing control unit (FLSCU), which adversely affects the fuel gravity feeding operation. This AD requires modification of the FLSCU wiring. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective October 4, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 4, 2018.

ADDRESSES: For service information identified in this final rule, contact Airbus SAS, Airworthiness Office—EIAS, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; phone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: account.airworth-eas@airbus.com; internet: <http://www.airbus.com>. You may view this service information at the FAA,

Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0411.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0411; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3223.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus SAS Model A319-115 and -132 airplanes, and Model A320-214, -216, -232, and -233 airplanes. The NPRM published in the **Federal Register** on May 15, 2018 (83 FR 22426). The NPRM was prompted by a report indicating that certain modified airplanes do not have electrical ground wires on the FLSCU, which adversely affects the fuel gravity feeding operation. The NPRM proposed to require modification of the FLSCU wiring.

We are issuing this AD to address reduced fuel pressure at the engine inlet, potentially resulting in an uncommanded in-flight shutdown when flying at the fuel gravity feed ceiling levels.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2017-0216, dated October 30, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus SAS Model A319-115 and -132 airplanes, and Model A320-214, -216, -232, and -233 airplanes. The MCAI states:

Airbus introduced mod 154327 on A319 and A320 aeroplanes which substituted the pump fuel feed system from the centre fuel tank with a jet pump transfer system, based on the Airbus A321 design. Following the modification introduction, it was discovered that the modified aeroplanes do not have electrical ground signals that replicate those from the deleted centre tank pump pressure