

may change the proposed airworthiness standards based on received comments.

Background

On September 26, 2018, the FAA issued a notice of availability; request for comments, entitled “Proposed Primary Category Design Standards; Vertical Aviation Technologies (VAT) Model S-52L Rotorcraft” (83 FR 48574) (“notice of availability”). The notice of availability established a 60-day comment period.

The FAA finds that a 30-day comment period is sufficient for the public to analyze and provide meaningful comment to notice of availability. The date by which to file comments is therefore shortened from November 26, 2018, to October 26, 2018. The FAA does not anticipate any further action to be taken regarding this comment period.

Shortening of Comment Period

Accordingly, the comment period for the notice of availability has been shortened to close on October 26, 2018.

Issued in Ft Worth, Texas, on September 27, 2018.

Jorge Castillo,

Acting Manager, Rotorcraft Standards Branch, Policy and Innovation Division, Aircraft Certification Service.

[FR Doc. 2018-21661 Filed 10-5-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0809; Product Identifier 2018-NM-092-AD]

RIN 2120-AA64

Airworthiness Directives; Dassault Aviation Model FALCON 2000 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Dassault Aviation Model FALCON 2000 airplanes. This proposed AD was prompted by a report of chafing of a wire bundle located at the bottom of the right hand electrical cabinet. This proposed AD would require a one-time general visual inspection of the wiring bundle for damage, measurement of the clearance between the metallic plate and the wiring bundle, and corrective actions if necessary. We are proposing

this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by November 23, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; internet <http://www.dassaultfalcon.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0809; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2018-0809; Product Identifier 2018-NM-092-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory,

economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018-0114, dated May 23, 2018, (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Dassault Aviation Model FALCON 2000 airplanes. The MCAI states:

One Falcon 2000 aeroplane experienced some chafing of a wire bundle located at the bottom of the right-hand (RH) electrical cabinet (between Frames 4 and 5). The wire loom interfered with a metallic (ground) plate of terminal strip 700J and at least 12 wires were damaged. This wire loom includes 250 wires and in case of chafing, any wire may be damaged.

This condition, if not detected and corrected, could lead to improper functioning of aeroplane systems [such as loss of wing anti-icing or wing anti-icing inoperative indication, loss of normal braking indication, and loss of “No take-off” indication], possibly resulting in reduced control of the aeroplane.

To address this potential unsafe condition, Dassault developed a modification M3889 to improve the clearance between the metallic plate and the wire loom, and published the SB [Dassault Aviation Service Bulletin F2000-436] to inspect and modify aeroplanes in service.

For the reasons described above, this [EASA] AD requires a one-time inspection of the wiring bundle for interference or damage, measurement of the clearance between the metallic plate and the wiring bundle, and depending on findings, modification of the aeroplane by cutting out the lower part of the ground plate of terminal strip 700J and adding an edge protection to prevent interference. Aeroplanes that do not have a metallic plate installed are not affected by this [EASA] AD.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0809.

Related Service Information Under 14 CFR Part 51

Dassault Aviation has issued Service Bulletin F2000-436, dated September 28, 2017. This service information

describes procedures for a one-time general visual inspection of the wiring bundle for damage (including chafing), measurement of the clearance between the metallic plate and the wiring bundle, and corrective actions. Corrective actions include modification of the airplane by cutting out the lower part of the ground plate of terminal strip 700J and adding an edge protection to prevent interference and replacement of damaged wires. This service information is reasonably available because the interested parties have access to it through their normal course

of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described

previously is likely to exist or develop on other products of the same type design.

Proposed Requirements of This NPRM

This proposed AD would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

We estimate that this proposed AD affects 195 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
4 work-hours × \$85 per hour = \$340	\$0	\$340	\$66,300

We estimate the following costs to do the necessary on-condition action that would be required based on the results

of any required actions. We have no way of determining the number of aircraft

that might need this on-condition action:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost *	Cost per product
2 work-hours × \$85 per hour = \$170	\$0	\$170

* We have received no definitive data for the parts cost for the on-condition actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance

and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Dassault Aviation: Docket No. FAA–2018–0809; Product Identifier 2018–NM–092–AD.

(a) Comments Due Date

We must receive comments by November 23, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Dassault Aviation Model FALCON 2000, certificated in any category, manufacturer serial numbers 70 through 231 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical power.

(e) Reason

This AD was prompted by a report of chafing of a wire bundle located at the bottom of the right hand (RH) electrical cabinet. We are issuing this AD to address such chafing, which may cause damage to wires within the bundle, and, if not detected and corrected, could lead to improper functioning of airplane systems (such as loss of wing anti-icing or wing anti-icing inoperative indication, loss of normal braking indication, and loss of "No take-off" indication), which could result in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

Within 25 months after the effective date of this AD, for airplanes equipped with a metallic plate at the bottom of the RH electrical cabinet, do the following actions as specified in paragraphs (g)(1) and (g)(2) of this AD.

(1) Perform a general visual inspection of the wiring bundle for damage (including chafing), in accordance with the Accomplishment Instructions of Dassault Aviation Service Bulletin F2000-436, dated September 28, 2017.

(2) Measure the clearance between the metallic plate and the wire bundle at the bottom of the RH electrical cabinet in accordance with the Accomplishment Instructions of Dassault Aviation Service Bulletin F2000-436, dated September 28, 2017.

(h) Corrective Action

(1) If, during the inspection required by paragraph (g)(1) of this AD, any damage is found, before further flight, replace all damaged wires using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(2) If, during the measurement as required by paragraph (g)(2) of this AD, the detected clearance is less than the criteria as specified in Dassault Aviation Service Bulletin F2000-436, dated September 28, 2017, before further flight, modify the metallic plate in accordance with the Accomplishment Instructions of Dassault Aviation Service Bulletin F2000-436, dated September 28, 2017.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Dassault Aviation's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018-0114, dated May 23, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0809.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

(3) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; internet <http://www.dassaultfalcon.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on September 26, 2018.

John P. Piccola,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-21609 Filed 10-5-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2018-0805; Product Identifier 2018-NM-103-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Defense and Space S.A. (Formerly Known as Construcciones Aeronauticas, S.A.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Airbus Defense and Space S.A. Model CN-235, CN-235-200 and CN-235-300 airplanes. This proposed AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This proposed AD would require revising the maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by November 23, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus Defense and Space, Services/Engineering support, Avenida de Aragón 404, 28022 Madrid, Spain; telephone: +34 91 585 55 84; fax: +34 91 585 31 27; email:

MTA.TechnicalService@airbus.com.

You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.