

# Proposed Rules

Federal Register

Vol. 83, No. 223

Monday, November 19, 2018

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2018-0980; Product Identifier 2017-SW-123-AD]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Helicopters Deutschland GmbH Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for Airbus Helicopters Deutschland GmbH (Airbus Helicopters) Model MBB-BK 117 C-2 helicopters. This proposed AD would require establishing or reducing the life limit of various parts. This proposed AD is prompted by recalculations. The actions of this proposed AD are intended to address an unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by January 18, 2019.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.

- *Fax:* 202-493-2251.

- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590-0001.

- *Hand Delivery:* Deliver to the "Mail" address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-

0980; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the European Aviation Safety Agency (EASA) AD, the economic evaluation, any comments received, and other information. The street address for Docket Operations (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

For service information identified in this proposed rule, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at [http://www.helicopters.airbus.com/website/en/ref/Technical-Support\\_73.html](http://www.helicopters.airbus.com/website/en/ref/Technical-Support_73.html). You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

**FOR FURTHER INFORMATION CONTACT:** Matt Fuller, Senior Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email [matthew.fuller@faa.gov](mailto:matthew.fuller@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to participate in this rulemaking by submitting written comments, data, or views. We also invite comments relating to the economic, environmental, energy, or federalism impacts that might result from adopting the proposals in this document. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit only one time.

We will file in the docket all comments that we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, we will consider all comments we receive on or before the closing date for comments. We will consider comments filed after the comment period has closed if it is

possible to do so without incurring expense or delay. We may change this proposal in light of the comments we receive.

#### Discussion

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD No. 2017-0174, dated September 12, 2017 (EASA AD 2017-0174), to correct an unsafe condition for Airbus Helicopters Model MBB-BK 117 C-2 helicopters. EASA advises that recalculation by Airbus Helicopters has resulted in new or reduced life limits for certain parts. EASA AD 2017-0174 states the life limits are mandatory for continued airworthiness and failing to replace life-limited parts as specified could result in an unsafe condition. To address this condition, EASA AD 2017-0174 requires replacing the affected parts before exceeding their new or reduced life limit.

#### FAA's Determination

These helicopters have been approved by the aviation authority of Germany and are approved for operation in the United States. Pursuant to our bilateral agreement with Germany, EASA, its technical representative, has notified us of the unsafe condition described in its AD. We are proposing this AD because we evaluated all known relevant information and determined that an unsafe condition is likely to exist or develop on other products of the same type design.

#### Related Service Information

We reviewed Airbus Helicopters Alert Service Bulletin ASB MBB-BK117 C-2-04A-008, Revision 0, dated April 27, 2017, for Model MBB-BK 117 C-2 and C-2e helicopters. This service information specifies entering into the helicopter records the reduced and new airworthiness life limits for certain part-numbered main rotor head, swash plate, rotor flight controls, cyclic controls, and upper controls parts.

#### Proposed AD Requirements

This proposed AD would require establishing and reducing the life limit of the following parts: Main rotor head—nut, upper and lower quadruple nut, bolts, and inner sleeve; swash plate control ring assembly; rotor flight control collective bellcrank-K; cyclic

control rod tube; and upper control forked lever.

#### Costs of Compliance

We estimate that this proposed AD would affect 128 helicopters of U.S. Registry. We estimate that operators may incur the following costs in order to comply with this AD. Labor costs are estimated at \$85 per work-hour.

Replacing a nut would take about 5 work-hours and parts would cost about \$3,352 for an estimated replacement cost of \$3,777.

Replacing a quadruple nut upper would take about 5 work-hours and parts would cost about \$3,283 for an estimated replacement cost of \$3,708.

Replacing a quadruple nut lower would take about 5 work-hours and parts would cost about \$3,405 for an estimated replacement cost of \$3,830.

Replacing a bolt would take about 2 work-hours and parts would cost about \$370 for an estimated replacement cost of \$540.

Replacing an inner sleeve would take about 2 work-hours and parts would cost about \$20,073 for an estimated replacement cost of \$20,243.

Replacing a control ring assembly would take about 5 work-hours and parts would cost about \$11,141 for an estimated replacement cost of \$11,566.

Replacing a bellcrank-K (collective) would take about 4 work-hours and parts would cost about \$3,400 for an estimated replacement cost of \$3,740.

Replacing a control rod tube would take about 4 work-hours and parts would cost about \$1,084 for an estimated replacement cost of \$1,424.

Replacing a forked lever would take about 3 work-hours and parts would cost about \$6,049 for an estimated replacement cost of \$6,304.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

##### **Airbus Helicopters Deutschland GmbH:**

Docket No. FAA-2018-0980; Product Identifier 2017-SW-123-AD.

##### **(a) Applicability**

This AD applies to Airbus Helicopters Deutschland GmbH Model MBB-BK 117 C-2 helicopters with a part listed in Table 1 to paragraph (e) of this AD installed, certificated in any category.

**Note 1 to paragraph (a) of this AD:** Helicopters with an MBB-BK117 C-2e designation are Model MBB-BK117 C-2 helicopters.

##### **(b) Unsafe Condition**

This AD defines the unsafe condition as a part remaining in service beyond its fatigue life. This condition could result in failure of a part and loss of control of the helicopter.

##### **(c) Comments Due Date**

We must receive comments by January 18, 2019.

##### **(d) Compliance**

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

##### **(e) Required Actions**

Before further flight, remove from service any part that has reached or exceeded its new or reduced life limit as listed in Table 1 to paragraph (e) of this AD. Thereafter, remove from service each part on or before reaching its new or reduced life limit as listed in Table 1 to paragraph (e) of this AD. For purposes of this AD, a "landing" is counted any time the helicopter lifts off into the air and then lands again regardless of the duration of the landing and regardless of whether the engine is shut down.

**BILLING CODE 4910-13-P**

Part Name	Part Number (P/N)	Life Limit
Nut	B622M1003201	65,800 landings or 10,123 hours time-in-service (TIS) if the number of landings is unknown
Quadruple nut upper Quadruple nut lower	B622M1004201 B622M1005201	60,000 landings or 9,230 hours TIS if the number of landings is unknown
Bolt	B622M1006201 B622M1007201	31,200 landings or 4,800 hours TIS if the number of landings is unknown
Inner sleeve	B622M1009201	13,300 hours TIS
Control ring assembly	B623M2001101	27,600 hours TIS
Bellcrank-K (collective) (4)	B670M7021201	21,500 hours TIS
Control rod tube	B291M1015201	30,000 hours TIS
Forked lever	B671M7007201 B671M7007205	22,500 Hours TIS

Table 1 to Paragraph (e)

**BILLING CODE 4910-13-C****(f) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Safety Management Section, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email [9-ASW-FTW-AMOC-Requests@faa.gov](mailto:9-ASW-FTW-AMOC-Requests@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before

operating any aircraft complying with this AD through an AMOC.

**(g) Additional Information**

(1) Airbus Helicopters Alert Service Bulletin ASB MBB-BK117 C-2-04A-008, Revision 0, dated April 27, 2017, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at [http://www.helicopters.airbus.com/website/en/ref/Technical-Support\\_73.html](http://www.helicopters.airbus.com/website/en/ref/Technical-Support_73.html). You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2017-0174, dated September 12, 2017. You may view the EASA AD on the internet at <http://www.regulations.gov> in the AD Docket.

**(h) Subject**

Joint Aircraft Service Component (JASC) Code: 6220, Main Rotor Head; 6230 Main Rotor Mast/Swashplate; and 6710, Main Rotor Control.

Issued in Fort Worth, Texas, on November 6, 2018.

**James A. Grigg,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2018-24995 Filed 11-16-18; 8:45 am]

**BILLING CODE 4910-13-P**