

union for a reporting period in the calendar year. For purposes of calculating the financial institution's average amount of insured shares, the financial institution shall be treated as having no insured shares for reporting periods following the date of termination of federal share insurance coverage. For purposes of this subparagraph, a financial institution that terminates federal share insurance coverage from the NCUSIF through liquidation will be treated as terminating federal share insurance coverage during the calendar year when it enters liquidation.

(D) *Mergers between federally insured credit unions.* A continuing federally insured credit union that merges with a federally insured credit union shall receive an equity distribution equivalent to what the continuing federally insured credit union and the merging federally insured credit union would have received separately but for the consummation of the merger provided that the merging federally insured credit union has filed at least one quarterly Call Report as a federally insured credit union for a reporting period in the calendar year for which the Board declares the distribution. For purposes of calculating the continuing federally insured credit union's average amount of insured shares, any insured shares previously reported by the merging federally insured credit union on its quarterly Call Reports filed prior to the consummation of the merger during that calendar year for which the Board declares the distribution shall be combined with the insured shares reported on the continuing federally insured credit union's quarterly Call Reports.

(E) *Purchase and assumption transactions.* A federally insured credit union that acquires all of the insured shares of another federally insured credit union in the calendar year for which the Board declares an NCUSIF equity distribution shall receive an amount equivalent to what the acquiring federally insured credit union and the selling federally insured credit union would have received but for the consummation of the purchase and assumption transaction provided that the selling federally insured credit union has filed at least one quarterly Call Report as a federally insured credit union for a reporting period in the calendar year for which the Board declares an NCUSIF equity distribution. For purposes of calculating the acquiring federally insured credit union's average amount of insured shares, any insured shares previously reported during that calendar year for

which the Board declares an NCUSIF equity distribution by the selling federally insured credit union on its quarterly Call Reports filed prior to the consummation of the purchase and assumption transaction shall be combined with the insured shares reported on the acquiring federally insured credit union's quarterly Call Reports.

(c) *Expiration.* This section shall expire and no longer be applicable after December 31, 2022.

Appendix A to Part 71 [Removed]

- 4. Remove Appendix A to part 741.

Appendices B and C to Part 71 [Redesignated as Appendices A and B to Part 71]

- 5. Redesignate appendix B and appendix C as appendix A and appendix B, respectively.

[FR Doc. 2018-03622 Filed 2-22-18; 8:45 am]

BILLING CODE 7535-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0774; Product Identifier 2017-NM-036-AD; Amendment 39-19201; AD 2018-04-06]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are superseding Airworthiness Directive (AD) 2012-12-05, which applied to all The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. AD 2012-12-05 required repetitive inspections for cracking under the stop fittings and intercostal flanges and for cracking of the intercostal web, attachment clips, stringer splice channels, frame, reinforcement angle, shear web, frame outer chord and inner chord; a one-time inspection to detect missing fasteners; repetitive inspections of the cargo barrier net fitting for cracking; repetitive inspections for cracking of the stringer S-15L aft intercostal; and repair or corrective action if necessary. For certain airplanes, this AD adds new repetitive inspections of certain areas of the frame inner chord, and applicable on-condition actions. This AD was prompted by reports of additional

cracking in locations not covered by the inspections in AD 2012-12-05. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 30, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 30, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of July 23, 2012 (77 FR 36139, June 18, 2012).

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of September 9, 2009 (74 FR 38901, August 5, 2009).

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740; telephone: 562-797-1717; internet: <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0774.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0774; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Galib Abumeri, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5324; fax: 562-627-5210; email: galib.abumeri@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2012–12–05, Amendment 39–17084 (77 FR 36139, June 18, 2012) (“AD 2012–12–05”). AD 2012–12–05 applied to all The Boeing Company Model 737–100, –200, –200C, –300, –400, and –500 series airplanes. The NPRM published in the **Federal Register** on August 15, 2017 (82 FR 38637). The NPRM was prompted by reports of additional cracking in locations not covered by the inspections in AD 2012–12–05. The NPRM proposed to continue to require repetitive inspections for cracking under the stop fittings and intercostal flanges and for cracking of the intercostal web, attachment clips, stringer splice channels, frame, reinforcement angle, shear web, frame outer chord and inner chord; a one-time inspection to detect missing fasteners; repetitive inspections of the cargo barrier net fitting for cracking; repetitive inspections for cracking of the stringer S–15L aft intercostal; and repair or corrective action if necessary. For certain airplanes, the NPRM also proposed to add new repetitive inspections of certain areas of the frame inner chord, and applicable on-condition actions. We are issuing this AD to detect and correct fatigue cracking of the intercostals on the forward and aft sides of the forward entry door cutout, which could result in loss of the forward entry door and rapid decompression of the airplane.

Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM and the FAA’s response to each comment.

Support for the NPRM

The Boeing Company supported the NPRM.

Effect of Winglets on Accomplishing the Proposed Actions

Aviation Partners Boeing stated that accomplishing the Supplemental Type Certificate (STC) ST01219SE does not affect the actions specified in the NPRM.

We agree with the commenter. We have redesignated paragraph (c) of the proposed AD as paragraph (c)(1) of this AD and added paragraph (c)(2) to this AD to state that installation of STC ST01219SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

Request To Add AMOC Language

Southwest Airlines (SWA) asked that a note be added to paragraph (s) of the proposed AD to provide provisions for AMOCs previously approved for AD 2012–12–05. SWA stated that the language in paragraph (s) of the proposed AD does not account for AMOCs previously approved for AD 2012–12–05.

We agree with the commenter’s request. We have added paragraphs (s)(5) and (s)(6) to this AD to include approval of AMOCs previously approved for AD 2012–12–05.

Change to Final Rule

We have revised paragraph (r) of this AD to provide credit for the actions specified in paragraphs (i), (j), and (m) of this AD, if those actions were performed before September 9, 2009

(the effective date of AD 2009–16–14, Amendment 39–15987 (74 FR 38901, August 5, 2009)), using Boeing Special Attention Service Bulletin 737–53–1204, dated June 19, 2003.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this AD with the changes described previously, and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

Related Service Information Under 1 CFR Part 51

We reviewed Boeing Alert Service Bulletin 737–53A1240, Revision 2, dated November 2, 2016. The service information describes procedures for, among other actions, repetitive inspections of the fastener holes in the station (STA) 351.2 frame inner chord at stringer S–17L, and applicable on-condition actions. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 411 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspections for cracking under the stop fittings and intercostal flanges [retained actions from AD 2012–12–05] (411 airplanes).	18 work-hours × \$85 per hour = \$1,530 per inspection cycle.	\$0	\$1,530 per inspection cycle.	\$628,830 per inspection cycle.
Inspection of areas forward of the aft entry door [retained actions from AD 2012–12–05] (411 airplanes).	2 work-hours × \$85 per hour = \$170 per inspection cycle.	0	\$170 per inspection cycle.	\$69,870 per inspection cycle.
Inspection of areas aft of the forward entry door [retained actions from AD 2012–12–05] (411 airplanes).	1 work-hour × \$85 per hour = \$85 per inspection cycle.	0	\$85 per inspection cycle.	\$34,935 per inspection cycle.
Inspection for missing fasteners [retained actions from AD 2012–12–05] (411 airplanes).	1 work-hour × \$85 per hour = \$85	476	\$561	\$230,571.
Inspection of fastener holes (new action) (160 airplanes).	27 work-hours × \$85 per hour = \$2,295 per inspection cycle.	0	\$2,295 per inspection cycle.	\$367,200 per inspection cycle.

We estimate the following costs to do any necessary repairs that are required

based on the results of the inspections. We have no way of determining the

number of aircraft that might need these repairs:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Repair of cracking done in accordance with Boeing Alert Service Bulletin 737-53A1240.	24 work-hours × \$85 per hour = \$2,040	\$11,856	\$13,896

We have received no definitive data that enables us to provide cost estimates for the other on-condition corrective actions specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2012-12-05, Amendment 39-17084 (77 FR 36139, June 18, 2012), and adding the following new AD:

2018-04-06 The Boeing Company:
Amendment 39-19201; Docket No. FAA-2017-0774; Product Identifier 2017-NM-036-AD.

(a) Effective Date

This AD is effective March 30, 2018.

(b) Affected ADs

This AD replaces AD 2012-12-05, Amendment 39-17084 (77 FR 36139, June 18, 2012) ("AD 2012-12-05").

(c) Applicability

(1) This AD applies to all The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rstc.nsf/0/ebd1cec7b301293e86257cb30045557a/\\$FILE/ST01219SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rstc.nsf/0/ebd1cec7b301293e86257cb30045557a/$FILE/ST01219SE.pdf)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracking of the station (STA) 348.2 frame above the two outboard fasteners attaching the frame inner chord and door stop fittings, and in the outboard chord at stringer S-16L; missing fasteners in the STA 348.2 frame inner chord; and additional cracking in locations not covered by the inspections in AD 2012-12-05. We are issuing this AD to detect and correct fatigue cracking of the intercostals on the forward and aft sides of the forward entry door cutout, which could result in loss of the forward entry door and rapid decompression of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Initial Compliance Time for Model 737-100, -200, -200C, -300, -400, and -500 Series Airplanes, With No Changes

This paragraph restates the requirements of paragraph (i) of AD 2012-12-05, with no changes. For all Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, as identified in Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007: Before the accumulation of 15,000 total flight cycles, or within 4,500 flight cycles after November 1, 2005 (the effective date of AD 2005-20-03, Amendment 39-14296 (70 FR 56361, September 27, 2005) ("AD 2005-20-03")), whichever occurs later: Do the inspections required by paragraphs (i) and (j) of this AD.

(h) Retained Initial Compliance Time for Model 737-200C Series Airplanes, With No Changes

This paragraph restates the requirements of paragraph (j) of AD 2012-12-05, with no changes. For all Model 737-200C series airplanes, as identified in Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007: Before the accumulation of 15,000 total flight cycles, or within 4,500 flight cycles after September 9, 2009 (the effective date of AD 2009-16-14, Amendment 39-15987 (74 FR 38901, August 5, 2009) ("AD 2009-16-14")), whichever occurs later, do the inspection required by paragraph (k) of this AD.

(i) Retained Initial Inspection for Group 1 Configuration Airplanes, With No Changes

This paragraph restates the requirements of paragraph (k) of AD 2012-12-05, with no changes. For Group 1 airplanes identified in Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007: Perform a

detailed inspection for cracking of the intercostal web, attachment clips, and stringer splice channels; and a high frequency eddy current (HFEC) inspection for cracking of the stringer splice channels located forward and aft of the forward entry door; and do all applicable corrective actions before further flight; in accordance with Parts 1 and 2 of the Work Instructions of Boeing Special Attention Service Bulletin 737-53-1204, dated June 19, 2003, or Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007; or in accordance with Parts 1, 2, 4, and 5 of the Work Instructions of Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010. After September 9, 2009 (the effective date of AD 2009-16-14), and until July 23, 2012 (the effective date of AD 2012-12-05), Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007; or Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010, may be used to accomplish the actions required by this paragraph. As of July 23, 2012, only Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010, may be used to accomplish the actions required by this paragraph.

(j) Retained Initial Inspection for Cargo Configuration Airplanes (Forward of the Forward Entry Door), With No Changes

This paragraph restates the requirements of paragraph (l) of AD 2012-12-05, with no changes. For Group 2 cargo airplanes identified in Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007; Perform a detailed inspection for cracking of the intercostal webs and attachment clips located forward of the forward entry door, and do all applicable corrective actions before further flight, in accordance with Part 3 of the Work Instructions of Boeing Special Attention Service Bulletin 737-53-1204, dated June 19, 2003, or Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007; or in accordance with Part 3 of Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010. After September 9, 2009 (the effective date of AD 2009-16-14), and until July 23, 2012 (the effective date of AD 2012-12-05), Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007; or Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010; may be used to accomplish the actions required by this paragraph. As of July 23, 2012, only Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010, may be used to accomplish the actions required by this paragraph.

(k) Retained Initial Inspection for Cargo Configuration Airplanes (Aft of the Forward Entry Door), With No Changes

This paragraph restates the requirements of paragraph (m) of AD 2012-12-05, with no changes. For Group 2 cargo airplanes identified in Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007; Perform a detailed inspection for cracking of the intercostal webs and attachment clips located aft of the forward entry door, and do all applicable corrective

actions before further flight, in accordance with Part 4 of the Work Instructions of Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007; or in accordance with Part 3 of Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010. As of July 23, 2012 (the effective date of AD 2012-12-05), only Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010, may be used to accomplish the actions required by this paragraph.

(l) Retained Repetitive Inspections, With No Changes

This paragraph restates the requirements of paragraph (n) of AD 2012-12-05, with no changes. Repeat the inspections required by paragraphs (i), (j), and (k) of this AD thereafter at intervals not to exceed 6,000 flight cycles after the previous inspection, or within 3,000 flight cycles after September 9, 2009, whichever occurs later.

(m) Retained Exceptions to Boeing Alert Service Bulletin 737-53-1204, With No Changes

This paragraph restates the requirements of paragraph (o) of AD 2012-12-05, with no changes. Do the actions required by paragraphs (g), (h), (i), (j), (k), and (l) of this AD by accomplishing all the applicable actions specified in the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-53-1204, dated June 19, 2003; Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007; or Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010; except as provided by paragraphs (m)(1) and (m)(2) of this AD. After September 9, 2009 (the effective date of AD 2009-16-14), and until July 23, 2012 (the effective date of AD 2012-12-05), Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007; or Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010; may be used to accomplish the actions required by this paragraph. As of July 23, 2012, only Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010, may be used to accomplish the actions required by this paragraph.

(1) Where Boeing Special Attention Service Bulletin 737-53-1204, dated June 19, 2003; Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007; or Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010; specifies to contact Boeing for repair instructions: Before further flight, repair using a method approved in accordance with the procedures specified in paragraph (s) of this AD.

(2) Where Boeing Special Attention Service Bulletin 737-53-1204, dated June 19, 2003; or Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007; specifies a compliance time relative to the date of a service bulletin, this AD requires compliance relative to September 9, 2009 (the effective date of AD 2009-16-14). Where Boeing Special Attention Service Bulletin 737-53-1204, dated June 19, 2003; or Boeing Alert Service Bulletin 737-53A1204, Revision 1, dated March 26, 2007; specifies a compliance time relative to the date of the

initial release of a service bulletin, this AD requires compliance relative to November 1, 2005 (the effective date of AD 2005-20-03).

(n) Retained Exceptions to Boeing Alert Service Bulletin 737-53A1204, Revision 2, Dated June 24, 2010, With No Changes

This paragraph restates exceptions to Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010, specified in paragraph (r) of AD 2012-12-05, with no changes.

(1) The access and restoration instructions identified in the Work Instructions of Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010, are not required by this AD. Operators may perform those actions in accordance with approved maintenance procedures.

(2) The use of Boeing Drawing 65-88700 is not allowed when accomplishing the actions required by this AD in accordance with the Work Instructions of Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010.

(o) Retained Initial and Repetitive Inspections of the S-15L Aft Intercostal and Cargo Barrier Net Fitting for Model 737-200C Series Airplanes, With No Changes

This paragraph restates the requirements of paragraph (s) of AD 2012-12-05, with no changes. For Group 2 airplanes identified in Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010: Before the accumulation of 15,000 total flight cycles, or within 4,500 flight cycles after July 23, 2012 (the effective date of AD 2012-12-05), whichever occurs later, do initial detailed and HFEC inspections for cracking of the S-15L aft intercostal between body station (BS) 348.2 and BS 360, and do a detailed inspection of the cargo barrier net fitting at the intercostal, in accordance with Figure 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1204, Revision 2, dated June 24, 2010. If any cracking is found, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (s) of this AD. Repeat the inspections thereafter at intervals not to exceed 6,000 flight cycles.

(p) Actions for Boeing Alert Service Bulletin 737-53A1240, Revision 2, Dated November 2, 2016, Including New Repetitive Inspections of Certain Fastener Holes

(1) For airplanes identified as Group 1 and Group 3 in Boeing Alert Service Bulletin 737-53A1240, Revision 2, dated November 2, 2016: Except as required by paragraph (q) of this AD, at the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1240, Revision 2, dated November 2, 2016, do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1240, Revision 2, dated November 2, 2016.

(2) For airplanes identified as Group 2 in Boeing Alert Service Bulletin 737-53A1240, Revision 2, dated November 2, 2016: Within 120 days after the effective date of this AD, do actions to correct the unsafe condition using a method approved in accordance with

the procedures specified in paragraph (s) of this AD.

(q) Exceptions to Service Information Specifications

(1) Where Boeing Alert Service Bulletin 737–53A1240, Revision 2, dated November 2, 2016, uses the phrase “after the Revision 2 date of this service bulletin,” for purposes of determining compliance with the requirements of this AD, the phrase “after the effective date of this AD” must be used.

(2) Where Boeing Alert Service Bulletin 737–53A1240, Revision 2, dated November 2, 2016, specifies contacting Boeing, and specifies that action as RC: This AD requires using a method approved in accordance with the procedures specified in paragraph(s) of this AD.

(r) Credit for Previous Actions

(1) This paragraph provides credit for the actions specified in paragraphs (i), (j), and (m) of this AD, if those actions were performed before September 9, 2009 (the effective date of AD 2009–16–14, Amendment 39–15987 (74 FR 38901, August 5, 2009)), using Boeing Special Attention Service Bulletin 737–53–1204, dated June 19, 2003.

(2) This paragraph provides credit for the actions specified in paragraph (p) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 737–53A1240, Revision 1, dated June 29, 2010, provided the conditions specified in paragraphs (r)(2)(i) and (r)(2)(ii) of this AD are met and except as provided by paragraph (r)(2)(iii) of this AD. Boeing Alert Service Bulletin 737–53A1240, Revision 1, dated June 29, 2010, was incorporated by reference in AD 2012–12–05.

(i) Note 1 of paragraph 3.A of the Accomplishment Instructions of Boeing Alert Service Bulletin 737–53A1240, Revision 1, dated June 29, 2010, was disregarded when accomplishing the actions.

(ii) Boeing Drawing 65–88700 was not used when accomplishing the actions in accordance with the Work Instructions of Boeing Alert Service Bulletin 737–53A1240, Revision 1, dated June 29, 2010.

(iii) The access and restoration instructions identified in the Work Instructions of Boeing Alert Service Bulletin 737–53A1240, Revision 1, dated June 29, 2010, are not required. Operators are allowed to perform those actions in accordance with approved maintenance procedures.

(s) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (t)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager

of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (q)(2) of this AD: For service information that contains steps that are labeled as RC, the provisions of paragraphs (s)(4)(i) and (s)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(5) AMOCs approved previously for AD 2012–12–05 are approved as AMOCs for the corresponding provisions of paragraphs (g) through (o) of this AD.

(6) AMOCs approved previously for AD 2012–12–05 are approved as AMOCs for the corresponding provisions of Boeing Alert Service Bulletin 737–53A1240, Revision 2, dated November 2, 2016, that are required by paragraph (p)(1) of this AD.

(t) Related Information

(1) For more information about this AD, contact Galib Abumeri, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5324; fax: 562–627–5210; email: galib.abumeri@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (u)(6) and (u)(7) of this AD.

(u) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on March 30, 2018.

(i) Boeing Alert Service Bulletin 737–53A1240, Revision 2, dated November 2, 2016.

(ii) Reserved.

(4) The following service information was approved for IBR on July 23, 2012 (77 FR 36139, June 18, 2012).

(i) Boeing Alert Service Bulletin 737–53A1204, Revision 2, dated June 24, 2010.

(ii) Reserved.

(5) The following service information was approved for IBR on September 9, 2009 (74 FR 38901, August 5, 2009).

(i) Boeing Alert Service Bulletin 737–53A1204, Revision 1, dated March 26, 2007.

(ii) Reserved.

(6) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740; telephone: 562–797–1717; internet: <https://www.myboeingfleet.com>.

(7) You may view this service information at FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(8) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 9, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018–03434 Filed 2–22–18; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2017–1021; Product Identifier 2017–NM–052–AD; Amendment 39–19198; AD 2018–04–03]

RIN 2120–AA64

Airworthiness Directives; Fokker Services B.V. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Fokker Services B.V. Model F28 Mark 0100 airplanes. This AD was prompted by a report that a jammed control cable prevented the full extension of the nose landing gear (LG). This AD requires a general visual inspection of the LG handle reflex cable conduit connector for the presence of a grease nipple, a maintenance records check of affected airplanes, a detailed inspection for