

this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-11522 (65 FR 3799, January 25, 2000), and by adding a new airworthiness directive (AD), to read as follows:

Airbus Industrie: Docket 2000-NM-104-AD. Supersedes AD 2000-02-04, Amendment 39-11522.

Applicability: Model A300 B2-203 and B4-203 series airplanes in a forward facing cockpit version, as listed in Airbus Service Bulletin A300-22A0115, Revision 02, dated March 7, 2000; and all Model A300-600 and A310 series airplanes; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent a sudden change in pitch due to an out-of-trim condition combined with an autopilot disconnect, which could result in reduced controllability of the airplane, accomplish the following:

Repetitive Inspections

(a) At the applicable time specified by paragraph (a)(1) or (a)(2) of this AD: Perform an inspection of the autotrim function by testing the flight control computer (FCC)/flight augmentation computer (FAC) integrity in logic activation of the autotrim, in accordance with Airbus Service Bulletin A300-22A6042, Revision 01 (for Model A300-600 series airplanes); A300-22A0115, Revision 02 (for Model A300 series airplanes); or A310-22A2053, Revision 01 (for Model A310 series airplanes); all dated March 7, 2000; as applicable. If any discrepancy is found, prior to further flight, perform all applicable corrective actions (including trouble-shooting, replacing the FCC and/or FAC, retesting, checking the wires between certain FCC and FAC pins, and repairing damaged wires) in accordance with the applicable service bulletin. Repeat the inspection thereafter at intervals not to exceed 500 flight hours.

(1) For airplanes on which the pitch trim system test has been performed in accordance with the requirements of AD 2000-02-04, amendment 39-11522: Inspect within 500 flight hours after accomplishment of the test required by that AD, or within 20 days after the effective date of this AD, whichever occurs later.

(2) For all other airplanes: Inspect within 20 days after the effective date of this AD.

Reporting Requirement

(b) For all inspections required by paragraph (a) of this AD: At the applicable time specified by paragraph (b)(1) or (b)(2) of this AD, submit a report of the inspection results (both positive and negative findings) to AI/SE-D32 Technical Data and Documentation Services, Airbus Industrie Customer Services Directorate, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex France; fax (+33) 5 61 93 28 06.

(1) For inspections accomplished after the effective date of this AD: Submit the report within 10 days after performing the inspection.

(2) For inspections accomplished prior to the effective date of this AD: Submit the

report within 10 days after the effective date of this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in French airworthiness directive 2000-115-304(B) R1, dated May 3, 2000.

Issued in Renton, Washington, on June 6, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 00-14794 Filed 6-9-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-107-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-300, -400, and -500 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Boeing Model 737-300, -400, and -500 series airplanes. This proposal would require replacement of the existing autothrottle computer with a new, improved autothrottle computer. This proposal is prompted by reports of asymmetric thrust conditions during flight caused by irregular autothrottle operation in which the thrust levers slowly move apart causing the airplane

to bank excessively and go into a roll. The actions specified by the proposed AD are intended to prevent such conditions, which could result in loss of control of the airplane.

DATES: Comments must be received by July 27, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-107-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Thanh Truong, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2552; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following

statement is made: "Comments to Docket Number 2000-NM-107-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-107-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received reports on certain Boeing Model 737-300, -400, and -500 series airplanes indicating an asymmetric thrust condition caused by irregular autothrottle operation, in which the thrust levers slowly move apart causing the airplane to bank and roll. This thrust condition exceeds the autopilot roll authority and results in a bank angle of more than 30 degrees. In one incident, the airplane rolled more than 46 degrees without crew recognition. Without pilot intervention, an airplane that has asymmetric thrust can bank excessively and go into a roll. Such conditions, if not corrected, could result in loss of control of the airplane.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 737-22A1130, dated September 24, 1998, which describes procedures for replacement of the existing autothrottle computer with a new, improved autothrottle computer. The improved autothrottle computer disengages the autothrottle if an asymmetric thrust condition is detected, and prevents the airplane from rolling to an excessive bank angle.

Accomplishment of the actions specified in the alert service bulletin is intended to adequately address the unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the alert service bulletin described previously, except as discussed below.

Differences Between Proposed Rule and Alert Service Bulletin

Operators should note that this proposed AD would require replacement of the autothrottle computer to be accomplished within one year after the effective date of this

AD. The alert service bulletin recommends that this replacement should be accomplished "as soon as manpower and materials are available." However, in developing an appropriate compliance time for the proposed replacement, the FAA considered not only the degree of urgency associated with addressing the subject unsafe condition, but also the number of proposed requirements and the availability of required parts. The FAA has determined that one year represents an appropriate interval of time allowable wherein all of these actions can be accomplished during scheduled airplane maintenance and an ample number of required parts will be available for modification of the U.S. fleet within the proposed compliance period. The FAA also finds that such a compliance time will not adversely affect the safety of the affected airplanes.

Cost Impact

There are approximately 1,974 airplanes of the affected design in the worldwide fleet. The FAA estimates that 799 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed replacement, and that the average labor rate is \$60 per work hour. Required parts would cost between \$1,400 and \$4,200 per airplane. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be between \$1,460 and \$4,260 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 2000–NM–107–AD.

Applicability: All Model 737–300, –400, and –500 series airplanes; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent a severe asymmetric thrust condition during flight which could result in loss of control of the airplane, accomplish the following:

Replacement

(a) Within 1 year after the effective date of this AD: Replace the existing autothrottle computer with a new, improved autothrottle computer in accordance with Boeing Alert Service Bulletin 737–22A1130, dated September 24, 1998.

Spares

(b) As of the effective date of this AD, no person shall install on any airplane, an autothrottle computer having part number

10–62017–1, –2, –3, –4, –5, –11, –21, –23, –25, or –27.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permit

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on June 6, 2000.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00–14793 Filed 6–9–00; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 00–ASW–6]

Proposed Modification of Federal Airways in the Vicinity of Dallas/Fort Worth, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to amend fourteen Federal airways in the vicinity of Dallas/Fort Worth, TX. The FAA is proposing this action to simplify the airway structure, thereby, enhancing the management of aircraft operations in the area.

DATES: Comments must be received on or before July 28, 2000.

ADDRESSES: Send comments on this proposal in triplicate to: Manager, Air Traffic Division, ASW–500, Docket No. 00–ASW–6, Federal Aviation Administration, 2601 Meacham Blvd; Fort Worth, TX 76193–0500. The official docket may be examined in the Rules Docket, Office of the Chief Counsel, Room 916, 800 Independence Avenue, SW., Washington, DC, weekdays, except Federal holidays, between 8:30 a.m. and 5 p.m.

An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division, Federal Aviation Administration, 2601 Meacham Blvd; Fort Worth, TX 76193–0500.

FOR FURTHER INFORMATION CONTACT: Bil Nelson, Airspace and Rules Division, ATA–400, Office of Air Traffic Airspace Management, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267–8783.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed, stamped postcard on which the following statement is made: “Comments to Airspace Docket No. 00–ASW–6.” The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the Rules Docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM

An electronic copy of this document may be downloaded using a modem and suitable communications software from the FAA regulations section of the Fedworld electronic bulletin board service (telephone: 703–321–3339) or the Government Printing Office’s electronic bulletin board service (telephone: 202–512–1661).

Internet users may reach the FAA’s web page at <http://www.faa.gov> or the