

service information in English as it appears on the document.

(3) For service information identified in this AD, contact Schempp-Hirth Flugzeugbau GmbH, Kребenstrasse 25, Kirchheim unter Teck, Germany; phone: +49 7021 7298-0; email: info@schempp-hirth.com; website: schempp-hirth.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on June 2, 2023.

Michael Linegang,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-12302 Filed 6-8-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-1207; Project Identifier MCAI-2022-00925-R]

RIN 2120-AA64

Airworthiness Directives; Leonardo S.p.a. Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Leonardo S.p.a. Model A119 and AW119 MKII helicopters. This proposed AD was prompted by a report of an electrical failure of a starter-generator caused by a ruptured drive shaft. This proposed AD would require visually inspecting the drive shaft of an affected starter-generator and depending on the results, performing a dye penetrant inspection. Depending on the results of the dye penetrant inspection, this proposed AD would require replacing the starter-generator, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by July 24, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2023-1207; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For EASA material that is proposed for IBR in this NPRM, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. The EASA material is also available at regulations.gov under Docket No. FAA-2023-1207.

Other Related Service Information:

For Leonardo Helicopters service information identified in this NPRM, contact Leonardo S.p.a., Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone (+39) 0331-225074; fax (+39) 0331-229046; or at customerportal.leonardocompany.com/en-US/. You may also view this service information at the FAA contact information under *Material Incorporated by Reference* above.

FOR FURTHER INFORMATION CONTACT: Hal Jensen, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (303) 342-1080; email hal.jensen@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or

arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2023-1207; Project Identifier MCAI-2022-00925-R” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Hal Jensen, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (303) 342-1080; email hal.jensen@faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2022-0148, dated July 14, 2022 (EASA AD 2022-0148), to correct an unsafe condition for Leonardo S.p.a. Helicopters Model A119 and AW119MKII helicopters.

This proposed AD was prompted by a report of an electrical failure of a starter-generator, caused by a ruptured drive shaft, which was not detected by the generator control unit and caused

partial loss of battery power. The FAA is proposing this AD to prevent electrical failure of the starter-generator, which could result in complete loss of electrical power and subsequent loss of control of the helicopter. See EASA AD 2022-0148 for additional background information.

Related Service Information Under 1 CFR Part 51

EASA AD 2022-0148 requires a one-time inspection of the drive shaft of the affected starter-generator and, depending on findings, replacing the affected part with a serviceable part as defined therein. EASA AD 2022-0148 also requires reporting the inspection results (including no findings) to Leonardo and implementing improved removal and reinstallation procedures for the starter-generator.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Other Related Service Information

The FAA also reviewed Leonardo Helicopters Alert Service Bulletin No. 119-121, dated June 21, 2022. This service information specifies procedures for performing visual and dye penetrant inspections, and replacing a starter-generator.

FAA's Determination

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its AD. The FAA is proposing this AD after evaluating all known relevant information and determining that the unsafe condition described previously is likely to exist or develop on other helicopters of these same type designs.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2022-0148, described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this proposed AD and except as discussed under "Differences Between this Proposed AD and the EASA AD."

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD

process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2022-0148 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2022-0148 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2022-0148 does not mean that operators need comply only with that section. For example, where the proposed AD requirement refers to "all required actions and compliance times," compliance with this proposed AD requirement would not be limited to the section titled "Required Action(s) and Compliance Time(s)" in EASA AD 2022-0148. Service information referenced in EASA AD 2022-0148 for compliance will be available at regulations.gov under Docket No. FAA-2023-1207 after the FAA final rule is published.

Differences Between This Proposed AD and the EASA AD

Service information referenced in EASA AD 2022-0148 does not specify a compliance time to proceed with subsequent procedures if there is misalignment or if the alignment is not clear, whereas this proposed AD would require proceeding with those subsequent procedures before further flight.

Service information referenced in EASA AD 2022-0148 specifies contacting LH [Leonardo Helicopters] spare management to send a starter-generator directly to an authorized repair station for repair, and sending a starter-generator directly to an authorized repair station for repair, whereas this proposed AD would not require those actions.

EASA AD 2022-0148 specifies reporting inspection results to Leonardo, whereas this proposed AD would not.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 136 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this proposed AD.

Visually inspecting a starter-generator drive shaft would take about 1 work-hour for an estimated cost of \$85 per helicopter and \$11,560 for the U.S. fleet.

If required, dye-penetrant inspecting a starter-generator drive shaft would take about 3 work-hours for an estimated cost of \$255 per helicopter.

If required, replacing a starter-generator would take about 2 work-hours and parts would cost about \$11,500 for an estimated cost of \$11,670 per helicopter.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Leonardo S.p.a.: Docket No. FAA–2023–1207; Project Identifier MCAI–2022–00925–R.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by July 24, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Leonardo S.p.a. Model A119 and AW119 MKII helicopters, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 2435, Starter-Generator.

(e) Unsafe Condition

This AD was prompted by a report of an electrical failure of a starter-generator that was caused by a ruptured drive shaft. The failure was not detected by the generator control unit and caused partial loss of battery power. The FAA is issuing this AD to prevent electrical failure of the starter-generator, possibly due to incorrect installation or removal. The unsafe condition, if not addressed, could result in complete loss of electrical power and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency EASA AD 2022–0148, dated July 14, 2022 (EASA AD 2022–0148).

(h) Exceptions to EASA AD 2022–0148

(1) Where EASA AD 2022–0148 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2022–0148 requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(3) Where paragraph (1) of EASA AD 2022–0148 states to, “inspect the drive shaft;” for this AD, replace that text with, “inspect the drive shaft for misalignment and a crack.”

(4) Where the service information referenced in EASA AD 2022–0148 specifies

to proceed with subsequent procedures if there is misalignment or if the alignment is not clear; for this AD, proceed with those subsequent procedures before further flight.

(5) Where the service information referenced in EASA AD 2022–0148 states, “with reference to Annex A, perform a liquid penetrant inspection of the drive-shaft, in order to detect the presence of eventual cracks;” for this AD, replace that text with “With reference to Annex A, perform a dye penetrant inspection of the drive-shaft in order to detect any cracks.”

(6) Where the service information referenced in paragraph (1) of EASA AD 2022–0148 specifies contacting LH [Leonardo Helicopters] spare management to send a starter-generator directly to an authorized repair station for repair and sending the starter-generator to an authorized repair station for repair, this AD does not require those actions.

(7) Where paragraphs (2) and (4) of EASA AD 2022–0148 state, “Part II of the ASB;” for this AD, replace that text with, “AMP Data Modules 19–A–24–30–04–00A–520A–A, Starter Generator—Remove Procedure and 19–A–24–30–04–00A–720A–A, Starter Generator—Install Procedure, each Issue 001 and dated May 24, 2021. Except where AMP Data Module 19–A–24–30–04–00A–520A–A Starter Generator—Remove Procedure specifies discarding parts; for this AD, remove those parts from service.”

(8) This AD does not require paragraph (3) of EASA AD 2022–0148.

(9) This AD does not adopt the “Remarks” section of EASA AD 2022–0148.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2022–0148 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199, provided they are restricted to visual flight rules (VFR) with night operations prohibited and no passengers are onboard.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Hal Jensen, Aviation Safety Engineer,

FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (303) 342–1080; email hal.jensen@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2022–0148, dated July 14, 2022.

(ii) [Reserved]

(3) For EASA AD 2022–0148, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on June 2, 2023.

Michael Linegang,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–12335 Filed 6–8–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2023–1208; Project Identifier AD–2023–00325–E]

RIN 2120–AA64

Airworthiness Directives; General Electric Company Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain General Electric Company (GE) Model CF6–80E1A2, CF6–80E1A3, CF6–80E1A4, and CF6–80E1A4/B engines. This proposed AD was prompted by a manufacturer investigation that revealed that a certain forward outer seal and certain high-pressure turbine rotor (HPTR) stage 1