

and the torque tube. The FAA is issuing this AD to detect and address disbonding. The unsafe condition, if not addressed, could result in increased tail rotor vibrations, physical failure of the torque tube, and consequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) TRB Inspection With Applicable Corrective Actions

For helicopters with TRB P/N 70101–31000 (all dash numbers), before the first flight of each day:

(1) Visually inspect each TRB for a crack, leading edge erosion, and trailing edge skin disbonding and separation, paying particular attention to the area from the midspan to the pitch control horn. If there is a crack, any leading edge erosion, trailing edge disbonding, or trailing edge separation, before further flight, remove the TRB from service and replace with a serviceable part.

(2) Tap test inspect each TRB for disbonding in the pitch horn to torque tube bond area. If there is any disbonding, before further flight remove the TRB from service and replace with a serviceable part.

(h) TRB Modification and Applicable Re-Identification

(1) For helicopters with TRB P/N 70101–31000–043, P/N 70101–31000–048, P/N 70101–31000–050, P/N 70101–31000–051, or P/N 70101–31000–052 without a split pitch horn installed, accomplish the safety enhancement modification kit. This action must be accomplished by an authorized Sikorsky Aircraft overhaul facility, or by a method approved by the Manager, East Certification Branch, FAA, within the compliance time specified in paragraph (h)(1)(i) or (ii) of this AD.

Note 1 to the introductory text of paragraph (h)(1): Upon completion of the safety enhancement modification kit, the TRB is marked with P/N 70070–10052–041.

Note 2 to the introductory text of paragraph (h)(1): Information on the safety enhancement modification kit is in Sikorsky Aircraft Corporation (Sikorsky) Alert Service Bulletin 70–05–52, Revision B, dated March 27, 2025, and Sikorsky Alert Service Bulletin 70–05–58, Revision A, dated July 10, 2025.

(i) TRBs manufactured on or before December 31, 2007: within 12 months after the effective date of this AD.

(ii) TRBs manufactured on or after January 1, 2008: within 48 months after the effective date of this AD.

(2) For helicopters with TRB P/N 70101–31000–046 without a split pitch horn installed, accomplish the split pitch horn modification. This action must be accomplished by an authorized Sikorsky Aircraft overhaul facility or by a method approved by the Manager, East Certification Branch, FAA, within the compliance time specified in paragraph (h)(2)(i) or (ii) of this AD.

Note 3 to the introductory text of paragraph (h)(2): Upon completion of the split pitch horn modification, the TRB is marked with P/N 70070–15005–042.

Note 4 to the introductory text of paragraph (h)(2): Information on the split pitch horn modification is in Sikorsky Alert Service Bulletin 70–05–52, Revision B, dated March 27, 2025, and Sikorsky Alert Service Bulletin 70–05–58, Revision A, dated July 10, 2025.

(i) TRBs manufactured on or before December 31, 2007: within 12 months after the effective date of this AD.

(ii) TRBs manufactured on or after January 1, 2008: within 48 months after the effective date of this AD.

(i) Revise Maintenance Procedures Manual

Upon completion of the modification required by paragraph (h)(1) of this AD (when the TRB P/N is changed to P/N 70070–10052–041), revise the airworthiness limitation section of the existing helicopter maintenance manual or instructions for continued airworthiness and the existing approved maintenance or inspection program, as applicable, by incorporating Sikorsky Aircraft Model S–70A Blackhawk Derivatives Maintenance Manual Temporary Revision No. 82, dated June 27, 2023.

(j) Provisions for Alternative Actions and Intervals

After the action required by paragraph (i) of this AD has been done, no alternative actions and associated intervals are allowed unless they are approved as specified in the provisions of the alternative methods of compliance (AMOC) paragraph.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, East Certification Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the East Certification Branch, send it to the attention of the person identified in paragraph (l)(1) of this AD and email to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Additional Information

(1) For more information about this AD, contact Isabel Saltzman, Aviation Safety Engineer, FAA, 1701 Columbia Avenue, College Park, GA 30337; phone: (781) 238–7649; email: ECB-COS@faa.gov.

(2) Material identified in this AD that is not incorporated by reference is available at the address specified in paragraph (m)(3) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Sikorsky Aircraft Corporation Model S–70A Blackhawk Derivatives Maintenance Manual Temporary Revision No. 82, dated June 27, 2023.

(ii) [Reserved]

(3) For Sikorsky Aircraft Corporation material identified in this AD, contact your local Sikorsky Field Representative or Sikorsky's Service Engineering Group at Sikorsky Aircraft Corporation, 124 Quarry Road, Trumbull, CT 06611; phone 1–800–Winged-S or 203–416–4299; email wcs_cust_service_eng.gr-sik@lmco.com. Operators may also log on to the Sikorsky 360 website at sikorsky360.com.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 10101 Hillwood Parkway, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on April 20, 2026.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2026–07937 Filed 4–22–26; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2026–3866; Project Identifier MCAI–2025–01200–R]

RIN 2120–AA64

Airworthiness Directives; Bell Textron Canada Limited Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Bell Textron Canada Limited Model 505 helicopters. This proposed AD was prompted by a report of a quality escape in the production installation of a washer installed on the tail rotor pitch link assembly (pitch link assembly). This proposed AD would require a one-time visual inspection for proper installation of the washer installed on the pitch link assembly and, depending on the results of the inspection, corrective actions. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by June 8, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA-2026-3866; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For Transport Canada material identified in this proposed AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario, K1A 0N5, Canada; phone: (888) 663-3639; email: *TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca*. You may find the Transport Canada material on the Transport Canada website at *tc.canada.ca/en/aviation*.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 10101 Hillwood Parkway, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

FOR FURTHER INFORMATION CONTACT:

David Enns, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (316) 946-4147; email: *david.enns@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under **ADDRESSES**. Include “Docket No. FAA-2026-3866; Project Identifier MCAI-2025-01200-R” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing

date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to David Enns, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF-2025-34, dated July 3, 2025 (Transport Canada AD CF-2025-34) (also referred to as the MCAI), to correct an unsafe condition on certain Bell Textron Canada Limited Model 505 helicopters. The MCAI states Bell Textron Canada Limited has discovered a quality escape in the production installation of the pitch link assemblies where a washer was installed in the wrong location. The MCAI further states this incorrect installation could cause fracture of the pitch horn stud due to fatigue or when the rotor blade exceeds the travel during certain control inputs and blade flapping angles. The MCAI requires a one-time inspection of the pitch link assembly for proper installation of washer, part number 206-010-795-105, and depending on the inspection results, reassembling the pitch link assembly and washer or replacing the

pitch link assembly, tail rotor blade pitch horn, packings, and conical washer. The unsafe condition, if not addressed, could result in fracture of the pitch horn stud due to fatigue or when the rotor blade exceeds the travel during certain control inputs and blade flapping angles and loss of directional control of the helicopter.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA-2026-3866.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed Transport Canada AD CF-2025-34, which specifies procedures for a one-time visual inspection for proper installation of the pitch link assembly and, depending on the results of the inspection, reassembling the pitch link assembly and washer or removing and replacing the pitch link assembly, tail rotor pitch horn, packings, and conical washer.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

These products have been approved by the civil aviation authority (CAA) of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in Transport Canada AD CF-2025-34, described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this proposed AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some CAA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate Transport Canada AD CF-2025-34 by

reference in the FAA final rule. This proposed AD would, therefore, require compliance with Transport Canada AD CF–2025–34 in its entirety through that incorporation, except for any differences identified as exceptions in the

regulatory text of this proposed AD. Material required by Transport Canada AD CF–2025–34 for compliance will be available at *regulations.gov* under Docket No. FAA–2026–3866 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 10 helicopters of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspect pitch link assembly	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$850

The FAA estimates the following costs to do any replacements that would be required based on the results of the

proposed inspection. The agency has no way of determining the number of

helicopters that might need these replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replace pitch link assembly, tail rotor pitch horn, packings, and conical washer.	4 work-hours × \$85 per hour = \$340 (per assembly).	\$4,396 (per assembly)	Up to \$9,472.
Remove and reassemble pitch link assembly	1 work-hour × \$85 per hour = \$85	\$0	\$85.

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or

on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Bell Textron Canada Limited; Docket No. FAA–2026–3866; Project Identifier MCAI–2025–01200–R.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by June 8, 2026.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bell Textron Canada Limited Model 505 helicopters, certificated in any category, as identified in Transport Canada AD CF–2025–34, dated July 3, 2025 (Transport Canada AD CF–2025–34).

(d) Subject

Joint Aircraft System Component (JASC) Code 6400, Tail rotor system

(e) Unsafe Condition

This AD was prompted by a report of a quality escape in the production installation of a washer installed on the tail rotor pitch link assembly (pitch link assembly). The FAA is issuing this AD to detect proper installation. The unsafe condition, if not addressed, could result in fracture of the pitch horn stud due to fatigue or when the rotor blade exceeds the travel during certain control inputs and blade flapping angles and loss of directional control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Transport Canada AD CF–2025–34.

(h) Exceptions to Transport Canada AD CF–2025–34

(1) Where Transport Canada AD CF–2025–34 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where Transport Canada AD CF–2025–34 requires compliance in terms of air time, this AD requires using hours time-in-service.

(3) Where paragraph (1) of Transport Canada AD CF–2025–34 specifies “Perform a one-time inspection of the tail rotor pitch link assembly installation”, this AD requires replacing that text with “Perform a one-time inspection of the pitch link assembly installation and, if applicable, remove and reassemble the pitch link assembly and washer”.

(4) Where the material referenced in Transport Canada AD CF–2025–34 specifies to discard certain parts, this AD requires removing those parts from service.

(i) Special Flight Permit

Special flight permits, as described in 14 CFR 21.197 and 21.199, are not allowed.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Additional Information

For more information about this AD, contact David Enns, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (316) 946–4147; email: david.enns@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Transport Canada AD CF–2025–34, dated July 3, 2025.

(ii) [Reserved]

(3) For Transport Canada material identified in this AD, contact Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada phone: (888) 663–3639; email: TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca. You may find this material on the Transport Canada website at tc.canada.ca/en/aviation.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 10101 Hillwood Parkway, Fort

Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on April 20, 2026.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2026–07935 Filed 4–22–26; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2026–3865; Project Identifier AD–2025–01395–T]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2021–02–13, which applies to certain The Boeing Company Model 737–600, –700, –700C, –800, and –900 series airplanes. AD 2021–02–13 requires inspections of the fuselage skin and bear strap at the forward galley door between certain stations for cracks, and applicable on-condition actions. Since the FAA issued AD 2021–02–13, a report was received of cracking outside the required inspection area, and it has been determined that additional airplanes may be subject to the identified unsafe condition. This proposed AD would continue to require the actions of AD 2021–02–13 and would add airplanes to the applicability. This proposed AD would also add inspections for an extended inspection area. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by June 8, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2026–3865; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For Boeing material identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website myboeingfleet.com.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at regulations.gov under Docket No. FAA–2026–3865.

FOR FURTHER INFORMATION CONTACT: Luis Cortez-Muniz, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3958; email: luis.a.cortez-muniz@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under the **ADDRESSES** section. Include “Docket No. FAA–2026–3865; Project Identifier AD–2025–01395–T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each