

## Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a “significant regulatory action” under Executive Order 12866, and

(2) Will not affect intrastate aviation in Alaska.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

#### 2026–08–51 Airbus Helicopters

**Deutschland GmbH (AHD):** Amendment 39–23249; Docket No. FAA–2026–3867; Project Identifier MCAI–2026–00403–R.

#### (a) Effective Date

The FAA issued Emergency Airworthiness Directive (AD) 2026–08–51 on April 16, 2026 (also referred to as the emergency AD), directly to affected owners and operators. As a result of such actual notice, the emergency AD was effective for those owners and operators on the date it was received. This AD contains the same requirements as the emergency AD and, for those who did not receive actual notice, is effective on May 14, 2026.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all Airbus Helicopters Deutschland GmbH (AHD) Model MBB–BK 117 D–3 helicopters, certificated in any category.

#### (d) Subject

Joint Aircraft Service Component (JASC) Code: 6300, Main rotor drive system.

#### (e) Unsafe Condition

This AD was prompted by a report of a crack on the affected part, which was detected after the crew reported increased vibration of the helicopter. The mandatory continuing airworthiness information defines the affected part as a rotor hub-shaft manufacturer part number D623M1501203 and D623M1501204. The FAA is issuing this AD to address cracking of the rotor hub-shaft, which could lead to failure of the main rotor transmission and consequent loss of control of the helicopter.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with European Union Aviation Safety Agency Emergency AD 2026–0078–E, dated April 13, 2026 (EASA Emergency AD 2026–0078–E).

#### (h) Exceptions to EASA Emergency AD 2026–0078–E

(1) Where EASA Emergency AD 2026–0078–E refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA Emergency AD 2026–0078–E requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(3) This AD does not adopt the “Remarks” section of EASA Emergency AD 2026–0078–E.

#### (i) Special Flight Permits

Special flight permits, as described in 14 CFR 21.197 and 21.199, are not allowed.

#### (j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: [AMOC@faa.gov](mailto:AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (k) Additional Information

For more information about this AD, contact David Enns, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (316) 946–4147; email: [david.enns@faa.gov](mailto:david.enns@faa.gov).

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) Emergency AD 2026–0078–E, dated April 13, 2026.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: [ADS@easa.europa.eu](mailto:ADS@easa.europa.eu); website: [easa.europa.eu](http://easa.europa.eu). You may find the EASA material on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu).

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 10101 Hillwood Parkway, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on April 23, 2026.

**Steven W. Thompson,**

*Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2026–08324 Filed 4–28–26; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2025–2275; Project Identifier AD–2025–00796–T; Amendment 39–23317; AD 2026–08–09]

RIN 2120–AA64

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain The Boeing Company Model 757–200 and –300 series airplanes. This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective June 3, 2026.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of June 3, 2026.

**ADDRESSES:**

*AD Docket:* You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2025–2275; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

*Material Incorporated by Reference:*

- For Aviation Partners Boeing material identified in this AD, contact Aviation Partners Boeing, 555 Andover Park West, Suite 200, Tukwila, WA 98188; telephone 206–830–7699; email [leng@aviationpartners.com](mailto:leng@aviationpartners.com); website [aviationpartnersboeing.com](https://aviationpartnersboeing.com).
- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2025–2275.

**FOR FURTHER INFORMATION CONTACT:**

Sarah Illg, Aviation Safety Engineer, FAA, 3960 Paramount Boulevard, Lakewood, CA 90712; phone: 206–231–3517; email: [Sarah.A.Illg@faa.gov](mailto:Sarah.A.Illg@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Background**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 757–200 and –300 series airplanes. The NPRM was published in the **Federal Register** on September 8, 2025 (90 FR 43159). The NPRM was prompted by an operator report indicating that during a maintenance H-check inspection, a crack was found at the splice fitting between the original wing and the Aviation Partners Boeing (APB) modified lower wing skin panel, which is spliced at wing station (WS) 711 on a Boeing Company Model 757–200 airplane with the APB blended winglets installed in accordance with STC ST01518SE. APB reviewed the crack finding and determined the existing airworthiness limitations (AWL) structural significant items (SSI) 57–20–32B (which is required by AD 2020–01–18, Amendment 39–19824 ((85 FR 5304, January 30, 2020); corrected February 26, 2020 (85 FR 10969))) (AD 2020–01–18) does not provide adequate probability of detection for foreseeable fatigue cracking of SSIs at WS 711. If cracks grow undetected, it may result in

the inability of a principal structural element to sustain limit loads. The FAA determined that it is necessary to revise the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations for The Boeing Company Model 757–200 and –300 airplanes that have been modified in accordance with STC ST01518SE, with or without blended or scimitar blended winglets installed. In the NPRM, the FAA stated that incorporating the revision required by the proposed AD would terminate the requirements of paragraphs (g) and (h)(2) of AD 2020–01–18. In the NPRM, the FAA proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA is issuing this AD to address fatigue cracking on the wing and winglet. This condition, if not addressed, could result in the inability of a principal structural element to sustain limit loads, which could adversely affect the structural integrity of the airplane.

**Discussion of Final Airworthiness Directive**

**Comments**

The FAA received comments from three commenters, who supported the NPRM without change.

The FAA received an additional comment from Aviation Partners Boeing (APB). The following presents the comment received on the NPRM and the FAA's response to the comment.

**Request To Remove a Fax Number**

APB requested that the FAA remove the fax number listed for APB contact information in the Material Incorporated by Reference section and paragraph (l)(3) of the proposed AD. APB stated that it no longer has an active fax machine.

The FAA agrees and has removed the fax number in the Material Incorporated by Reference section and paragraph (l)(3) of this AD accordingly.

**Conclusion**

The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, and any other changes described previously, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

**Material Incorporated by Reference Under 1 CFR Part 51**

The FAA reviewed Aviation Partners Boeing AP57.2–0604.2 Supplement to D622N001–9 (Sep 2020) 757 Maintenance Planning Data (MPD) Document Section 9 Airworthiness Limitations (AWLs) and Certification Requirements (CMRs) Boeing 757–200 with Winglets FAA STC Number ST01518SE and EASA STC Number 10015659, Revision February 2022; and Aviation Partners Boeing AP57.3–0604.2 Supplement to D622N001–9 (Sep 2020) 757 Maintenance Planning Data (MPD) Document Section 9 Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs) 757–300 with Blended Winglets FAA STC ST01518SE and EASA STC Number 10015659, Revision August 2022. This material specifies airworthiness limitations for structural inspections, structural safe life parts, systems, and certification maintenance requirements.

The FAA also reviewed Aviation Partners Boeing AP57.2–0604.2–DTR Supplement to D622N001–DTR (Oct 2018) 757 Damage Tolerance Rating (DTR) Check Form Document for Boeing 757–200 with Winglets FAA STC Number ST01518SE and EASA STC Number 10015659, Revision August 2023; and Aviation Partners Boeing AP57.3–0604.2–DTR Supplement to D622N001–DTR (Oct 2018) 757 Damage Tolerance Rating (DTR) Check Form Document for Boeing 757–300 with Blended Winglets FAA STC Number ST01518SE and EASA STC Number 10015659, Revision August 2023. This material provides the DTR check forms and the procedure for their use.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**Costs of Compliance**

The FAA estimates that this AD affects 156 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, the FAA estimates the average total cost per operator to be

\$7,650 (90 work-hours × \$85 per work-hour).

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Reporting .....	1 work-hour × \$85 per hour = \$85 .....	\$0	\$85

**Paperwork Reduction Act**

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a currently valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to take approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

This AD will not have federalism implications under Executive Order

13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2026-08-09 The Boeing Company:**  
Amendment 39-23317; Docket No. FAA-2025-2275; Project Identifier AD-2025-00796-T.

**(a) Effective Date**

This airworthiness directive (AD) is effective June 3, 2026.

**(b) Affected ADs**

This AD affects AD 2020-01-18, Amendment 39-19824 ((85 FR 5304, January 30, 2020); corrected February 26, 2020 (85 FR 10969)) (AD 2020-01-18).

**(c) Applicability**

This AD applies to The Boeing Company Model 757-200 and -300 series airplanes, certificated in any category, that have been modified in accordance with supplemental

type certificate (STC) ST01518SE, with or without blended or scimitar blended winglets installed.

**(d) Subject**

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks; 57, Wings.

**(e) Unsafe Condition**

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address fatigue cracking on the wing and winglet. This condition, if not addressed, could result in the inability of a principal structural element to sustain limit loads, which could adversely affect the structural integrity of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Maintenance or Inspection Program Revision**

(1) For Model 757-200 series airplanes: Within 30 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the service information specified in paragraphs (g)(1)(i) and (ii) of this AD. The initial compliance time for doing the tasks is at the time specified in the service information identified in paragraphs (g)(1)(i) and (ii) of this AD, or within 6 months or 500 flight cycles after the effective date of this AD, whichever occurs later.

(i) Aviation Partners Boeing AP57.2-0604.2 Supplement to D622N001-9 (Sep 2020) 757 Maintenance Planning Data (MPD) Document Section 9 Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs) Boeing 757-200 with Winglets FAA STC Number ST01518SE and EASA STC Number 10015659, Revision February 2022.

(ii) Aviation Partners Boeing AP57.2-0604.2-DTR Supplement to D622N001-DTR (Oct 2018) 757 Damage Tolerance Rating (DTR) Check Form Document for Boeing 757-200 with Winglets FAA STC Number ST01518SE and EASA STC Number 10015659, Revision August 2023.

(2) For Model 757-300 series airplanes: Within 30 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the service information specified in paragraphs (g)(2)(i) and (ii) of this AD. The initial compliance time for doing the tasks is at the time specified in the service information identified in paragraphs (g)(2)(i) and (ii) of this AD, or within 6 months or 500 flight cycles after the effective date of this AD, whichever occurs later.

(i) Aviation Partners Boeing AP57.3–0604.2 Supplement to D622N001–9 (Sep 2020) 757 Maintenance Planning Data (MPD) Document Section 9 Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs) 757–300 with Blended Winglets FAA STC ST01518SE and EASA STC Number 10015659, Revision August 2022.

(ii) Aviation Partners Boeing AP57.3–0604.2–DTR Supplement to D622N001–DTR (Oct 2018) 757 Damage Tolerance Rating (DTR) Check Form Document for Boeing 757–300 with Blended Winglets FAA STC Number ST01518SE and EASA STC Number 10015659, Revision August 2023.

(3) The reports specified in the service information identified in paragraphs (g)(1)(i) and (ii) of this AD and (g)(2)(i) and (ii) of this AD must be submitted within 10 days after the airplane is returned to service, instead of 10 days after each individual finding as specified in the service information identified in paragraphs (g)(1)(i) and (ii) of this AD and (g)(2)(i) and (ii) of this AD.

#### (h) No Alternative Actions or Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals, may be used unless the actions and intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (j) of this AD.

#### (i) Terminating Action for Paragraphs (g) and (h)(2) of AD 2020–01–18

Accomplishing the actions required by paragraph (g) this AD terminates the requirements specified in paragraphs (g) and (h)(2) of AD 2020–01–18 for The Boeing Company Model 757–200 and –300 series airplanes that have been modified in accordance with STC ST01518SE, with or without blended or scimitar blended winglets installed.

#### (j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR–770, West Certification Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the West Certification Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: [AMOC@faa.gov](mailto:AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR–770, West Certification Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet

the certification basis of the airplane, and the approval must specifically refer to this AD.

(3) AMOCs approved previously for AD 2020–01–18; AD 2006–11–11 Amendment 39–14615 (71 FR 30278, May 26, 2006); and AD 2001–20–12, Amendment 39–12460 (66 FR 52492, October 16, 2001); are approved as AMOCs for the corresponding provisions of this AD, except for AMOCs that included revised compliance times.

#### (k) Related Information

For more information about this AD, contact Sarah Illg, Aviation Safety Engineer, FAA, 3960 Paramount Boulevard, Lakewood, CA 90712; phone: 206–231–3517; email: [Sarah.A.Illg@faa.gov](mailto:Sarah.A.Illg@faa.gov).

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Aviation Partners Boeing AP57.2–0604.2 Supplement to D622N001–9 (Sep 2020) 757 Maintenance Planning Data (MPD) Document Section 9 Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs) Boeing 757–200 with Winglets FAA STC Number ST01518SE and EASA STC Number 10015659, Revision February 2022.

(ii) Aviation Partners Boeing AP57.2–0604.2–DTR Supplement to D622N001–DTR (Oct 2018) 757 Damage Tolerance Rating (DTR) Check Form Document for Boeing 757–200 with Winglets FAA STC Number ST01518SE and EASA STC Number 10015659, Revision August 2023.

(iii) Aviation Partners Boeing AP57.3–0604.2 Supplement to D622N001–9 (Sep 2020) 757 Maintenance Planning Data (MPD) Document Section 9 Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs) 757–300 with Blended Winglets FAA STC ST01518SE and EASA STC Number 10015659, Revision August 2022.

(iv) Aviation Partners Boeing AP57.3–0604.2–DTR Supplement to D622N001–DTR (Oct 2018) 757 Damage Tolerance Rating (DTR) Check Form Document for Boeing 757–300 with Blended Winglets FAA STC Number ST01518SE and EASA STC Number 10015659, Revision August 2023.

(3) For Aviation Partners Boeing material identified in this AD, contact Aviation Partners Boeing, 555 Andover Park West, Suite 200, Tukwila, WA 98188; telephone 206–830–7699; email [leng@aviationpartners.com](mailto:leng@aviationpartners.com); website [aviationpartnersboeing.com](http://aviationpartnersboeing.com).

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on April 23, 2026.

**Steven W. Thompson,**

*Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2026–08304 Filed 4–28–26; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA–2025–2554; Project Identifier MCAI–2025–00014–T; Amendment 39–23316; AD 2026–08–08]**

**RIN 2120–AA64**

#### **Airworthiness Directives; ATR—GIE Avions de Transport Régional Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain ATR—GIE Avions de Transport Régional Model ATR72 airplanes. This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective June 3, 2026.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 3, 2026.

#### **ADDRESSES:**

*AD Docket:* You may examine the AD docket at [regulations.gov](http://regulations.gov) under Docket No. FAA–2025–2554; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

*Material Incorporated by Reference:*

- For European Union Aviation Safety Agency (EASA) material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).