

# Proposed Rules

Federal Register

Vol. 91, No. 83

Thursday, April 30, 2026

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2026-3876; Project Identifier AD-2025-01892-T]

RIN 2120-AA64

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all The Boeing Company Model 757 airplanes. This proposed AD was prompted by reports of crack damage at existing reinforcing repairs in the fuselage frame lower lobe areas in certain sections. This proposed AD would require doing an inspection for any existing reinforcing repairs in the fuselage frame lower lobe areas in certain sections and applicable on-condition actions. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by June 15, 2026.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2026-3876; or in person at

Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

*Material Incorporated by Reference:*

- For Boeing material identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website [myboeingfleet.com](https://myboeingfleet.com).

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2026-3876.

**FOR FURTHER INFORMATION CONTACT:** Wayne Ha, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; 562-627-5238; email: [wayne.ha@faa.gov](mailto:wayne.ha@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under the **ADDRESSES** section. Include “Docket No. FAA-2026-3876; Project Identifier AD-2025-01892-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

**Confidential Business Information**

CBI is commercial or financial information that is both customarily and

actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Wayne Ha, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 562-627-5238; email: [wayne.ha@faa.gov](mailto:wayne.ha@faa.gov). Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Background**

The FAA has received reports of crack damage at existing reinforcing repairs in the fuselage frame lower lobe areas in sections 43 and 46 between stringers S-20 and S-25 from station (STA) 440 to STA 820 and between stringers S-25 and S-28 from STA 1300 to STA 1661, on the left and right sides of the airplane. Removal of one repair revealed crack damage on the first fastener row of a repair splice initiating from the repair fastener hole on the inner frame flange growing to both edges. The repair did not include any post-repair inspections. The reports indicate that existing reinforcing repairs could be lacking necessary post-repair, damage tolerant inspections, which could lead to undetected cracks at the repaired frame locations. This condition, if not addressed, could result in the inability of a principal structural element to sustain limit load, which could adversely affect the structural integrity of the airplane.

**FAA’s Determination**

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

**Material Incorporated by Reference Under 1 CFR Part 51**

The FAA reviewed Boeing Alert Requirements Bulletin 757–53A0129 RB, dated December 8, 2025. This material specifies procedures for performing a general visual inspection (GVI) for any existing reinforcing repairs in the fuselage frame lower lobe areas in sections 43 and 46, between S–20 and S–25 from STA 440 to STA 820 and between S–25 and S–28 from STA 1300 to STA 1661, on the left and right sides

of the airplane, and applicable on-condition actions. On-condition actions include contacting Boeing for further instructions and doing the instructions.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**Proposed AD Requirements in This NPRM**

This proposed AD would require accomplishing the actions specified in

the material already described, except for any differences identified as exceptions in the regulatory text of this proposed AD. For information on the procedures and compliance times, see this material at *regulations.gov* under Docket No. FAA–2026–3876.

**Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 427 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection for existing reinforcing repairs.	Up to 263 work-hours × \$85 per hour = \$22,355.	\$0	Up to \$22,355 .....	Up to \$9,545,585.

The FAA has received no definitive data on which to base the cost estimates for the on-condition actions specified in this proposed AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**The Boeing Company:** Docket No. FAA–2026–3876; Project Identifier AD–2025–01892–T.

**(a) Comment Due Date**

The FAA must receive comments on this airworthiness directive (AD) by June 15, 2026.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all The Boeing Company Model 757–200, –200PF, –200CB, and –300 series airplanes, certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 53, Fuselage.

**(e) Unsafe Condition**

This AD was prompted by reports of crack damage at existing reinforcing repairs in the fuselage frame lower lobe areas in sections 43 and 46. The FAA is issuing this AD to address existing reinforcing repairs in the fuselage frame lower lobe areas that could be lacking post-repair, damage tolerant inspections, which could lead to undetected cracks at repaired frame locations. The unsafe condition, if not addressed, could result in the inability of a principal structural element to sustain limit load, which could adversely affect the structural integrity of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 757–53A0129 RB, dated December 8, 2025, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757–53A0129 RB, dated December 8, 2025.

**Note 1 to paragraph (g):** Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 757–53A0129 dated December 8, 2025, which is referred to in Boeing Alert Requirements Bulletin 757–53A0129 RB, dated December 8, 2025.

**(h) Exceptions to Requirements Bulletin Specifications**

(1) Where the Compliance Time column of the tables in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 757–53A0129 RB, dated December 8, 2025, refers to the original issue date of Requirements

Bulletin 757–53A0129 RB, this AD requires using the effective date of this AD.

(2) Where Boeing Alert Requirements Bulletin 757–53A0129 RB, dated December 8, 2025, specifies contacting Boeing for repair instructions: This AD requires doing the repair and applicable on-condition actions before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: [AMOC@faa.gov](mailto:AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR–520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

#### (j) Additional Information

For more information about this AD, contact Wayne Ha, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; 562–627–5238; email: [wayne.ha@faa.gov](mailto:wayne.ha@faa.gov).

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 757–53A0129 RB, dated December 8, 2025.

(ii) [Reserved]

(3) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; [website myboeingfleet.com](http://website.myboeingfleet.com).

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA,

visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on April 27, 2026.

#### Brian Knaup,

Acting Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2026–08385 Filed 4–29–26; 8:45 am]

BILLING CODE 4910–13–P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 73

[Docket No. FAA–2025–2635; Airspace Docket No. 25–AWA–5]

RIN 2120–AA66

#### Establishment of Prohibited Area P–75; New York, NY

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to establish Prohibited Area 75 (P–75) in the vicinity of the New York, NY, residence of the President of the United States. The United States Secret Service (USSS) requested FAA restrict aircraft operations in the vicinity of President Trump’s New York residence. To provide adequate safeguards for the USSS to fully secure the non-Governmental property and protect USSS protectees in the interest of national security, FAA is proposing to establish a prohibited area in the immediate vicinity of the presidential residence.

**DATES:** Comments must be received on or before June 15, 2026.

**ADDRESSES:** Send comments identified by FAA Docket No. FAA–2025–2635 and Airspace Docket No. 25–AWA–5 using any of the following methods:

- *Federal eRulemaking Portal:* Go to [www.regulations.gov](http://www.regulations.gov) and follow the online instructions for sending your comments electronically.

- *Mail:* Send comments to Docket Operations; U.S. Department of Transportation (DOT), 1200 New Jersey Avenue SE, Room W58–213, West Building 5th Floor, Washington, DC 20590–0001.

- *Hand Delivery or Courier:* Take comments to Docket Operations in Room W58–213 of the West Building 5th Floor at 1200 New Jersey Avenue SE, Washington, DC 20590 between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Fax:* Fax comments to Docket Operations at (202) 493–2251.

*Docket:* Background documents or comments received may be read at [www.regulations.gov](http://www.regulations.gov) at any time. Follow the online instructions for accessing the docket or go to the Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

#### FOR FURTHER INFORMATION CONTACT:

Brian Vidis, Rules and Regulations Group, Policy Directorate, Federal Aviation Administration, 600 Independence Avenue SW, Washington, DC 20597; telephone: (202) 267–8783.

#### SUPPLEMENTARY INFORMATION:

##### I. Executive Summary

FAA proposes to add a regulation to Title 14 of the Code of Federal Regulations (14 CFR) part 73, subpart C to establish a prohibited area in the vicinity of Trump Tower in New York, New York. The prohibited area is necessary according to the United States Secret Service (USSS) to protect the President, secure the non-Governmental property in accordance with the Presidential Protection Assistance Act of 1976, and exercise its authority under 18 U.S.C. 3056(a).<sup>1</sup>

Proposed § 73.95 would create Prohibited Area P–75 (P–75). P–75 would prohibit aircraft operations from the surface to 1,000 feet above ground level (AGL) beginning at lat. 40°45′52″ N, long. 073°57′ 11″ W; then counterclockwise along an arc with a 1 nautical mile (NM) radius centered at lat. 40°45′ 46″ N, long. 073°58′30″ W; to lat. 40°44′48″ N, long. 73°58′ 09″ W, with a straight line to the point of beginning. In other words, P–75 would cover a circle with a 1 NM radius centered on Trump Tower and with a flat edge on the southeast side that parallels the East River. Aircraft operations would not be permitted within P–75 unless the using agency, which would be USSS, granted authorization to enter the area.<sup>2</sup>

##### II. Authority for This Rulemaking

FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator.

<sup>1</sup> Public Law 94–524 (Oct. 17, 1976) enabling the President to designate one non-governmental property to be fully secured by the USSS on a permanent basis.

<sup>2</sup> 14 CFR 73.83 states that “No person may operate an aircraft within a prohibited area unless authorization has been granted by the using agency.”