

publication, as an official document of the Department of Energy. This administrative process in no way alters the legal effect of this document upon publication in the **Federal Register**.

Signed in Washington, DC, on July 15, 2026.

Treena V. Garrett,

Federal Register Liaison Officer, U.S.
Department of Energy.

PART 821—IMPLEMENTING VOLUNTARY AGREEMENTS UNDER THE DEFENSE PRODUCTION ACT

■ Accordingly, the interim final rule that amended chapter III of title 10 of the Code of Federal Regulations by adding part 821, which was published in the **Federal Register** at 90 FR 41279 on August 25, 2025, is adopted as final without change.

[FR Doc. 2026–14461 Filed 7–16–26; 8:45 am]

BILLING CODE 6450–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2025–3436; Project Identifier MCAI–2024–00314–R; Amendment 39–23408; AD 2026–14–07]

RIN 2120–AA64

Airworthiness Directives; Bell Textron Canada Limited Helicopters

AGENCY: Federal Aviation
Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Bell Textron Canada Limited (Bell) Model 407 helicopters. This AD was prompted by a report of a fractured pilot cyclic stick tube and subsequent findings of other pilot cyclic stick tubes with fatigue cracking. This AD requires repetitively inspecting the pilot cyclic stick tube assembly for a crack and, depending on the results, repairing or replacing the pilot cyclic stick tube assembly. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective August 21, 2026.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 21, 2026.

ADDRESSES:

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2025–3436; or in person at

Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–91, West Building Fifth Floor, Room W58–213, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For Transport Canada material identified in this AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario, K1A 0N5, Canada; phone: (888) 663–3639; email: tc.airworthinessdirectives-consignesdenavigabilite.TC@tc.gc.ca; website: tc.canada.ca/en/aviation. You may find the Transport Canada material on the Transport Canada website at tc.canada.ca/en/aviation.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 10101 Hillwood Parkway, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2025–3436.

FOR FURTHER INFORMATION CONTACT:

Alexis Whitaker, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (516) 228–7309; email: alexis.j.whitaker@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bell Model 407 helicopters. The NPRM was published in the **Federal Register** on November 18, 2025 (90 FR 51602). The NPRM was prompted by AD CF–2024–18, dated May 29, 2024 (Transport Canada AD CF–2024–18) (also referred to as the MCAI), issued by Transport Canada, which is the aviation authority for Canada. The MCAI states that Bell received a report that a pilot cyclic stick tube assembly having part number (P/N) 206–001–342–101 fractured at the lower end of the tube near the upper slotted area where it is held in place in the pivot assembly. Examination of the fractured pilot cyclic stick tube and subsequent findings of other cracked pilot cyclic stick tubes revealed fatigue cracking. Further investigation identified the root cause of the pilot cyclic stick tube cracking as the

application of excessive force to the cyclic stick during the freedom of movement of the controls and cyclic centering light operation check as part of the interior and prestart check, which resulted in elevated stress at the slotted area and was aggravated by the high stress concentration design feature of the upper slotted area.

In the NPRM, the FAA proposed to require repetitively inspecting the pilot cyclic stick tube assembly for cracking and, depending on the results, repairing or replacing the pilot cyclic stick tube assembly. The FAA is issuing this AD to detect and correct a crack in the pilot cyclic stick tube which, if not addressed, could lead to an in-flight failure of the pilot cyclic stick tube and consequent loss of control of the helicopter.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2025–3436.

Discussion of Final Airworthiness Directive

Comments

The FAA received comments from the Citizens Rulemaking Alliance. The following presents the comments received on the NPRM and the FAA's response to each comment.

Request To Issue an NPRM or Justify Forgoing Notice and Comment

The Citizens Rulemaking Alliance requested that the FAA either convert this action to an NPRM or provide its justification for finding good cause to bypass notice and comment procedures, extend the effective date to at least 30 days after publication, commit in the preamble to responding to comments, and adjust the AD accordingly within a defined short timeframe. Alternatively, the commenter requested that the AD record be supplemented to provide a more specific explanation tied to the particular failure mode why an NPRM was impracticable. The commenter asserted the FAA has not adequately justified use of the good cause exemption to bypass notice and comment and the 30-day delayed effective date.

The FAA notes the comment was submitted in response to an NPRM for which the FAA provided a 45-day comment period. This final rule is effective 35 days after its publication in the **Federal Register**. Therefore, no change to this AD is necessary.

Request To Comply With the Paperwork Reduction Act (PRA)

The Citizens Rulemaking Alliance requested that the FAA revise the proposed AD to comply with the PRA

if reporting is required or suspend any reporting provisions until PRA requirements are satisfied. If reporting is not required, the commenter requested the FAA clarify that in the AD.

The FAA notes paragraph (i) of this AD specifies that this AD does not require reporting. If an AD were to require reporting, the preamble of the final rule would include a paragraph titled “Paperwork Reduction Act” that would provide the applicable OMB control number, required PRA statements, and the estimated time to collect the required information (burden). Any costs associated with the reporting requirement would be included in the Costs of Compliance section in the preamble of the final rule. Therefore, the FAA did not change this AD as a result of this comment.

Request To Make Incorporation by Reference (IBR) Materials Reasonably Available

The Citizens Rulemaking Alliance stated that the FAA’s current practices for IBR frequently fail to meet the legal and regulatory standards for reasonable availability. The commenter called on the FAA to guarantee that all IBR materials are easily and freely accessible to the public and affected parties for both commenting and compliance purposes. The commenter also requested that this access be documented in the rulemaking record.

The FAA notes that this AD incorporates by reference Transport Canada AD CF–2024–18, not the manufacturer service information referenced in that Transport Canada AD. The FAA posted Transport Canada AD CF–2024–18 to the AD docket when the NPRM was published in the **Federal Register**. The material referenced in Transport Canada AD CF–2024–18 may only be posted before the final rule’s publication if it is already publicly available or if there is written consent from the owner of that material. Additionally, the FAA provided notice in the NPRM that the material referenced in Transport Canada AD CF–2024–18 will be available in the AD docket after this AD is published. Therefore, the FAA did not change this AD as a result of this comment.

Request To Consider Impact on Small Entities and Compliance Costs

The Citizens Rulemaking Alliance requested that the FAA expand the proposed economic analysis to consider the impacts on small-entities and to offer explicit alternatives where

justified. The commenter argued that the FAA’s standard labor rate of \$85 per work-hour underestimates total labor costs and downtime experienced by operators and maintenance providers. The commenter instead suggested a labor rate between \$110 and \$140 per work-hour, in addition to accounting for costs related to ferry flights, lost revenue, and parts scarcity.

Compliance Costs

The FAA has determined that the current labor rate of \$85 per hour remains accurate for this AD. The FAA evaluates this rate periodically, based on U.S. Bureau of Labor Statistic data found at data.bls.gov/oes, and will change the rate when appropriate. The FAA used a blended wage rate to estimate the labor rate for this AD, where the FAA assumes 60 percent weight for aircraft mechanics (at a fully burdened mean wage rate of \$69.85 per hour) and 40 percent for general and operations managers (at a fully burdened mean wage rate of \$108.15 per hour). To calculate the blended wage rate, the FAA multiplied each wage rate by its corresponding weight and added up the products to obtain a wage rate of \$85.17, which the FAA rounded down to \$85.

The FAA also recognizes that, in doing the actions required by an AD, operators might incur indirect or incidental costs in addition to the direct costs. The cost analysis in an AD typically describes only the direct costs of the specific actions required by an AD, which does not include indirect or incidental costs such as downtime, loss of revenue, planning, or time necessitated by other administrative actions since those costs might vary significantly among operators. In the Cost of Compliance section of the proposed AD, the FAA disclosed the estimated number of work hours, the number of helicopters affected on the U.S. registry (updated in this final rule), and an estimated parts cost. Since the FAA has assessed and disclosed the total known costs of the AD requirements in the Costs of Compliance section of the proposed AD, and the commenter did not provide additional cost data for the FAA to consider in its cost analysis, it is not necessary to provide additional cost information for this AD.

Small Entities to Which This AD Applies

The FAA has considered the AD’s impact on small businesses and

provides the following factual basis for its Regulatory Flexibility Act (RFA) certification.

The Regulatory Flexibility Act of 1980, Public Law 96–354, 94 Stat. 1164 (5 U.S.C. 601–612), as amended by the Small Business Regulatory Enforcement Fairness Act of 1996 (Pub. L. 104–121, 110 Stat. 857, Mar. 29, 1996) and the Small Business Jobs Act of 2010 (Pub. L. 111–240, 124 Stat. 2504, Sept. 27, 2010), requires Federal agencies to consider the effects of the regulatory action on small business and other small entities and to minimize any significant economic impact. The term “small entities” comprises small businesses and not-for-profit organizations that are independently owned and operated and are not dominant in their fields, and governmental jurisdictions with populations of less than 50,000.

The FAA used the definition of small entities in the RFA for this analysis. The RFA defines small entities as small businesses, small governmental jurisdictions, or small organizations. In 5 U.S.C. 601(3), the RFA defines “small business” to have the same meaning as “small business concern” under section 3 of the Small Business Act. The Small Business Act authorizes the Small Business Administration (SBA) to define “small business” by issuing regulations.

The SBA (2023) has established size standards for various types of economic activities, or industries, under the North American Industry Classification System (NAICS). These size standards generally define small businesses based on the number of employees or annual receipts. Note that the SBA definition of a small business applies to the parent company and all affiliates as a single entity.

To identify small entities, the FAA first identified the primary NAICS of the entity or parent company, and then used data from different sources (*e.g.*, company annual reports, Bureau of Transportation Statistics) to determine whether the entity meets the applicable size standard. This AD will affect approximately 299 domestic entities, of which the FAA identified approximately 91 as small entities. The table below presents the industries of the small entities, the average annual revenue, and the AD’s estimated low-case and high-case cost burden relative to that average annual revenue.

ESTIMATED NUMBER OF SMALL ENTITIES BY INDUSTRY AND COST SIGNIFICANCE

NAICS code	Description	Affected small entities	Average annual revenue ¹ (\$)	Average per-entity impact (cost/revenue)	
				Low-case (%)	High-case (%)
111998	All Other Miscellaneous Crop Farming.	1	368,190	0.18	0.55
112990	All Other Animal Production	3	510,257	0.16	0.58
115210	Support Activities for Animal Production.	1	7,270,000	0.01	0.03
211120	Crude Petroleum Extraction	1	37,500,000	0.00	0.01
236115	New Single-family Housing Construction (Except For-Sale Builders).	1	16,690,000	0.00	0.01
237120	Oil and Gas Pipeline and Related Structures Construction.	1	10,780,000	0.01	0.02
237210	Land Subdivision	1	2,340,000	0.03	0.09
237310	Highway, Street, and Bridge Construction.	2	27,810,000	0.00	0.01
238160	Roofing Contractors	1	2,850,000	0.01	0.07
332994	Small Arms, Ordnance, and Ordnance Accessories Manufacturing.	1	10,030,000	0.00	0.02
333241	Food Product Machinery Manufacturing.	1	23,510,000	0.00	0.01
336413	Other Aircraft Part and Auxiliary Equipment Manufacturing.	1	3,050,000	0.01	0.07
336612	Boat Building	1	13,210,000	0.00	0.02
423520	Coal and Other Mineral and Ore Merchant Wholesalers.	1	2,680,000	0.01	0.08
423690	Other Electronic Parts and Equipment Merchant Wholesalers.	1	9,870,000	0.00	0.02
423860	Transportation Equipment and Supplies (except Motor Vehicle) Merchant Wholesalers.	1	1,050,000	0.19	0.58
424720	Petroleum and Petroleum Products Merchant Wholesalers (except Bulk Stations and Terminals).	1	68,740,000	0.00	0.00
425120	Wholesale Trade Agents and Brokers.	1	86,250	0.79	2.35
441110	New Car Dealers	1	1,950,000	0.01	0.10
445320	Beer, Wine, and Liquor Retailers ..	1	1,460,000	0.01	0.14
481211	Nonscheduled Chartered Passenger Air Transportation.	9	4,472,556	0.17	0.55
481212	Nonscheduled Chartered Freight Air Transportation.	1	4,470,000	0.02	0.05
481219	Other Nonscheduled Air Transportation.	27	4,046,684	0.15	0.59
482111	Line Haul Railroads	1	120,380,000	0.00	0.00
483111	Deep Sea Freight Transport	1	85,390,000	0.00	0.00
487990	Scenic and Sightseeing Transportation, Other.	5	1,410,280	0.31	0.91
488190	Other Support Activities for Air Transportation.	1	4,590,000	0.01	0.04
523999	Miscellaneous Financial Investment Activities.	1	1,020,000	0.07	0.20
531210	Offices of Real Estate Agents and Brokers.	1	7,770,000	0.00	0.03
532411	Commercial Air, Rail, and Water Transportation Equipment Rental and Leasing.	5	6,707,156	0.08	0.37
541330	Engineering Services	1	10,250,000	0.00	0.04
541715	Other Aircraft Parts and Auxiliary Equipment.	1	308,970	0.22	0.66
551112	Offices of Other Holding Companies.	1	319,540	0.06	0.63
561110	Office Administrative Services	2	995,205	0.06	0.52
611512	Flight Training	6	815,272	0.15	0.63
611620	Sports and Recreation Instruction	1	1,070,000	0.08	0.38
621910	Ambulance Services	4	11,147,500	0.11	0.44

¹ Source: Dun & Bradstreet, D&B Hoovers, retrieved April 28, 2026, app.hoovers.dnb.com; ZoomInfo, ZoomInfo Technologie Inc., retrieved April 28, 2026, zoominfo.com.

Small Entity Impacts

While the FAA has determined that this final rule affects a substantial number of small entities, the compliance costs of the AD relative to each small entity’s annual revenue is minimal in both the low- and high-case scenarios. In the high-case scenario, the AD’s cost as a percentage of annual revenue imposes a mean impact of 0.46 percent. Therefore, as provided in section 605(b), the FAA certifies that this AD will not result in a significant economic impact on a substantial number of small entities.

The FAA did not change this AD as a result of this comment.

Conclusion

These products have been approved by the civil aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed Transport Canada AD CF–2024–18, which specifies procedures for revising the applicable Bell 407 rotorcraft flight manual (RFM) Normal Procedures section to limit the allowable freedom of movement during

interior and prestart checks for certain serial-numbered helicopters (Group 1 helicopters). Transport Canada AD CF–2024–18 also specifies procedures for inspecting the pilot cyclic stick tube assembly for cracks and replacing or repairing and reidentifying any cracked pilot cyclic stick tube assembly for certain other serial-numbered helicopters (Group 2 helicopters). If, as a result of an inspection, a pilot cyclic stick tube assembly is repaired rather than replaced, Transport Canada AD CF–2024–18 further specifies procedures for repetitive inspections of the repaired pilot cyclic stick tube assembly and replacement within 24 months after the repair. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Differences Between This AD and the MCAI

The MCAI only applies to helicopter serial numbers 53000 through 53900, 53911 through 53999, 54000 through 54166, 54300 through 54800, 54805 through 54999, 56300 through 56305, and 56311 through 56315, whereas this AD applies to all serial numbered Model 407 helicopters with cyclic stick tube assembly P/N 206–001–342–101 or P/N 206–001–342–101FM installed.

The MCAI specifies procedures for revising the applicable Bell 407 RFM Normal Procedures section for certain serial-numbered helicopters to limit the allowable freedom of movement during interior and prestart checks, whereas this AD does not because the full sweep for freedom of movement is necessary to clear icing and detect any jamming or binding during the pre-start check.

This AD also adds a repetitive inspection for pilot cyclic stick tube assemblies that have accumulated 3,600 or more hours time-in-service, at intervals not to exceed every 300 hours time-in-service or 6 months, whichever occurs first. This is from a determination that a pilot cyclic control stick could experience high loading during hydraulic-off training and other emergency procedure situations. This inspection is not part of the MCAI.

Interim Action

The FAA considers that this AD is to be an interim action. If final action is later identified, the FAA might consider further rulemaking.

Costs of Compliance

The FAA estimates that this AD affects 972 helicopters of U.S. registry, of which 651 helicopters would have or will accumulate 3,600 hours time-in-service within the 2-year analysis period. The FAA estimates the following costs to comply with this AD.

The FAA estimates operators of all helicopters will incur an initial inspection cost of \$340, and operators of a helicopter with over 3,600 hours time-in-service will also incur a recurrent inspection cost of \$340. Repetitive inspections will occur once per inspection cycle, which is either every 6 months or every 300 hours time-in-service. The FAA assumes that the inspection cycle is 6 months for each helicopter. Based upon the results of an inspection, operators could incur three conditional repair costs. The FAA cannot estimate the number of conditional repairs each operator would need to undertake. The table below presents the estimated costs for required inspections and any conditional repair and replacement costs.

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product
Required: Inspect pilot cyclic stick tube assembly	Up to 4 work-hours × \$85 per hour = \$340	\$0	\$340
Conditional: Repair pilot cyclic stick tube assembly	6 work-hours × \$85 per hour = \$510	0	510
Conditional: Repetitively inspect pilot cyclic stick tube assembly.	2 work-hours (per inspection) × \$85 per hour = \$170	0	170
Conditional: Replace pilot cyclic stick tube assembly ..	2 work-hours × \$85 per hour = \$170	1,544	1,714

The FAA used a 2-year analysis period for estimating the costs of this AD. Because the FAA cannot estimate the number of helicopters which would need repair or replacement, the FAA has created a low-case and high-case cost scenario. In the low-case scenario,

helicopters would only incur inspections costs. In the high-case scenario, all helicopters would have to replace their pilot cyclic sticks based upon the results of their initial inspection.

In the low-case scenario, all 972 helicopters would incur an initial inspection cost of \$340, and all helicopters with over 3,600 hours time-in-service (651 helicopters) would undergo 3 repetitive inspections of \$340 each. In the high-case scenario, all 972

helicopters would incur an initial inspection cost of \$340 and an initial pilot cyclic repair cost of \$510. All 972 helicopters would then undergo 3 repetitive inspections of \$510 (the sum

of the required \$340 inspection cost and \$170 conditional inspection cost). In year 2 of the analysis period, all helicopters would incur a \$1,714 cost to replace their pilot cyclic tube. The

tables below present the costs associated with the low- and high-case scenarios and a summary of the total costs of this AD.

LOW-CASE INSPECTION COST

Year	Affected helicopters	Initial inspections	Recurrent inspections	Inspection cost	Repair/replacement cost	Total cost
1	972	972	651	\$551,820	\$0	\$551,820
2	651	0	1,302	442,680	0	442,680
Total		972	1,953	994,500	0	994,500

HIGH-CASE INSPECTION AND REPAIR COST

Year	Affected helicopters	Initial inspections	Recurrent inspections	Inspection cost	Repair/replacement cost	Total cost
1	972	972	972	\$826,200	\$495,720	\$1,321,920
2	972	0	1,944	991,440	1,666,008	2,657,448
Total		972	2,916	1,817,640	2,161,728	3,979,368

SUMMARY OF COSTS

Industry costs	Present value			Annualized	
	Undiscounted	7%	3%	7%	3%
Low-Case Cost	\$994,500	\$902,373	\$953,016	\$499,095	\$498,056
High-Case Cost	3,979,368	3,556,557	3,788,317	1,967,103	1,979,816

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2026–14–07 Bell Textron Canada Limited:
Amendment 39–23408; Docket No. FAA–2025–3436; Project Identifier MCAI–2024–00314–R.

(a) Effective Date

This airworthiness directive (AD) is effective August 21, 2026.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bell Textron Canada Limited Model 407 helicopters, certificated in any category, with a pilot cyclic stick tube assembly part number (P/N) 206–001–342–101 or P/N 206–001–342–101FM installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 6710, Main rotor control.

(e) Unsafe Condition

This AD was prompted by a report of a fractured pilot cyclic stick tube and subsequent findings of other pilot cyclic stick tubes with fatigue cracking. The FAA is issuing this AD to detect and correct a crack in the pilot cyclic stick tube which, if not addressed, could lead to an in-flight failure of the pilot cyclic stick tube and consequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Transport Canada AD CF–2024–18, dated May 29, 2024 (Transport Canada AD CF–2024–18).

(2) For a pilot cyclic stick tube assembly that has accumulated 3,600 or more hours time-in-service if, after complying with paragraph (g)(1) of this AD, no cracks are identified, thereafter, at intervals not to exceed 300 hours time-in-service or 6 months, whichever occurs first, perform a detailed inspection of the pilot cyclic stick tube assembly in accordance with Part II paragraph A. of Transport Canada AD CF–2024–18.

(h) Exceptions to Transport Canada AD CF–2024–18

(1) Where Transport Canada AD CF–2024–18 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where Transport Canada AD CF–2024–18 requires compliance in terms of air time, this AD requires using hours time-in-service.

(3) This AD does not adopt Part I, Rotorcraft Flight Manual (RFM) Revision-Applicable to Group 1 Helicopters, of Transport Canada AD CF–2024–18.

(4) Where Transport Canada AD CF–2024–18 states “Part II-Inspection and Replacement or Repair of Cyclic Stick Tube Assembly-Applicable to Group 2 Helicopters”, this AD requires replacing that text with “Part II-Inspection and Replacement or Repair of Cyclic Stick Tube Assembly-All Helicopters”.

(i) No Reporting Requirement

Although the material referenced in Transport Canada AD CF–2024–18 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Additional Information

For more information about this AD, contact Alexis Whitaker, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite

410, Westbury, NY 11590; phone: (516) 228–7309; email: alexis.j.whitaker@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Transport Canada AD CF–2024–18, dated May 29, 2024.

(ii) [Reserved].

(3) For Transport Canada material identified in this AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario, K1A 0N5, Canada; phone: (888) 663–3639; email: tc.airworthinessdirectives-consignesdenavigabilite.TC@tc.gc.ca; website: tc.canada.ca/en/aviation. You may find the Transport Canada material on the Transport Canada website at tc.canada.ca/en/aviation.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 10101 Hillwood Parkway, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on July 9, 2026.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2026–14481 Filed 7–16–26; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2026–7216; Project Identifier MCAI–2026–00693–A; Amendment 39–23409; AD 2026–14–08]

RIN 2120–AA64

Airworthiness Directives; Diamond Aircraft Industries GmbH

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Diamond Aircraft Industries GmbH (DAI) Model DA 42, DA 42 NG, and DA 42 M–NG airplanes. This AD was prompted by occurrences of uncommanded rudder deflection caused by a cracked nose landing gear (NLG)

hydraulic actuator rod end, which could lead to failure of the NLG actuator and interference with the rudder control system, forcing the rudder into left-hand deflection. This AD requires revising the existing airplane flight manual (AFM) for your airplane to provide the flight crew with revised operating limitations, repetitively inspecting certain NLG hydraulic actuator rod ends for cracks, deformation, corrosion, damage, and free movement of the spherical bearing, and depending on the results of any inspection, replacing the affected NLG hydraulic actuator rod end with a serviceable part. This AD also prohibits the installation of an affected NLG hydraulic actuator rod end unless certain conditions are met. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 20, 2026.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 20, 2026.

The FAA must receive comments on this AD by August 31, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2026–7216; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For Diamond Aircraft material identified in this AD, contact DAI, N.A. Otto-Straße 5, A–2700 Wiener Neustadt, Austria; phone: +43 2622 26700; email: office@diamond-air.at; website: diamondaircraft.com/.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 1100 Main, Kansas City, MO 64105. For information