

(4) You may view this material at FAA, Airworthiness Products Section, Operational Safety Branch, 10101 Hillwood Parkway, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on July 20, 2026.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2026-14881 Filed 7-22-26; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2026-7226; Project Identifier MCAI-2025-01346-R]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus Helicopters (AH) Model EC130B4 helicopters. This proposed AD was prompted by reports of weaknesses in the locking mechanisms on the left-hand side swinging and sliding door. This proposed AD would require modifying the swinging door star support and sliding door star support stringer. This proposed AD would also prohibit installing an affected composite door on any helicopter unless certain requirements are met. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by September 8, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2026-7226; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this proposed AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 10101 Hillwood Parkway, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

FOR FURTHER INFORMATION CONTACT:

Thanh Tran, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (562) 275-5304; email: thanh.b.tran@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under **ADDRESSES**. Include “Docket No. FAA-2026-7226; Project Identifier MCAI-2025-01346-R” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Peter Schmitt, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued AD 2020-25-11, Amendment 39-21353 (85 FR 81376, December 16, 2020) (AD 2020-25-11), for certain AH Model EC120B and Model EC130B4 helicopters. AD 2020-25-11 was prompted by an AD originated by EASA, which is the Technical Agent for the Member States of the European Union. EASA issued EASA AD 2020-0095, dated April 29, 2020 (EASA AD 2020-0095), to correct an unsafe condition for certain AH Model EC 120 B and Model EC 130 B4 helicopters. EASA AD 2020-0095 states that several incidents on the left-hand side swing and sliding doors have revealed some weaknesses in the locking mechanism. The results of the subsequent investigation identified a sliding door star support failure, which could inhibit the operation of the sliding door from the inside and delay the evacuation of passengers during an emergency.

AD 2020-25-11 requires modifying the sliding door star support stringer on certain AH Model EC120B and AH Model EC130B4 helicopters. The FAA issued AD 2020-25-11 to address failure of the sliding door star support, which could inhibit the operation of the sliding door from the inside and delay the evacuation of passengers during an emergency.

Actions Since AD 2020–25–11 Was Issued

Since the FAA issued AD 2020–25–11, EASA issued AD 2024–0232, dated December 5, 2024 (EASA AD 2024–0232) (also referred to as the MCAI). The MCAI states that since EASA AD 2020–0095 was issued, it has been identified that AH Model EC130B4 helicopters that have embodied EC MOD 07 3796 were erroneously excluded from the applicability. All AH Model EC130B4 helicopters were also excluded from AD 2020–25–11.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2026–7226.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed EASA AD 2024–0232, which specifies procedures for modifying the door locking/unlocking mechanism by installing a reinforcing bracket and replacing rod ends and prohibits installing a composite door on any helicopter unless this modification is accomplished. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination

These products have been approved by the civil aviation authority (CAA) of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, that

authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2024–0232, described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this proposed AD. See “Differences Between this Proposed AD and the MCAI” for a discussion of the general differences included in this proposed AD.

Differences Between This Proposed AD and the MCAI

EASA AD 2024–0232 specifies to accomplish the modification of the locking/unlocking mechanism within 24 months. This proposed AD would require the modification to be accomplished within 460 hours time-in-service (TIS) based on an average of 230 hours TIS per year. The FAA has determined this compliance time represents the maximum interval of time allowable for the affected helicopters to continue to safely operate before the modification is done.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD

process, the FAA developed a process to use some CAA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2024–0232 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2024–0232 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2024–0232 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2024–0232. Material required by EASA AD 2024–0232 for compliance will be available at *regulations.gov* under Docket No. FAA–2026–7226 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 214 helicopters of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS				
Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Perform modification	20 work-hours × \$85 per hour = \$1,700	\$642	\$2,342	\$501,188

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds

necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus Helicopters: Docket No. FAA–2026–7226; Project Identifier MCAI–2025–01346–R.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by September 8, 2026.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus Helicopters Model EC130B4 helicopters, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 5200, Doors.

(e) Unsafe Condition

This AD was prompted by reports of weaknesses in the locking mechanisms on the left-hand side swing and sliding door. The FAA is issuing this AD to address failure of the sliding door star support, which could inhibit the operation of the sliding door from the inside, and delay the evacuation of passengers during an emergency.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency AD 2024–0232, dated December 5, 2024 (EASA AD 2024–0232).

(h) Exceptions to EASA AD 2024–0232

(1) Where EASA AD 2024–0232 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph (1) of EASA AD 2024–0232 specifies to complete the actions within 24 months after its effective date, this AD requires completion within 460 hours time-in-service after the effective date of this AD.

(3) Where the material referenced in EASA AD 2024–0232 specifies performing a dye penetrant inspection, for the purposes of this AD, it is not permitted to use Type 2 colored

dye penetrant for inspections required by paragraph (g) of this AD.

(4) Where the material referenced in EASA AD 2024–0232 specifies discarding certain parts, this AD requires removing those parts from service.

(5) Where the material referenced in EASA AD 2024–0232 specifies “check”, this AD requires replacing that text with “inspect”.

(6) This AD does not adopt the “Remarks” section of EASA AD 2024–0232.

(i) No Reporting Requirement

Although the material referenced in EASA AD 2024–0232 specifies to submit certain information to the manufacturer, this AD does not require that action.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Additional Information

For more information about this AD, contact Thanh Tran, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (562) 275–5304; email: thanh.b.tran@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2024–0232, dated December 5, 2024.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 10101 Hillwood Parkway, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on July 20, 2026.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2026–14886 Filed 7–22–26; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2026–7225; Project Identifier MCAI–2023–01036–E]

RIN 2120–AA64

Airworthiness Directives; Rolls-Royce Deutschland Ltd & Co KG Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2023–12–16, which applies to certain Rolls-Royce Deutschland Ltd & Co KG (RRD) Model Trent 1000 engines. AD 2023–12–16 requires an inspection of the high-pressure turbine (HPT) triple seal for excessive wear and, depending on the results of the inspection, replacement of the HPT triple seal and the intermediate-pressure turbine (IPT) disk. Since the FAA issued AD 2023–12–16, the manufacturer has developed a modification that removes the need for the inspection of the HPT triple seal. This proposed AD would continue to require an inspection of the HPT triple seal for excessive wear and, depending on the results of the inspection, replacement of the HPT triple seal and IPT disk. This proposed AD would remove certain engine serial numbers from the applicability of the existing AD. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by September 8, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.
- *Fax:* (202) 493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5