

under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus SAS: Docket No. FAA–2026–4639; Project Identifier MCAI–2025–01360–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by July 6, 2026.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS Model A330–841 and Model A330–941 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by reports of crack findings on the sloping rib. The FAA is issuing this AD to address cracking on the sloping rib. The unsafe condition, if not addressed, could affect the handling qualities of the airplane, which could result in reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2025–0179, dated August 13, 2025 (EASA AD 2025–0179).

(h) Exceptions to EASA AD 2025–0179

(1) Where EASA AD 2025–0179 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph (2) of EASA AD 2025–0179 specifies “If any damage is found on a sloping rib, before next flight, contact Airbus for approved repair instructions and, within the compliance time specified therein,

accomplish those instructions accordingly”, this AD requires replacing that text with “If any cracking is detected on a sloping rib during any inspection required by this AD, the cracking must be repaired before further flight using a method approved by the Manager, AIR–520, Continued Operational Safety Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature. If any damage other than cracking is detected on a sloping rib during any inspection required by this AD, before next flight, contact Airbus for approved instructions and, within the compliance time identified therein, accomplish those instructions accordingly.”

(3) This AD does not adopt the “Remarks” section of EASA AD 2025–0179.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Continued Operational Safety Branch, FAA; or EASA; or Airbus SAS’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (i)(2) of this AD, if any material referenced in EASA AD 2025–0179 contains paragraphs that are labeled as RC, the instructions in RC paragraphs, including subparagraphs under an RC paragraph, must be done to comply with this AD; any paragraphs, including subparagraphs under those paragraphs, that are not identified as RC are recommended. The instructions in paragraphs, including subparagraphs under those paragraphs, not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the instructions identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to instructions identified as RC require approval of an AMOC.

(j) Additional Information

For more information about this AD, contact Bill Ashforth, Aviation Safety

Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3520; email: Bill.ashforth@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2025–0179, dated August 13, 2025.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on May 15, 2026.

Lona C. Saccomando,

Acting Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2026–10047 Filed 5–19–26; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2026–4640; Project Identifier MCAI–2024–00073–E]

RIN 2120–AA64

Airworthiness Directives; Rolls-Royce Deutschland Ltd & Co KG Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Rolls-Royce Deutschland Ltd & Co KG (RRD) Model Trent7000–72 and Trent7000–72C engines. This proposed AD was prompted by reports of engine in-flight shut-downs (IFSDs) caused by the premature failure of certain parts. This proposed AD would prohibit the installation of certain lubrication/scavenge pumps unless certain

installation criteria are met. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by July 6, 2026.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2026-4640; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

FOR FURTHER INFORMATION CONTACT:

Barbara Caufield, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (781) 238-7146; email: barbara.caufield@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under **ADDRESSES**. Include “Docket No. FAA-2026-4640; Project Identifier MCAI-2024-00073-E” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any

recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Barbara Caufield, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2024-0029, dated January 29, 2024 (EASA AD 2024-0029) (also referred to as the MCAI), to correct an unsafe condition on RRD Model Trent7000-72 and Trent7000-72C engines. The MCAI states that there have been reports of engine IFSDs prompted by low oil pressure indications. An investigation revealed that these events were caused by early-life failure of the internal eccentric ring/gerotor in certain affected lubrication/scavenge oil pumps due to eccentric contact between the ring and gerotor causing wear on the components. To address this potential unsafe condition, the manufacturer published service material that provides installation criteria for the affected oil pumps. This condition, if not corrected,

could result in failure of the affected oil pump, and engine IFSD with consequent reduced control or loss of control of the airplane.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2026-4640.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed EASA AD 2024-0029, which specifies installation criteria for affected oil pumps each time an affected part is installed or reinstalled on an engine. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

These products have been approved by the civil aviation authority (CAA) of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2024-0029, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some CAA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, EASA AD 2024-0029 is incorporated by reference in this AD. This AD requires compliance with EASA AD 2024-0029 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using common terms that are the same as the heading of a particular section in EASA AD 2024-0029 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required

actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2024–0029. Material required by EASA AD 2024–

0029 for compliance will be available at *regulations.gov* under Docket No. FAA–2026–4640 after this AD is published.

engines, installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 98

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Verify installation criteria before each pump installation.	.50 work-hours × \$85 per hour = \$42.50	\$0	\$42.50	\$4,165

The FAA estimates the following costs to do any necessary screening tests that would be required based on the

results of the proposed installation criteria verification. The agency has no way of determining the number of

engines that might need these screening tests:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Perform oil pump screening test	4 work-hours × \$85 per hour = \$340	\$0	\$33,320

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Rolls-Royce Deutschland Ltd & Co KG:
Docket No. FAA–2026–4640; Project Identifier MCAI–2024–00073–E.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by July 6, 2026.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Rolls-Royce Deutschland Ltd & Co KG Model Trent7000–72 and Trent7000–72C engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7261, Turbine Engine Oil System.

(e) Unsafe Condition

This AD was prompted by reports of engine in-flight shut-downs (IFSDs) due to low oil pressure indications, which were caused by the early-life failure of the internal eccentric ring/gerotor. The FAA is issuing this AD to require certain installation criteria be met for affected oil pumps prior to installation or reinstallation on an engine. The unsafe condition, if not addressed, could result in failure of the affected oil pump, and engine IFSD with consequent reduced control or loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraph (h) of this AD, perform all required actions within the compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2024–0029, dated January 29, 2024 (EASA AD 2024–0029).

(h) Exceptions to EASA AD 2024–0029

(1) Where EASA AD 2024–0029 requires compliance from its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph (1) of EASA AD 2024–0029 states “From the effective date of this AD, it is allowed to install an affected part on any engine, or an engine equipped with an affected part on any airplane, provided that, prior to installation, it is determined

that the installation criteria defined in the NMSB are met”, this AD requires replacing that text with “From the effective date of this AD, do not install an affected part unless the installation criteria defined in the NMSB are met”.

(3) This AD does not adopt the “Remarks” paragraph of EASA AD 2024–0029.

(i) Alternative Methods of Compliance (AMOCs)

The Manager, AIR–520 Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager, AIR–520 Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Additional Information

For more information about this AD, contact Barbara Caufield, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (781) 238–7146; email: barbara.caufield@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2024–0029, dated January 29, 2024.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu; website: easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on May 15, 2026.

Lona C. Saccomando,

Acting Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2026–10076 Filed 5–19–26; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF JUSTICE

Drug Enforcement Administration

21 CFR Parts 1303 and 1315

[Docket No. DEA–1278]

RIN 1117–AB86

Revision of Applications for Manufacturing and Procurement Quotas

AGENCY: Drug Enforcement Administration, Department of Justice.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Drug Enforcement Administration (DEA) proposes to revise existing regulations relating to the management of quotas for schedule I and II controlled substances and the list I chemicals, ephedrine, pseudoephedrine, and phenylpropanolamine, to be utilized by DEA-registered manufacturers. This rule is being proposed to: restructure DEA’s manufacturing and procurement quota regulations for more clarity and consistency; clarify which use-specific subcategories for quotas should be used for controlled substances that will be sold domestically and controlled substances that will be exported; and revise the applications for individual manufacturing and procurement quota. The changes are necessary to increase visibility into the controlled substance supply chain by providing DEA with more detailed information allowing the agency to react more precisely in preventing drug shortages; and to ensure that enough of the schedule I and II controlled substances and three list I chemicals can be manufactured to meet estimated scientific, medical, lawful export, and inventory needs. This rule also contains revisions to use gender neutral language and other non-substantive revisions.

DATES: Comments must be received by July 20, 2026. Commenters should be aware that the electronic Federal Docket Management System will not accept comments after 11:59 p.m. Eastern Time on the last day of the comment period.

ADDRESSES: Comments must be submitted in one of the following two ways (please choose only one of the ways listed):

- Electronically at <https://www.regulations.gov>. Follow the “Submit a comment” instructions. If you are reading this document on federalregister.gov, you may use the green “SUBMIT A PUBLIC COMMENT” button beneath this rulemaking’s title to submit a comment to the [regulations.gov](https://www.regulations.gov) docket.

- You may mail written comments to the following address: Drug Enforcement Administration, Attn: DEA Federal Register Representative/DPW, 8701 Morrisette Drive, Springfield, Virginia 22152. Mailed comments must be received by the close of the comment period.

Do not include any personally identifiable information (such as name, address, or other contact information) or confidential business information that you do not want publicly disclosed. All comments are public records; they are publicly displayed exactly as received, and will not be deleted, modified, or redacted. Comments may be submitted anonymously.

Follow the search instructions on <https://www.regulations.gov> to view public comments.

FOR FURTHER INFORMATION CONTACT: Heather Achbach, Regulatory Drafting & Policy Section, Diversion Control Division, Drug Enforcement Administration; Telephone: (571) 776–3882.

SUPPLEMENTARY INFORMATION:

Posting of Public Comments

Please note that all comments received in response to this docket are considered part of the public record. The Drug Enforcement Administration (DEA) will make all comments available for public inspection online at <http://www.regulations.gov>. Such information includes personal or business identifiers (such as name, address, state or federal identifiers, etc.) voluntarily submitted by the commenter. Generally, all information voluntarily submitted by the commenter, unless clearly marked as Confidential Information in the method described below, will be publicly posted. Comments may be submitted anonymously. The Freedom of Information Act applies to all comments received.

Commenters submitting comments which include personal identifying information (PII), confidential, or proprietary business information that the commenter does not want made publicly available should submit two copies of the comment. One copy must be marked “CONTAINS CONFIDENTIAL INFORMATION” and should clearly identify all PII or business information the commenter does not want to be made publicly available, including any supplemental materials. DEA will review this copy, including the claimed PII and confidential business information, in its consideration of comments. The second copy should be marked “TO BE PUBLICLY POSTED” and must have all