

Issued in Kansas City, Missouri on April 20, 2015.

Earl Lawrence,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-09743 Filed 4-24-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-0655; Directorate Identifier 2013-NM-070-AD; Amendment 39-18142; AD 2015-08-06]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are superseding Airworthiness Directive (AD) 2007-14-05 for all Airbus Model A310 and Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes). AD 2007-14-05 required revising the Airworthiness Limitations section of the Instructions for Continued Airworthiness by incorporating certain certification maintenance requirements. This new AD requires revising the maintenance or inspection program to incorporate more restrictive maintenance requirements and airworthiness limitations. This AD was prompted by a determination that more restrictive maintenance requirements and airworthiness limitations are necessary. We are issuing this AD to prevent safety-significant latent failures that would, in combination with one or more other specific failures or events, result in a hazardous or catastrophic failure condition of avionics, hydraulic systems, fire detection systems, fuel systems, or other critical systems.

DATES: This AD becomes effective June 1, 2015.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of June 1, 2015.

The Director of the Federal Register approved the incorporation by reference of certain other publications listed in this AD as of August 22, 2007 (72 FR 39307, July 18, 2007).

ADDRESSES: You may examine the AD docket on the Internet at [http://](http://www.regulations.gov/)

www.regulations.gov/ #!docketDetail;D=FAA-2014-0655; or in person at the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0655.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2007-14-05, Amendment 39-15127 (72 FR 39307, July 18, 2007). AD 2007-14-05 applied to all Airbus Model A310 and A300-600 series airplanes. The NPRM published in the **Federal Register** on October 1, 2014 (79 FR 59154).

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2013-0072, dated March 20, 2013, corrected January 15, 2015, (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A310 and Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes). The MCAI states:

The airworthiness limitations for Airbus aeroplanes are currently published in Airworthiness Limitations Section (ALS) documents.

The airworthiness limitations applicable to the A300-600 and A300-600ST Certification Maintenance Requirements (CMR) were previously specified in the Airbus A300-600 CMR document referenced AUST5/829/85.

DGAC [Direction Générale de l’Aviation Civile] France issued AD F2005-123 http://ad.easa.europa.eu/blob/easa_ad_F_2005_123.pdf/AD F-2005-123 (EASA approval 2005-6070) [which corresponds to FAA AD 2007-14-05, Amendment 39-15127 (72 FR 39307, July 18, 2007)] to require compliance to the requirements as specified in this document.

Since that AD was issued, the CMR tasks are now specified in Airbus A300-600 and Airbus A310 ALS Part 3 documents, which are approved by the European Aviation Safety Agency (EASA). These documents introduce more restrictive maintenance requirements and/or airworthiness limitations. Failure to comply with the maintenance requirements contained in these documents could result in an unsafe condition.

For the reasons described above, this new [EASA] AD retains the requirements of DGAC France AD F-2005-123, which is superseded, and requires the implementation of the new or more restrictive maintenance requirements as specified in Airbus A310 ALS Part 3 Revision 00 and A300-600 ALS Part 3 Revision 00, as applicable to the aeroplane type/model.

This [EASA] AD is republished to correct typographical errors of the MRBR tasks numbers in Table 1 of the [EASA] AD.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/> #!documentDetail;D=FAA-2014-0655-0002.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (79 FR 59154, October 1, 2014) or on the determination of the cost to the public.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this AD as proposed, with minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (79 FR 59154, October 1, 2014) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (79 FR 59154, October 1, 2014).

Related Service Information Under 14 CFR Part 51

Airbus has issued A310 Airworthiness Limitations Section (ALS) Part 3, Certification Maintenance Requirements (CMR), dated November 30, 2012. Airbus has also issued A300-600 ALS Part 3, Certification Maintenance Requirements (CMR), dated April 18, 2012. This service information describes mandatory

maintenance tasks operators must perform at specified intervals. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI. This service information is

reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this AD.

Costs of Compliance

We estimate that this AD affects 156 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Retained actions from AD 2007–14–05 Amendment 39–15127 (72 FR 39307, July 18, 2007).	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$13,260
Revision of maintenance or inspection program [new action].	1 work-hour × \$85 per hour = \$85	0	85	13,260

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> #!docketDetail;D=FAA-2014-0655; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2007–14–05, Amendment 39–15127 (72 FR 39307, July 18, 2007), and adding the following new AD:

2015–08–06 Airbus: Amendment 39–18142. Docket No. FAA–2014–0655; Directorate Identifier 2013–NM–070–AD.

(a) Effective Date

This AD becomes effective June 1, 2015.

(b) Affected ADs

This AD replaces AD 2007–14–05, Amendment 39–15127 (72 FR 39307, July 18, 2007).

(c) Applicability

This AD applies to all Airbus Model A310–203, –204, –221, –222, –304, –322, –324, and –325 airplanes; and all Model A300 B4–601, B4–603, B4–620, and B4–622 airplanes, Model A300 B4–605R and B4–622R airplanes, Model A300 F4–605R and F4–622R airplanes, and Model A300 C4–605R Variant F airplanes; certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by a determination that more restrictive maintenance requirements and airworthiness limitations are necessary. We are issuing this AD to prevent safety-significant latent failures that would, in combination with one or more other specific failures or events, result in a hazardous or catastrophic failure condition of avionics, hydraulic systems, fire detection systems, fuel systems, or other critical systems.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Revision to the Airworthiness Limitations Section of the Instructions for Continued Airworthiness

This paragraph restates the requirements of paragraph (f) of AD 2007–14–05, Amendment 39–15127 (72 FR 39307, July 18, 2007), with no changes. Within 3 months after August 22, 2007 (the effective date of AD 2007–14–05), revise the Airworthiness Limitations section of the Instructions for Continued Airworthiness by incorporating Airbus A300–600 Certification Maintenance Requirements (CMRs) AI/ST5/829/85, Issue 12, dated February 2005 (for Model A300–600 series airplanes); or Airbus A310 CMR AI/ST5/849/85, Issue 12, dated February 2005 (for Model A310 series airplanes); as applicable. Accomplish the actions specified in the applicable CMRs at the intervals specified in the applicable CMRs, except as provided by paragraph (h) of this AD. Where the CMRs specify to contact the Direction

Générale de l'Aviation Civile (DGAC), operators are required to contact the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. The actions must otherwise be accomplished in accordance with the applicable CMRs.

(h) Retained Transition/Grace Period for Maintenance Significant Item (MSI) 78.30.00 Tasks

This paragraph restates the requirements of paragraph (g) of AD 2007-14-05, Amendment 39-15127 (72 FR 39307, July 18, 2007), with no changes. For tasks identified in MSI 78.30.00, "Thrust Reverser Actuation and Cowling," of Section 2, "CMR 'Two Star' Tasks," of Airbus A300-600 CMR AI/ST5/829/85, Issue 12, dated February 2005; and Airbus A310 CMR AI/ST5/849/85, Issue 12, dated February 2005: The initial compliance time is within 2,000 flight cycles or 12 months after August 22, 2007 (the effective date of AD 2007-14-05), whichever occurs later. Thereafter, actions identified in MSI 78.30.00 must be accomplished within the repetitive interval specified in the applicable CMRs. Where the CMRs specify to contact the DGAC, operators are required to contact the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, for such approvals. The actions must be accomplished in accordance with the applicable CMRs.

(i) New Revision of Maintenance or Inspection Program

Within 3 months after the effective date of this AD, revise the maintenance or inspection program, as applicable, to incorporate Airbus A310 Airworthiness Limitations Section (ALS) Part 3, Certification Maintenance Requirements (CMR), dated November 30, 2012; or Airbus A300-600 ALS Part 3, Certification Maintenance Requirements (CMR), dated April 18, 2012. Except as required by paragraph (k) of this AD, the initial compliance time for accomplishing the actions is at the applicable time specified in Airbus A310 ALS Part 3, Certification Maintenance Requirements (CMR), dated November 30, 2012; or Airbus A300-600 ALS Part 3, Certification Maintenance Requirements (CMR), dated April 18, 2012, as applicable; or within 3 months after the effective date of this AD; whichever occurs later. Accomplishing the requirements in this paragraph terminates the requirements in paragraph (g) of this AD.

(j) New No Alternative Actions or Intervals

After accomplishment of the revision required by paragraph (i) of this AD, no alternative actions (e.g., inspections) or intervals, may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (l) of this AD.

(k) New Compliance Time for Model A300-600 Series Airplanes

For CMR Task 213000-A0001-1-C, "Pressurization Control," as identified in Sub-part 3-1, CMR Tasks, of the Airbus A300-600 ALS Part 3, Certification Maintenance Requirements (CMR), dated April 18, 2012: The initial compliance time

for the task is at the applicable time specified in paragraphs (k)(1), (k)(2), and (k)(3) of this AD.

(1) For airplanes having accumulated less than 40,000 total flight hours since first flight of the airplane as of the effective date of this AD: Before the accumulation of 40,001 total flight hours.

(2) For airplanes having accumulated 40,000 total flight hours or more since first flight of the airplane as of the effective date of this AD, and on which Aging Systems Maintenance (ASM) Task 213115-04-1, "Cabin Pressure Safety Valve;" or Maintenance Review Board Report (MRBR) Tasks 21.30.00/06 and 21.30.00/08, "Pressurization Control," have been accomplished: Before the accumulation of 14,000 flight hours after the most recent accomplishment of ASM Tasks 213115-04-1, or MRBR Tasks 21.30.00/06 and 21.30.00/08, whichever occurs later.

(3) For airplanes having accumulated 40,000 total flight hours or more since first flight of the airplane as of the effective date of this AD, and on which ASM Task 213115-04-1, or MRBR Tasks 21.30.00/06 and 21.30.00/08, have not been accomplished: Within 3 months after the effective date of this AD.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(m) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2013-0072, dated March 20, 2013, (corrected January 15, 2015) for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0655.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on June 1, 2015.

(i) Airbus A300-600 Airworthiness Limitations Section Part 3, Certification Maintenance Requirements, dated April 18, 2012.

(ii) Airbus A310 Airworthiness Limitations Section Part 3, Certification Maintenance Requirements, dated November 30, 2012.

(4) The following service information was approved for IBR on August 22, 2007 (72 FR 39307, July 18, 2007).

(i) Airbus A300-600 Certification Maintenance Requirements AI/ST5/829/85, Issue 12, dated February 2005.

(ii) Airbus A310 Certification Maintenance Requirements AI/ST5/849/85, Issue 12, dated February 2005.

(5) For service information identified in this AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 9, 2015.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-09285 Filed 4-24-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-0930; Directorate Identifier 2015-NM-040-AD; Amendment 39-18144; AD 2015-08-08]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).