

Title: FRA Emergency Order No. 31, Notice No. 1.

OMB Control Number: 2130-0611.

Abstract: On May 21, 2015, FRA issued Emergency Order No. 31 (EO or Order) to require that the National Railroad Passenger Corporation (Amtrak) take actions to control passenger train speed at certain locations on main line track in the Northeast Corridor (as defined by 49 U.S.C. 24905(c)(1)(A)). Amtrak was required to immediately implement code changes to its Automatic Train Control (ATC) System to enforce the passenger train speed limit ahead of the

curve at Frankford Junction in Philadelphia, Pennsylvania, where a fatal accident occurred on May 12, 2015. Amtrak was also required to identify all other curves on the Northeast Corridor where there is a significant reduction (more than 20 miles per hour (mph)) from the maximum authorized approach speed to those curves for passenger trains. Amtrak was then required to develop and comply with an FRA-approved action plan to modify its existing ATC System or other signal systems (or take alternative operational actions) to enable enforcement of passenger train speeds at the identified

curves. Amtrak also had to install additional wayside passenger train speed limit signage at appropriate locations on its Northeast Corridor right-of-way. FRA is continuing this Emergency Order in full force and effect, and is now seeking regular clearance for the information collection associated with this Emergency Order.

Form Number(s): N/A.

Affected Public: Businesses.

Respondent Universe: 1 Railroad.

Frequency of Submission: On occasion.

Reporting Burden:

Emergency Order No. 31—Item:	Respondent universe	Total annual responses	Average time per response	Total annual burden hours
(1) Amtrak survey of Northeast Corridor (NEC) main line track system to create list identifying each main track curve where there is a reduction of more than 20 mph from the maximum authorized speed to that curve.	1 Railroad	1 list	32 hours	32
(2) Development and submission of Amtrak Action Plan to FRA.	1 Railroad	1 action plan	80 hours	80
(3) Installation of Additional Wayside Signs throughout NEC, particularly along curve locations, to alert engineers and conductors of maximum authorized train speed.	1 Railroad	186 NEC wayside signs	15.4839 minutes per sign.	48
—Notice by Amtrak to FRA of Installation of Signs along NEC designated in its.	1 Railroad	6 notices	15 minutes	2
(4) Relief Petition to FRA to take action not in Accordance with this Emergency Order.	1 Railroad	1 petition request	80 hours	80

Total Estimated Annual Responses: 195.

Total Estimated Annual Burden: 242. *Status:* Regular Review.

Pursuant to 44 U.S.C. 3507(a) and 5 CFR 1320.5(b), 1320.8(b)(3)(vi), FRA informs all interested parties that it may not conduct or sponsor, and a respondent is not required to respond to, a collection of information unless it displays a currently valid OMB control number.

Authority: 44 U.S.C. 3501–3520.

Rebecca Pennington,
Chief Financial Officer.

[FR Doc. 2015-15214 Filed 6-19-15; 8:45 am]

BILLING CODE 4910-06-P

DEPARTMENT OF TRANSPORTATION

Federal Transit Administration

[Safety Advisory 15-1]

Audits of Subway Tunnel Environments

AGENCY: Federal Transit Administration, DOT.

ACTION: Notice of safety advisory.

SUMMARY: On June 17, 2015, the Federal Transit Administration (FTA) issued

Safety Advisory 15-1 to advise rail fixed guideway public transportation systems (RFGPTS) with subway tunnel environments of forthcoming audits to be conducted by State Safety Oversight Agencies (SSOAs) with oversight jurisdiction in the assessment of tunnel ventilation systems, emergency procedures for fire and smoke events, training programs to ensure compliance with those emergency procedures, and application of industry best standards in maintenance and emergency procedures. Additionally, FTA instructed all State Safety Oversight Agencies to conduct inspections of the rail transit agencies' tunnel ventilation systems, and to audit the rail transit agencies within their jurisdiction for the purpose of determining the mileage and characteristics of subway tunnels, assessing the adequacy of the rail transit agencies' emergency procedures, ensuring compliance with those emergency procedures, and determining compliance with industry best standards in maintenance and emergency procedure. The FTA issued Safety Advisory 15-1 in response to an urgent safety recommendation by the National Transportation Safety Board (NTSB). The FTA Safety Advisory 15-1, "Audit All Rail Fixed Guideway

Public Transportation Systems (RFGPTS) with Subway Tunnel Environments," is available on the FTA public Web site, <http://www.fta.dot.gov/tso.html>.

FOR FURTHER INFORMATION CONTACT: For program matters, Thomas Littleton, Associate Administrator for Transit Safety and Oversight, (202) 366-1738 or Thomas.Littleton@dot.gov. For legal matters, Scott Biehl, Senior Counsel, (202) 366-0826 or Scott.Biehl@dot.gov.

SUPPLEMENTARY INFORMATION: On January 12, 2015, at 3:15 p.m., Eastern Standard Time, a southbound Yellow Line rapid rail train number 302 operated by the Washington Metropolitan Area Transit Authority (WMATA) stopped after encountering heavy smoke in a subway tunnel between the L'Enfant Plaza station and the Potomac River Bridge. After stopping, the rear car of train 302 was about 386 feet from the south end of the L'Enfant Plaza station platform. The operator of train 302 informed WMATA's Operation Control Center (OCC) that the train had stopped due to heavy smoke. A following Yellow Line train, number 510, stopped about 100 feet short of the south end of the same platform, but its cars were entirely within the L'Enfant Plaza station. At

3:16 p.m., WMATA's OCC activated the under-platform fans at the L'Enfant Plaza Green and Yellow Line platforms, but because the fans were in exhaust mode—not supply mode—the activation of the fans pulled smoke toward rather than away from both trains. Moreover, the operator of train 302 had not shut off the train ventilation system that draws outside air into the train cars. WMATA procedure required the train operator to receive permission from the OCC to shut off the train ventilation system. Since both the station and vent shaft fans were all activated in exhaust mode—not supply mode—there was not a supply of fresh air to help move the smoke through the tunnel.

A post-accident inspection found that two of the four fans had tripped an overload circuit breaker and were non-operational.

Police and emergency responders assisted in the evacuation of both trains and the L'Enfant Plaza station. A limited number of passengers aboard train 302 were able to self-evacuate. One passenger died and 86 others were transported to local medical facilities for treatment for smoke inhalation. The WMATA incurred an estimated \$120,000 in damage to assets. During its investigation, the NTSB determined the cause of the smoke to have been an electrical arcing incident, and the source of the smoke to have been about 1,100 feet ahead (south) of train 302. Further, as part of its investigation, the NTSB determined that WMATA did not have a written ventilation procedure for smoke and fire events in a tunnel, and that the ventilation strategy WMATA deployed during this accident was not consistent with best practice.

On February 11, 2015, the NTSB issued three urgent safety recommendations to WMATA, two urgent safety recommendations to the American Public Transportation Association, and urgent safety recommendation R-15-007 to FTA, calling for audits for all rail transit agencies that have subway tunnel environments to assess the state of good repair of their tunnel ventilation systems, their written emergency procedures for fire and smoke events, and their training programs to ensure compliance with those procedures, and to verify that the rail transit agencies are applying industry best standards, such as the National Fire Protection Association (NFPA) Code 130, *Standards for Fixed Guideway Transit and Passenger Rail Systems*, in their maintenance and emergency procedures. The FTA responded to the NTSB safety recommendation by letter of March 13, 2015, stating, in part, that

we have identified the rail transit agencies with operational subway tunnel environments and will engage the State Safety Oversight Agencies (SSOAs) that have safety oversight jurisdiction over these rail transit agencies, in accordance with 49 U.S.C. 5329 and 5330 and 49 CFR part 659, for the purpose of addressing R-15-007.

To that end, on June 17, 2015, the FTA Office of Transit Safety and Oversight issued Safety Advisory 15-1, addressed to the RFGPTS that have operational subway tunnel environments, and a letter addressed to the SSOAs that have safety oversight jurisdiction over these the rail transit agencies, with instructions to conduct audits to (1) determine the extent of subway tunnel mileage at each such rail transit agency, and the characteristics of its operational subway tunnel environments; (2) assess each rail transit agency's written emergency procedures for fire and smoke events; (3) assess each rail transit agency's training programs for ensuring compliance with those emergency procedures; and (4) determine each rail transit agency's compliance with industry best standards, such as NFPA Code 130, in their maintenance and emergency procedures. Additionally, the SSOAs were instructed to complete a Tunnel Ventilation System Inspection of each such rail transit agency, using the audit tools provided by FTA, and to submit the results of their audits with supporting documentation no later than August 31, 2015. For additional guidance, FTA referred the SSOAs to the joint FTA/Federal Highway Administration *Highway and Rail Transit Tunnel Inspection Manual, 2005 Edition*, which sets forth established industry inspection standards. The FTA will use the data and information from these audits by the SSOAs in conducting a broader analysis for responding to NTSB recommendation R-15-007, and potentially, for future rulemaking and guidance to the rail transit industry. Both the FTA Safety Advisory 15-1 and the June 17, 2015 letter addressed to the SSOAs are available on the FTA public Web site, <http://www.fta.dot.gov/tso.html>.

The FTA's issuance of Safety Advisory 15-1 is in accordance with FTA's authority to "investigate public transportation accidents and incidents and provide guidance to recipients regarding prevention of accidents and incidents." 49 U.S.C. 5329(f) (5). The requests for information and data from the SSOAs and the rail transit agencies within their jurisdiction are based on FTA's authority to request program information pertinent to rail transit

safety under the State Safety Oversight rule, 49 CFR 659.39(d).

Readers who have an interest in the January 12, 2015, WMATA accident that led to the urgent recommendations by the NTSB and FTA's issuance of Safety Advisory 15-1 can obtain further information about that accident in two reports issued on June 17, 2015: A Safety Management Inspection that FTA conducted of WMATA from March 16 to April 3, 2015, and a Safety Management System gap analysis FTA performed for WMATA from March 3 to March 5, 2015. Both documents are available on the FTA public Web site, <http://www.fta.dot.gov/tso.html>.

Therese W. McMillan,
Acting Administrator.

[FR Doc. 2015-15256 Filed 6-19-15; 8:45 am]

BILLING CODE P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-2015-0047]

Supplemental Notice of Public Hearing To Determine Whether Fiat Chrysler Has Reasonably Met Its Obligations To Remedy Recalled Vehicles and To Notify NHTSA, Owners, and Purchasers of Recalls

AGENCY: National Highway Traffic Safety Administration (NHTSA), DOT.

ACTION: Supplemental notice of public hearing.

SUMMARY: NHTSA will hold a public hearing on whether Fiat Chrysler Automobiles US LLC (Fiat Chrysler) has reasonably met its obligations to remedy recalled vehicles and to notify NHTSA, owners, and purchasers of recalls. This notice provides supplemental information on the subject matter of the hearing.

DATES: The public hearing will be held beginning at 10 a.m. ET on July 2, 2015, at the U.S. Department of Transportation, 1200 New Jersey Avenue SE., Washington, DC 20590. If you wish to attend or speak at the hearing, you must register in advance no later than June 30, 2015 (and June 26, 2015, for non-U.S. citizens), by following the instructions in the Procedural Matters section of this notice. NHTSA will consider late registrants to the extent time and space allows, but cannot ensure that late registrants will be able to attend or speak at the hearing. To ensure that NHTSA has an opportunity to consider