

(a) Comments Due Date

We must receive comments by May 12, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all serial numbers of the airplanes listed in table 1 of paragraph (c) of this AD, that are:

(1) Equipped with a BRP-Powertrain GmbH & Co KG (formerly Rotax Aircraft Engines)

912 A series engine with a part number (P/N) 413235 or 413236 cylinder head installed in position 2 or 3; and
(2) certificated in any category.

TABLE 1 OF PARAGRAPH (c)—AFFECTED AIRPLANES

Type certificate holder	Aircraft model	Engine model
Aeromot-Indústria Mecânico-Metalúrgica Ltda	AMT-200	912 A2
Diamond Aircraft Industries	HK 36 R "SUPER DIMONA"	912 A
DIAMOND AIRCRAFT INDUSTRIES GmbH	HK 36 TS and HK 36 TC	912 A3
Diamond Aircraft Industries Inc	DA20-A1	912 A3
HOAC-Austria	DV 20 KATANA	912 A3
Iniziativa Industriali Italiane S.p.A	Sky Arrow 650 TC	912 A2
SCHEIBE-Flugzeugbau GmbH	SF 25C	912 A2, 912 A3

(d) Subject

Air Transport Association of America (ATA) Code 72: Engine—Reciprocating.

(e) Reason

This AD was prompted by design change of the engine cylinder head temperature sensor without a concurrent revision of the engine model designation, the engine part number, or the cockpit indication to the pilot. The sensor now measures the coolant temperature rather than the cylinder head temperature. If the engine coolant temperature with a maximum engine operating limit of 120 °C is displayed on a Cylinder Head Temperature indicator with a typical limit marking greater than 120 °C, the pilot will be unable to identify coolant temperature limit exceedances. This could result in loss of coolant, which could cause an inflight engine shutdown and forced landing.

(f) Actions and Compliance

Unless already done, do the following actions:

(1) Within 6 months after the effective date of this AD, for engines with cylinder heads listed in paragraph (c)(1) of this AD installed on both position 2 and position 3, change the engine model designation on the engine type data plate to include a "–01" suffix following paragraph 3.1.1) of the Accomplishment/Instructions in Rotax Aircraft Engines BRP Service Bulletin SB-912-068 and SB-914-049 (co-published as one document), dated April 16, 2015.

(2) Within 6 months after the effective date of this AD, for engines with only one cylinder head listed paragraph (c)(1) of this AD installed in a position 2 or 3, in order to keep such cylinder installed, you must replace the cylinder head installed on the unchanged position (2 or 3, as applicable) with a cylinder head having a P/N listed in paragraph (c)(1) of this AD, and change the engine model designation on the engine type data plate to include a "–01" suffix following paragraph 3.1.1) of the Accomplishment/Instructions in Rotax Aircraft Engines BRP Service Bulletin SB-912-068 and SB-914-049 (co-published as one document), dated April 16, 2015.

(3) Before further flight after doing the required actions in paragraphs (f)(1) or (f)(2)

of this AD as applicable, modify the aircraft and related documentation to indicate a Maximum Coolant Temperature limit of 120 °C using FAA-approved procedures.

(i) Such procedures can be found by contacting your aircraft type certificate holder or the FAA contact specified in paragraph (g)(1) of this AD. The service documents referenced in paragraph (h) of this AD are examples of FAA-approved procedures for the applicable aircraft.

(ii) These re-identified engines remain eligible for installation on approved aircraft-engine combinations.

(4) As of the effective date of this AD, do not install any other P/N cylinder head unless that installation is done following approved instructions provided by BRP-Powertrain at the address provided in paragraph (h) of this AD.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Jim Rutherford, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2015-0240, dated December 18, 2015; Rotax Aircraft Engines BRP Service Bulletin SB-912-066 R1/SB-914-047 R1 (published as one document), Revision 1, dated April 23, 2015; Diamond

Aircraft Industries GmbH Optional Service Bulletin OSB 36-111, dated September 17, 2015; Diamond Aircraft Industries GmbH Work Instruction WI-OSB 36-111, dated September 17, 2015; Diamond Aircraft Service Bulletin No.: DA20-72-04, dated January 22, 2015; Diamond Aircraft Industries GmbH Optional Service Bulletin OSB 20-066, dated September 17, 2015; Diamond Aircraft Industries GmbH Work Instruction WI-OSB 20-066, dated September 17, 2015; and Scheibe Aircraft GmbH Service Information 02/14-1, dated December 15, 2014, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-4878. For service information related to this AD, contact BRP-Powertrain GmbH & Co. KG, Welser Strasse 32, A-4623 Gunskirchen, Austria; phone: +43 7246 601 0; fax: +43 7246 601 9130; Internet: <http://www.rotax-aircraft-engines.com>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on March 10, 2016.

Pat Mullen,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-06279 Filed 3-25-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2016-1074; Airspace Docket No. 16-ASO-3]

Proposed Revocation of Class D Airspace; North, SC

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to remove Class D Airspace at North, SC, as the North Air Force Auxiliary Field Air Traffic Control Tower is no longer staffed, and controlled airspace is no longer required. This action would enhance the safety and airspace management in North, SC.

DATES: Comments must be received on or before May 12, 2016.

ADDRESSES: Send comments on this rule to: U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE., West Bldg. Ground Floor Rm. W12-140, Washington, DC 20590-0001; Telephone: 1-800-647-5527; Fax: 202-493-2251. You must identify the Docket Number FAA-2016-1074; Airspace Docket No. 16-ASO-3, at the beginning of your comments. You may also submit and review received comments through the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527), is on the ground floor of the building at the above address.

FAA Order 7400.9Z, Airspace Designations and Reporting Points, and subsequent amendments can be viewed on line at <http://www.faa.gov/airtraffic/publications/>. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: 202-267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.9Z at NARA, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-6364.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator.

Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This proposed rulemaking is promulgated under the authority described in Subtitle VII, Part, A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would remove Class D airspace at North Air Force Auxiliary Field, North, SC.

Comments Invited

Interested persons are invited to comment on this rule by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2016-1074; Airspace Docket No. 16-ASO-3) and be submitted in triplicate to the Docket Management System (see **"ADDRESSES"** section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Persons wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2016-1074; Airspace Docket No. 16-ASO-3." The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded from and comments submitted through <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports/airtraffic/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal Holidays. An informal docket may also be examined between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal Holidays at the office of the Eastern Service Center, Federal Aviation Administration, Room 350, 1701 Columbia Avenue, College Park, Georgia 30337.

Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking distribution System, which describes the application procedure.

Availability and Summary of Documents for Incorporation by Reference

This document proposes to amend FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, and effective September 15, 2015. FAA Order 7400.9Z is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.9Z lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Proposal

The FAA is considering an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 to remove Class D airspace at North Air Force Auxiliary Field, North, SC. The air traffic control tower is no longer in use. Therefore, the airspace is no longer necessary.

Class D airspace designations are published in Paragraph 5000 of FAA Order 7400.9Z, dated August 6, 2015, and effective September 15, 2015, which is incorporated by reference in 14 CFR 71.1. The Class D airspace designation listed in this document will be published subsequently in the Order.

Regulatory Notices and Analyses

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February

26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

This proposal would be subject to an environmental analysis in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures" prior to any FAA final regulatory action.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment:

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, effective September 15, 2015, is amended as follows:

Paragraph 5000 Class D Airspace.

* * * * *

ASO SC D North, SC [Removed]

Issued in College Park, Georgia, on March 15, 2016.

Ryan W. Almasy,

Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization.

[FR Doc. 2016–06842 Filed 3–25–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2016–3937; Airspace Docket No. 16–AWA–1]

RIN 2120–AA66

Proposed Amendment of Class C Airspace; Syracuse Hancock International Airport, NY

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to modify the Syracuse Hancock International Airport Class C airspace area by removing a cutout from the surface area that was put in place to accommodate operations at an airport that is now permanently closed.

DATES: Comments must be received on or before May 27, 2016. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA, Order 7400.9 and publication of conforming amendments.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, M–30, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12–140, Washington, DC 20590–0001; telephone: (202) 366–9826. You must identify FAA Docket No. FAA–2016–3937 and Airspace Docket No. 16–AWA–1 at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1–800–647–5527), is on the ground floor of the building at the above address.

FAA Order 7400.9Z, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: 202–267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA

Order 7400.9Z at NARA, call 202–741–6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Airspace Policy Group, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267–8783.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would amend the Syracuse, NY, Class C airspace area to maintain efficient airport operations.

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA–2016–3937 and Airspace Docket No. 16–AWA–1) and be submitted in triplicate to the Docket Management Facility (see **ADDRESSES** section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to FAA Docket No. FAA–2016–3937 and