

Table 1 to paragraph (g) of this AD

Airplane Model	Airplane Serial Numbers	Applicable Service Bulletin
CL-600-2B19	7002 through 8999 inclusive	Bombardier Service Bulletin 601R-22-017, Revision C, dated May 11, 2016
CL-600-2C10	10002 through 10344 inclusive	Bombardier Service Bulletin 670BA-22-007, Revision A, dated February 16, 2016
CL-600-2D15 and CL-600-2D24	15001 through 15400 inclusive	

(h) Credit for Previous Actions

(1) This paragraph provides credit for actions required by paragraph (g) of this AD for Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes, if those actions were performed before the effective date of this AD using the service information specified in paragraph (h)(1)(i), (h)(1)(ii), or (h)(1)(iii) of this AD.

(i) Bombardier Service Bulletin 601R-22-017, dated September 24, 2014.

(ii) Bombardier Service Bulletin 601R-22-017, Revision A, dated February 26, 2015.

(iii) Bombardier Service Bulletin 601R-22-017, Revision B, dated July 16, 2015.

(2) This paragraph provides credit for actions required by paragraph (g) of this AD for Model CL-600-2C10 (Regional Jet Series 700, 701, & 702), Model CL-600-2D15 (Regional Jet Series 705), and Model CL-600-2D24 (Regional Jet Series 900) airplanes, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 670BA-22-007, dated October 15, 2014.

(i) Parts Installation Limitations

As of 24 months after the effective date of this AD, no person may install, on any airplane, a yaw damper actuator having part number 622-9968-001, unless it has been modified in accordance with the applicable service information specified in table 1 to paragraph (g) of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the New York ACO, send it to ATTN: Program Manager, Continuing Operational Safety, New York ACO Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight

standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2017-06, effective February 14, 2017, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0495.

(2) For more information about this AD, contact Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Section, New York ACO Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7318; fax 516-794-5531.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (l)(4) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 601R-22-017, Revision C, dated May 11, 2016.

(ii) Bombardier Service Bulletin 670BA-22-007, Revision A, dated February 16, 2016.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email ac.yul@aero.bombardier.com; internet: <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch,

2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on March 2, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-05014 Filed 3-22-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY**Coast Guard****33 CFR Part 165**

[Docket No. USCG-2018-0063]

RIN 1625-AA00

Safety Zone: Juan Benitez Fireworks Display, San Francisco, CA

AGENCY: Coast Guard, DHS.

ACTION: Temporary final rule.

SUMMARY: The Coast Guard is establishing a temporary moving safety zone in the navigable waters of the San Francisco Bay near Point Cavallo in support of the Juan Benitez Fireworks Display on March 24, 2018. This safety zone is established to ensure the safety of participants and spectators from the dangers associated with pyrotechnics. Unauthorized persons or vessels are prohibited from entering into, transiting through, or remaining in the safety zone without permission of the Captain of the Port or their designated representative.

DATES: This rule is effective from 9:00 a.m. to 8:40 p.m. on March 24, 2018.

ADDRESSES: Documents mentioned in this preamble are part of docket USCG–2018–0063. To view documents mentioned in this preamble as being available in the docket, go to <http://www.regulations.gov>, type the docket number in the “SEARCH” box and click “SEARCH.” Click on Open Docket Folder on the line associated with this rulemaking.

FOR FURTHER INFORMATION CONTACT: If you have questions on this rule, call or email Lieutenant Junior Grade Emily Rowan, U.S. Coast Guard Sector San Francisco; telephone (415) 399–7443 or email at D11-PF-MarineEvents@uscg.mil.

SUPPLEMENTARY INFORMATION:

I. Table of Acronyms

APA Administrative Procedure Act
 COTP U.S. Coast Guard Captain on the Port
 DHS Department of Homeland Security
 FR Federal Register
 NOAA National Oceanic and Atmospheric Administration
 NPRM Notice of proposed rulemaking
 PATCOM U.S. Coast Guard Patrol Commander
 U.S.C. United States Code

II. Background Information and Regulatory History

The Coast Guard is issuing this temporary final rule without prior notice and opportunity to comment pursuant to authority under section 4(a) of the Administrative Procedure Act (APA) (5 U.S.C. 553(b)). This provision authorizes an agency to issue a rule without prior notice and opportunity to comment when the agency for good cause finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under 5 U.S.C. 553(b)(B), the Coast Guard finds that good cause exists for not publishing a notice of proposed rulemaking (NPRM) with respect to this rule. Since the Coast Guard received notice of this event on February 22, 2018, notice and comment procedures would be impracticable in this instance.

For similar reasons as those stated above, under 5 U.S.C. 553(d)(3), the Coast Guard finds that good cause exists for making this rule effective less than 30 days after publication in the **Federal Register**.

III. Legal Authority and Need for Rule

The Coast Guard is issuing this rule under authority in 33 U.S.C. 1231. The Captain of the Port (COTP) San Francisco has determined that potential hazards associated with the planned fireworks display on March 24, 2018, will be a safety concern for anyone within a 100-foot radius of the fireworks

barge and anyone within a 560-foot radius of the fireworks firing site. This rule is needed to protect spectators, vessels, and other property from hazards associated with pyrotechnics.

IV. Discussion of the Rule

This rule establishes a temporary safety zone during the loading and transit of the fireworks barge, until after completion of the fireworks display. During the loading of the pyrotechnics onto the fireworks barge, scheduled to take place from 9:00 a.m. to 2:00 p.m. on March 24, 2018, at Pier 50 in San Francisco, CA, the safety zone will encompass the navigable waters around and under the fireworks barge within a radius of 100 feet.

The fireworks barge will remain at Pier 50 until the start of its transit to the display location. Towing of the barge from Pier 50 to the display location is scheduled to take place from 5:30 p.m. to 7:00 p.m. on March 24, 2018 where it will remain until the conclusion of the fireworks display.

At 8:00 p.m. on March 24, 2018, 30 minutes prior to the commencement of the 10-minute fireworks display, the safety zone will increase in size and encompass the navigable waters around and under the fireworks barge within a radius of 560 feet in approximate position 37°49'48" N, 122°28'26" W (NAD 83) for the Juan Benitez Fireworks Display. The safety zone shall terminate at 8:40 p.m. on March 24, 2018.

The effect of the temporary safety zone is to restrict navigation in the vicinity of the fireworks loading, transit, and firing site. Except for persons or vessels authorized by the COTP or the COTP’s designated representative, no person or vessel may enter or remain in the restricted areas. These regulations are needed to keep spectators and vessels away from the immediate vicinity of the fireworks firing sites to ensure the safety of participants, spectators, and transiting vessels.

V. Regulatory Analyses

We developed this rule after considering numerous statutes and executive orders related to rulemaking. Below we summarize our analyses based on a number of these statutes and Executive orders, and we discuss First Amendment rights of protestors.

A. Regulatory Planning and Review

Executive Orders 12866 and 13563 direct agencies to assess the costs and benefits of available regulatory alternatives and, if regulation is necessary, to select regulatory approaches that maximize net benefits. Executive Order 13771 directs agencies

to control regulatory costs through a budgeting process. This rule has not been designated a “significant regulatory action,” under Executive Order 12866. Accordingly, this rule has not been reviewed by the Office of Management and Budget (OMB), and pursuant to OMB guidance it is exempt from the requirements of Executive Order 13771.

This regulatory action determination is based on the limited duration and narrowly tailored geographic area of the safety zone. Although this rule restricts access to the waters encompassed by the safety zone, the effect of this rule will not be significant because the local waterway users will be notified via public Broadcast Notice to Mariners to ensure the safety zone will result in minimum impact. The entities most likely to be affected are waterfront facilities, commercial vessels, and pleasure craft engaged in recreational activities.

B. Impact on Small Entities

The Regulatory Flexibility Act of 1980 (RFA), 5 U.S.C. 601–612, as amended, requires federal agencies to consider the potential impact of regulations on small entities during rulemaking. The term “small entities” comprises small businesses, not-for-profit organizations that are independently owned and operated and are not dominant in their fields, and governmental jurisdictions with populations of less than 50,000. The Coast Guard certifies under 5 U.S.C. 605(b) that this rule will not have a significant economic impact on a substantial number of small entities.

This rule may affect the following entities, some of which may be small entities: owners and operators of waterfront facilities, commercial vessels, and pleasure craft engaged in recreational activities and sightseeing, if these facilities or vessels are in the vicinity of the safety zone at times when this zone is being enforced. This rule will not have a significant economic impact on a substantial number of small entities for the following reasons: (i) This rule will encompass only a small portion of the waterway for a limited period of time, and (ii) the maritime public will be advised in advance of these safety zones via Broadcast Notice to Mariners.

Under section 213(a) of the Small Business Regulatory Enforcement Fairness Act of 1996 (Pub. L. 104–121), we want to assist small entities in understanding this rule. If the rule would affect your small business, organization, or governmental jurisdiction and you have questions concerning its provisions or options for

compliance, please contact the person listed in the **FOR FURTHER INFORMATION CONTACT** section.

Small businesses may send comments on the actions of Federal employees who enforce, or otherwise determine compliance with, Federal regulations to the Small Business and Agriculture Regulatory Enforcement Ombudsman and the Regional Small Business Regulatory Fairness Boards. The Ombudsman evaluates these actions annually and rates each agency's responsiveness to small business. If you wish to comment on actions by employees of the Coast Guard, call 1-888-REG-FAIR (1-888-734-3247). The Coast Guard will not retaliate against small entities that question or complain about this rule or any policy or action of the Coast Guard.

C. Collection of Information

This rule will not call for a new collection of information under the Paperwork Reduction Act of 1995 (44 U.S.C. 3501-3520).

D. Federalism and Indian Tribal Governments

A rule has implications for federalism under Executive Order 13132, Federalism, if it has a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. We have analyzed this rule under that Order and have determined that it is consistent with the fundamental federalism principles and preemption requirements described in Executive Order 13132.

Also, this rule does not have tribal implications under Executive Order 13175, Consultation and Coordination with Indian Tribal Governments, because it does not have a substantial direct effect on one or more Indian tribes, on the relationship between the Federal Government and Indian tribes, or on the distribution of power and responsibilities between the Federal Government and Indian tribes. If you believe this rule has implications for federalism or Indian tribes, please contact the person listed in the **FOR FURTHER INFORMATION CONTACT** section above.

E. Unfunded Mandates Reform Act

The Unfunded Mandates Reform Act of 1995 (2 U.S.C. 1531-1538) requires Federal agencies to assess the effects of their discretionary regulatory actions. In particular, the Act addresses actions

that may result in the expenditure by a State, local, or tribal government, in the aggregate, or by the private sector of \$100,000,000 (adjusted for inflation) or more in any one year. Though this rule will not result in such expenditure, we do discuss the effects of this rule elsewhere in this preamble.

F. Environment

We have analyzed this rule under Department of Homeland Security Management Directive 023-01, which guides the Coast Guard in complying with the National Environmental Policy Act of 1969 (42 U.S.C. 4321-4370f), and have determined that this action is one of a category of actions that do not individually or cumulatively have a significant effect on the human environment. This rule involves safety zones of limited size and duration. It is categorically excluded from further review under Categorical Exclusion L60(a) of Appendix A, Table 1 of DHS Instruction Manual 023-01-001-01, Rev. 01. A Record of Environmental Consideration supporting this determination is available in the docket where indicated under **ADDRESSES**.

G. Protest Activities

The Coast Guard respects the First Amendment rights of protesters. Protesters are asked to contact the person listed in the **FOR FURTHER INFORMATION CONTACT** section to coordinate protest activities so that your message can be received without jeopardizing the safety or security of people, places or vessels.

List of Subjects in 33 CFR Part 165

Harbors, Marine safety, Navigation (water), Reporting and recordkeeping requirements, Security measures, Waterways.

For the reasons discussed in the preamble, the Coast Guard amends 33 CFR part 165 as follows:

PART 165—REGULATED NAVIGATION AREAS AND LIMITED ACCESS AREAS

■ 1. The authority citation for part 165 continues to read as follows:

Authority: 33 U.S.C. 1231; 50 U.S.C. 191; 33 CFR 1.05-1, 6.04-1, 6.04-6, and 160.5; Department of Homeland Security Delegation No. 0170.1.

■ 2. Add § 165.T11-918 to read as follows:

§ 165.T11-918 Safety Zone; Juan Benitez Fireworks Display, San Francisco Bay, San Francisco, CA.

(a) *Location.* The following area is a safety zone: All navigable waters of the San Francisco Bay within 100 feet of the fireworks barge during loading at Pier 50, as well as transit to and arrival at Point Cavallo. The safety zone will expand to all navigable waters around and under the fireworks barge within a radius of 560 feet in approximate position 37°49'48" N, 122°28'26" W (NAD 83) at 8:00 p.m., 30 minutes prior to the start of the 10 minute fireworks display scheduled to begin at 8:30 p.m. on March 24, 2018.

(b) *Enforcement period.* The zone described in paragraph (a) of this section will be enforced from 9:00 a.m. until approximately 8:40 p.m. March 24, 2018. The Captain of the Port San Francisco (COTP) will notify the maritime community of periods during which these zones will be enforced via Broadcast Notice to Mariners in accordance with 33 CFR 165.7.

(c) *Definitions.* As used in this section, "designated representative" means a Coast Guard Patrol Commander, including a Coast Guard coxswain, petty officer, or other officer on a Coast Guard vessel or a Federal, State, or local officer designated by or assisting the COTP in the enforcement of the safety zone.

(d) *Regulations.* (1) Under the general regulations in 33 CFR part 165, subpart C, entry into, transiting or anchoring within this safety zone is prohibited unless authorized by the COTP or the COTP's designated representative.

(2) The safety zone is closed to all vessel traffic, except as may be permitted by the COTP or a designated representative.

(3) Vessel operators desiring to enter or operate within the safety zone must contact the COTP or a designated representative to obtain permission to do so. Vessel operators given permission to enter or operate in the safety zone must comply with all directions given to them by the COTP or a designated representative. Persons and vessels may request permission to enter the safety zones on VHF-23A or through the 24-hour Command Center at telephone (415) 399-3547.

Dated: March 19, 2018.

Anthony J. Ceraolo,

Captain, U.S. Coast Guard, Captain of the Port, San Francisco.

[FR Doc. 2018-05925 Filed 3-22-18; 8:45 am]

BILLING CODE 9110-04-P