Revision 1, dated March 14, 2017: Within 120 days after the effective date of this AD, inspect the airplane and do all applicable corrective actions using a method approved in accordance with the procedures specified in paragraph (l) of this AD.

# (h) Revision of Maintenance or Inspection Program

Within 60 days after the effective date of this AD: Revise the maintenance or inspection program, as applicable, to incorporate the applicable Airworthiness Limitations (AWLs) from Boeing 737–100/200/200C/300/400/500 Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs), D6–38278–CMR, dated May 2016 or November 2017, as identified in paragraphs (h)(1) and (h)(2) of this AD.

(1) 28–AWL–18 and 28–AWL–26, "Fuel Boost Pump Wires In Conduit Installation—In Fuel Tank," for Boeing Model 737–100, –200, –200C series airplanes.

(2) 28–AWL–18 and 28–AWL–25, "Fuel Boost Pump Wires In Conduit Installation—In Fuel Tank," for Boeing Model 737–300, –400, –500 series airplanes.

## (i) No Alternative Critical Design Configuration Control Limitations (CDCCLs)

After the maintenance or inspection program, as applicable, has been revised as required by paragraph (h) of this AD, no alternative CDCCLs may be used unless the CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (l) of this AD.

# (j) Exceptions to Service Information Specifications

For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Service Bulletin 737–28A1273, Revision 1, dated March 14, 2017, uses the phrase "the original issue date of this service bulletin," this AD requires using "after the effective date of this AD."

# (k) Terminating Action for Requirements of AD 2007–24–02

Accomplishment of the actions required by paragraph (g) of this AD terminates all requirements of AD 2007–24–02.

# (l) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (m) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.
- (2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.
- (3) An AMOC that provides an acceptable level of safety may be used for any repair,

modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (l)(4)(i) and (l)(4)(ii) of this AD apply

apply

- (i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.
- (ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

## (m) Related Information

For more information about this AD, contact Serj Harutunian, Aerospace Engineer, Propulsion Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5254; fax: 562–627–5210; email: serj.harutunian@faa.gov.

# (n) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.
- (i) Boeing Alert Service Bulletin 737–28A1273, Revision 1, dated March 14, 2017.
- (ii) Boeing 737–100/200/200C/300/400/500 Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs), D6–38278–CMR, dated May 2016.
- (iii) Boeing 737–100/200/200C/300/400/500 Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs), D6–38278–CMR, dated November 2017.
- (3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet https://www.myboeingfleet.com.
- (4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.
- (5) You may view this service information that is incorporated by reference at the

National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http:// www.archives.gov/federal-register/cfr/ibrlocations.html.

Issued in Renton, Washington, on February 15, 2018.

#### Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018–03824 Filed 3–2–18; 8:45 am]

BILLING CODE 4910-13-P

#### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 71

[Docket No. FAA-2014-0839; Airspace Docket No. 14-AEA-7]

# Amendment of Class E Airspace; Selinsgrove, PA

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

SUMMARY: This action amends Class E airspace extending upward from 700 feet above the surface in Selinsgrove, PA. A new area navigation (RNAV) global positioning system (GPS) standard instrument approach procedure has been developed at Penn Valley Airport, requiring airspace reconfiguration at the airport. This action enhances the safety and airspace management of instrument flight rules (IFR) operations at the airport. This action also updates the geographic coordinates of the airport.

**DATES:** Effective 0901 UTC, May 24, 2018. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.11B, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/ air traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11B at NARA, call (202) 741-6030, or go to https://

www.archives.gov/federal-register/cfr/ibr-locations.html.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Avenue, College Park, GA 30337; telephone (404) 305–6364.

#### SUPPLEMENTARY INFORMATION:

# **Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends Class E airspace extending upward from 700 feet above the surface at Penn Valley Airport, Selinsgrove, PA, to support IFR operations at the airport.

# History

The FAA published a notice of proposed rulemaking in the **Federal Register** (82 FR 55060, November 20, 2017) for Docket No. FAA—2014—0839 to amend Class E airspace extending upward from 700 feet above the surface at Penn Valley Airport, Selinsgrove, PA. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.11B dated August 3, 2017, and effective September 15, 2017, which is incorporated by reference in 14 CFR part 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

# Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.11B, Airspace Designations and Reporting Points, dated August 3, 2017, and effective September 15, 2017. FAA Order 7400.11B is publicly available as listed in the ADDRESSES section of this

document. FAA Order 7400.11B lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

## The Rule

This amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 amends Class E airspace extending upward from 700 feet above the surface within a 9-mile radius (increased from an 8-mile radius) of Penn Valley Airport, Selinsgrove, PA, to accommodate the new RNAV (GPS) standard instrument approach procedure to Runway 35 developed for the safety and management of IFR operations at the airport.

The action removes the segment extending northbound from the Selinsgrove VOR/DME because it is no longer required as part of the airspace redesign.

The geographic coordinates of the airport are amended to coincide with the FAA's aeronautical database, and the name of the navigation aid is corrected from VORTAC to VOR/DME.

## Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a ''significant rule'' under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

# **Environmental Review**

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5–6.5a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

## Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

# Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

# PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120, E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

#### §71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.11B, Airspace Designations and Reporting Points, dated August 3, 2017, effective September 15, 2017, is amended as follows:

Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.

#### AEA PA E5 Selinsgrove, PA [Amended]

Penn Valley Airport, PA

(Lat. 40°49′16″ N, long. 76°51′551″ W) Selinsgrove VOR/DME

(Lat. 40°47′27" N, long. 76°53′03" W)

That airspace extending upward from 700 feet above the surface within a 9-mile radius of Penn Valley Airport, and within 5 miles southeast of the Selinsgrove VOR/DME 207° radial, extending from the 9-mile radius 10 miles southwest of the VOR/DME.

Issued in College Park, Georgia, on February 23, 2018.

#### Ryan W. Almasy,

Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization.

[FR Doc. 2018-04325 Filed 3-2-18; 8:45 am]

BILLING CODE 4910-13-P

#### **DEPARTMENT OF THE TREASURY**

# Office of Foreign Assets Control

# 31 CFR Part 510

# **North Korea Sanctions Regulations**

**AGENCY:** Office of Foreign Assets Control, Treasury.

**ACTION:** Final rule.

SUMMARY: The Department of the Treasury's Office of Foreign Assets Control (OFAC) is amending the North Korea Sanctions Regulations and reissuing them in their entirety, in order to implement three recent Executive orders and to reference the North Korea Sanctions and Policy Enhancement Act of 2016 and the Countering America's