

development process. A series of public meetings will be held in the City of Conway. In addition, a public hearing will be held. The draft EIS will be available for public and agency review and comment prior to the public hearing.

To ensure that the full range of issues related to this proposed action are addressed and all significant issues identified, comments and suggestions are invited from all interested parties. Comments or questions concerning this proposed action and the EIS should be directed to the FHWA at the address provided above.

(Catalog of Federal Domestic Assistance Program Number 20.205, Highway Planning and Construction. The regulations implementing Executive Order 12372 regarding intergovernmental consultation of Federal programs and activities apply to this program.)

Issued on: May 3, 2000.

Gary A. DalPorto,

Planning and Research Engineer, FHWA, Little Rock, Arkansas.

[FR Doc. 00-11861 Filed 5-10-00; 8:45 am]

BILLING CODE 4910-22-M

DEPARTMENT OF TRANSPORTATION

Federal Highway Administration

Environmental Impact Statement: Tucker County, West Virginia

AGENCY: Federal Highway Administration (FHWA), DOT

ACTION: Notice of Intent.

SUMMARY: The FHWA is issuing this notice to advise the public that a Supplemental Environmental Impact Statement (SEIS) will be prepared for the Blackwater Avoidance area of the Thomas-to-Davis portion of the Parsons-to-Davis project of the proposed Appalachian Corridor H highway in Tucker County, West Virginia.

FOR FURTHER INFORMATION CONTACT:

Henry E. Compton, Division Environmental Coordinator, Federal Highway Administration, West Virginia Division, Geary Plaza, Suite 200, 700 Washington Street East, Charleston, West Virginia, 25301, Telephone: (304) 347-5268.

SUPPLEMENTARY INFORMATION: In accordance with a court approved settlement agreement, the FHWA in cooperation with the West Virginia Department of Transportation (WVDOT) will prepare an SEIS to examine one or more potential alignment shifts for the Thomas-to-Davis section of Parsons-to-Davis project of the proposed Appalachian Corridor H highway in

Tucker County, West Virginia. A Record of Decision (ROD) for the entire Appalachian Corridor H highway (FHWA-WV-EIS-92-01-F) from Aggregates to the WV/VA state line, a distance of approximately 100 miles, was approved on August 2, 1996. The proposed Parsons-to-Davis project will provide a divided four-lane, partial control of access highway on new location for a distance of approximately 9 miles. The purpose of this project is to provide safe and efficient travel between population centers in Tucker County (Parsons Area and Thomas/Davis Area), while also contributing to the completion of Corridor H in West Virginia.

Alternates under consideration in the SEIS will be: (1) The no-action alternative, (2) the preferred alternative that was approved in the 1996 ROD, and (2) one or more alternatives that avoid the Blackwater Area identified in Exhibit 4 of the court approved Corridor H Settlement Agreement. Based on preliminary studies, it is expected that the avoidance alternatives considered in the SEIS will include one or more alignments that would shift the project to the north, resulting in additional connections to US 219, WV Route 32, and WV Route 93 in the vicinity of the towns of Thomas and Davis. However, final decisions on the scope of the SEIS will be made only after an opportunity for comment by interested agencies and the public during the scoping process, which will occur in May 2000.

Letters describing the proposed action and soliciting comments will be sent to appropriate federal, state, and local agencies, and to private organizations and citizens who have expressed or are known to have an interest in this proposal.

To ensure the full range of issues related to this proposed action are addressed and all significant issues identified, comments and suggestions are invited from all interested parties. Comments or questions concerning this proposed action should be directed to the FHWA at the address provided above.

(Catalog of Federal Domestic Assistance Program Number 20.205, Highway Research Planning and Construction. The regulations implementing Executive Order 12372 regarding intergovernmental consultation on Federal programs and activities apply to this program)

Issued on: May 2, 2000.

Henry E. Compton,

Environmental Coordinator, Charleston, West Virginia.

[FR Doc. 00-11860 Filed 5-10-00; 8:45 am]

BILLING CODE 4910-22-M

DEPARTMENT OF TRANSPORTATION

Federal Railroad Administration

[Docket Number FRA-1999-6364]

Northeast Illinois Railroad Corporation; Cancellation of Public Hearing

On April 4, 2000, the Federal Railroad Administration (FRA) published a notice in the **Federal Register** (65 FR 17704) announcing that a public hearing will be held based upon the Northeast Illinois Railroad Corporation's (Metra) request seeking a permanent waiver of compliance with the *Passenger Equipment Safety Standards*, 49 CFR part 238.303, which requires exterior calendar day inspection, and 238.313, which requires a class one brake test be performed by a qualified maintenance person. Metra has withdrawn its request; therefore, the hearing scheduled for Tuesday, May 16, 2000, in Chicago, Illinois, has been canceled.

FRA regrets any inconvenience occasioned by the cancellation of this hearing.

Issued in Washington, DC on May 8, 2000.

Grady C. Cothen, Jr.,

Deputy Associate Administrator for Safety Standards and Program Development.

[FR Doc. 00-11865 Filed 5-10-00; 8:45 am]

BILLING CODE 4910-06-P

DEPARTMENT OF TRANSPORTATION

Federal Railroad Administration

Notice of Safety Advisory 2000-1

AGENCY: Federal Railroad Administration (FRA), Department of Transportation (DOT).

ACTION: Notice of Safety Advisory.

SUMMARY: FRA is issuing Safety Advisory 2000-1 addressing safety concerns involving Model B1 relays, manufactured by General Railway Signal (GRS), between the years 1960 and 1985, and their potential to stick and remain in the energized position. ALSTOM Signaling, Inc., which has acquired GRS, estimates that approximately 2,000,000 relays are affected worldwide.

FOR FURTHER INFORMATION CONTACT:

William E. Goodman, Staff Director, Signal and Train Control Division, Office of Safety Assurance and Compliance, FRA, 1120 Vermont Avenue, NW, RRS-13, Mail Stop 25, Washington, DC 20590 (telephone 202-493-6325) or Mark Tessler, Trial Attorney, Office of Chief Counsel, 1120 Vermont Avenue, NW, RCC-12, Mail

Stop 10, Washington, DC 20590 (telephone 202-493-6061).

SUPPLEMENTARY INFORMATION: In a Safety Notice issued on August 18, 1995, GRS stated that it had received reports of ten incidents of a residual screw in the armature of a Type B1 relay not releasing from the lower core head surface within the specified time. GRS stated that this condition could develop in any application using one or more B1 relays. FRA is concerned about potential malfunctions in such relays which are critical to signal systems and their impact on safety if they do not operate within specified parameters.

In its Safety Notice, GRS concluded that:

1. The condition arises from the transfer of material from the cadmium-tin plated core head to the copper-silicon residual screw, which can cause the residual screw to adhere to the core head.

2. Any B1 relay manufactured by GRS between January 1960 and December 1985 incorporating residual screw Part No. 20360-012-00 (Catalog No. P62-255) could develop this condition.

3. The condition is more likely to occur in B1 Relays normally in the energized position used in one or more of the following circumstances:

- a. High temperature, *i.e.* ambient temperatures above 100 degrees Fahrenheit (38 degrees Celsius) on a regular basis; and/or

- b. Number of operations of the B1 Relay is less than four (4) times per day.

In order to avoid this condition, GRS recommended that all B1 Relays manufactured between January 1960 and December 1985 incorporating screw Part No. 20360-012-00 should be modified by replacing the residual screw in accordance with instructions provided by GRS.

FRA has determined that the safety of railroad employees and the general public compels the issuance of this Safety Advisory. Occurrences of GRS B1 Type relay failures have caused FRA serious concern about the safety of certain relays. The relays of concern were first identified by General Railway Signal, now ALSTOM Signaling, in a Safety Notice issued August 18, 1995. Any B1 relay manufactured by GRS between January 1960 and December 1985 incorporating residual screw Part No. 20360-012-00 (Catalog No. P62-255) could develop the condition of concern. The condition arises from the transfer of material from the cadmium-tin plated core head to the copper-silicon residual screw, which can cause the residual screw to adhere to the core head, not allowing the armature to

release from the lower core head surface within the specified time. The GRS recommended corrective action was to clean the relays, replace the residual screw, and in some cases replace the relay cores and bracket.

In July of 1999, after B1 relay failures were reported on the signal system of Washington Metropolitan Area Transit Authority, the FRA notified the Association of American Railroads, the American Public Transit Association, and the American Short Line and Regional Railroad Association, making those associations aware of the potential safety issue and asking that they bring the matter to the attention of their members.

Recommended Action

Subsequent to the July 1999 industry notification, additional reports of B1 relay failures have been reported to FRA. Due to these reports FRA is issuing this Safety Advisory, to again make all users of B1 relays aware of the potential problem and its recognized solution. While FRA is not at this time requiring immediate inspection and repair or replacement of all such relays, FRA strongly recommends that railroads accelerate B1 relay inspection and testing programs so that all B1 relays have been inspected (and repaired or replaced, if necessary) as soon as possible. FRA further recommends that all inspection and testing forces be made aware of this problem and especially of the likelihood that the condition is more likely to occur in B1 relays normally in the energized position and used in high temperature on a regular basis, or in which the number of operations of the relay is less than four times per day. (See GRS Safety Notice.)

FRA notes that present railroad safety regulations at title 49 of the Code of Federal Regulations require periodic testing of each relay affecting the safety of train operations (49 CFR 236.106) and each relay affecting the proper functioning of grade crossing warning systems (49 CFR 234.263). FRA further notes that 49 CFR 236.11 and 234.207 require that when any essential component of a signal system or highway rail crossing warning system fails to perform its intended signaling function or is not in correspondence with known operating conditions, the cause shall be determined and the faulty component adjusted, repaired, or replaced without undue delay. Therefore, if the B1 relay fails to perform as intended, pursuant to §§ 236.11 and 234.207, it must be replaced.

Copies of the Safety Notice issued by GRS, will be made available through the Regional Signal & Train Control Specialist or through the Signal & Train Control Division at FRA Headquarters, at 202-493-6325.

Issued in Washington, DC on May 5, 2000.

George Gavalla,

Associate Administrator for Safety.

[FR Doc. 00-11866 Filed 5-10-00; 8:45 am]

BILLING CODE 4910-06-P

DEPARTMENT OF THE TREASURY

Submission for OMB Review; Comment Request

May 4, 2000.

The Department of Treasury has submitted the following public information collection requirement(s) to OMB for review and clearance under the Paperwork Reduction Act of 1995, Public Law 104-13. Copies of the submission(s) may be obtained by calling the Treasury Bureau Clearance Officer listed. Comments regarding this information collection should be addressed to the OMB reviewer listed and to the Treasury Department Clearance Officer, Department of the Treasury, Room 2110, 1425 New York Avenue, NW., Washington, DC 20220.

DATES: Written comments should be received on or before June 12, 2000 to be assured of consideration.

Internal Revenue Service (IRS)

OMB Number: 1545-0805.

Form Number: IRS Form 5472.

Type of Review: Extension.

Title: Information Return of a 25% Foreign-Owned U.S. Corporation or a Foreign Corporation or a Foreign Corporation Engaged in a U.S. Trade or Business.

Description: Form 5472 is used to report information transactions between a U.S. corporation that is 25% foreign owned or a foreign corporation that is engaged in a U.S. trade or business and related foreign parties. The IRA uses Form 5472 to determine if inventory or other costs deducted by the U.S. or foreign corporation are correct.

Respondents: Business or other for-profit.

Estimated Number of Respondents/Recordkeepers: 75,000.

Estimated Burden Hours Per Respondent/Recordkeeper:

Recordkeeping—17 hr., 42 min.

Learning about the law or the form—3 hr., 5 min.

Preparing and sending the form to the IRS—3 hr., 30 min.

Frequency of Response: Annually.