

Proposed Rules

Federal Register

Vol. 88, No. 192

Thursday, October 5, 2023

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF AGRICULTURE

Rural Housing Service

7 CFR Parts 3550 and 3555

[Docket No. RHS–23–SFH–0007]

RIN 0575–AD32

Updating Manufactured Housing Provisions; Extension of Comment Period

AGENCY: Rural Housing Service, Department of Agriculture (USDA).
ACTION: Proposed rule; extension of comment period.

SUMMARY: The Rural Housing Service (RHS or Agency), a Rural Development agency of the United States Department of Agriculture (USDA), is announcing an extension of the public comment period by 15 days for the notice of proposed rulemaking for the “Updating Manufactured Housing Provisions.” The intent of the extended comment period is to allow the public additional time to review and provide comments on the proposed changes.

DATES: The comment period for the proposed rule published on August 16, 2023, at 88 FR 55601, is extended. Comments must be received on or before October 31, 2023.

ADDRESSES: Comments may be submitted electronically by the Federal eRulemaking Portal: Go to <https://www.regulations.gov> and, in the “Search Field” box, labeled “Search for dockets and documents on agency actions,” enter the following docket number: https://aiomostl0as096.usda.net/desktop/container/?locale=en_US-/home (RHS–23–SFH–0007) or RIN# 0575–AD32, then click search. To submit or view public comments, select the following document title: (Updating Manufactured Housing Provisions) from the “Search Results,” and select the “Comment” button. Before inputting your comments, you may also review the “Commenter’s Checklist” (optional). Insert your comments under the

“Comment” title, click “Browse” to attach files (if available). Input your email address and select “Submit Comment.” Information on using [Regulations.gov](https://www.regulations.gov), including instructions for accessing documents, submitting comments, and viewing the docket after the close of the comment period, is available through the site’s “FAQ” link.

Other Information: Additional information about Rural Development and its programs is available on the internet at <https://www.rurdev.usda.gov/index.html>.

All comments will be available for public inspection online at the Federal eRulemaking Portal (<https://www.regulations.gov>).

FOR FURTHER INFORMATION CONTACT:

Sonya Evans, Finance & Loan Analyst, SFH Direct Loan Division, Rural Housing Service, Rural Development, United States Department of Agriculture, 1400 Independence Avenue SW, Washington, DC 20250, Phone: 423–268–4333, Email: sonya.evans@usda.gov. Or contact Stephanie Freeman, Finance & Loan Analyst, Policy, Analysis, and Communications Branch, Single Family Housing Guaranteed Loan Division, Rural Housing Service, Rural Development, United States Department of Agriculture, 1400 Independence Avenue SW, Washington, DC 20250, Phone: 314–457–6413, Email: stephanie.freeman@usda.gov.

SUPPLEMENTARY INFORMATION: In the **Federal Register** of August 16, 2023 (88 FR 55601), the Agency published a proposed rule entitled, “Updating Manufactured Housing Provisions.” The intent of the proposed rule is to suggest Agency changes to the current regulations for the Single-Family Housing (SFH) Section 502 Direct and the SFH Guaranteed Loan Program to allow the Agency to give borrowers increased purchase options within a competitive market and increase adequate housing along with an enhanced customer experience with the SFH programs. The proposed rule initially provided a 60-day period for submission of public comments on or before October 16, 2023. The Agency is extending the comment period for public comments to October 31, 2023, to

allow for additional review and submission time.

Joaquin Altoro,

Administrator, Rural Housing Service.

[FR Doc. 2023–22184 Filed 10–4–23; 8:45 am]

BILLING CODE 3410–XV–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2023–1989; Project Identifier AD–2023–00512–E]

RIN 2120–AA64

Airworthiness Directives; International Aero Engines, LLC Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain International Aero Engines, LLC (IAE) Model PW1124G1–JM, PW1127G–JM, PW1127GA–JM, PW1129G–JM, PW1130G–JM, PW1133G–JM, and PW1133GA–JM engines. This proposed AD was prompted by a report that certain high-pressure compressor (HPC) 2nd stage rotors and HPC 4th stage rotors have potentially degraded knife-edge seals and abrasive coating of the rear wing 4th stage rotor due to having been cleaned in alkaline solution without masking the knife-edge seal coating. Operating in this condition could result in material degradation and fracture of the HPC 2nd stage rotor and HPC 4th stage rotor. This proposed AD would require replacement of certain HPC 2nd stage rotors and HPC 4th stage rotors. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by November 20, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to www.regulations.gov. Follow the instructions for submitting comments.
- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) by searching for and locating Docket No. FAA-2023-1989; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For Pratt & Whitney service information identified in this NPRM, contact International Aero Engines, LLC, 400 Main Street, East Hartford, CT 06118; phone: (860) 565-0140; email: help24@pw.utc.com; website: connect.prattwhitney.com.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

FOR FURTHER INFORMATION CONTACT:

Mark Taylor, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (781) 238-7229; email: mark.taylor@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2023-1989; Project Identifier AD-2023-00512-E” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any

recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Mark Taylor, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA was notified that on certain IAE Model PW1124G1-JM, PW1127G-JM, PW1127GA-JM, PW1129G-JM, PW1130G-JM, PW1133G-JM, and PW1133GA-JM engines, a batch of HPC 2nd stage rotors and HPC 4th stage

rotors could have degraded knife-edge seals and abrasive coating on the rear wing 4th stage rotor due to having been cleaned in alkaline solution without masking the knife-edge seal coating. Operating in this condition could result in material degradation and fracture of the HPC 2nd stage rotor and HPC 4th stage rotor. This condition, if not addressed, could result in uncontained part release or dual-engine shutdown, damage to the engine, damage to the airplane, and loss of the airplane.

FAA’s Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Pratt & Whitney Service Bulletin (SB) PW1000G-C-72-00-0208-00A-930A-D, Issue 001, dated September 13, 2022. This service information identifies the affected HPC 2nd stage rotors and HPC 4th stage rotors and specifies procedures for inspection and repair of the HPC 2nd stage rotors and HPC 4th stage rotors. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

Proposed AD Requirements in This NPRM

This proposed AD would require replacement of the affected HPC 2nd stage rotor and HPC 4th stage rotor with parts eligible for installation.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 6 engines installed on airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace HPC 2nd stage rotor and HPC 4th stage rotor with repaired parts.	73 work-hours × \$85 per hour = \$6,205	\$0	\$6,205	\$37,230

Operators may choose to use new parts instead of repaired parts to comply with this proposed AD. For replacement

with new parts, the FAA estimates the following costs:

Action	Labor cost	Parts cost	Cost per product
Replace HPC 2nd stage rotor	32 work-hours × \$85 per hour = \$2,720	\$312,000	\$314,720
Replace HPC 4th stage rotor	32 work-hours × \$85 per hour = \$2,720	244,000	246,720

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

International Aero Engines, LLC: Docket No. FAA-2023-1989; Project Identifier AD-2023-00512-E.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by November 20, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to International Aero Engines, LLC Model PW1124G1-JM, PW1127G-JM, PW1127GA-JM, PW1129G-JM, PW1130G-JM, PW1133G-JM, and PW1133GA-JM engines having a high-pressure compressor (HPC) 2nd stage rotor or HPC 4th stage rotor having a part number and serial number identified in the Applicability, Table 2, of Pratt & Whitney Service Bulletin (SB) PW1000G-C-72-00-0208-00A-930A-D, Issue 001, dated September 13, 2022 (Pratt & Whitney SB PW1000G-C-72-00-0208-00A-930A-D).

(d) Subject

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section.

(e) Unsafe Condition

This AD was prompted by a report that certain HPC 2nd stage rotors and HPC 4th stage rotors have potentially degraded knife-edge seals and abrasive coating of the rear wing 4th stage rotor due to having been cleaned in alkaline solution without masking the knife-edge seal coating. The FAA is issuing this AD to prevent material degradation and fracture of the HPC 2nd stage rotor and HPC 4th stage rotor. The unsafe condition, if not addressed, could result in uncontained part release or dual-engine shutdown, damage to engine, damage to airplane, and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

- (1) At the next engine shop visit after the effective date of this AD, remove the HPC 2nd stage rotor having a part number and

serial number identified in the Applicability, Table 2, of Pratt & Whitney SB PW1000G-C-72-00-0208-00A-930A-D and replace with a part eligible for installation.

- (2) At the next engine shop visit after the effective date of this AD, remove the HPC 4th stage rotor having a part number and serial number identified in the Applicability, Table 2, of Pratt & Whitney SB PW1000G-C-72-00-0208-00A-930A-D and replace with a part eligible for installation.

(h) Definitions

- (1) For the purposes of this AD, a "part eligible for installation" is:

- (i) Any HPC 2nd stage rotor or HPC 4th stage rotor, as applicable, that does not have a part number and serial number identified in the Applicability, Table 2, of Pratt & Whitney SB PW1000G-C-72-00-0208-00A-930A-D; or
- (ii) Any HPC 2nd stage rotor or HPC 4th stage rotor, as applicable, that has incorporated Pratt & Whitney SB PW1000G-C-72-00-0208-00A-930A-D.

- (2) For the purposes of this AD, an engine shop visit is the induction of an engine into the shop for maintenance involving the separation of the "H" flange.

(i) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, AIR-520 Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the AIR-520 Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to: ANE-AD-AMOC@faa.gov.
- (2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

- (2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Mark Taylor, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (781) 238-7229; email: mark.taylor@faa.gov.

(k) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Pratt & Whitney Service Bulletin PW1000G-C-72-00-0208-00A-930A-D, Issue 001, dated September 13, 2022.

(ii) [Reserved]

(3) For Pratt & Whitney service information identified in this AD, contact International Aero Engines, LLC, 400 Main Street, East Hartford, CT 06118; phone: (860) 565-0140; email: help24@pw.utc.com; website: connect.prattwhitney.com.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on September 29, 2023.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-22174 Filed 10-4-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-1987; Project Identifier MCAI-2023-00807-T]

RIN 2120-AA64

Airworthiness Directives; ATR—GIE Avions de Transport Régional Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2021-17-02, which applies to all ATR—GIE Avions de Transport Régional Model ATR42-200, -300, and -320 airplanes. AD 2021-17-02 requires a one-time inspection for discrepancies of the wire bundles between the left- and right-hand angle of attack (AOA) probes and the crew alerting computer, and, depending on findings, applicable corrective actions. AD 2021-17-02 also required for certain airplanes, modifying the captain stick shaker wiring, and for all airplanes, revising the existing aircraft flight manual (AFM) and applicable corresponding operational procedures to incorporate procedures for the stick pusher/shaker. Since the FAA issued AD 2021-17-02, a

modification was developed to the affected wiring. This proposed AD would require installing a new AOA power supply unit and revising the existing AFM, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by November 20, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2023-1987; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For the EASA ADs identified in this NPRM, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website ad.easa.europa.eu. It is also available at regulations.gov under Docket No. FAA-2023-1987.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 206-231-3220; email: shahram.daneshmandi@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or

arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2023-1987; Project Identifier MCAI-2023-00807-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Shahram Daneshmandi, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 206-231-3220; email: shahram.daneshmandi@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued AD 2021-17-02, Amendment 39-21685 (86 FR 48490, August 31, 2021) (AD 2021-17-02), for all ATR—GIE Avions de Transport Régional Model ATR42-200, -300, and -320 airplanes. AD 2021-17-02 was prompted by an MCAI originated by EASA, which is the Technical Agent for the Member States of the European Union. EASA issued AD 2021-0024, dated January 19, 2021, to correct false