§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2017-06-02 Fokker Services B.V.:

Amendment 39–18826; Docket No. FAA–2016–9302; Directorate Identifier 2016–NM–037–AD.

(a) Effective Date

This AD is effective April 26, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Fokker Services B.V. Model F28 Mark 0100 airplanes, certificated in any category, all serial numbers if equipped with Rolls-Royce TAY 650–15 engines.

(d) Subject

Air Transport Association (ATA) of America Code 11, Placards and Markings.

(e) Reason

This AD was prompted by reports of uncontained engine fan blade failures in Rolls-Royce TAY 650–15 engines. We are issuing this AD to prevent certain engine thrust settings during ground operation, which can cause the fan blades to flutter and fail, resulting in damage to the airplane and possible injury to personnel.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Installation of Caution Placard

Within 6 months after the effective date of this AD, install a caution placard in the flight compartment, between the standby engine indicator (SEI) and the multi-functional display unit (MFDU), in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100–11–027, dated April 18, 2013.

Note 1 to paragraph (g) of this AD: Additional information can be found in Fokker All Operators Message AOF100.177 #05, dated April 18, 2013.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149. Information may be emailed to: 9-ANM-116AMOG-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Fokker Services B.V.'s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(i) Related Information

- (1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2013–0141, dated July 12, 2013, for related information. This MCAI may be found in the AD docket on the Internet at http:// www.regulations.gov by searching for and locating Docket No. FAA–2016–9302.
- (2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1137; fax 425–227–1149.
- (3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (j)(3) and (j)(4) of this AD.

(j) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.
- (i) Fokker Service Bulletin SBF100–11–027, dated April 18, 2013.
 - (ii) Reserved.
- (3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone: +31 (0)88–6280–350; fax: +31 (0)88–6280–111; email: technicalservices@fokker.com; Internet http://www.myfokkerfleet.com.
- (4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.
- (5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http://www.archives.gov/federal-register/cfr/ibrlocations.html.

Issued in Renton, Washington, on March 7, 2017.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 2017–05161 Filed 3–21–17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Office of the Secretary

14 CFR Part 234

[Docket No. DOT-OST-2014-0056] RIN 2105-AE66

Enhancing Airline Passenger Protections III: Extension of Compliance Date for Provision Concerning Baggage Handling Statistics Report

AGENCY: Office of the Secretary (OST), Department of Transportation (DOT).

ACTION: Final rule.

22, 2017.

SUMMARY: The Department of Transportation is amending its regulations by extending the compliance date from January 1, 2018, to January 1, 2019, for the provision concerning reporting of baggage handling statistics in the Department's final rule on enhancing airline passenger protections. This extension is necessary to ensure consistency with the change of compliance date for the Department's final rule on reporting of data for mishandled baggage and wheelchairs.

DATES: This final rule is effective March

FOR FURTHER INFORMATION CONTACT:

Blane A. Workie, Office of Aviation Enforcement and Proceedings, U.S. Department of Transportation, 1200 New Jersey Ave. SE., Washington, DC, 20590, 202–366–9342, 202–366–7152 (fax), blane.workie@dot.gov (email).

SUPPLEMENTARY INFORMATION: On November 3, 2016, the Department of Transportation published a final rule in the Federal Register (81 FR 76800), titled "Enhancing Airline Passenger Protections III" (RIN 2105-AE11). This rule, among other things, expands the pool of carriers that must report airline service and performance data from any carrier that accounts for at least 1% of domestic scheduled passenger revenue to any carrier that accounts for at least 0.5% of domestic scheduled passenger revenue. It also requires reporting carriers to separately report airline service and performance data for their domestic scheduled flights operated by their code-share partners. This means that, under the November 2016 final

rule, for air transportation taking place on or after January 1, 2018, airlines that account for at least 0.5% of domestic scheduled passenger revenue must provide airline service and performance data for flights they operate and separately for flights held out with their designator code and operated by their code-share partners. The airline service and performance data that is required consists of on-time performance, mishandled baggage and oversales data.

On March 2, 2017, the Department issued a rule extending the compliance date of its final rule on reporting of data for mishandled baggage and wheelchairs in aircraft cargo compartments to January 1, 2019. That final rule addressed the methodology for collection of mishandled baggage information and required separate statistics for mishandled wheelchairs and scooters used by passengers with disabilities. The change to the matrix on how to report mishandled baggage and to provide separate reporting of mishandled wheelchairs and scooters was incorporated into the Department's **Enhancing Airline Passenger Protections** III final rule. As such, this document is extending the compliance date to January 1, 2019 for the provision concerning baggage handling statistics in the Department's final rule on enhancing airline passenger protections. The compliance date for the requirements pertaining to on-time performance and oversales remain unchanged.

As is the case today, until January 1, 2019, airlines that account for at least 1% of domestic scheduled passenger revenue will continue to provide mishandled baggage data only for flights they operate based on the number of Mishandled Baggage Reports and the number of domestic passenger enplanement. Airlines that account for at least 0.5% but less than 1% of the domestic scheduled passenger revenue are not required to provide mishandled baggage data until February 15, 2019 for air transportation taking place on or after January 1, 2019. Separate statistics for mishandled wheelchairs and scooters used by passengers with disabilities and transported in aircraft cargo compartment are not required until January 1, 2019.

List of Subjects in 14 CFR Part 234

Air carriers, Mishandled baggage, Ontime statistics, Reporting, Uniform system of accounts.

Issued this 9th day of March 2017, in Washington, DC under authority delegated in 49 CFR 1.27(n):

Judith S. Kaleta,

Deputy General Counsel.

Accordingly, the Department of Transportation amends 14 CFR part 234 as follows:

PART 234—[AMENDED]

■ 1. The authority citation for part 234 continues to read as follows:

Authority: 49 U.S.C. 329, 41101, and 41701.

■ 2. Section 234.6 is revised to read as follows:

§ 234.6 Baggage-handling statistics.

(a) For air transportation taking place before January 1, 2019, an air carrier certificated under 49 U.S.C. 41102 that accounts for at least 1 percent of domestic scheduled-passenger revenues in the most recently reported 12-month period as defined by the Department's Office of Airline Information, and as reported to the Department pursuant to part 241 of this title shall, for the flights it operates, report monthly to the Department on a domestic system basis, excluding charter flights, the total number of passengers enplaned systemwide and the total number of mishandled-baggage reports filed with the carrier for any nonstop flight, including a mechanically delayed flight, to or from any airport within the contiguous 48 states that accounts for at least 1 percent of domestic scheduledpassenger enplanements in the previous calendar year, as reported to the Department pursuant to part 241 of this title.

(b) For air transportation taking place on or after January 1, 2019, an air carrier certificated under 49 U.S.C. 41102 that accounts for at least 0.5 percent of domestic scheduled-passenger revenues in the most recently reported 12-month period as defined by the Department's Office of Airline Information, and as reported to the Department pursuant to part 241 of this title shall report monthly to the Department on a domestic system basis, excluding charter flights:

(1) The total number of checked bags enplaned, including gate checked baggage, "valet bags," interlined bags, and wheelchairs and scooters enplaned in the aircraft cargo compartment for any domestic nonstop scheduled passenger flight, including a mechanically delayed flight, operated by the carrier to or from any U.S. large, medium, small or non-hub airport as defined in 49 U.S.C. 41702 and

separately for any domestic nonstop scheduled passenger flight, including a mechanically delayed flight, held out with only the carrier's designator code to or from any U.S. large, medium, small, or non-hub airport as defined in 49 U.S.C. 47102 and operated by any code-share partner that is a certificated air carrier or commuter air carrier;

(2) The total number of wheelchairs and scooters that were enplaned in the aircraft cargo compartment for any domestic nonstop scheduled passenger flight, including a mechanically delayed flight, operated by the carrier to or from any U.S. large, medium, small or nonhub airport as defined in 49 U.S.C. 41702 and separately for any domestic nonstop scheduled passenger flight, including a mechanically delayed flight, held out with only the carrier's designator code to or from any U.S. large, medium, small, or non-hub airport as defined in 49 U.S.C. 47102 and operated by any code-share partner that is a certificated air carrier or commuter air carrier;

(3) The number of mishandled checked bags, including gate-checked baggage, "valet bags," interlined bags and wheelchairs and scooters that were enplaned in the aircraft cargo compartment for any domestic nonstop scheduled passenger flight, including a mechanically delayed flight, operated by the carrier to or from any U.S. large, medium, small or non-hub airport as defined in 49 U.S.C. 41702 and separately for any domestic nonstop scheduled passenger flight, including a mechanically delayed flight, held out with only the carrier's designator code to or from any U.S. large, medium, small, or non-hub airport as defined in 49 U.S.C. 47102 and operated by any code-share partner that is a certificated air carrier or commuter air carrier; and

(4) The number of mishandled wheelchairs and scooters that were enplaned in the aircraft cargo compartment for any domestic nonstop scheduled passenger flight, including a mechanically delayed flight, operated by the carrier to or from any U.S. large, medium, small or non-hub airport as defined in 49 U.S.C. 41702 and separately for any domestic nonstop scheduled passenger flight, including a mechanically delayed flight, held out with only the carrier's designator code to or from any U.S. large, medium, small, or non-hub airport as defined in 49 U.S.C. 47102 and operated by any code-share partner that is a certificated air carrier or commuter air carrier.

(c) The information in paragraphs (a) and (b) of this section shall be submitted to the Department within 15 days after the end of the month to which the

information applies and must be submitted with the transmittal accompanying the data for on-time performance in the form and manner set forth in accounting and reporting directives issued by the Director, Office of Airline Information.

[FR Doc. 2017–05113 Filed 3–21–17; 8:45 am] BILLING CODE 4910–9X–P

DEPARTMENT OF DEFENSE

Department of the Navy

32 CFR Part 706

Certifications and Exemptions Under the International Regulations for Preventing Collisions at Sea, 1972

AGENCY: Department of the Navy, DoD. **ACTION:** Final rule.

SUMMARY: The Department of the Navy (DoN) is amending its certifications and exemptions under the International Regulations for Preventing Collisions at Sea, 1972 (72 COLREGS), to reflect that the Deputy Assistant Judge Advocate General (DAJAG) (Admiralty and Maritime Law) has determined that USS PORTLAND (LPD 27) is a vessel of the Navy which, due to its special construction and purpose, cannot fully comply with certain provisions of the 72 COLREGS without interfering with its special function as a naval ship. The intended effect of this rule is to warn mariners in waters where 72 COLREGS apply.

DATES: This rule is effective March 22, 2017 and is applicable beginning March 2, 2017.

FOR FURTHER INFORMATION CONTACT:

Commander Theron R. Korsak, (Admiralty and Maritime Law), Office of the Judge Advocate General, Department of the Navy, 1322 Patterson Ave. SE., Suite 3000, Washington Navy Yard, DC 20374–5066, telephone 202–685–5040.

SUPPLEMENTARY INFORMATION: Pursuant to the authority granted in 33 U.S.C. 1605, the DoN amends 32 CFR part 706.

This amendment provides notice that the DAJAG (Admiralty and Maritime Law), under authority delegated by the Secretary of the Navy, has certified that USS PORTLAND (LPD 27) is a vessel of the Navy which, due to its special construction and purpose, cannot fully comply with the following specific provisions of 72 COLREGS without interfering with its special function as a naval ship: Annex I paragraph 2(i)(i), Rule 27(a)(i) and (b)(i), pertaining to the placement of all-round task lights in a vertical line; Annex I, paragraph 3(a), pertaining to the horizontal distance between the forward and after masthead lights; and Annex I, paragraph 2(k) as described in Rule 30(a)(i), pertaining to the vertical separation between anchor lights. The DAJAG (Admiralty and Maritime Law) has also certified that the lights involved are located in closest possible compliance with the applicable 72 COLREGS requirements.

Moreover, it has been determined, in accordance with 32 CFR parts 296 and 701, that publication of this amendment for public comment prior to adoption is impracticable, unnecessary, and

contrary to public interest since it is based on technical findings that the placement of lights on this vessel in a manner differently from that prescribed herein will adversely affect the vessel's ability to perform its military functions.

List of Subjects in 32 CFR Part 706

Marine safety, Navigation (water), Vessels.

For the reasons set forth in the preamble, the DoN amends part 706 of title 32 of the Code of Federal Regulations as follows:

PART 706—CERTIFICATIONS AND EXEMPTIONS UNDER THE INTERNATIONAL REGULATIONS FOR PREVENTING COLLISIONS AT SEA, 1972

■ 1. The authority citation for part 706 continues to read:

Authority: 33 U.S.C. 1605.

- 2. Section 706.2 is amended by:
- a. In Table Three, adding, in alpha numerical order, by vessel number, an entry for USS PORTLAND (LPD 27);
- b. In Table Four, paragraph 20., adding, in alpha numerical order, by vessel number, an entry for USS PORTLAND (LPD 27); and
- c. In Table Five, by adding, in alpha numerical order, by vessel number, an entry for USS PORTLAND (LPD 27).

The additions read as follows:

§ 706.2 Certifications of the Secretary of the Navy under Executive Order 11964 and 33 U.S.C. 1605.

* * * * *

TABLE THREE

| | Vessel | No. | Masthead lights arc of visibility; rule 21(a) | Side lights arc of visibility; rule 21(b) | Stern light arc of visibility; rule 21(c) | Side lights distance inboard of ship's sides in meters 3(b) annex 1 | Stern light, distance forward of stern in meters; rule 21(c) | Forward anchor light, height above hull in meters; 2(K) annex 1 | Anchor lights relationship of aft light to forward light in meters 2(K) annex |
|--------------|--------|-------------|--|--|--|---|---|--|---|
| USS PORTLAND | * | * LPD 27 | * | * | * | | * | * | 1.55 below. |
| | * | * | * | * | * | | * | * | |

Table Four 20. * * *

* * * * *