principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM– 116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): Except as required by paragraphs (g)(1) and (g)(2) of this AD: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014–0136, dated June 13, 2014, for related information. This MCAI may be found in the AD docket on the Internet at *http://www.regulations.gov* by searching for and locating Docket No. FAA– 2016–9192.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (k)(4) of this AD.

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A330–53–3215, Revision 02, dated November 23, 2016.

(ii) Airbus Service Bulletin A340–53–4215, Revision 02, dated November 23, 2016.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email *airworthiness.A330-A340@airbus.com*; Internet *http://www.airbus.com*.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http:// www.archives.gov/federal-register/cfr/ibrlocations.html.

Issued in Renton, Washington, on March 28, 2017.

### Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 2017–06712 Filed 4–19–17; 8:45 am] BILLING CODE 4910–13–P

#### DEPARTMENT OF TRANSPORTATION

### **Federal Aviation Administration**

### 14 CFR Part 71

[Docket No. FAA-2016-9286; Airspace Docket No. 16-ANM-13]

# Establishment of Class E Airspace, Denver, CO

**AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule.

**SUMMARY:** This action establishes Class E en route airspace extending upward from 1,200 feet above the surface to accommodate instrument flight rules (IFR) aircraft under control of the Denver Air Route Traffic Control Center (ARTCC), Denver, CO. Establishment of this airspace area is necessary to ensure controlled airspace exists in those areas where the Federal airway structure is inadequate.

**DATES:** Effective 0901 UTC, June 22, 2017. The Director of the Federal Register approves this incorporation by reference action under Title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.11A, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/ air\_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: 202–267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to http://www.archives.gov/ federal register/code of federalregulations/ibr locations.html.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15. FOR FURTHER INFORMATION CONTACT: Tom Clark, Federal Aviation Administration, Operations Support Group, Western Service Center, 1601 Lind Avenue SW., Renton, WA 98057; telephone (425) 203–4511.

#### SUPPLEMENTARY INFORMATION:

#### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes Class E en route airspace at Denver Air Route Traffic Control Center, Denver, CO to ensure controlled airspace exists in those areas where the Federal airway structure is inadequate.

# History

On November 16, 2016, the FAA published in the **Federal Register** (81 FR 80620) Docket FAA–2016–9286 a notice of proposed rulemaking to establish Class E en route airspace extending upward from 1,200 feet above the surface at Denver, CO. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6006 of FAA Order 7400.11A, dated August 3, 2016, and effective September 15, 2016, which is incorporated by reference in 14 CFR part 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

### Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.11A, Airspace Designations and Reporting Points, dated August 3, 2016, and effective September 15, 2016. FAA Order 7400.11A is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11A lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

## The Rule

This amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 establishes Class E en route airspace extending upward from 1,200 feet above the surface at Denver, CO, within the area controlled by the Denver Air Route Traffic Control Center, Denver, CO. This airspace is established to support en route IFR operations where the airway structure is inadequate.

# **Regulatory Notices and Analyses**

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT **Regulatory Policies and Procedures (44** FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

## **Environmental Review**

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5–6.5a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

#### Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

### Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

## PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

#### §71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.11A, Airspace Designations and Reporting Points, dated August 3, 2016, and effective September 15, 2016, is amended as follows:

Paragraph 6006 En Route Domestic Airspace Areas.

\* \* \* \* \*

### ANM CO E6 Denver, CO [New]

That airspace extending upward from 1,200 feet above the surface within an area bounded by lat. 44°57'30" N., long. 103°10'00" W.; to lat. 44°42'00" N., long. 101°29'00" W.; to lat. 43°42'30" N., long. 101°24'30" W.; to lat. 43°17'20" N., long. 100°06'00" W.; to lat. 42°00'00" N., long. 099°01'00" W.; to lat. 39°59'00" N., long.099°03'30" W.; to lat. 39°28'00" N., long. 098°48'00" W.; to lat. 37°30'00" N., long. 102°33'00" W.; to lat. 36°43'00" N., long. 105°00'00" W.; to lat. 36°43'00" N., long. 106°05'00" W.; to lat. 36°12'00" N., long. 107°28'00" W.; to lat. 36°02'00" N., long. 108°13'00" W.; to lat. 35°42'00" N., long. 110°14'00" W.; to lat. 35°46'00" N., long. 111°50'30" W.; to lat. 36°25'15" N., long. 111°30′15″ W.; to lat. 36°44′00″ N., long. 111°36′30″ W.; to lat. 37°24′45″ N., long. 111°52'45" W.; to lat. 37°50'00" N., long. 110°53'00" W.; to lat. 38°07'45" N., long. 110°09'25" W.; to lat. 38°12'00" N., long. 109°59'00" W.; to lat. 38°56'00" N., long. 109°59'00" W.; to lat. 39°13'00" N., long.  $109^\circ 59' 00''$  W.; to lat.  $39^\circ 35' 00''$  N., long. 110°18'00" W.; to lat. 40°00'00" N., long. 109°10'00" W.; to lat. 40°51'00" N., long. 109°06'00" W.; to lat. 41°22'00" N., long. 108°16'30" W.; to lat. 41°36'30" N., long. 108°00'00" W.; to lat. 42°25'00" N., long. 107°03'00" W.; to lat. 43°53'00" N., long. 107°17′00″ W.; to lat. 44°19′00″ N., long. 106°16'00" W.; to lat. 45°14'15" N., long. 106°00'00" W.; to lat. 45°07'00" N., long. 104°15′00" W.; thence to the point of beginning.

Issued in Seattle, Washington, on April 7, 2017.

### Sam S.L. Shrimpton,

Acting Group Manager, Operations Support Group, Western Service Center. [FR Doc. 2017–07788 Filed 4–19–17; 8:45 am] BILLING CODE 4910–13–P

# DEPARTMENT OF TRANSPORTATION

## Federal Aviation Administration

### 14 CFR Part 71

[Docket No. FAA-2016-9264; Airspace Docket No. 16-AWP-1]

### Establishment, Modification and Revocation of Air Traffic Service (ATS) Routes; Western United States

**AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule.

**SUMMARY:** This action modifies three jet routes and four VHF Omnidirectional Range (VOR) Federal airways; removes two VOR Federal Airway routes, and establishes four and modifies three low altitude Area Navigation (RNAV) routes (T-routes) in the western United States. The FAA is taking this action due to the scheduled decommissioning of the Manteca, CA, and Maxwell, CA, VOR facilities, which provide navigation guidance for portions of the affected routes. This action enhances the safety and management of aircraft along these routes within the National Airspace System (NAS). The VOR Federal airway, V–244, published in the notice of proposed rulemaking, requires more coordination and is not being finalized in this action.

**DATES:** Effective date 0901 UTC, June 22, 2017. The Director of the Federal Register approves this incorporation by reference action under Title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA, Order 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.11A, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/ *air traffic/publications/.* For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11A at NARA, call (202) 741–6030, or go to *http://* www.archives.gov/federal register/ code of federal-regulations/ibr locations.html.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

**FOR FURTHER INFORMATION CONTACT:** Kenneth Ready, Airspace Policy Group,