(g) Retained Inspection and Corrective Action, With Revised Service Information

This paragraph restates the requirements of paragraph (g) of AD 2014-03-07, with revised service information. For airplanes identified in Boeing Service Bulletin MD11-28-126, Revision 1, dated June 18, 2009: Within 60 months after February 4, 2010 (the effective date of AD 2009-26-16, Amendment 39-16155 (74 FR 69249, December 31, 2009)), do the actions specified in paragraphs (g)(1) through (g)(5) of this AD, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Service Bulletin MD11-28-126, Revision 1, dated June 18, 2009; Revision 4, dated November 29, 2011; or Revision 6, dated July 1, 2016; except as required by paragraph (k) of this AD. As of the effective date of this AD, only Boeing Service Bulletin MD11-28-126, Revision 6, dated July 1, 2016, may be used. Do all applicable corrective actions before further

- (1) Do a general visual inspection of the wire bundles between Stations 1238.950 and 1361.000 to determine if wires touch the upper surface of the center upper auxiliary fuel tank, and mark the location, as applicable.
- (2) Do a detailed inspection for splices and damage of all wire bundles above the center upper auxiliary fuel tank between Stations 1218.950 and 1381.000.
- (3) Do a detailed inspection for damage (burn marks) of the upper surface of the center upper auxiliary fuel tank.
- (4) Do a detailed inspection for damage (burn marks) on the fuel vapor barrier seal.
- (5) Install a nonmetallic barrier/shield sleeving, new clamps, new attaching hardware, and a new extruded channel.

(h) Retained Additional Inspections and Corrective Action, With Revised Service Information

This paragraph restates the requirements of paragraph (h) of AD 2014-03-07, with revised service information. For airplanes in Group 1, Configuration 2; Group 2, Configuration 2; and Group 5, Configuration 2; as identified in Boeing Service Bulletin MD11-28-126, Revision 4, dated November 29, 2011: Within 60 months after March 26, 2014 (the effective date of AD 2014-03-07). do a detailed inspection of wire bundles for splices and damage (chafing, arcing, and broken insulation) and damage (burn marks) on the upper surface of the center upper auxiliary fuel tank and fuel vapor barrier seal; install barrier/shield sleeving and clamping; and do all applicable corrective actions at the applicable locations specified in paragraphs (h)(1) through (h)(3) of this AD, in accordance with the Accomplishment Instructions of Boeing Service Bulletin MD11-28-126, Revision 4, dated November 29, 2011; or Boeing Service Bulletin MD11 28-126, Revision 6, dated July 1, 2016; except as required by paragraph (k) of this AD. As of the effective date of this AD, only Boeing Service Bulletin MD11-28-126, Revision 6, dated July 1, 2016, may be used for the actions required by this paragraph. Do all applicable corrective actions before further flight.

- (1) For Group 1, Configuration 2 airplanes, between Stations 1238.950 and 1381.000, Stations 1238.950 and 1256.000, and Stations 1238.950 and 1256.800, depending on passenger or freighter configuration.
- (2) For Group 2, Configuration 2 airplanes, between Stations 1238.950 and 1275.250, and Stations 1238.950 and 1275.250, passenger configuration only.
- (3) For Group 5, Configuration 2 airplanes, between Stations 1381.000 and 1238.950.

(i) New Inspections and Corrective Actions for Certain Airplanes

For Groups 1, 2, and 5 Configuration 2 airplanes, as identified in Boeing Service Bulletin MD11–28–126, Revision 6, dated July 1, 2016: Within 60 months after the effective date of this AD, do the actions required by paragraphs (i)(1) and (i)(2) of this AD, in accordance with the Accomplishment Instructions of Boeing Service Bulletin MD11–28–126, Revision 6, dated July 1, 2016.

- (1) Do a general visual inspection of the wire bundles at the additional center upper auxiliary fuel tank locations to determine if wires touch the upper surface of the fuel tank, and mark the location as applicable.
- (2) Do a detailed inspection of the wire bundles for splices and damage on the upper surface of the center upper auxiliary fuel tank and fuel vapor barrier seal; install barrier/ shield sleeving, clamping, and extruded channels, as applicable; and do all applicable corrective actions before further flight; except as required by paragraph (k) of this AD.

(j) New Requirements for Line Number 579

For airplane Line Number 579: Within 60 months after the effective date of this AD, do the actions specified in paragraphs (g)(1) through (g)(5) of this AD, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Service Bulletin MD11–28–126, Revision 6, dated July 1, 2016, except as required by paragraph (k) of this AD. Do all applicable corrective actions before further flight.

(k) Exception to Service Information Specifications

Where Boeing Service Bulletin MD11–28–126, Revision 1, dated June 18, 2009; Boeing Service Bulletin MD11–28–126, Revision 4, dated November 29, 2011; or Boeing Service Bulletin MD11–28–126, Revision 6, dated July 1, 2016; specifies to contact The Boeing Company for repair instructions: Before further flight, repair the auxiliary fuel tank using a method approved in accordance with the procedures specified in paragraph (m) of this AD.

(l) Credit for Previous Actions

- (1) This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before March 26, 2014 (the effective date of AD 2014–03–07), using the service information specified in paragraphs (l)(1)(i) or (l)(1)(ii) of this AD.
- (i) Boeing Service Bulletin MD11–28–126, Revision 2, dated November 18, 2010.
- (ii) Boeing Service Bulletin MD11–28–126, Revision 3, dated June 3, 2011.

(2) This paragraph provides credit for actions required by paragraph (h) of this AD, if those actions were performed before March 26, 2014 (the effective date of AD 2014–03–07), using Boeing Service Bulletin MD11–28–126, Revision 3, dated June 3, 2011.

(m) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (n)(1) of this AD. Information may be emailed to: 9ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) AMOCs approved previously for AD 2014–03–07 are approved as AMOCs for the corresponding provisions of this AD.

(n) Related Information

(1) For more information about this AD, contact Samuel Lee, Aerospace Engineer, Propulsion Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5262; fax: 562–627–5210; email: samuel.lee@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110–SK57, Seal Beach, CA 90740; telephone 562–797–1717; Internet https://www.myboeingfleet.com. You may view this referenced service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on July 28, 2017.

John P. Piccola, Jr.,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2017-16560 Filed 8-16-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2015-2891; Airspace Docket No. 15-ANE-1]

Proposed Establishment of Class E Airspace; Deblois, ME

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to establish Class E airspace extending upward from 700 feet above the surface in Deblois, ME, to accommodate new area navigation (RNAV) global positioning system (GPS) standard instrument approach procedures (SIAPs) serving Deblois Flight Strip. Controlled airspace is necessary for the safety and management of instrument flight rules (IFR) operations at the airport.

DATES: Comments must be received on or before October 2, 2017.

ADDRESSES: Send comments on this rule to: U. S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE., West Bldg Ground Floor Rm W12-140, Washington, DC 20590; Telephone: 1-800-647-5527, or (202) 366-9826. You must identify the Docket No. FAA-2015-2891; Airspace Docket No. 15-ANE-1, at the beginning of your comments. You may also submit and review received comments through the Internet at http://www.regulations.gov. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays.

FAĂ Order 7400.11A, Airspace Designations and Reporting Points, and subsequent amendments can be viewed on line at http://www.faa.gov/air traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC, 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11A at NARA, call (202) 741–6030, or go to http:// www.archives.gov/federal register/ code of federal-regulations/ibr locations.html.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305–6364.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the

authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This proposed rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would establish Class E airspace extending upward from 700 feet above the surface at Deblois Flight Strip, Deblois, ME, to support IFR operations in standard instrument approach procedures at the

Comments Invited

Interested persons are invited to comment on this proposed rule by submitting such written data, views, or arguments, as they may desire.

Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA–2015–2891 and Airspace Docket No. 15–ANE–1) and be submitted in triplicate to DOT Docket Operations (see ADDRESSES section for address and phone number). You may also submit comments through the Internet at http://www.regulations.gov.

Persons wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2015-2891; Airspace Docket No. 15-ANE-1." The postcard will be date/time stamped and returned to the commenter.

All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded through the internet at http://www.regulations.gov. Recently published rulemaking

documents can also be accessed through the FAA's Web page at http:// www.faa.gov/air_traffic/publications/ airspace amendments/.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the ADDRESSES section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays. An informal docket may also be examined between 8:00 a.m. and 4:30 p.m., Monday through Friday, except federal holidays at the office of the Eastern Service Center, Federal Aviation Administration, room 350, 1701 Columbia Avenue, College Park, Georgia 30337.

Availability and Summary of Documents for Incorporation by Reference

This document proposes to amend FAA Order 7400.11A, Airspace Designations and Reporting Points, dated August 3, 2016, and effective September 15, 2016. FAA Order 7400.11A is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11A lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Proposal

The FAA is considering an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 to establish Class E airspace extending upward from 700 feet above the surface within a 7-mile radius of Deblois Flight Strip, Deblois, ME, providing the controlled airspace required to support the new RNAV (GPS) standard instrument approach procedures for IFR operations at the airport.

Class E airspace designations are published in Paragraph 6005 of FAA Order 7400.11A, dated August 3, 2016, and effective September 15, 2016, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

Regulatory Notices and Analyses

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February

26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

This proposal would be subject to an environmental analysis in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures" prior to any FAA final regulatory action.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.11A, Airspace Designations and Reporting Points, dated August 3, 2016, effective September 15, 2016, is amended as follows:

Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.

ANE ME E5 Deblois Flight Strip, Deblois, ME [New]

Deblois Flight Strip, ME (Lat. 44°43'35" N., long. 67°59'27" W.)

That airspace extending upward from 700 feet above the surface within a 7-mile radius of Deblois Flight Strip, and within 1-mile either side of a 135° bearing from the airport, extending from the 7-mile radius to 10.5 miles southeast of the airport.

Issued in College Park, Georgia, on August 8, 2017

Ryan W. Almasy,

Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization. [FR Doc. 2017–17259 Filed 8–16–17; 8:45 am] BILLING CODE 4910–13–P

AMERICAN BATTLE MONUMENTS COMMISSION

36 CFR Part 407

RIN 3263-AA00

Commission.

AGENCY: American Battle Monuments

ACTION: Proposed rule.

ABMC Privacy Program

SUMMARY: This rule provides guidance and assigns responsibility for the privacy program under the American Battle Monuments Commission (ABMC) pursuant to the Privacy Act of 1974 and applicable Office of Management Budget (OMB) guidance.

DATES: Send comments on or before October 16, 2017.

ADDRESSES: You may send comments, identified by RIN number, by the following method:

• Federal Rulemaking Portal: http://www.regulations.gov.

Follow the instructions for submitting comments. All submissions received must include the agency name and docket number or RIN for this document. The general policy for comments and other submissions from members of the public is to make these submissions available for public viewing at http://www.regulations.gov as they are received without change, including any personal identifiers or contact information.

FOR MORE INFORMATION CONTACT: Edwin L. Fountain, General Counsel, American Battle Monuments Commission, 2300 Clarendon Boulevard Suite 500, Arlington VA 22201, fountaine@abmc.gov.

SUPPLEMENTARY INFORMATION: The authority for this rulemaking is 5 U.S.C. 552a, the Privacy Act of 1974, as amended, which requires the implementation of the Act by Federal agencies.

This action ensures that ABMC's collection, use, maintenance, or dissemination of information about individuals for purposes of discharging its statutory responsibilities will be performed in accordance with the Privacy Act of 1974 and applicable OMB guidance. This rule:

- Establishes rules of conduct for ABMC personnel and ABMC contractors involved in the design, development, operation, or maintenance of any system of records.
- Establishes appropriate administrative, technical, and physical safeguards to ensure the security and confidentiality of records and to protect against any anticipated threats or

hazards to their security or integrity that could result in substantial harm, embarrassment, inconvenience, or unfairness to any individual about whom information is maintained.

- Ensures that guidance, assistance, and subject matter expert support are provided ABMC staff, contractors and the public as needed in the implementation and execution of and compliance with the ABMC Privacy Program.
- Ensures that laws, policies, procedures, and systems for protecting individual privacy rights are implemented throughout ABMC.

Regulatory Procedures

Executive Order 12866, Regulatory Planning and Review, and Executive Order 13563, Improving Regulation and Regulatory Review

Executive Orders 12866 and 13563 direct agencies to assess all costs and benefits of available regulatory alternatives and, if regulation is necessary, to select regulatory approaches that maximize net benefits (including potential economic, environmental, public health and safety effects, distributive impacts, and equity). Executive Order 13563 emphasizes the importance of quantifying both costs and benefits, of reducing costs, of harmonizing rules, and of promoting flexibility. This rule benefits the public and the United States Government by providing clear procedures for members of the public, contractors, and employees to follow with regard to the ABMC privacy program. This rule has been designated a not significant regulatory action.

Unfunded Mandates Reform Act

Section 202 of the Unfunded Mandates Reform Act of 1995 (UMRA) (2 U.S.C. 1532) requires agencies to assess anticipated costs and benefits before issuing any rule whose mandates require spending in any 1 year of \$100 million in 1995 dollars, updated annually for inflation. In 2016, that threshold is approximately \$146 million. This rule will not mandate any requirements for State, local, or tribal governments, nor will it affect private sector costs.

Public Law 96–354, Regulatory Flexibility Act

The ABMC certifies this proposed rule is not subject to the Regulatory Flexibility Act (5 U.S.C. Ch. 6) because it would not, if promulgated, have a significant economic impact on a substantial number of small entities. Therefore, the Regulatory Flexibility