

- Replacing the yoke assembly would require 6 work-hours and \$798 for parts, for a cost of \$1,308 per helicopter.

- Inspecting for and applying sealant would require 1 work-hour and \$30 for parts, for a cost of \$115 per helicopter.

Based on these costs, we expect a total cost of \$1,423 per helicopter and \$354,327 for the U.S. operator fleet.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Robinson Helicopter Company: Docket No. FAA-2017-0682; Directorate Identifier 2017-SW-028-AD.

(a) Applicability

This AD applies to Robinson Helicopter Company (Robinson) Model R66 helicopters, serial numbers 0003 through 0752, with a tail rotor drive shaft assembly part number (P/N) D224-3 or D224-4 tail rotor drive shaft assembly installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as failure of a tail rotor driveshaft forward bearing. This condition could result in failure of the tail rotor driveshaft and subsequent loss of helicopter control.

(c) Comments Due Date

We must receive comments by May 29, 2018.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

Within 100 hours TIS:

- (1) Replace the tail rotor drive shaft forward yoke assembly with a yoke assembly part number D224-5, if not previously done.
- (2) Remove the forward inspection plug assembly from the tailcone and either remove the B322-2 cover from the top of the third tailcone bay or, if an antenna is installed, remove the antenna and pull the circuit breaker.
- (3) Visually inspect the forward and aft sides of the hanger bearing and damper bearing for sealant along the junction of the seal and bearing outer race. If the sealant is less than 0.5 inch in length, clean the area and apply a minimum 0.5 inch long bead of polysulfide fuel-resistant sealant at the junction of the seal and bearing outer race.

(f) Alternative Methods of Compliance (AMOC)

- (1) The Manager, Los Angeles ACO Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Danny Nguyen, Aerospace Engineer, Los Angeles ACO Branch, Compliance & Airworthiness Division, FAA,

3960 Paramount Blvd., Lakewood, California 90712; telephone (562) 627-5247; email 9-ANM-LAACO-AMOC-REQUESTS@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

For service information identified in this AD, contact Robinson Helicopter Company, 2901 Airport Drive, Torrance, CA 90505; telephone (310) 539-0508; fax (310) 539-5198; or at <http://www.robinsonheli.com/servelib.htm>. You may review a copy of information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6510, Tail Rotor Drive Shaft.

Issued in Fort Worth, Texas, on March 23, 2018.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2018-06449 Filed 3-29-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2017-0954; Airspace Docket No. 17-AEA-16]

Proposed Amendment of Class D and Class E Airspace; Beaver Falls, PA; and Zelienople, PA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E airspace extending upward from 700 feet or more above the surface, at Beaver Falls, PA, as the University of Pittsburgh Medical Center Beaver Valley Heliport has closed, and controlled airspace is no longer required. The geographic coordinates of the Ellwood City VORTAC, noted in the Beaver County Airport, Beaver Falls, PA, description, also would be amended in the associated Class E airspace. Also, the term Airport Facility Directory would be replaced with Chart Supplement. Additionally, this action would amend Class E airspace extending upward from 700 feet or more above the surface at Zelienople

Municipal Airport (formerly Zelenople Airport), PA, by recognizing the airport's name change and updating the airport's geographical coordinates. Controlled airspace is necessary for the safety and management of instrument flight rules (IFR) operations at these airports.

DATES: Comments must be received on or before May 14, 2018.

ADDRESSES: Send comments on this proposal to: U. S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE, West Bldg. Ground Floor Rm W12-140, Washington, DC 20590; telephone: 1(800) 647-5527, or (202) 366-9826. You must identify the Docket No.

FAA-2017-0954; Airspace Docket No. 17-AEA-16, at the beginning of your comments. You may also submit and review received comments through the internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays.

FAA Order 7400.11B, Airspace Designations and Reporting Points, and subsequent amendments can be viewed on line at <http://www.faa.gov/air-traffic/publications/>. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC, 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11B at NARA, call (202) 741-6030, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Ave., College Park, GA 30337; telephone (404) 305-6364.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is

promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would amend Class D and E airspace at Beaver County Airport, Beaver Falls, PA, and Class E airspace at Zelenople Municipal Airport, Zelenople, PA, to support IFR operations at these airports.

Comments Invited

Interested persons are invited to comment on this rule by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers and be submitted in triplicate to the address listed above. You may also submit comments through the internet at <http://www.regulations.gov>.

Persons wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2017-0954; Airspace Docket No. 17-AEA-16." The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded through the internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's web page at http://www.faa.gov/air-traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the

ADDRESSES section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays. An informal docket may also be examined between 8:00 a.m. and 4:30 p.m., Monday through Friday, except federal holidays at the office of the Eastern Service Center, Federal Aviation Administration, room 350, 1701 Columbia Avenue, College Park, GA 30337.

Availability and Summary of Documents for Incorporation by Reference

This document proposes to amend FAA Order 7400.11B, Airspace Designations and Reporting Points, dated August 3, 2017, and effective September 15, 2017. FAA Order 7400.11B is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11B lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Proposal

The FAA is considering an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 to amend Class E airspace extending upward from 700 feet or more above the surface of removing University of Pittsburgh Medical Center Beaver Valley Heliport, contained within the Beaver County Airport airspace description, as the heliport has closed. Also, the term Airport/Facility Directory would be replaced with Chart Supplement, and exclusionary language would be removed from the airspace description, in the associated Class D and E airspace.

Additionally, the geographic coordinates of the Ellwood City VORTAC would be adjusted in the associated Class E airspace to be in concert with the FAA's aeronautical database.

Finally, the Zelenople Municipal Airport, (formerly Zelenople Airport), Zelenople, PA, name change would be recognized, and the geographic coordinates of the airport would be adjusted to coincide with the FAA's aeronautical database. Exclusionary language also would be removed from the airspace description as it is not needed to describe the boundary.

Class D and E airspace designations are published in Paragraphs 5000, 6004, and 6005, respectively, of FAA Order 7400.11B, dated August 3, 2017, and effective September 15, 2017, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

Regulatory Notices and Analyses

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

This proposal will be subject to an environmental analysis in accordance with FAA Order 1050.1F, “Environmental Impacts: Policies and Procedures” prior to any FAA final regulatory action.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.11B, Airspace Designations and Reporting Points, dated August 3, 2017, and effective September 15, 2017, is amended as follows:

Paragraph 5000 Class D Airspace.

* * * * *

AEA PA D Beaver Falls, PA [Amended]

Beaver County Airport, PA
(Lat. 40°46′21″ N, long. 80°23′29″ W)

That airspace extending upward from the surface to and including 3,800 feet MSL

within a 3.9-mile radius of the Beaver County Airport. This Class D airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Chart Supplement.

Paragraph 6004 Class E Airspace Designated as an Extension to Class D or E Surface Area.

* * * * *

AEA PA E4 Beaver Falls, PA [Amended]

Beaver County Airport, PA
(Lat. 40°46′21″ N, long. 80°23′29″ W)
Ellwood City VORTAC
(Lat. 40°49′30″ N, long. 80°12′41″ W)

That airspace extending upward from the surface within 1.3 miles each side of the Ellwood City VORTAC 248° radial extending from the 3.9-mile radius of Beaver County Airport to 1.3 miles west of the VORTAC. This Class E airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Chart Supplement.

Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.

* * * * *

AEA PA E5 Beaver Falls, PA [Amended]

Beaver County Airport, PA
(Lat. 40°46′21″ N, long. 80°23′29″ W)
Ellwood City VORTAC
(Lat. 40°49′30″ N, long. 80°12′42″ W)

That airspace extending upward from 700 feet above the surface within a 6.4-mile radius of Beaver County Airport, and within 1.8-miles each side of Ellwood City VORTAC 248° radial extending from the 6.4-mile radius to the VORTAC.

* * * * *

AEA PA E5 Zelienople, PA [Amended]

Zelienople Municipal Airport, PA
(Lat. 40°48′07″ N, long. 80°09′39″ W)

That airspace extending upward from 700 feet above the surface within a 6-mile radius of Zelienople Municipal Airport.

Issued in College Park, Georgia, on March 14, 2018.

Ryan W. Almasy,
Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization.

[FR Doc. 2018–06389 Filed 3–29–18; 8:45 am]

BILLING CODE 4910–13–P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA–R05–OAR–2017–0100; EPA–R05–OAR–2017–0501; FRL–9976–10—Region 5]

Air Plan Approval; Michigan; Revisions to Volatile Organic Compound Rules

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: The Environmental Protection Agency (EPA) is proposing to approve revised rules submitted by the State of Michigan as State Implementation Plan (SIP) revisions. The main revision specifies volatile organic compound (VOC) limits for cutback and emulsified asphalts as well as the test methods for determining the VOC content of these products. Michigan also moved the adoption by reference citations from Part 6. Emission Limitations and Prohibitions—Existing Sources of Volatile Organic Emissions to Part 9. Emission Limitations and Prohibitions—Miscellaneous and updated references to federal test methods in several of its Part 6 rules.

DATES: Comments must be received on or before April 30, 2018.

ADDRESSES: Submit your comments, identified by Docket ID No. EPA–R05–OAR–2017–0100 or EPA–R05–OAR–2017–0501 at <http://www.regulations.gov> or via email to Aburano.Douglas@epa.gov. For comments submitted at Regulations.gov, follow the online instructions for submitting comments. Once submitted, comments cannot be edited or removed from Regulations.gov. For either manner of submission, EPA may publish any comment received to its public docket. Do not submit electronically any information you consider to be Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Multimedia submissions (audio, video, etc.) must be accompanied by a written comment. The written comment is considered the official comment and should include discussion of all points you wish to make. EPA will generally not consider comments or comment contents located outside of the primary submission (*i.e.* on the web, cloud, or other file sharing system). For additional submission methods, please contact the person identified in the **FOR FURTHER INFORMATION CONTACT** section. For the full EPA public comment policy, information about CBI or multimedia submissions, and general guidance on making effective comments, please visit <http://www2.epa.gov/dockets/commenting-epa-dockets>.

FOR FURTHER INFORMATION CONTACT:

Steven Rosenthal, Environmental Engineer, Attainment Planning and Maintenance Section, Air Programs Branch (AR–18J), Environmental Protection Agency, Region 5, 77 West Jackson Boulevard, Chicago, Illinois 60604, (312) 886–6052, rosenthal.steven@epa.gov.