

Consumer Information, and 581, Bumper Standard.

The petitioner contends that the non-U.S. certified MY 2016 Porsche 911R vehicles not-conforming to FMVSSs are capable of being readily modified to meet the following FMVSSs, in the manner indicated:

- FMVSS No. 101, *Controls and Displays*:

Replacement of Instrument Cluster: 991-641-215-01 and programming of the Instrument Cluster and Gateway Module are required to bring these systems into compliance with FMVSS.

- FMVSS No. 108, *Lamps, Reflective Devices and Associated Equipment*:

The following modifications must be made to the European specification model, to fully meet this FMVSS: The wiring harness for the USA side marker lights is standard but not active in the Porsche 911R. Replacement of the following parts and programming is necessary to activate the USA lighting programs systems.

Headlight LH: 991-631-997-50, Headlight RH: 991-631-998-50, Taillamp RH: 991-631-145-84, Taillamp LH: 991-631-145-83, Front Side Marker Lamp: 991-631-257-05, Front Side Marker Lamp: 991-631-258-05.

- FMVSS No. 110, *Tire Selection and Rims and Motor Home/Recreation Vehicle Trailer Load Carrying Capacity Information for Motor Vehicles with a GVWR of 4,536 Kilograms (10,000 pounds) or Less*:

The European specification model requires the tire placard to be installed to meet this FMVSS. The tire/rim label is available to meet the new regulations.

- FMVSS No. 111, *Rear Mirrors*:

The European specification model drivers inside rearview mirror meets this FMVSS. However, the passenger's outside rearview mirror must be changed to the U.S. companion model part to meet this FMVSS. Passenger's Outside Rearview mirror: 991-731-048-01.

The sample vehicle, a MY 2016 Porsche 911R (VIN: WP0ZZZ99ZGxxxxxxx), which is claimed to have been originally manufactured for sale in Europe, was fitted with the U.S. specification Passenger's Rearview Mirror—991-731-048-01 to be brought into compliance with this FMVSS.

- FMVSS No. 201, *Occupant Protection in Interior Impact*:

The following parts need to be changed to bring the European specification model into compliance with this FMVSS.

The sample vehicle, a MY 2016 Porsche 911R (VIN:

WP0ZZZ99ZGxxxxxxx), which is claimed to have been originally manufactured for sale in Europe, was fitted with the U.S. specification *Driver's Sun Visor*: 991-731-981-09, *Passenger's Sun Visor*: 991-731-982-09 from the factory, and is already in compliance with this FMVSS.

- FMVSS No. 208, *Occupant Crash Protection*:

The following parts need to be changed to bring the European specification model into compliance with this FMVSS:

Passenger Seat Occupant Detection Repair Kit: 918-618-945-01.

Passenger Bucket Seat Repair Kit: 918-521-904-03.

Airbag Control Unit: 991-618-201-08.

Passenger's Seat Wiring Harness: 991-622-785-01.

Driver's Seat Wiring Harness: 991-622-786-01.

Both Driver's and Passenger's Seat Position Sensors: 9P1-898-070.

Passenger Seatbelt Buckle: 991-803-184-07.

Passenger's Side Knee Airbag: 991-803-061-00, with 2 Hexagon Head Bolts: 999-919 278-01.

Driver's Side Knee Airbag: 991-803-061-00, with 2 Hexagon Head Bolts: 999-919-278-.

Overhead Dome Light Module: 991-613-224-10.

Dashboard Wiring Harness: 991-612-902-00.

Body Wiring Harness: 991-612-901-00.

- FMVSS No. 301, *Fuel System Integrity*:

Parts of these systems, which include the ORVR (On board Refueling Vapor Recovery) systems, must be replaced and programming of the Engine Control Module to bring into compliance with FMVSS 301.

The sample vehicle, a MY 2016 Porsche 911R (VIN: WP0ZZZ99ZGxxxxxxx), which is claimed to have been originally manufactured for sale in Europe, *Fuel Tank Filler Neck*: 991-201-044-13, *Activated Charcoal Canister*: 991-201-225-93, DMTL.

Pressure Switch: 991-606-621-07, *Breather Vapor Line*: 991-201-251-06, *DME, Engine Control, Module*: 991-618-603-00.

- 49 CFR part 565 *Vehicle Identification Number (VIN) Requirements* and Part 567 *Certification*:

A VIN plate must be added to both European and Mexican specifications models near the left windshield post and a reference and certification label must be added in the left front door post area to meet these regulations.

- 49 CFR part 575 *Consumer Information*:

Owner's manual and all other information manuals must be replaced with the OEM Manuals for both the European and Mexican specification models. Owner's Manual—86075400, Quick Reference Guide—86076100.

- 49 CFR 581 *Bumper Standard*:

The European specification requires the front and rear bumpers to be modified or changed to meet this FMVSS. Front Bumper—86235610, Rear Bumper—86320810.

The sample vehicle, a MY 2016 Porsche 911R (VIN: WP0ZZZ99ZGxxxxxxx), which is claimed to have been originally manufactured for sale in Europe, was fitted with the U.S. Rear Bumper—991-505-141-91 from the factory and is already in compliance with this regulation.

(Authority: 49 U.S.C. 30141(a)(1)(A), (a)(1)(B), and (b)(1); 49 CFR 593.7; delegation of authority at 49 CFR 1.95 and 501.8.)

Otto G. Matheke III,

Director, Office of Vehicle Safety Compliance.

[FR Doc. 2026-18197 Filed 9-4-26; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF THE TREASURY

Office of the Comptroller of the Currency

Agency Information Collection Activities: Information Collection Renewal; Submission for OMB Review; Supervisory Guidance: Supervisory Review Process of Capital Adequacy (Pillar 2) Related to the Implementation of the Basel II Advanced Capital Framework

AGENCY: Office of the Comptroller of the Currency (OCC), Treasury.

ACTION: Notice and request for comment.

SUMMARY: The OCC, as part of its continuing effort to reduce paperwork and respondent burden, invites comment on a continuing information collection, as required by the Paperwork Reduction Act of 1995 (PRA). In accordance with the requirements of the PRA, the OCC may not conduct or sponsor, and the respondent is not required to respond to, an information collection unless it displays a currently valid Office of Management and Budget (OMB) control number. The OCC is soliciting comment concerning the renewal of its information collection titled, "Supervisory Guidance: Supervisory Review Process of Capital Adequacy (Pillar 2) Related to the

Implementation of the Basel II Advanced Capital Framework.” The OCC is also giving notice that it has sent the collection to OMB for review.

DATES: Comments must be received by October 8, 2026.

ADDRESSES: Commenters are encouraged to submit comments by email, if possible. You may submit comments by any of the following methods:

- *Email:* prainfo@occ.treas.gov.
- *Mail:* Chief Counsel’s Office,

Attention: Comment Processing, Office of the Comptroller of the Currency, Attention: 1557–0242, 400 7th Street SW, Suite 1E–216, Washington, DC 20219.

- *Hand Delivery/Courier:* 400 7th Street SW, Suite 1E–216, Washington, DC 20219.

- *Fax:* (571) 293–4835.

Instructions: You must include “OCC” as the agency name and “1557–0242” in your comment. In general, the OCC will publish comments on www.reginfo.gov without change, including any business or personal information provided, such as name and address information, email addresses, or phone numbers. Comments received, including attachments and other supporting materials, are part of the public record and subject to public disclosure. Do not include any information in your comment or supporting materials that you consider confidential or inappropriate for public disclosure.

Written comments and recommendations for the proposed information collection should also be sent within 30 days of publication of this notice to www.reginfo.gov/public/do/PRAMain. You can find this information collection by selecting “Currently under 30-day Review—Open for Public Comments” or by using the search function.

You may review comments and other related materials that pertain to this information collection following the close of the 30-day comment period for this notice by the method set forth in the next bullet.

- **Viewing Comments Electronically:** Go to www.reginfo.gov. Hover over the “Information Collection Review” tab and click on “Information Collection Review” from the drop-down menu. From the “Currently under Review” drop-down menu, select “Department of Treasury” and then click “submit.” This information collection can be located by searching OMB control number “1557–

0242” or “Supervisory Guidance: Supervisory Review Process of Capital Adequacy (Pillar 2) Related to the Implementation of the Basel II Advanced Capital Framework.” Upon finding the appropriate information collection, click on the related “ICR Reference Number.” On the next screen, select “View Supporting Statement and Other Documents” and then click on the link to any comment listed at the bottom of the screen.

- For assistance in navigating www.reginfo.gov, please contact the Regulatory Information Service Center at (202) 482–7340.

FOR FURTHER INFORMATION CONTACT:

Shaquita Merritt, Clearance Officer, (202) 649–5490, Chief Counsel’s Office, Office of the Comptroller of the Currency, 400 7th Street SW, Washington, DC 20219. If you are deaf, hard of hearing, or have a speech disability, please dial 7–1–1 to access telecommunications relay services.

SUPPLEMENTARY INFORMATION: Under the PRA (44 U.S.C. 3501 *et seq.*), Federal agencies must obtain approval from the OMB for each collection of information that they conduct or sponsor.

“Collection of information” is defined in 44 U.S.C. 3502(3) and 5 CFR 1320.3(c) to include agency requests or requirements that members of the public submit reports, keep records, or provide information to a third party. The OCC asks the OMB to extend its approval of the collection in this notice.

Title: Supervisory Guidance: Supervisory Review Process of Capital Adequacy (Pillar 2) Related to the Implementation of the Basel II Advanced Capital Framework.

OMB Control No.: 1557–0242.

Type of Review: Regular.

Affected Public: Businesses or other for-profit.

Description: In 2008, the OCC, Board of Governors of the Federal Reserve System, and Federal Deposit Insurance Corporation issued a supervisory guidance document to assist banking organizations in implementing the supervisory review process, or Pillar 2, of the advanced approaches risk-based capital rule.¹ Therefore, this guidance is relevant for OCC-supervised national banks and Federal savings associations (collectively, banks) that are subject to the advanced approaches capital rule.² It does not apply to small banks.

Paragraphs 37, 41, 43, and 46 of the guidance contain information collections. Paragraph 37 provides that a bank should clearly state the definition of capital used in any aspect of its internal capital adequacy assessment process (ICAAP) and document any changes in the internal definition of capital. Paragraph 41 provides that banks should maintain thorough documentation of ICAAP. Paragraph 43 specifies that the board of directors should approve the bank’s ICAAP, review it on a regular basis, and approve any changes. Boards of directors, under paragraph 46, should periodically, and at least annually, review the assessment of overall capital adequacy and analyze how measures of internal capital adequacy compare with other capital measures (such as regulatory or accounting).

Estimated Burden

Estimated Frequency of Response: On occasion.

Estimated Number of Respondents: 16.

Estimated Burden per Respondent: 140 hours.

Estimated Total Annual Burden: 2,240 hours.

Comments: On June 12, 2026, the OCC published a 60-day notice for this information collection at 91 FR 35794. No comments were received.

Comments continue to be invited on:

(a) Whether the collection of information is necessary for the proper performance of the functions of the OCC, including whether the information has practical utility;

(b) The accuracy of the OCC’s estimate of the burden of the collection of information;

(c) Ways to enhance the quality, utility, and clarity of the information to be collected;

(d) Ways to minimize the burden of the collection on respondents, including through the use of automated collection techniques or other forms of information technology; and

(e) Estimates of capital or start-up costs and costs of operation, maintenance, and purchase of services to provide information.

Carl Kaminski,

Assistant Director, Office of the Comptroller of the Currency.

[FR Doc. 2026–18259 Filed 9–4–26; 8:45 am]

BILLING CODE 4810–33–P

¹ 73 FR 44620 (July 31, 2008).

² See 12 CFR 3.100(b).